

EN5010

INS. CASE OWNER:

CC6/III1900

LKK:

IDAC:

Surveyor:

KSC

DOE:

ASSIGNMENT

25/1/19

Date / Time:

25/1/19

Registered in Meriten:

25/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 4863 u.

Name of Insured:

CTOL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/2/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: ng an unmy

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Midmodis

Kian Vian

Punggol New Co

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLT 6291P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hui Yang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting Ir (1st):	
	Non-Reporting Ir (2nd):	
	Non-Reporting Ir (Final):	
	Notification Ir (if non-pickup):	
	Call OI:	
	After call Ir to OI:	
	Documentation Check List: Handler Typist	
	Notification Ir (if non-pickup):	☒
	After call Ir to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / CIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: 45	SS 16,700.00	12 days Reduction: 41,033.13 = 40
FINAL SETTLEMENT	Date/Time: 21/1/19	Confirm with: Sandra
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: Nil.
Repair Cost: (w/ GST)	SS 17,869.00	
Loss of Rental (LOR):	SS -	(days)
Loss of Use (LOU):	SS 1400.00	(100 x 14 days)
Loss of Income (LOI):	SS -	(5 x days)
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LO ☐	[Tick only one]
GIA/LTA Search:	SS -	
Site fee:	SS -	
Disbursement:	SS -	(e.g. Tow / Independent)
Legal Cost:	SS -	
Total:	SS 19,269.00	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 19,269.00	Name 1: Hui Yang Motor Pte Ltd
Payee 2: (Strike if N.A.)	SS -	Name 2:
Payee 3: (Strike if N.A.)	SS -	Name 3:

ASS. REC. BY:

REF: TU /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Hui Yang

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8786

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCT 8291P Yr Regn: 11, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1797Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 120578 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: EVW40 - 0026610Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rlm / STP A/Rlm orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Crown Ride

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 10/2/19 D.O.I. 25/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

N/S Area & Rec. d/s

The U/C / Chassis frame & Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass toL/S 916,700 - (Red = \$11,037.13 / 40 T.)12 repair days + 1 Sunday + 1 PRS = 14 days.

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

10/02/2019

Owner: MKM CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT6291P

balance b/f

\$ 23,082.85

1pc rear end panel
1pc rear end panel inner garnish
1pc rear float panel garnish
1pc rear float panel LH side garnish
1pc * air bag control unit

By \$ 531.35 X
In \$ 371.85 X
In \$ 581.90 X
In \$ 381.25 X
In \$ 1,217.45 X

13,982.55
14,409.79

less 25%

\$ 26,166.65

\$ 6,541.66

\$ 19,624.99

1set rear parking sensor
2pcs rear tyre @\$160.00

wire 00
192SN Pn s.nett \$ 280.00 200SN
392.00 s.nett \$ 320.00 60SN

remove & refit rear cushios
remove & refit rear undercarriage
remove & refit petrol tank
remove & refix rear windscreen glass
remove & refit roof top tirm
remove & refit air bag & reset
reprogram ECU & Hybrid Battery
towing
sealant N/A
tuffkote
wiring
spray painting
labour charges
Total

\$ 180.00 1201
\$ 380.00 2401
\$ 180.00 601
\$ 150.00 1201
\$ 160.00 1001
\$ 320.00 2501
\$ 380.00 2501
\$ 100.00 ✓
\$ 80.00 401A
\$ 120.00 ✓
\$ 120.00 801
\$ 1,600.00 12001
\$ 1,600.00 14001
\$ 25,594.99

4040.00



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

10/02/2019

Owner: MKM CAR LEASING PTE LTD

SUPPLEMENTARY TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT6291P

1pc	rear axle	2315-60	B1 \$ 2,850.85 ✓
			\$ 2,850.85
	less 25%		
			\$ 712.71
	Total		
			\$ 2,138.14

1736.33



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

10/02/2019

Owner: MKM CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT6291P

1pc	rear LH door	R	\$ 1,217.45	✓
2pcs	rear LH door hinge @\$141.45	R	\$ 282.90	X
1pc	rear LH door frame sticker	re	\$ 132.25	✓
1pc	rear LH door glass motor & gear		\$ 374.45	?
1pc	rear LH door glass pillar		\$ 181.25	?
1pc	rear LH door inner lock		\$ 581.90	?
1pc	rear LH door inner rubber	re	\$ 172.45	X
1pc	rear LH door panel	re	\$ 621.25	X
1pc	LH side skirt	CM	\$ 681.90	✓
1pc	LH side air bag	Refr	\$ 1,712.45	✓
1pc	LH side air bag impact sensor	re	\$ 381.90	✓
1pc	rear LH fender	R	\$ 971.50	✓
1pc	rear LH fender air-duct	CM	\$ 178.85	✓
1pc	rear LH fender inner shield	CM	\$ 182.25	✓
8pcs	rear LH fender inner shield clip @\$5.00	re	\$ 40.00	✓
1pc	rear LH fender inner garnish	Refr	\$ 691.45	✓
1pc	rear LH wheel house		\$ 561.60	?
2pcs	rear sport rim @\$1218.10	nd/cm	\$ 2,436.20	✓
2pcs	rear adsorber @\$274.45		\$ 548.90	?
2pcs	rear wheel bearing @\$561.60	re	\$ 1,123.20	✓
2pcs	rear ABS sensor @\$381.85		\$ 763.70	?
1pc	rear LH disc plate		\$ 531.35	?
1pc	rear LH brake caliper	re	\$ 371.85	X
1pc	roof top trim	CM	\$ 1,715.45	✓
2pcs	rear taillamp @\$581.90	CM	\$ 1,163.80	✓
2pcs	rear taillamp lower bracket @\$172.10		\$ 344.20	?
1pc	rear taillamp RH panel		\$ 377.45	?
1pc	rear tailgate	R	\$ 1,518.45	✓
1pc	rear tailgate "PRIUS" emblem	re	\$ 61.10	✓
1pc	rear tailgate "HYBRID" emblem	re	\$ 63.90	✓
1pc	rear tailgate inner lock	re	\$ 581.90	X
1pc	rear tailgate inner rubber	re	\$ 374.45	X
1pc	rear tailgate inner garnish		\$ 581.90	?
1pc	rear tailgate windscreen moulding	re	\$ 175.45	✓
1pc	rear bumper	R	\$ 681.90	✓
2pcs	rear bumper side retainer @\$172.10	CM	\$ 344.20	✓
2pcs	rear bumper side reflector @\$178.85	015?	\$ 357.70	✓
	balance c/f		\$ 23,082.85	



India
26/02/19 (Tue)
LICK

Not Authorized
11 hrs 8?
Recovery After Paint
12 days

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

10/02/2019

Owner: MKM CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLT6291P

balance b/f				\$ 23,082.85
1pc	rear end panel	Pr	\$ 531.35	X
1pc	rear end panel inner garnish	Pr	\$ 371.85	X
1pc	rear float panel garnish	Pr	\$ 581.90	X
1pc	rear float panel LH side garnish	Pr	\$ 381.25	X
1pc	air bag control unit		\$ 1,217.45	?
				\$ 26,166.65
less 25%				\$ 6,541.66
				\$ 19,624.99
1set	rear parking sensor		s.nett \$ 280.00	?
2pcs	rear tyre @\$160.00	Pr	s.nett \$ 320.00	60% Pr
remove & refit rear cushios			\$ 180.00	1200
remove & refit rear undercarriage			\$ 380.00	2400
remove & refit petrol tank			\$ 180.00	600
remove & refix rear windscreen glass			\$ 150.00	1200
remove & refit roof top trim			\$ 160.00	1000
remove & refit air bag & reset			\$ 320.00	2500
reprogram ECU & Hybrid Battery			\$ 380.00	2500
towing			\$ 100.00	✓
sealant			\$ 80.00	4000
tuffkote			\$ 120.00	✓
wiring			\$ 120.00	400
spray painting			\$ 1,600.00	12000
labour charges			\$ 1,600.00	14000
Total				
				\$ 25,594.99

LKK Auto Consultants hence notify the Repairer of the following:

- To recover betweenment spray painting
- To ensure damaged part of body recovery
- Parts prices are subject to confirmation
- This quote is only for a "without Reproduction" basis
- No work is to be done without approval
- Insurance claim must be recovered and submitted to LKK Auto Consultants from Insurance Company

Authorised by Repairer
Signature
Date



Print Received Message

This mail is associated with :

***SLT6291P (MCT19020259)**

[SHD4663U]

TP

MKM CAR LEASING PTE LTD

Feb 10 2019 12:00PM

[COMFORT TRANSPORTATION PTE LTD]

Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 14/11/2019 09:43 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$19269.00) - SLT6291P - Claim Handler: Sundari Nagarajan

Approved:19269.00:Request TP WS to issue Tax invoice for Repairs in III's favour

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Feb 2019 Edit Reg		25 Feb 2019 00:00 Edit Adj Rpt	S\$16,700.00 Edit Estimates	S\$16,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	MKH CAR LEASING PTE LTD, Co. Reg. No.: 201224734R								
Vehicle Reg. No.:	SLT6291P	Date of Loss:	10/02/2019 12:00 - :59 [15 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19020259	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD4663U	Policy No. (Claimant):	999994421						
		Excess:							
Repairer:	Hul Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagaraajan - 6347 6071]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (14/11/2019): Alert - Adj Mandate Approved (S\$19269.00) - SLT6291P - Claim Handler: Sundari Na... - III_SG (28/08/2019): Alert - Adj Mandate Approved (S\$0.00) - SLT6291P - Claim Handler: Sundari Nagara... - III_SG (12/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SLT6291P - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT6291P (MCT19020259)
[SHD4663U]
TP
MKM CAR LEASING PTE LTD
Feb 10 2019 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Video							1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail	Print
1	12/07/19 17:25	Video - Accident- IV					Load MP4	
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	01/10/19 11:13	General View					Load JPG	☒
2	01/10/19 11:13	General View					Load JPG	☒
3	01/10/19 11:13	General View					Load JPG	☒
4	01/10/19 11:13	General View					Load JPG	☒
5	01/10/19 11:13	General View					Load JPG	☒
6	01/10/19 11:13	General View					Load JPG	☒
7	01/10/19 11:13	General View					Load JPG	☒
8	01/10/19 11:13	General View					Load JPG	☒
9	01/10/19 11:13	General View					Load JPG	☒
10	01/10/19 11:13	General View					Load JPG	☒
11	01/10/19 11:13	General View					Load JPG	☒
12	01/10/19 11:13	General View					Load JPG	☒
13	01/10/19 11:13	General View					Load JPG	☒
14	01/10/19 11:13	General View					Load JPG	☒
15	01/10/19 11:13	General View					Load JPG	☒
16	01/10/19 11:13	General View					Load JPG	☒
17	01/10/19 11:13	General View					Load JPG	☒
18	01/10/19 11:13	General View					Load JPG	☒
19	01/10/19 11:13	General View					Load JPG	☒
20	01/10/19 11:13	General View					Load JPG	☒
21	01/10/19 11:13	General View					Load JPG	☒
22	01/10/19 11:13	General View					Load JPG	☒
23	01/10/19 11:13	General View					Load JPG	☒
24	01/10/19 11:13	General View					Load JPG	☒
25	01/10/19 11:13	General View					Load JPG	☒
26	01/10/19 11:13	General View					Load JPG	☒
27	01/10/19 11:13	General View					Load JPG	☒
28	01/10/19 11:13	General View					Load JPG	☒
29	01/10/19 11:13	General View					Load JPG	☒
30	01/10/19 11:16	General View					Load JPG	☒
31	01/10/19 11:16	General View					Load JPG	☒
32	01/10/19 11:16	General View					Load JPG	☒
33	01/10/19 11:16	General View					Load JPG	☒
34	01/10/19 11:16	General View					Load JPG	☒
35	01/10/19 11:16	General View					Load JPG	☒
36	01/10/19 11:16	General View					Load JPG	☒
37	01/10/19 11:16	General View					Load JPG	☒
38	01/10/19 11:16	General View					Load JPG	☒
39	01/10/19 11:16	General View					Load JPG	☒
40	01/10/19 11:16	General View					Load JPG	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
41	01/10/19 11:16	General View	 Load JPG	☒
42	01/10/19 11:16	General View	 Load JPG	☒
43	01/10/19 11:16	General View	 Load JPG	☒
44	01/10/19 11:16	General View	 Load JPG	☒
45	01/10/19 11:16	General View	 Load JPG	☒
46	01/10/19 11:16	General View	 Load JPG	☒
47	01/10/19 11:16	General View	 Load JPG	☒
48	01/10/19 11:16	General View	 Load JPG	☒
49	01/10/19 11:16	General View	 Load JPG	☒
50	01/10/19 11:16	General View	 Load JPG	☒
51	01/10/19 11:16	General View	 Load JPG	☒
52	01/10/19 11:16	General View	 Load JPG	☒
53	01/10/19 11:16	General View	 Load JPG	☒
54	01/10/19 11:16	General View	 Load JPG	☒
55	01/10/19 11:16	General View	 Load JPG	☒
56	01/10/19 11:16	General View	 Load JPG	☒
57	01/10/19 11:16	General View	 Load JPG	☒
58	01/10/19 11:16	General View	 Load JPG	☒
59	01/10/19 11:16	General View	 Load JPG	☒
60	01/10/19 11:16	General View	 Load JPG	☒
61	01/10/19 11:16	General View	 Load JPG	☒
62	01/10/19 11:16	General View	 Load JPG	☒
63	01/10/19 11:16	General View	 Load JPG	☒
64	01/10/19 11:16	General View	 Load JPG	☒
65	01/10/19 11:16	General View	 Load JPG	☒
66	01/10/19 11:16	General View	 Load JPG	☒
67	01/10/19 11:16	General View	 Load JPG	☒
68	01/10/19 11:16	General View	 Load JPG	☒
69	01/10/19 11:16	General View	 Load JPG	☒
70	01/10/19 11:16	General View	 Load JPG	☒
71	01/10/19 11:16	General View	 Load JPG	☒
72	01/10/19 11:16	General View	 Load JPG	☒
73	01/10/19 11:16	General View	 Load JPG	☒
74	01/10/19 11:16	General View	 Load JPG	☒
75	01/10/19 11:16	General View	 Load JPG	☒
76	01/10/19 11:16	General View	 Load JPG	☒
77	01/10/19 11:16	General View	 Load JPG	☒
78	01/10/19 11:16	General View	 Load JPG	☒
79	01/10/19 11:16	General View	 Load JPG	☒
80	01/10/19 11:16	General View	 Load JPG	☒
81	01/10/19 11:16	General View	 Load JPG	☒
82	01/10/19 11:16	General View	 Load JPG	☒
83	01/10/19 11:16	General View	 Load JPG	☒
84	01/10/19 11:16	General View	 Load JPG	☒
85	01/10/19 11:16	General View	 Load JPG	☒
86	01/10/19 11:16	General View	 Load JPG	☒
87	01/10/19 11:16	General View	 Load JPG	☒
88	01/10/19 11:16	General View	 Load JPG	☒
89	01/10/19 11:16	General View	 Load JPG	☒
90	01/10/19 11:16	General View	 Load JPG	☒
91	01/10/19 11:16	General View	 Load JPG	☒
92	01/10/19 11:16	General View	 Load JPG	☒
93	01/10/19 11:16	General View	 Load JPG	☒
94	01/10/19 11:16	General View	 Load JPG	☒
95	01/10/19 11:16	General View	 Load JPG	☒

Video			1 per page	☒
No.	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 17:45	TP EST & GIA REPORT		Load PDF
2	26/02/19 16:46	TP ESTIMATE- MARKED		Load PDF
3	01/10/19 11:22	LOD AND OTHER DOCUMENTS		Load PDF
4	25/10/19 15:04	WORKSHOP INVOICE		Load PDF
5	25/10/19 15:04	LOD		Load PDF
6	18/12/19 10:37	AUTHORISATION TO ACT FORM		Load PDF
7	18/12/19 10:37	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 08:55	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19003492/KGB3Q2

Date: 18/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: SLT6291P Insured Vehicle No: SHD4663U
 Vehicle No: SLT6291P Date of Loss: 10/02/2019 Nature of Claim: TP Claim No: MCT19020259

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT6291P
 Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A) Engine No: 2ZR0A05027
 Reg. Date: 03/11/2017 (Man. Year: 2017) Chassis No: ZVW400026610
 Colour: Metallic Silver Odometer: 120578 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Goodride 8 mm Rear Left Side: Goodride 8 mm
 Front Right Side: Goodride 8 mm Rear Right Side: Goodride 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,443.12	16,572.00	5,871.12	26.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	4,000.00	1,290.00	24.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,733.12	20,572.00	7,161.12	25.82
Approved Total (Overridden) (S\$)		16,700.00		
(S\$)	27,733.12	16,700.00	11,033.12	39.78
+ GST 7.00/7.00% (S\$)	1,941.32	1,169.00	772.32	39.78
Nett Amount (S\$)	29,674.44	17,869.00	11,805.44	39.78
+ Loss of Use (14.0 x S\$100.00/day) (S\$)		1,400.00		
Nett Liability (S\$)		19,269.00		

INSPECTION

Date of Assignment: 25/02/2019
 Date Inspected: 25/02/2019 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming
 AutoCare
 Singapore 575721
 Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2019)

Parts: 144 TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT6291P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Bent	1,217.45 FL	*1,217.45 FL
2	2		*REAR LH DOOR HINGE	Repair	282.90 FL	*- FL
3	1		*REAR LH DOOR FRAME STICKER	Necessary	132.25 FL	*132.25 FL
4	1		*REAR LH DOOR GLASS MOTOR & GEAR	Distorted / Jammed	374.45 FL	*374.45 FL
5	1		*REAR LH DOOR GLASS PILLAR	Dented	181.25 FL	*181.25 FL
6	1		*REAR LH DOOR INNER LOCK	Dented	581.90 FL	*581.90 FL
7	1		*REAR LH DOOR INNER RUBBER	Serviceable	172.45 FL	*- FL
8	1		*REAR LH DOOR PANEL	Serviceable	621.25 FL	*- FL
9	1		*LH SIDE SKIRT	Cracked	681.90 FL	*681.90 FL
10	1		*LH SIDE AIR BAG	Burst	1,712.45 FL	*1,712.45 FL
11	1		*LH SIDE AIR BAG IMPACT SENSOR	Necessary	381.90 FL	*381.90 FL
12	1		*REAR LH FENDER	Bent	971.50 FL	*971.50 FL
13	1		*REAR LH FENDER AIR-DUCT	Cracked	178.85 FL	*178.85 FL
14	1		*REAR LH FENDER INNER SHIELD	Cracked	182.25 FL	*182.25 FL
15	8		*REAR LH FENDER INNER SHIELD CLIP	Necessary	40.00 FL	*40.00 FL
16	1		*REAR LH FENDER INNER GARNISH	Deformed	691.45 FL	*691.45 FL
17	1		*REAR LH WHEEL HOUSE	Bent	581.60 FL	*581.60 FL
18	2		*REAR SPORT RIM	Dented / Cracked	2,436.20 FL	*2,436.20 FL
19	1		*REAR ABSORBER	N/S Bent	548.90 FL	*212.30 FL
20	2		*REAR WHEEL BEARING	Necessary (1 PCS ONLY)	1,123.20 FL	*561.60 FL
21	2		*REAR ABS SENSOR	Serviceable	763.70 FL	*- FL
22	1		*REAR LH DISE PLATE	Serviceable	531.35 FL	*- FL
23	1		*REAR LH BRAKE CALIPER	Serviceable	371.85 FL	*- FL
24	1		*ROOF TOP TRIM	Cracked	1,715.45 FL	*1,715.45 FL
25	1		*REAR TAILLAMP	Cracked	1,163.80 FL	*561.35 FL
			(2 PCS)			
26	2		*REAR TAILLAMP LOWER BRACKET	Cracked	344.20 FL	*344.20 FL
27	1		*REAR TAILLAMP RH PANEL	Bent	377.45 FL	*377.45 FL
28	1		*REAR TAILGATE	Bent	1,518.45 FL	*1,450.00 FL
29	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	61.10 FL	*61.10 FL
30	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	63.90 FL	*63.90 FL
31	1		*REAR TAILGATE INNER LOCK	Repair	581.90 FL	*- FL
32	1		*REAR TAILGATE INNER RUBBER	Serviceable	374.45 FL	*- FL
33	1		*REAR TAILGATE INNER GARNISH	Deformed	581.90 FL	*581.90 FL
34	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	175.45 FL	*175.45 FL
35	1		*REAR BUMPER	Bent	681.90 FL	*681.90 FL
36	2		*REAR BUMPER SIDE RETAINER	Cracked	344.20 FL	*344.20 FL
37	2		*REAR BUMPER SIDE REFLECTOR	Serviceable	357.70 FL	*- FL
38	1		*REAR END PANEL	Bent	531.35 FL	*531.35 FL
39	1		*REAR END PANEL INNER GARNISH	Serviceable	371.85 FL	*- FL
40	1		*REAR FLOOR PANEL GARNISH	Serviceable	581.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR FLOOR PANEL LH SIDE GARNISH	Serviceable	381.25 FL	*- FL
42	1		*AIR BAG CONTROL UNIT	Necessary	1,217.45 FL	*1,217.45 FL
43	1		*SET REAR PARKING SENSOR	Dented	280.00 FS	*200.00 FS
44	2		*REAR TYRE (60%)	Punctured	320.00 FS	*192.00 FS
45	1		*SEALANT	Necessary	80.00 FS	*40.00 FS
46	1		*REAR AXLE	Bent	2,850.85 FL	*2,315.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 29,697.50 21,952.00
 - List Item Discount on L Items 25.00/25.00% (S\$) 7,254.38 5,380.00

Total Parts (S\$) 22,443.12 16,572.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR CUSHIOS	New	180.00	120.00
2	REMOVE & REFIT REAR UNDERCARRIAGE	New	380.00	240.00
3	REMOVE & REFIT PETROL TANK	New	180.00	60.00
4	REMOVE & REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
5	REMOVE & REFIT ROOF TOP TRIM	New	160.00	100.00
6	REMOVE & REFIT AIR BAG & RESET	New	320.00	250.00
7	REPROGRAM ECU & HYBRID BATTERY	New	380.00	250.00
8	TOWING	New	100.00	100.00
9	TUFFKOTE	New	120.00	120.00
10	WIRING	New	120.00	40.00
11	SPRAY PAINTING	New	1,600.00	1,200.00
12	LABOUR CHARGES	New	1,600.00	1,400.00
Gross Labour Cost (S\$)			5,290.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >