



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 3127E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	CRACKED	638.00	638.00
1	FRONT BUMPER NUMBER PLATE GARNISH	DENTED	51.40	51.40
5	FRONT BUMPER CLIP @\$3.90	NECESSARY	19.50	19.50
	LESS 20% DISCOUNT		-141.78	-141.78
			567.12	567.12
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
			35.00	35.00
	<b><u>LABOUR</u></b>			
	REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE & REALIGN THE SAME.		300.00	220.00
	PUTTY & RESPRAY FRT BUMPER, BONNET & ALL AFFECTED AREAS.		450.00	280.00
			750.00	500.00
	<b>GRAND TOTAL</b>		<b>1,352.12</b>	<b>1,102.12</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>900.00</b>

Report Ref No. CS/SPF19003493/Kqd3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$900-\$1,100**

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**