

LINDA LIAO

ABWIN SERVICE PTE LTD

DID: 67139417 Fax: 67139415 HP: 97519596

Attn Owner

Date

To

: LEE LI QUN

: 08/03/2019

: ECICS LIMITED

: Motor Claim Department

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No.

: 5083517663-02

Vehicle No.

: SLF-8463-X

TP Vehicle No. : SKS-1537-G

Make & Model : TOYOTA SIENTA 1.5G CVT ABS D/AIRBAG

Accident Date: 22/02/2019

FINAL REPAIR COST DETAILS

		REPAIR AMOUNT	SURVEYOR APP.
1	REAR BUMPER REFLECTOR RH	\$75.60	-
1	REAR BUMPER REFLECTOR LH	\$75.60	-v
(S) 1	REAR BUMPER BRACKET LH	\$185.60	\$185.60
(f) 1	REAR BUMPER BRACKET RH	\$185.60	\$185.60
(i) 1	REAR BUMPER CENTRE GARNISH	\$258.40	\$258.40
1	REAR BUMPER SIDE GARNISH RH	\$195.60	500-000-000-00-00-00-00-00-00-00-00-00-0
(8) 1	REAR BUMPER SIDE GARNISH LH	\$195.60	\$195.60
1 1	REAR END INNER PANEL	\$678.70	\$678.70
2 1	REAR END OUTER PANEL	\$485.60	\$485.60
QJ 1	REAR END PANEL TOP GARNISH	\$395.60	\$395.60
2) 10	REAR END PANEL TOP GARNISH CLIP	\$50.00	\$50.00
1	REAR SEAT BELT RH	\$811.60	
1	REAR SEAT BELT LH	\$811.60	·
] 1	LH REAR FENDER TOP GARNISH (SUPPLEMENTARY) $$	A \$356.80	\$356.80
) 1	LH REAR FENDER INNER TRIMBOARD (SUPPLEMENTARY) $$ $$	A \$650.80	\$650.80 /
1	(SUPPLEMENTARY)	(pp) A \$125.80	\$125.80)
1	TAILGATE HANDLE GARNISH (SUPPLEMENTARY) / BR	SW) A \$95.60	\$95.60 /
	Sub Total	\$13,156.75	\$8,212.50
	Discount 20% on Parts	(\$2,631.35)	(\$1,642.50)
	25%	\$10,525.40	\$6,570.00 4
Special N	<u>Jett</u>		
1	REAR BUMPER REVERSE SENSOR	\$450.00	\$450.00
1	REAR NUMBER PLATE WITH CASING	\$65.00	\$35.00
1	REAR WINDSCREEN SEALANT	\$65.00	\$65.00 /
10	REAR BUMPER CLIPS	\$30.00	\$30.00 /
	Sub Total	\$610.00	\$580.00
Labour &	ı Misc		
	TO STRAIGHTEN AND PANEL BEAT ACCIDNET AREAS	\$2,500.00	\$800.00

ABWIN SERVICE PTE LTD, 8 KAKI BUKIT AVENUE 4 - GATE 2, #07-48 PREMIER @ KAKI BUKIT, SINGAPORE 415875

Company Registration No. 201318685G