

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19003504/UKA3Q2

Date: 13/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100231180-08

Claimant

Vehicle No : SLX1726P

Insured Vehicle No : SJY7962C

Date of Loss: 25/01/2019

Nature of Claim: TP

Claim No: 9851402747SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX1726P

Make & Model: KIA CERATO FORTE, 1.6 SX (A)

Engine No: G4FC9H291697

Reg. Date: 24/09/2009 (Man. Year: 2009)

Chassis No: KNAFW411MA5124767

Colour: Brown

Odometer: 153543 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17

Rear Tyre Size: 215/50Z R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,679.00	1,008.00	1,671.00	62.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,140.00	910.00	44.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,729.00	2,148.00	2,581.00	54.58
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	4,729.00	1,500.00	3,229.00	68.28
+ GST 7.00/7.00% (S\$)	331.03	105.00	226.03	68.28
Nett Amount (S\$)	5,060.03	1,605.00	3,455.03	68.28
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,907.00		
Global Sum Settlement (S\$)		1,900.00		

INSPECTION

Date of Assignment: 19/08/2019

Date Inspected: 19/08/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Repair	772.00 FL	*- FL
2	1		*REAR DOOR STICKER LH	Not Necessary	27.00 FL	*- FL
3	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	59.00 FL	*- FL
4	1		*FRONT DOOR LH	Dented / Bent	752.00 FL	*752.00 FL
5	1		*FRONT DOOR STICKER LH	Necessary	27.00 FL	*27.00 FL
6	2		*FRONT DOOR OUTER HANDLE LH	Cut (1 PCS ONLY)	682.00 FL	*341.00 FL
7	1		*FRONT DOOR OUTER MOULDING LH	Not Necessary	59.00 FL	*- FL
8	1		*WING MIRROR LH	Repair	532.00 FL	*- FL
9	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FS	*- FS
10	1		*FRONT FENDER LH (NPA)	Repair	0.00 FS	*- FS
11	1		*FRONT WHEEL RIM COVER LH (Missing)	Not Consistent With The Impact	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,970.00	1,120.00
- List Item Discount on L Items 10.00/10.00% (\$)	291.00	112.00

Total Parts (\$)	2,679.00	1,008.00
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	400.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	680.00
3	ANTI-RUST COATING	New	250.00	60.00
Gross Labour Cost (S\$)			2,050.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >