

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 7686T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT SHIELD	CUT	470.00	470.00
1	COPERTURA LATERALE SUPERIOR ESCUDO SX	CUT	233.00	233.00
1	COPERTURA LATERALE SUPERIOR ESCUDO DX	CUT	233.00	233.00
1	RH COVER	CUT	180.00	180.00
1	LH COVER	CUT	180.00	180.00
1	FOOTREST RH	CUT	32.00	32.00
1	FOOTREST LH	CUT	32.00	32.00
1	SPOILER (BOTTOM)	CRACKED	222.00	222.00
1	LH HALF REAR FAIRING	CUT	183.00	183.00
1	COPERTURA ANTERIORE MANUBRIO (TOP COVER)	CUT	141.00	141.00
1	MANUBRIO CON PI (HANDLE BAR)	BENT	194.00	194.00
2	FR. BR. LEVER	CUT	23.00	23.00
1	FORCELLA ANTERIORE COMPLETA (FORK)	BENT	751.00	751.00
1	INDICATORE DIREZIONE ANTERIORE DA (HEADBIP)	SCRATCHED	50.00	50.00
1	TOP FRAME	TO REPAIR SEE LABOUR	172.00	-
1	BODY FRAME	TO REPAIR SEE LABOUR	1,338.00	-
1	EXHAUST PIPE PROTECTOR	CUT	50.00	50.00
1	EXHAUST PIPE	CRACKED	1,070.00	1,070.00
	LESS 10% DISCOUNT		-	-404.40
			5,554.00	3,639.60
	<u>LABOUR</u>			
	CHECK FORK		280.00	120.00
	CHECK BODY. INCLUSIVE OF THE REPAIR OF TOP FRAME AND BODY FRAME.		380.00	200.00
	LABOUR.		250.00	200.00
			910.00	520.00
	GRAND TOTAL		6,464.00	4,159.60
	RECOMMENDED COST OF REPAIRS			4,159.60

Report Ref No. CS/TP19003537/Gqd3s2

XING GUO QIANG**M.MATAI, AMSAE-A****Automotive Assessor****ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.