

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 7686T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT SHIELD	сит	470.00	470.00
1	COPERTURA LATERALE SUPERIOR ESCUDO SX	сит	233.00	233.00
1	COPERTURA LATERALE SUPERIOR ESCUDO DX	сит	233.00	233.00
1	RH COVER	сит	180.00	180.00
1	LH COVER	сит	180.00	180.00
1	FOOTREST RH	сит	32.00	32.00
1	FOOTREST LH	сит	32.00	32.00
1	SPOILER (BOTTOM)	CRACKED	222.00	222.00
1	LH HALF REAR FAIRING	сит	183.00	183.00
1	COPERTURA ANTERIORE MANUBRIO (TOP COVER)	сит	141.00	141.00
1	MANUBRIO CON PI (HANDLE BAR)	BENT	194.00	194.00
2	FR. BR. LEVER	сит	23.00	23.00
1	FORCELLA ANTERIORE COMPLETA (FORK)	BENT	751.00	751.00
1	INDICATORE DIREZIONE ANTERIORE DA (HEADBIP)	SCRATCHED	50.00	50.00
1	TOP FRAME	TO REPAIR SEE LABOUR	172.00	-
1	BODY FRAME	TO REPAIR SEE LABOUR	1,338.00	-
1	EXHAUST PIPE PROTECTOR	сит	50.00	50.00
1	EXHAUST PIPE	CRACKED	1,177.00	1,177.00
	LESS 10% DISCOUNT		-	-415.10
			5,661.00	3,735.90
	LABOUR			
	CHECK FORK		280.00	120.00
	CHECK BODY. INCLUSIVE OF THE REPAIR OF TOP FRAME AND BODY FRAME.		380.00	200.00
	LABOUR.		250.00	200.00
			-	-
			-	-
			910.00	520.00
	GRAND TOTAL		6,571.00	4,255.90

RECOMMENDED COST OF REPAIRS		4,255.90





Report Ref No. CS/TP19003537/Gqd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.