MINGHOT :				ND 1900 3550/E			1.1		
Men (Person)	Hidrel	tun	of	FWD	Dat	e/Time:	222	Masion	5.08
Estimated Cos	t:			Bill to:					
· · · · · · · · · · · · · · · · · · ·	ITP RES / O		010	ACTIB	Insured:	SKL	4555	×	
at Workshop i of	n/s 68 kuki	Br+ A	precis	101 Moturner	& Tel:	587	6647	1—	
Policy No: A	PY2017 -	000076	66-01	Claim No:	1201	9000	05016	5	
Sum Insured:				Excess:					
Make of Veh					D.0	D.A	21/02/	2009	
(Client's Recer CA / REV	1) / REP. / RE	V 24 HRS	(p)			5/2/19 I.O.D. Endorse	ancol;		
				octed: 70m _	Veh	icle_IN_Oi	D		
Date/Time	Action/Instr	uction ()	-) Estin	mate					
	SICO	571B-	×						
		≠555×-							
		He: 24/2			on the same				
		pair: 4	The state of the s		The work of the same of the sa				

Shot	ANATON I
26/2/19	SLC 95718 Hagin Mar. 14
10000 820423 8	Type M.Car/M.6ycle / Bus / Van / Lony / Taxi / Prime Mover /
Latinated treat	Truck / Trailer or
OD (1) WS/TP RES/OD RES/EVA/INV/MV	ILIKE TOPO Totto 1290
To the post Vehicle He SLC 9571B	0.1
GB kaki BK+ Ave 6 # 01-02 ARK	Loon Vo
GE ROAKS BICT THE 6 FF 01-02 TIME	
Irraned	Citio. Wyw 222162E M013061
Policy Ho	/ 1
Claims Ho	Gen. Cond/Good / Fair / Poor / Burnt
Sum Insured. Excess:	Steering (inprde) / Jammed / Leaked / Burnt or
(Client's Record)	Broke: (norder/Jammed/Leaked/Burnt &
Make of Veh: 70m 88766477	Modi: Nil /SRim / STD A/Rim or
1 20	Tyre Size. F: 205/55846
(Policy Condition)	R: #1
Remark The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF CONTINUAL
Ball or Market Value.	Front Rear
IDAC Accident Rport. Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 7 - mm
GIA / PR Seen Consistent? : Yes or No	L/Bat. 7 mm L/Bat. 7 mm
Est Repairs: days Res.: Yea or No	D.O.A. 21/2/19 D.O.I. 26/2/19
Lum Sum: % 3 Val.: Yes or No	Survey held at PIECISION
CA / REV / REP. / 24 HRS (MP) Vehicle: IN / OUT	Des. of Damages : Frt Rea / O/S / N/S / U/C / Rooftop or
Dale: Person Contacted:	The U/G / Chassis frame / Body Structure affected due to collision.
Baby Time Action / Instruction 3-4 K. Repar range 5-6K, 5	days Johnsto 27/3/2019
Date/Inno. Ede Pans to? : Preli. Report	Days Of Repair: S
; Final Report	Resurvey No. of Trip: 2 Survey Fee:
Onle/Time, File Roturn to?	Transportation.
Add Fee	land and the second sec
200	Intersew (\$) Hebs
Report Format : PRS ·	Tech thys (\$) Olivi
Lump Sum / LB E (S	Weekend (\$

Nivitha (LKK Auto)

From:

lionel.tan@fwd.com

Sent:

Friday, 22 February 2019 5:05 PM

To:

assignments@lkkauto.com; sur@lkkauto.com

Cc:

motorclaims.sg@fwd.com

Subject:

FW: OUR REF: AW-INS-P48-109638-19.jgv & YR REF: SKL 4555 X (Claim

1201900005016)

Attachments:

image003.wmz

Hi

Please attend to pre-repair survey notice below.

Regards,

Lionel

From: Lionel Tan Tian Pei - SGUser Sent: Friday, February 22, 2019 5:00 PM To: 'jenniferguay@visionlawllc.com'

Subject: RE: OUR REF: AW-INS-P48-109638-19.jgv & YR REF: SKL 4555 X (Claim 1201900005016)

WITHOUT PREJUDICE

Dear Sir/ Madam

We regret that we are objecting to your proposed list of surveyors.

We will be appointing *LKK AUTO CONSULTANTS PTE LTD* to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is any change in your client's workshop, please inform us soon. We reserve our rights for reinspection.

Regards,

Lionel

From: Jennifer Guay [mailto:jenniferguay@visionlawllc.com]

Sent: Friday, February 22, 2019 3:51 PM

To: Lionel Tan Tian Pei - SGUser Cc: Motor Claims SG - SG Common

Subject: RE: OUR REF: AW-INS-P48-109638-19.jgv & YR REF: SKL 4555 X (Claim 1201900005016)

PRE - REPAIR SURVEY

CLAIMANT: CHRISTIE EILEEN PHOON

ACCIDENT INVOLVING SLC 9571 B & SKL 4555 X ON 21 FEBRUARY 2019 ALONG FILTER LANE TOWARDS

WOODLANDS AVE 3

Dear Sirs

Refer to your email of 22 February 2019 informing that you wish to conduct a pre-repair survey and to your list of surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint

Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the

following surveyors for your consideration:-

1.B J Loi (Par Automotive Consultancy)

Please be informed that the pre-repair survey of our clients vehicle can be survey as follows:

Venue

: Precision Motorworks 68 Kaki Bukit Ave 6, ARK @ KB 01-02 Singapore 417896

Contact

TOM (Tel: 8876 6477)

Please let us hear from you by 22 February 19. Thank you.

Regards

Jennifer Guay

(Secretary for Ms Audrey Wong)

VISION LAW LLC

133 New Bridge Road #18-01 Chinatown Point Singapore 059413

Tel: 6534 2811 (Ext 116)

Fax: 6535 6802

From: lionel.tan@fwd.com [mailto:lionel.tan@fwd.com]

Sent: Friday, 22 February, 2019 3:50 PM
To: jenniferguay@visionlawllc.com
Cc: motorclaims.sg@fwd.com

Subject: RE: OUR REF: AW-INS-P48-SLC9571B-19.jgv & YR REF: SKL 4555 X (Claim 1201900005016)

Without Prejudice

Dear Sir/ Madam

Please select one of our surveyors as follows: -

- 1. LKK AUTO CONSULTANTS PTE LTD
- 2. INFINITI APPRAISAL SERVICE
- 3. AJAX INSPECTION SERVICES PTE LTD
- 4. APPRAISALS ASSOCIATES PTE LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.	
Lionel	
From: Jennifer Guay [mailto:jenniferguay@ Sent: Friday, 22 February, 2019 12:08 PM To: Motor Claims SG - SG Common Cc: johnkhor90@gmail.com Subject: OUR REF: AW-INS-P48-SLC9571B- Importance: High	
PRE - REPAIR SURVEY CLAIMANT: CHRISTIE EILEEN PHOON ACCIDENT INVOLVING SLC 9571 B & S WOODLANDS AVE 3	I SKL 4555 X ON 21 FEBRUARY 2019 ALONG FILTER LANE TOWARD:
Dear Sirs	
X driven by your driver at the material time. As a result of the accident, our client's vehic please let us know within 2 working days of	le has been damage. Before our client proceed to repair the damage vehicle your receipt of this notice whether you or your insurer would like to conduct not receive any reply from you within the stipulated timeline, our client sha
Regards	For Surveyor
Jennifer Guay (Secretary) VISION LAW LLC 133 New Bridge Road #18-01 Chinatown Point Singapore 059413 Tel: 6534 2811 (Ext 116) Fax: 6535 6802	Please initial here after completion of pre-repair survey. Thank you. Appointed Surveyor: Name & Signature Contact: Date & Time
	Surveyor during repair: Date & Time:
VISION LAW LLC Advocates & Solicitors (Incorporated with limited liability)	Surveyor after repair: Date & Time:
	8-01/02 Chinatown Point, Singapore 059413 1 HDB Hub (Biz 3 Lobby 1), Singapore 310490
DISCLAIMER: The contents of this email (including an	y attachments) are confidential and privileged and only intended for

the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413 Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> Back to OneMotoring

Enquire Transfer Fee

nquire Transfer Fee			I#
Vehicle Details			
Vehicle No.:	SLC9571B		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLKSWAGEN		
Vehicle Model :	JETTA 1.4 TSI AT 1622G5		
Chassis No.:	WVWZZZ16ZEM013061		
Propellant:	Petrol		
Engine No.:	CAXD89409		
Engine Capacity :	1390 сс		
Maximum Power Output :	90.0 kW (120 bhp)		
Maximum Laden Weight:	1870 kg		
Unladen Weight:	1417 kg		
Year Of Manufacture :	2013		
Original Registration Date :	31 Mar 2014		
Lifespan Expiry Date :	•		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$77,201.00		
COE Expiry Date :	30 Mar 2024		
Road Tax Expiry Date:	30 Sep 2019		
PARF Eligibility Expiry Date :	30 Mar 2024		
Inspection Due Date :	31 Mar 2021		
Intended Transfer Date :	28 Mar 2019		
CO2 Emission :	138.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	•		
HC Emission :	•		
NOx Emission :	ė.		
PM Emission :	29		
Late renewal fee(s) will be impose	ed if road tax / lay up has expired. Please use Enqu	ire Road Tax Payable for fee(s) pay	able.
	t (if any), of a vehicle will follow the vehicle to the		
The state of the s	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(5\$
Transfer Fee :	25.00		25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	51321	
Vehicle No.:	SLC9571B	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	28 Mar 2019	
Vehicle Make:	VOLKSWAGEN	
Vehicle Model:	JETTA 1.4 TSI AT 1622G5	
Primary Colour:	Red	
Manufacturing Year:	2013	
Engine No.:	CAXD89409	
Chassis No.:	WVWZZZ16ZEM013061	
Maximum Power Output:	90.0 kW (120 bhp)	
Open Market Value:	\$19,046.00	
Original Registration Date:	31 Mar 2014	
First Registration Date:	31 Mar 2014	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$9,046.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	30 Mar 2024	
PARF Rebate Amount: Intended COE Rebate Details	\$6,784.00	
COE Expiry Date:	30 Mar 2024	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$77,201.00	
COE Rebate Amount:	\$38,642.00	
Total Rebate Amount:	\$45,426.00	

The information contained herein is correct as at 28 Mar 2019

OK

MOTORCAR (Rear)

ACTIONIAC)
(1)Replace (/) (2)Repair() (3)Check ()
(4)Not Consistent (C)

Aug 2005

chicle No: SLC.95718

	١	1	-
1	/	1	
/		.)	ķ.

NAC	INC.	Item	CO	VI 12	10
1137		Rear Number Plate	COL	YAC	QI
1138					
1139	993027	Rear Number Plate Base	CUT	1	1
-	993030	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DÛ	17	-
1142	993085	Rear Bumper Upper	PU	-	-
1143	993017	Rear Bumper Lower	VUT	1-	-
1144	993054	Rear Bumper Side	100	~	_
1145	993103	Rear Bumper Tow Cover	_	_	_
1146	992341	Rear Bumper Clips	-		
1147	992076	Page Damper Clips	NEC	V	
1148	002000	Rear Bumper Bracket			
1149	993008	Rear Bumper Side Retainer	BK	V	2
1150	993043	Rear Bumper Reinforcement		17	
	992970	Rear Bumper Beam	n erane		
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper	_	1	
1153	993040	Rear Bumper Protector	_	-	-
1154	993036	Rear Bumper Pad	_	+-	-
1155	993026	Rear Bumper Moulding	_	-	-
1156	993044	Rear Bumper Reflector	00	-	
1157	993023		11 R	V	_
1158	994023		-	-	
1159	993327	Rear End Panel	LIK	1	
1-160	993339		_	K	
1161	993333		-		
1162		Rear End Panel Inner Trim			
_	990333	Boot Compartment Inner Trim			1
1163	993851	Rear LH Taillamp			
164	993853	Rear LH Taillamp Garnish			
165	993859	Rear LH Taillamp Panel	1		_
166	995116	Rear RH Taillamp	_		-
167	993853	Rear RH Taillamn Garnich		-	-
168	993859	Rear RH Taillamp Panel	-	-	-
169	993554	Rear Apron Panel	_	-	_
170	992895	Bootlid	00	-	_
		Bootlid Emblem	NE C	V	-
172	990356	Bootlid Handle	NE C	V	J
	995250	Bootlid Moulding	-		
174	990376	Bootlid Reflector	-		
	995222	Bootlid Lamp LH	-		
	002800	Bootlid Lamp RH	CRA	V	
	005242	Bootlid Lock			- 1
178	990377	Bootlid Lock Bootlid Rubber		1.7	
179	000377	Bootlid Rubber			
-	002022	Bootlid Hinge			
180		Bootlid Spoiler	,		
-		Tailgate			185
	991328	Tailgate Emblem			_
	994643	Tailgate Outer Handle			
	994640	Tailgate Moulding	-		_
		Tailgate Garnish	-	-	
186	994648	Tailgate Reflector	-		
187	994549	Tailgate Lamp	-		
	994646	Tailgate Protector			
-	004676	Tailgate Wi			
-	004677	Tailgate Wiper Arm		1200	0.12-1
-	994677	Tailgate Wiper Blade			
	994679	Tailgate Wiper Nozzle			
	994555	Tailgate Wiper Motor			_
	994602	Tailgate Glass	1	1	-
		Tailgate Glass Rubber	-	-	
	994604	Tailgate Glass Moulding	-		_
	994607	Tailgate Glass Sealant	-		
	-	Tailgate Class Sealant			
-	7711671				
197 9				_	_
197 9	94651	Tailgate Rubber Tailgate Hinge			

NAC	INC	Item	1	-	_
1202	993784	Constant D	CON	AC	Qt
1203	004339	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
	995065				
1205	994326	T COOK DOLCW			
1206	993787	Spare Tyre Cover	-		-
1207	995323	Triangle Breakdown Sign			-
1208	990507	CD Changer Assy	_		-
1209	990164	Antenna	_	-	-
1210	990534	Centre Exhaust Pipe Assy	-	-	-
1211	990532	Centre Exhaust Mounting			-
1212	993364	Rear Exhaust Pipe	-	-	-
1213	993357	Rear Exhaust Chrome Pipe		-	-
1214	993361	Rear Exhaust Mounting	-	7	-
1215	993358	Rear Exhaust Heat Shield		-	-
1216	995223	Rear LH Chassis Member	0000	-	-
1217	993165	Rear RH Chassis Member		-	_
1218	993436	Rear LH Fender		-	-
1219	993449	Rear LH Fender Protector			-
1220	993420	Rear LH Fender Inner Panel	-	_	
1221	993431	Rear LH Fender Inner Trim	-	-	_
1222	993415	Rear LH Fender Inner Garnish	-	-	-
1223	993425	Rear LH Fender Inner Shield	-	-	_
1224	993621	Rear LH Mudflap		-	_
1225	993933	Rear LH Wheel Rim		-	-
1226	994025	Rear LH Rim Cover	-	\dashv	_
1227	995065	Rear LH Tyre		-	_
1228	993456	Rear RH Fender	-	-	_
1229	993450	Rear RH Fender Protector	-	-	_
1230	993420	Rear RH Fender Inner Panel		-	_
1231	993431	Rear RH Fender Inner Trim	-		_
1232	993415	Rear RH Fender Inner Garnish		\dashv	_
1233	993425	Rear RH Fender Inner Shield		-	_
1234	993622	Rear RH Mudflap	-	-	_
1235	993934	Rear RH Wheel Rim		-	_
1236	994025	Rear RH Rim Cover		-	
1237	995065	Rear RH Tyre	-	+	
1238	995162	Rear Fender Extension Panel LH		-	_
1239	993401	Rear Fender Extension Panel RH	-	-	-
1240	993430	Rear Fender Inner Top Garnish		\dashv	-
1241	993673	Rear Fender 1/4 Glass	-	-	-
1242	993452	Rear Fender 1/4 Glass Rubbar	-	-	_
1243	993453	Rear Fender 1/4 Glass Scalant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber		-	-
1246	993961	Rear Windscreen Moulding	-	-	
1247	993955	Rear Windscreen Scalant		-	
1248	994729	Third Brake Light		-	_
1249	993385	Rear Fender Air Grille	-	+	_
1250	992167	Fuel Lid	-	-	-
		Fuel Neck		-	
		Fuel Tank		-	
1253	992184	Fuel Tank Bracket		-	-
1254		Fuel Tank Float		+	_
1361	990247	Sticker		+	-
				-	-
3 4	A		-	+	_
				-	_
			-	-	
				-	
				_	
			-	-	-
		-		-	
	-				
			110		- 01

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subi	mitted	Ins Auth'ed	Status		
Main	21 Feb 2019 Edit Reg		22 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estima	ates	S\$0.00 View Rp	and the second second		Repor	ng for Sur t Case	vey
P/	tain	Re	ference		Claim	Details		Docume	nts	1 🛚	Show All
CLAIM SU	BFOLDER DE	TAILS		Report Control	and the second	The Chillian	[Creat	ed by adjuster]		Constitution in	
Insured:	NG WILL	AM, ID: S18026	51A				Analos II. soo				
Main Claimant:	CHRISTIE	EILEEN PHOON	, ID: S830513	21							
Vehicle Reg. No.:	SLC957	1B			Date	e of Loss:		2019 00:00 - :59 nths and 21 Days	From LTA	Reg Date (Man Yr)]
Claim Type:	TP / 120	1900005016			F 0.55 000	cy/Cover e No.:	PNPV2017-00007666-01				
Vehicle Reg. No. (Insured):	SKL4555	×			100000000000000000000000000000000000000	y No. imant):					
		C1911 19 10 10 11			Exc						
Repairer:	Precision	Motorworks Pte	Ltd (HQ) 68 KA	AKI BUKIT A	VENUE	6 #01-02	ARK@K	B, 417896 Kaki Bu	kit - Tel:		
Handling Insurer:	2000/00/00/00/00	apore Pte. Ltd. (COMPANY SIN	10.0008841	30,000,000	DENINOS.				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Ha	ndled by C	CHEN TS	UE YEE] [Fina	al Rpt du	ie 07/03/	2019]
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compose	e Case Ma
There are no	mail for this	case.									
ALL ASSO	CIATED TAS	iks⊡					View A	All Search Tasks	Create	New Task	Complet
Due Date	Priority	Type Task	Group Subj	iect Han	dler	Assign	ed By	Completed C	n Cr	eated On	Done

Claim Documents

*SLC9571B (1201900005016) [SKL4555X] TP **CHRISTIE EILEEN PHOON** Feb 21 2019 12:00AM [NG WILLIAM] Precision Motorworks Pte Ltd

1000		oad Photos Compose New Letter	View View in Browser
Pho	otos/Images		3 per page ▼
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Prin
1	27/02/19 08:18	General View	● Load JPG 🗹
2	27/02/19 08:18	General View	1 Load JPG №
3	27/02/19 08:18	General View	1 Load JPG 1
4	27/02/19 08:19	General View	1 Load JPG ☑
5	27/02/19 08:19	General View	● Load JPG 🗹
6	27/02/19 08:19	General View	● Load JPG 🗹
7	27/02/19 08:19	General View	● Load JPG
8	27/02/19 08:19	General View	● Load JPG 🗹
9	27/02/19 08:19	General View	● Load JPG 🗹
10	27/02/19 08:19	General View	1 Load JPG 2
11	27/02/19 08:19	General View	● Load JPG
12	27/02/19 08:19	General View	● Load JPG
13	27/02/19 08:19	General View	■ Load JPG
14	27/02/19 08:19	General View	● Load JPG
15	27/02/19 08:19	General View	Load JPG ✓
16	27/02/19 08:19	General View	● Load JPG
17	27/02/19 08:19	General View	■ Load JPG
18	27/02/19 08:19	General View	■ Load JPG
19	27/02/19 08:19	General View	€ Load JPG
20	27/02/19 08:19	General View	€ Load JPG
21	27/02/19 08:19	General View	● Load JPG
22	27/02/19 08:19	General View	● Load JPG
23	27/02/19 08:19	General View	■ Load JPG
24	27/02/19 08:19	General View	■ Load JPG
25	27/02/19 08:19	General View	● Load JPG
26	27/02/19 08:19	General View	1 Load JPG 2
27	27/02/19 08:19	General View	■ Load JPG
28	27/02/19 08:19	General View	1 Load JPG ✓
29	27/02/19 08:19	General View	1 Load JPG
30	27/02/19 08:19	General View	1 Load JPG ✓
31	27/02/19 08:19	General View	1 Load JPG
32	27/02/19 08:19	General View	1 Load JPG 2
33	27/02/19 08:19	Odometer Reading	1 Load JPG ☑
34	27/02/19 08:19	General View	1 Load JPG
35	27/02/19 08:19	General View	1 Load JPG

Pho	tos/Images		3 per page	•	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thum	bnail	_
36	27/02/19 08:19	General View	① Load	JPG	•
37	27/02/19 08:19	Chassis Number	① Load	JPG	•
38	27/02/19 18:07	Photographs of Damaged Parts	O Load	JPG	€
39	27/02/19 18:07	Photographs of Damaged Parts	① Load	JPG	•
40	27/02/19 18:07	Photographs of Damaged Parts	O Load	JPG	~
41	27/02/19 18:07	Photographs of Damaged Parts	① Load	JPG	•
42	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
43	27/02/19 18:07	Photographs of Damaged Parts	① Load	JPG	•
44	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
45	27/02/19 18:07	Photographs of Damaged Parts	₫ Load	JPG	1
46	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
47	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
48	27/02/19 18:07	Photographs of Damaged Parts	① Load	JPG	•
49	27/02/19 18:07	Photographs of Damaged Parts	3 Load	JPG	•
50	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
51	27/02/19 18:07	Photographs of Damaged Parts	① Load	JPG	•
52	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
53	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
54	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
55	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
56	27/02/19 18:07	Photographs of Damaged Parts	O Load	JPG	•
57	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
58	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
59	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
60	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
61	27/02/19 18:07	Photographs of Damaged Parts	① Load	JPG	•
62	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	4
63	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
64	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
65	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
66	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
67	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
68	27/02/19 18:07	Photographs of Damaged Parts	O Load	JPG	•
69	27/02/19 18:07	Photographs of Damaged Parts	1 Load	JPG	•
70	28/03/19 15:33	Photo After Spray	① Load	JPG	•
71	28/03/19 15:33	Photo After Spray	1 Load	JPG	1
72	28/03/19 15:33	Photo After Spray	① Load	JPG	•
73	28/03/19 15:33	Photo After Spray	① Load	JPG	€
74	28/03/19 15:33	Photo After Spray	① Load	JPG	•
75	28/03/19 15:33	Photo After Spray	1 Load	JPG	•
76	28/03/19 15:33	Photo After Spray	1 Load	JPG	•
77	28/03/19 15:33	Photo After Spray	1 Load	d JPG	•
78	28/03/19 15:33	Photo After Spray	1 Load	JPG	•
79	28/03/19 15:33	Photo After Spray	① Load	JPG	•
80	28/03/19 15:33	Photo After Spray	① Load	JPG	•
81	28/03/19 15:33	Photo After Spray	1 Load	JPG	•
82	28/03/19 15:33	Photo After Spray	€ Load	d JPG	•
83	28/03/19 15:33	Photo After Spray	1 Load	d JPG	•

Pho	tos/Images		3 per page	Y	•
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumb	nail F	Print
84	28/03/19 15:33	Photo After Spray	1 Load 3	PG	V
85	28/03/19 15:33	Photo After Spray	1 Load	PG	•
86	28/03/19 15:33	Photo After Spray	1 Load	PG	•
87	28/03/19 15:33	Photo After Spray	1 Load	IPG	•
88	28/03/19 15:33	Photo After Spray	① Load	IPG	•
89	28/03/19 15:33	Photo After Spray	① Load	IPG	•
90	28/03/19 15:33	Photo After Spray	1 Load	JPG	•
91	28/03/19 15:33	Photo After Spray	1 Load	JPG	\checkmark
92	28/03/19 15:33	Photo After Spray	1 Load	JPG	V
93	28/03/19 15:33	Photo After Spray	1 Load	JPG	1
94	28/03/19 15:33	Photo After Spray	1 Load	JPG	•
95	28/03/19 15:33	Photo After Spray	1 Load	JPG	•
96	28/03/19 15:33	Photo After Spray	● Load	JPG	€
97	28/03/19 15:33	Photo After Spray	① Load	JPG	1

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/FWD19003550/ECD3S2

Date:

29/03/2019

REFERENCE

Date of Loss:

Handling Insurer:

FWD Singapore Pte. Ltd.

Policy No:

PNPV2017-00007666-01

Claimant Vehicle

SLC9571B

21/02/2019

Insured Vehicle No:

Nature of Claim:

SKL4555X

TP

Claim No: 1201900005016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SLC9571B

Make & Model:

VOLKSWAGEN JETTA, 1.4 (A)

Engine No: Chassis No: CAXD89409

Reg. Date: Colour:

Red

31/03/2014 (Man. Year: 2013)

Odometer:

WVWZZZ16ZEM013061 85154 km

Engine Capacity:

1390 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes

Engine Modification:

Front Tyre Size: Front Left Side:

205/55R16

Rear Tyre Size:

205/55R16

Front Right Side:

Continental 7 mm Continental 7 mm Rear Left Side: Rear Right Side: Continental 7 mm Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

22/02/2019

Date Inspected:

26/02/2019 Inspected At:

Precision Motorworks Pte Ltd (HQ)

68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB

Singapore 417896

Estimated Period of Repair:

5.0 days

CHEN TSUE YEE Adjuster:

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 29 Mar 2019) Part Source: MRM-SG

VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SLC9571B)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >