

ASS. REC. BY

REP

es/FCI19003560/Kg d3 172

Special Instruction

CA/REV/REP

ASSIGNMENT (Office)

CWS

From (Person)

Serene ler

of

FCI

Date/Time

12:40pm @ 26/2/19

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

SGR 4647E

Insured

SHC 2429Z

at Workshop m/s

Trust Autoworks

Tel

9108 2728

of

Blk 5035 # 01-345 Amk Ind. park 2

Policy No

Claim No

D19001332MFSH

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

20/2/2019

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement

Date/Time

1:50pm @ 26/2/19

Person Contacted

Anthony

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SGR 4647E - NA/HP 19003251/h+

DOA: 20/2/19

SHC 2429Z - NA/HP 19003251/h+

DOA: 20/2/19

27/3/19 @

10.12am confirmed with Anthony LS \$3200, 5 days - (Red \$2977.53, 48%)

27/3/19 @

10.25am revised to Serene ler by email.

*

MV: \$19K (est); LTA: \$14437; NV: \$4563

ASS. REC. BY:

REF: P021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 819k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 27/2

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File pass to

27/2

Will email GIAK EH over.

L1Rg @ 3200 email

RECEIVED 27 MAR 2019

Date/Time, File Pass to?

1) 27/2 11:00 AM

Date/Time, File Return to?

2)

☐

: Prel. Report

☐

: Final Report

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Fees:

Others:

TOTAL

Report Format: TPLump Sum / I.B.d: (\$ 3200)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Veh No: SGR 4047EYr Regn: 02, 07Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota

c.c

1598Colour: M. Green

A/C:

Insured / Std / Nil / NA

Sp. Reading: 247779

T/Radio:

Insured / Std / Nil / NA

Eng/No: _____

C/No: MR0538EC107143473Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / STP A/Rim orTyre Size: F: 185/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/2/19D.O.I. 27/2/19

Survey held at _____

Des. of Damages: Nil / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

100

50

50+50

21

316

MOTOR SURVEY ASSIGNMENT

Date	22-02-2019	Our Ref No. D19001332MFSH
Accident Date	20-02-2019	Claim Type. Third Party
Insured Vehicle	SHC2429Z	Third Party Vehicle. SGR4647E
Survey Location	BLK 5035 #01-345 ANG MO KIO INDUSTRIAL PK 2	
Contact Person.	KELLEY CHOONG	
Contact No.	91082728/ 91082728	Fax No. 67338183
Survey Type	WITHOUT PREJUDICE: NO EST. COR *	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRUST AUTOWORKS	Attention. NIL
Cc : TP Solicitor	CHIA S ARUL LLC	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001332MFSH

Date: 27 March 2019

Our Ref: CS/FCI19003560/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGR 4647E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/02/2019 at the premises of M/s TRUST AUTOWORKS, and have the following to report:-

Workshop Estimate Amount	: S\$ 6,122.53 .
Revised Estimate Amount	: S\$ 4,008.53 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the n/s front portion & undercarriage.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 March 2019 10:25 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001332MFSH/1
Attachments: CSFCI19003560Kqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SGR 4647E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 26 February 2019 1:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001332MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 26 February 2019 12:40 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001332MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	9373B

Vehicle Details

Vehicle No.:	SGR4647E
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4635773
Chassis No.:	MR053ZEC107143473
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,245.00
Original Registration Date:	08 Feb 2007
First Registration Date:	08 Feb 2007
Transfer Count:	2
Actual ARF Paid:	\$16,770.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	07 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,197.00
COE Rebate Amount:	\$14,437.00
Total Rebate Amount:	\$14,437.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Mar 2019

OK

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Tan Seng Lim
Blk 223A Serangoon Ave 4
#14-223
Singapore 551223

Vehicle No : SGR 4647 E
Make : Toyota Altis
Year : 2007

*Not at hand
11 days @ 3200
Penny After Pcing
4 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front n/s fender
1 pc	Front n/s fender lamp
1 pc	Front n/s fender innershield
1 pc	Front n/s headlamp assy
1 pc	Front grille
1 pc	Front grille emblem
1 pc	Front bumper
1 pc	Front n/s bumper side retainer
1 pc	Front bumper reinforcement
1 pc	Front n/s bumper fog lamp
1 pc	Front n/s shock absorber
1 pc	Front n/s lower arm
1 pc	Front n/s kunckle arm
1 pc	Front n/s kunckle bearing
1 pc	Front n/s hub assy

refer photo

R	\$397.10	✓
L	\$35.70	X
CM	\$105.30	—
CM	\$385.10	—
CM	\$298.20	—
M	\$55.70	—
R	\$425.60	—
CM	\$55.10	—
R	\$355.20	—
L	\$175.20	—
R	\$385.60	—
L	\$405.90	X
R	\$435.60	—
M	\$155.70	—
R	\$325.70	—

Less 25 % $\frac{3,430.60}{25\%}$
\$2,997.53 $\frac{2,572.95}{2,572.95}$

S Nett

1 pc	Rear o/s tyre rim
------	-------------------

Net \$400.00 2 pcs

Labour Charges

Remove/renew the above parts including knocking, welding etc.

\$1,000.00 *6001*

To putty & spray paint on accident affected portion.

\$1,000.00 *6001*

Check/reconnect wiring.

\$45.00 *202*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SGR 4647 E

Labour Charges

To spray anti rust on accident affected portion.

Remove/renew front n/s undercarriages

Check and realign four wheel

balance c/f \$5,442.53

balance b/f \$5,442.53

\$120.00 30/

\$480.00 ? 150/ ✓

\$80.00 60/

Total \$6,122.53

Hi Kenneth

Paint - 2572.95

SWelt - 280.00

Labour - 1,460.00

4,312.95

Long h

~~3450.00~~

- 4 days

Measurement printout

Car standard measurement

Beissbarth © SL

M * R+ ** OK * AP_MALAYSIA / 1.00 / 272 / C

Date: 01.03.2019 16:19:30

Version (program)
v5.0b3100/v5.0b3100Version (FWA)
v5.0b1507Version (target data)
MalaysiaSerial number
QZ0000178Last service
24.02.2018**Customer****Vehicle****Vehicle:****Malaysia**

TOYOTA * ALTIS 2001-

Order

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-1°45'		-1°33'
	right	-1°11'		-1°21'
Individual Toe	left	+0°15'		+0°14'
	right	+0°13'		+0°09'
Total Toe		+0°28'		+0°24'
Setback		+0°06'		+0°04'
Geometrical driving axis		-0°01'		
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+2°23'		+2°44'
	right	+2°13'	-0°45' [+2°42'] +0°45'	+2°32'
K.P.I. 20°	left	+15°45'		
	right	+9°58'		
Toe out on turns	left	-1°18'		
	right	-1°27'		
Camber	left	-0°28'		-0°22'
	right	-0°36'	-0°45' [-0°31'] +0°45'	-0°41'
Individual Toe	left	-0°42'		+0°03'
	right	+0°03'	-0°06' [+0°00'] +0°06'	+0°04'
Total Toe		-0°39'	-0°12' [+0°00'] +0°12'	+0°08'
Setback		-0°04'		-0°03'
Included Angle 20°	left	+14°54'		
	right	+9°40'		

Measurement Summary

Car standard measurement

Beissbarth © SL

M * R+ ** OK * AP_MALAYSIA / 1.00 / 272 / C

Date: 28.02.2019 16:10:47

Before



Version (program)
v5.0b3100/v5.0b3100

Version (FWA)
v5.0b1507

Version (target data)
Malaysia

Serial number
QZ0000178

Last service
24.02.2018

Rear Axle		Initial Measurement	Target Data
Camber	left	-1°45'	
	right	-1°11'	
Individual Toe	left	+0°15'	
	right	+0°13'	
Total Toe		+0°28'	
Setback		+0°06'	
Geometrical driving axis		-0°01'	
Front Axle		Initial Measurement	Target Data
Castor 20°	left	+2°23'	-0°45' [+2°42'] +0°45'
	right	+2°13'	
K.P.I. 20°	left	+15°45'	
	right	+9°58'	
Toe out on turns	left	-1°18'	
	right	-1°27'	
Camber	left	-0°28'	-0°45' [-0°31'] +0°45'
	right	-0°36'	
Individual Toe	left	-0°42'	-0°06' [+0°00'] +0°06'
	right	+0°03'	
Total Toe		-0°39'	-0°12' [+0°00'] +0°12'
Setback		-0°04'	
Included Angle 20°	left	+14°54'	
	right	+9°40'	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003560/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2429Z	Veh. Inspected	SGR 4647E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001332MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	26/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053ZEC107143473	Colour	METALLIC GREEN	
Odometer	247779	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	YOKOHAMA	8 mm	
L/H Front Tyre	185/70 R14	YOKOHAMA	8 mm	
R/H Rear Tyre	185/70 R14	YOKOHAMA	8 mm	
L/H Rear Tyre	185/70 R14	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/02/2019	Inspection Date	27/02/2019	
Survey held at	BLK 5035 #01-345 AMK IND.PARK 2			
Repairer	TRUST AUTOWORKS			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 4647E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT N/S FENDER	BENT	397.10	397.10
1	FRONT N/S FENDER LAMP	SERVICEABLE	35.70	-
1	FRONT N/S FENDER INNERSHIELD	CRACKED	105.30	105.30
1	FRONT N/S HEADLAMP ASSY	CRACKED	385.10	385.10
1	FRONT GRILLE	CRACKED	298.20	298.20
1	FRONT GRILLE EMBLEM	NECESSARY	55.70	55.70
1	FRONT BUMPER	BENT	425.60	425.60
1	FRONT N/S BUMPER SIDE RETAINER	CRACKED	55.10	55.10
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	355.20	-
1	FRONT N/S BUMPER FOG LAMP	SERVICEABLE	175.20	-
1	FRONT N/S SHOCK ABSORBER	BENT	385.60	385.60
1	FRONT N/S LOWER ARM	SERVICEABLE	405.90	-
1	FRONT N/S KNUCKLE ARM	BENT	435.60	435.60
1	FRONT N/S KNUCKLE BEARING	NECESSARY	155.70	155.70
1	FRONT N/S HUB ASSY	BENT	325.70	325.70
	LESS 25% DISCOUNT		-999.17	-756.17
			2,997.53	2,268.53
<u>SPECIAL NETT ITEMS</u>				
1	REAR O/S TYRE RIM (SN)	DENTED	400.00	280.00
			400.00	280.00
<u>LABOUR</u>				
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		1,000.00	600.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		1,000.00	600.00
	CHECK/RECONNECT WIRING.		45.00	20.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.		120.00	30.00
	REMOVE/RENEW FRONT N/S UNDERCARRIAGES.		480.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK AND REALIGN FOUR WHEEL.		80.00	60.00
			2,725.00	1,460.00
GRAND TOTAL			6,122.53	4,008.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/FCI19003560/Kqd3n2

MARKET VALUE: \$19,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,437.00=NETT VALUE: \$4,563.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.