

REPAIR ESTIMATE*

MAKE

MODEL : HYUNDAI i40

MODEL	: HYUNDAI i40	Type	Unit Price	Amount
Qty	Parts Description/ Labour			
	Front Bumper Cover x rep-			\$ 1,052.20
	Front Bumper Bracket Top (RH) x su			\$ 22.40
	Front Bumper Retainer Mounting x su			\$ 9.20
	Front Wheel Rim (RH) x su			\$ 325.30
	Front Fender (RH) x rep- \$67.10			
	Front Wheel Hub Core (RH) - Impd			
	SUB TOTAL			\$ 1,409.10
	LESS 20%			\$ 281.82
	DISCOUNTED TOTAL			\$ 1,127.28
	Front Fender Advertisement Logo (RH) - m			\$ 100.00 Nett
	Front Tyre (RH) - at 50%			\$ 216.00 Nett
	TOTAL			\$ 316.00
	Labour Charge			\$ 400.00
	Panel Beating			\$ 600.00
	Spray Painting Charge			\$ 50.00
	Tuff Kote			\$ 80.00
	FRT Wheel Alignment			
	TOTAL LABOUR			\$ 1,130.00
	ESTIMATE TOTAL			\$ 2,573.28

1 Cal / 2 (11/11)

25/2/19 1120L

2 Rep,

P/P

After Rep by [Signature]

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 26.02.2019

REPAIR ESTIMATE

Time: 08:50:58

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305271656
REGN NO : SHD3470R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 23.02.2019 08:20
ACCIDENT DATE : 21.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0658-G I40VC CAP ASSY-WHEEL HUB 1 107.10 20.00 85.68

0002 T-205 WL-RP26 (I40/E220)WESTLAKE TYRE 2 1 216.00 50.00 108.00

SUB-TOTAL : 193.68

JOB NATURE

0000 L PANEL BEATING 200.00

0001 L SPRAY PAINTING CHARGE 400.00

0002 20-05 RENEW ADVERTISEMENT LOGO FENDER RH 100.00

SUB-TOTAL : 700.00

TOTAL : 893.68

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :