

ASS. REC. BY:

REF:

CS3/AIG/19003612/8cd302

Special Instruction:

Surveyor:

Mr. Jim

ASSIGNMENT (Office)

Front Person:

Chin Lee Ying

of

AIG

Date/Time:

25/2/19 @ 3:19pm.

Estimated Cost:

Bill to:

OD ☒ TP/WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SJR 6209M

Insured:

SLF 8960C

at Workshop n/s

Auto Rebuilt

Tel:

8288 3188

of

BLK 5037 # 01-397 Amk Ind. park 2

Policy No:

2100482384

Claim No:

714188519486

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:33am @ 26/2/19

Person Contacted:

Ahjian

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SJR 6209M-X
	SLF 8960C-X
	Dismantle: 27/2/2019
	After repair: 4/3/2019

REF: AIG

PRS

From

Date

26/2/19

Estimated Cost

OD ☒ TP / W5 / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SJR 6209M

at Workshop n/s

Auto Rebuilt

of BIK 5037, AMK Ind. part 2 #01-397

Insured

Policy No

Claims No

Sum Insured

Excess


(Client's Record)

Make of Veh:

Ahjion @ 8288 3188

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Rpt.

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1 up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SJR 6209M

In Regn

Jul, 09

Type ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

MERCEDES E 200

C.C. 1991

Colour

SILVER

A/C: Insured / Std / NI / NA

Sp Reading

253689

T/Radio: Insured / Std / NI / NA

Eng/Mo

C/No

WDB211CA12BA38905

Gen Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 265/35/18

R: 265/35/18

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

26/2/19

Survey held at

Auto Rebuilt

Des. of Damages: Frt / Rear / ☒ D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation

) S. R. S. St

) Photos

) Other

) . . .

TOTAL

Report Format:

DAR

Lump Sum / I.B.E. (\$))

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

TCRM
Nir 28/2/19


- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 25/2/2019 3:19:28 PM

Attachments:  Auto Rebuilt - Pre-Repair Notice (AIG)(SJR6209M).pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.AR (SJR6209M)
Your Ref: SLF8960C

25 February 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

BY FAX: 6835 7416 & EMAIL

URGENT

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: ANG OON PENG
TRAFFIC ACCIDENT ON 22 FEBRUARY 2019 AT ABOUT 19:10 HRS ALONG JURONG GATEWAY ROAD INVOLVING VEHICLES NO. SJR6209M & SLF8960C

We are instructed by Ang Oon Peng to notify you of a road accident 22 February 2019 at about 19:10 along Jurong Gateway Road involving our client's vehicle registration number SJR6209M and vehicle registration number SLF8960C driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Auto Rebuilt Trading
Address: Block 5037, #01-397
Ang Mo Kio Industrial Park 2
Singapore 569540
Contact: Ah Jian @ 8288 3188 / 6484 5825

Please liaise with the above workshop directly.

Yours faithfully

CrossBorders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5315E
Vehicle Details	
Vehicle No.:	SJR6209M
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	27195631194542
Chassis No.:	WDB2110412B438905
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$53,909.00
Original Registration Date:	01 Jul 2009
First Registration Date:	01 Jul 2009
Transfer Count:	0
Actual ARF Paid:	\$53,909.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2019
PARF Rebate Amount:	\$26,954.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$200.00
COE Rebate Amount:	\$5.00
Total Rebate Amount:	\$26,959.00

The information contained herein is correct as at 20 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/02/2019 12:38
Date Of Accident 22/02/2019 19:10
Exact Location Of Accident JURONG GATEWAY ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJR6209M
Insured/Policyholder
Name Of Registered Owner ANG OON PENG
NRIC No S1145315E
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97566867
Alternative Phone No OFFICE-97566867
Vehicle Particulars
Manufacturer MERCEDES-BENZ
Model E200
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company UNITED OVERSEAS INSURANCE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DPHN11022021801
Cover Note Number
Driver
Name of Driver ANG OON PENG
NRIC No S1145315E
Date Of Birth 15/01/1951
Occupation INDOOR
Date Of Driving Pass 30/07/1974
Driving Experience 44 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97566867
Fax Number OFFICE-97566867
Contact Number NOEMAIL
Email Address

Address 3 JALAN ANAK BUKIT #28-05
 Postcode 588998
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 3
 Passenger 1 NAME: : HO SOON CHENG (WIFE) 97566267
 GENDER: : FEMALE
 Passenger 2 NAME: : ANG XIN HUI (DAUGHTER)
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

WHILE WAITING AT TRAFFIC JUNCTION FOR LIGHT TO TURN GREEN. WHEN THE LIGHT TURNED GREEN, ALL CARS STARTS TO TRAVEL PAST THE JUNCTION. SUDDENLY, THE FRONT CARS APPLIED BRAKE AND I ALSO IMMEDIATELY APPLIED THE BRAKE AND MANAGE TO STOP MY CAR FROM HITTING THE CAR IN FRONT. SUDDENLY, THE CAR BEHIND SLF8960C HIT MY CAR FROM BEHIND. BOTH MY CAR FRONT HEADRESTS WERE ACTIVATED. HAVE DVR DATA CAPTURED. (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: CANNOT BE UPLOADED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF8960C
 Vehicle Make/Model/Colour KIA / RED
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LOH BENG HONG
 NRIC/Passport Number S1348527E

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	BR		
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	BR	✓	3
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DL	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SJR. 6209M

[illegible]

No of Items: 7

Assessor: TGLM

5/3/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2019 Edit Reg		25 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Loh Beng Hong, ID: S1348527E

Main Claimant:

ANG OON PENG, ID: S1145315E

Vehicle Reg. No.:

SJR6209M

Claim Type:

TP / 7141885194SG

Vehicle Reg. No. (Insured):

SLF8960C

Repairer:

Auto Rebuilt Trading (HQ) BLK 5037 Ang Mo Kio Industrial Park 2, # 01-397, 569540 Ang Mo Kio - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 07/03/2019]

Date of Loss:

22/02/2019 19:00 - :59
[115 Months and 21 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

2100482384 (Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (27/02/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS











































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR6209M (7141885194SG)
[SLF8960C]
TP
ANG OON PENG
Feb 22 2019 7:00PM
[Loh Beng Hong]
Auto Rebuilt Trading

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
2	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
3	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
4	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
5	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
6	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
7	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
8	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
9	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
10	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
11	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
12	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
13	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
14	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
15	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
16	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
17	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
18	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
19	20/03/19 16:23	General View													<div></div>	Load JPG	<div></div>	
20	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
21	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
22	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
23	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
24	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
25	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
26	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
27	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
28	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
29	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
30	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
31	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
32	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
33	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
34	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
35	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
36	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	
37	20/03/19 16:24	Photographs of Damaged Parts													<div></div>	Load JPG	<div></div>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/03/19 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	20/03/19 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/02/19 09:32	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003612/BCD3E2

Date: 21/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100482384

Claimant Vehicle No : SJR6209M

Insured Vehicle No : SLF8960C

Date of Loss: 22/02/2019

Nature of Claim:

TP

Claim No: 7141885194SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJR6209M**

Make & Model: MERCEDES-BENZ E200, 2.0 (A)

Engine No: 27195631194542

Reg. Date: 01/07/2009 (Man. Year: 2009)

Chassis No: WDB2110412B438905

Colour: Silver

Odometer: 253689 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35 R18

Rear Tyre Size:

265/35 R18

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/02/2019

Date Inspected: 26/02/2019 Inspected At:

Auto Rebuilt Trading (HQ)

BLK 5037 Ang Mo Kio Industrial Park 2, # 01-397

Singapore 569540

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Broken	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	3		*REAR BUMPER MOULDING CHROME	Broken	0.00 F	*- F
6	1		*REVERSE SENSOR	Dislodged	0.00 F	*- F
7	1		*STICKER	Repair	0.00 F	*- F
8	2		*HEAD REST (SAFETY)	Activated	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >