

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003621/ECD3E2

Date: 26/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800151499
Claimant Vehicle No : SJT9305M	Insured Vehicle No :	SMH2281X
Date of Loss: 17/02/2019	Nature of Claim:	TP Claim No: 7962858874SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9305M	Engine No:	4A910124844
Make & Model:	MITSUBISHI LANCER EX, 1.5 (A)	Chassis No:	JMYSRCY2A9U004553
Reg. Date:	10/11/2009 (Man. Year: 2009)	Odometer:	210376 km
Colour:	Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	26/02/2019	
Date Inspected:	26/02/2019 Inspected At:	1 KAKI BKT AVE 6#02-38 Repairer : Verve Motorworkz Pte. Ltd (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT RH DOOR	Repair	0.00 F	*- F	
2	1		*REAR RH DOOR	Repair	0.00 F	*- F	
3	1		*REAR BUMPER	Repair	0.00 F	*- F	
4	1		*REAR RH FENDER	Repair	0.00 F	*- F	
5	1		*RH RUNNLY BOARD GARNISH	Repair	0.00 F	*- F	
6	1		*REAR RH RIM	Cut	0.00 F	*- F	
7	1		*REAR RH ABSORBER	* Check	0.00 F	*- F	
8	1		*REAR RH LOWER ARM	* Check	0.00 F	*- F	
9	1		*REAR RH KNUCKLE ARM	* Check	0.00 F	*- F	
10	1		*REAR RH KNUCKLE ARM BEARING	* Check	0.00 F	*- F	
11	1		*REAR RH FENDER	Repair	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >