ASS REC. I	GQ	REF CS3/ Instilled	1045401 (JAQ	3-1 kutruotesa.	11.
Numbl From (Perso	dir. han	Absignm	INILA		1/2(18
Stimsted C	out:	- 14	Billing	Date/Time:0	1051013
D/TP/V	VS/TP RES / OD RES	E/EVA/INV/MV/	2		
to Inspect \ Workshop	chicle No:	SJT 62	59# In:	STS smed	769Z
	V	Villiam Lee Co	ar Air Con	Tel 9455 7	
olicy No	1.2 Kaki Buk 796367441mTi	1+ HV0 7 7	01-34		77.
um insured	210 20 [44111]	^		59041	
Inke of Veh			Excess:		
Bent's Recor				D.O.A. 18	05 2018
A / REV	REP. REV 24 HB	is .	4	H.O.D. Endorseine	nt.
A / REV	0.48am@22/s/1	Person Contacted Estimate	Mr-william		
Pate/Tunc I	Action/Instruction (Person Contacted Betimede - NATING 1800	giog Acx	VehicleN OUT	
hate/Time	Action/Instruction (S) I 6259 H	Person Contacted > Estimate - NATURAL ROBE WELLING 18000	4109/Kx	H.O.D. Endorseine Vehicl IN OUT	
ate/Time	Action/Instruction (SII 6259 H TIG 7697- (unfirmed with	Person Contacted > Estimate - NATING 18000 We fine to h	4109/Kx	H.O.D. Endorseine Vehicl IN OUT	10 A - 18/5/200
Pate/Tunc I	Action/Instruction (SII 6259 H TIG 7697- (unfirmed with	Person Contacted > Estimate - NATING 18000 We fine to h	4109/Kx	Vehicle IN OUT	10 A - 18/5/200
Pate/Time	Action/Instruction (S) I 6259 H	Person Contacted > Estimate - NATING 18000 We fine to h	4109/Kx	Vehicle IN OUT	10 A - 18/5/200
ate/Time	Action/Instruction (SII 6259 H TIG 7697- (unfirmed with	Person Contacted > Estimate - NATING 18000 We fine to h	4109/Kx	Vehicle IN OUT	10 A - 18/5/200
hate/Time	Action/Instruction (SII 6259 H TIG 7697- (unfirmed with	Person Contacted > Estimate - NATING 18000 We fine to h	4109/Kx	Vehicle IN OUT	10 A - 18/5/200
Pate/Time	Action/Instruction (SII 6259 H TIG 7697- (unfirmed with	Person Contacted > Estimate - NATING 18000 We fine to h	4109/Kx	Vehicle IN OUT	10 A - 18/5/200
Pate/Time	Action/Instruction (SII 6259 H TIG 7697- (unfirmed with	Person Contacted > Estimate - NATING 18000 We fine to h	4109/Kx	Vehicle IN OUT	10 A - 18/5/200

RECEIVED 1 0 APR 2019

5/4/19

REF CHILIF Colto MENT 9JT 6)54H Ricard VI Page 23 Uct 2009 M.of | I Mcyclg / Bus / Van / Lony / Taxl / Prime Mover / ruck / Trailer or OD | TP | WS | TP RES | OD RES | EVA | INV | MV Hyundai For Impact Vehicle No. Avando 1.6 More Red al Workshop mis Insured / Std / NI / NA Colour 147868 rë. T/Radio: Insured / Std / Nr / NA Sp.Reading Eng/No: Policy No. KMHDULURMAUS 1755 CHNo: Claims No. Gen Cond. Good / Fair / Poor / Burnt Sum insured. Steering Indrd / Jammed / Leaked / Burnt or Excess (Clarit's Record) Inforder / Jammed / Leaked / Burnt or Brake: Make of Vets. / S/Rim / STD A/Rim or Modi Tyre Site (Policy Condition) Remark: The veh had commenced its OX NIS BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO / YOKO or Ewplu Ball or Market Value **Etont** Read (DAC Accident Room) Consistent? Yes or No R/Bal R/Bal men htmi GIA / PR Seen Consistent? Yes or No L/Bal UBal mai THE DOA 18057018 Est Repairs 27052018 Res - Yes or No. 0.01 William Lee 3 Val. Yes or No. Lum Sum Survey held at Des. of Domages : Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Date Person Contacted The U/C / Chassis frame / Body Structure effected due to collision. Date | Time 1216 # 4'000 - +2'000 CHRISTIAN THE PARK NO. Preli. Report Days Of Repair: 5 Final Report Resurvey No. of Trip: Survey Ene 120 me Fig. Billion 15 Printportoter Add Fee: Side Imag 15

Report Format: PRS | Teaching 15 | 10 | 130

Nivitha (LKK Auto)

From:

Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>

Sent:

Wednesday, 27 February 2019 9:47 AM

To:

Admin-D (LKKAuto)

Cc:

SUR; williamleecar@gmail.com FW: SJT6259H Direct Settle estimate

Subject: Attachments:

SJT6259H Direct Settle estimate.pdf

Dear Catherine,

We have received the following bill from the third party workshop.

Kindly advise if the COR was agreed with the repairer?

This is a direct survey by LKK.

Thank you.

Ashik Madi

Executive, Claims Services (Motor)

D: +65 6594 2548 | F: +65 225 7402 | ashik_madi@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg







A Member of MS&AD INSURANCE GROUP

From: williamleecar lee [mailto:williamleecar@gmail.com]

Sent: Monday, 25 February, 2019 11:45 AM

To: Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>

Subject: SJT6259H Direct Settle estimate

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID: Vehicle Details	0222A
Vehicle No.:	SJT6259H
Vehicle to be Exported:	No
Intended De-registration Date:	07 Aug 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FC9U745122
Chassis No.:	KMHDU41BMAU891755
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,539.00
Original Registration Date:	23 Oct 2009
First Registration Date:	23 Oct 2009
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$11,539.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2019
PARF Rebate Amount: Intended COE Rebate Details	\$6,346.00
COE Expiry Date:	22 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,019.00
COE Rebate Amount:	\$1,812.00
Total Rebate Amount:	\$8,158.00

The information contained herein is correct as at 07 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 2. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	19/05/2018 15:33
Date Of Accident	18/05/2018 19:30
Exact Location Of Accident	LENG KEE ROAD
Country/State of Loss	SINGAPORE
PARTIE CARREST CONTROL OF THE CONTRO	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SJT6259H
Insured/Policyholder	
Name Of Registered Owner	EXCEL MOTORING
Co Reg No	53180222A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88115028
Alternative Phone No	OFFICE-88115028
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

Fleet Policy NO

Policy Number 5095127768-01

Cover Note Number

Driver

RAMESH S/O MUTHU KUMAR Name of Driver

NRIC No S7625455I 02/08/1976 Date Of Birth OUTDOOR Occupation 09/04/2003 Date Of Driving Pass

15 YEARS AND 1 MONTH **Driving Experience**

Gender MALE

(LOCAL) +65-88115028 Mobile Number

Fax Number

OTHERS-88115028 Contact Number

NOEMAIL EMáil Address

Address

BLK 432C YISHUN AVENUE 1

#05-545

Postcode

763432

OTHER - HIRER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

DRIZZLING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLS769Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

PUAR CHENG LOONG

NRIC/Passport Number

S7614891J

Contact Number

96611093 / 66036114

Address

TRANS EUROKARS MAZDA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Pulice for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the indigment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

i understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the staims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Fersonal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (ii) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (v) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's lightfure (If driver's not the policyholder)

Date & Time

Reporting Centre Personnel's Signatur

NRICITIN No.

Sketch Plan #2

SKETCH PLAN		Leng to	e Re		
	(3)		V		
L12h	W			A - SI	76259H S 7692
	7			R - 26	5 7612
	į				

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT locked A driving. Levis here Id suddenly Glorg 601 nfront torn tuen my faright 0.1 lone

DECLARATION

If We declare the foregoing particulars are true in every respect

Date & fema

Driver's Signature (If drawn is not the policyholder) bate & Time

Reporting Centre Personne's Signature

Name

Vehicle No.	SJT 6259 H
-------------	------------

Parts and Labour Assessment

Description of part

PARTS	CEL TECHNOLOGY	REPORT BY ALCOHOL

	Qty		Cost
1 FRONT GRILLE	1		366.00
2 FRONT GRILLE 'LOGO' EMBLEM	1		65.00
3 FRONT GRILLE CLIPS	6		39.00
4 FRONT RH HEADLAMP	1		480.00
5 FRONT RH HEADLAMP CLIPS	2		13.00
6 FRONT RH HEADLAMP LOWER BRACKET	1		35.00
7 FRONT BUMPER	1		435.00
8 FRONT BUMPER INNER SPONGE	1		113.00
9 FRONT BUMPER LOWER CENTER GRILLE	1		48.00
10 FRONT BUMPER LOWER RUBBER MOULDING	1		44.00
11 FRONT BUMPER LOWER UNDER COVER	1		44.00
12 FRONT BUMPER REINFORCEMENT	1		254.00
13 FRONT BUMPER RH FOG LAMP COVER	1		26.00
14 FRONT BUMPER SIDE RETAINER L/R	2		50.00
15 FRON SUPPORT PANEL	1		791.00
16 FRONT RH FENDER TOP GARNISH	1		28.00
17 FRONT RH FENDER TOP GARNISH CLIPS	3		19.50
18 FRONT RH FENDER	1		402.00
19 FRONT RH FENDER 'VVT' EMBLEM	1		22.00
20 FRONT RH FENDER BRACKET	1		15.00
21 FRONT RH FENDER INNER PANEL	1		493.00
22 FRONT RH FENDER INNER SHIELD	1		57.00
23 FRONT RH FENDER MUDFLAP	1		33.00
24 FRONT SUSPENSION RH ABS SENSOR	1		228.00
25 FRONT SUSPENSION RH DRIVE SHAFT ASSY	1		936.00
26 FRONT SUSPENSION RH KNUCKLE ARM	1		363.00
27 FRONT SUSPENSION RH KNUCKLE ARM BEARING	1		114.00
28 FRONT SUSPENSION RH LOWER ARM	1		282.00
29 FRONT SUSPENSION RH LOWER BALL JOINT	1		77.00
30 FRONT SUSPENSION RH POWER STEERING RACK END	1		112.00
31 FRONT SUSPENSION RH POWER STEERING TIE ROD	1		55.00
32 FRONT SUSPENSION RH SHOCK ABSORBER	1		194.00
33 FRONT SUSPENSION RH SHOCK ABSORBER TOP MOUNTING	1		96,00
34 FRONT SUSPENSION RH STABILIZER BAR LINK	1		69.00
		\$	6,398.50
Percentage discount 20%		5	1.279.70

Percentage discount 20% 1,279.70 Sub-total \$

SPECIAL NETT ITEMS

2 FRONT RH FENDER INNER SHIELD CLIPS - SET 3 FRONT RH 15" SPORT RIM 4 FRONT RH 185/65 R15 TYRE 1 266 Sub-total 5 67 LABOUR 1 To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing. 2 To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. 3 To road test driving, check and resetting wheel alignments system. 4 To re-spray painting on the front bonnet, front support panel, front fender and front bumper. 5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. Labour Total 5 3,45	1.5	FRONT BUMPER CLIPS - SET 1		20.00
3 FRONT RH 15" SPORT RIM 4 FRONT RH 185/65 R15 TYRE 1 260 Sub-total 5 67 LABOUR 1 To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing. 2 To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. 3 To road test driving, check and resetting wheel alignments system. 4 To re-spray painting on the front bonnet, front support panel, front fender and front bumper. 5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. Labour Total 5 3,45				30.00
4 FRONT RH 185/65 R15 TYRE 1 266 Sub-total 5 67 LABOUR 1 To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing. 2 To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. 3 To road test driving, check and resetting wheel alignments system. 4 To re-spray painting on the front bonnet, front support panel, front fender and front bumper. 5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. Labour Total 5 3,45				30.00
LABOUR 1 To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing. 2 To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. 3 To road test driving, check and resetting wheel alignments system. 4 To re-spray painting on the front bonnet, front support panel, front fender and front bumper. 5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. Labour Total S 3,455	3 1	RONT RH 15" SPORT RIM 1		350.00
LABOUR 1 To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing. 2 To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. 3 To road test driving, check and resetting wheel alignments system. 4 To re-spray painting on the front bonnet, front support panel, front fender and front bumper. 5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. Labour Total S 3,45	4 1	RONT RH 185/65 R15 TYRE 1		260.00
1 To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing. 2 To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. 3 To road test driving, check and resetting wheel alignments system. 4 To re-spray painting on the front bonnet, front support panel, front fender and front bumper. 5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. Labour Total \$ 3,45		Sub-total	5	670.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. To road test driving, check and resetting wheel alignments system. To re-spray painting on the front bonnet, front support panel, front fender and front bumper. To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. To apply anti-rust chemical on repaired and replaced panel. Labour Total S 3,45	J	LABOUR		
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion. To road test driving, check and resetting wheel alignments system. To re-spray painting on the front bonnet, front support panel, front fender and front bumper. To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. To apply anti-rust chemical on repaired and replaced panel. Labour Total S 3,45	1.	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing.		120.00
To read test driving, check and resetting wheel alignments system. 4 To re-spray painting on the front bonnet, front support panel, front fender and front bumper. 5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. 120 Labour Total \$ 3,45	2	To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub,		450.00
5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. 1,400 Labour Total S 3,45				160.00
5 To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to the accident. 6 To apply anti-rust chemical on repaired and replaced panel. 1,400 Labour Total S 3,45	4	To re-spray painting on the front bonnet, front support panel, front fender and front bumper.		1,200.00
To apply anti-rust chemical on repaired and replaced panel. 120 Labour Total S 3,45	5 7	To provide workmanship to change the above damaged bodyparts, repair, body alignments consistent to		1,400.00
	6 7	To apply anti-rust chemical on repaired and replaced panel.		120.00
				3920000
Parts & Labour Total \$ 9,23		Labour Total	_\$	3,450.00
		Parts & Labour Total	5	9,238.80

Best Regards,

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors UEN NO: 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16 MANHATTAN HOUSE

SINGAPORE 169876 TEL: (65) 6532 2455

FAX: (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: Ihling@tong.com.sg

Our Ref:

LLH/ing/1082/0219/WLC

Your Ref: SLS 769 Z

2 8 FEB 2019

LIEW YEW PHENG

388 Bukit Batok West Avenue 5

#12-366

Singapore 650388

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way#07-16 AIG Bullding Singapore 079120

Attn: Motor Claims Department

Dear Sirs,



(For your attention:without enclosures)

BY PDX NO. 8181

PDX Intercompany Exchange Pte Ltd

FROM TOMMY CHOO, MARK GO LLC 2141 PDX Box No.

ACCIDENT INVOLVING SJT 6259 H AND SLS 769 Z ON 18 MAY 2018 ALONG LENG KEE ROAD

We are instructed by M/s Excel Motoring, to claim damages against you or your insured, the driver of motor vehicle no. SLS 769 Z, in connection with a road traffic accident on 18 of May 2018, at about 19:30 hours along Leng Kee Road, involving our client's motor vehicle no. SJT 6259 H and motor vehicle no. SLS 769 Z driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligence and/or management of his motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our client had been put to loss and expenses, particulars of which are as follows:

		F 000 00
1	Costs of Repair	\$ 5,000.00
2	Loss of Use (\$80 x 8 days)	\$ 640.00
3	Loss of Use(Pre-repair)(\$80 x 2 days)	\$ 160.00
4	Survey Fees	\$ 400.00
5	Disbursement (at this stage)	\$ 93.00
6	Legal Cost (at this stage)	\$ 700.00
2576		\$ 6,993.00

DIRECTOR: LING LEONG HUI

CONSULTANTS : POOTS LAURENCE JAMES

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors UEN NO : 201523418E (a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16 MANHATTAN HOUSE SINGAPORE 169876 TEL: (65) 6532 2455

FAX: (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

Email: Ihling@tcmg.com.sg

A copy each of the following supporting documents is enclosed:

Copy of accident report and LTA search;

Copy of survey report and invoice and repair bill;

Colour photographs pertaining to our client's motor vehicle for your perusal.

We had on 21 of May 2018 notified your insurer, M/s AIG Asia Pacific Insurance Pte Ltd about the accident and the pre-repair inspection was conducted.

Please note that if you are insured and you wish to claim from your insurance policy, you should immediately pass this letter to your insurer.

Please note that you should send us an acknowledgment of receipt of this letter within fourteen (14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with the relevant documents within 8 weeks of your receipt of this letter.

Yours faithfully,

Encs.

cc. client

Enquire Vehicle & Owner Information (Vehicle No. SLS769Z As At 18 May 2018 / 19:30:00)

Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

LLH.SJT6259H.WLC

Current Owner Details

Owner ID Type:

Singapore NRIC

Owner ID:

57826010F

Owner Name:

LIEW YEW PHENG

Registered Address Type: HDB / HUDC

Registered Block/House

No.:

388

Registered Street Name: BUKIT BATOK WEST AVENUE 5

Registered Unit No.:

#12-366

Registered Building Name: -

Registered Postal Code: 650388

Current Vehicle Details

Vehicle No.:

5L5769Z

Make Description/Model: MAZDA / MAZDA5 WAGON 2.0 AT EU6

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Markezins

VATINGESIES / National PERF DATE & TRANS 100 SHAFTED BY SOUTHE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- Information provided m repudiate policy ability. d must be as truthful and occurate as possible. Any wiful n
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any false reporting may be referred to the Police for Investigation.

- This roport will be forwarded by the trauvers of the GM Records Management Centre established by the General Insurance Association of Singapore (GM) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made enalistic

	ACCIDENT STATEMENT	
Date Of Report	19/05/2018 15:33	
Date Of Accident	18/05/2018 19:30	
Exact Location Of Accident	LENG KEE ROAD	
Country/State of Lose	SINGAPORE	
	DETAILS OF OWN VEHICLE	

DE	ETAILS OF	OWN VEHICLE

Vehicle Registration Number

Insured/Policyholder

Name Of Registered Owner

EXCEL MOTORING

SJT6259H

Co Reg No 53180222A Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-88115028 Alternative Phone No. OFFICE-88115028

Vehicle Particulars

Manufacturer HYUNDAI

Model AVANTE 1.6 AT ABS D/AB 2WD 4DR

Exact Purpose for which vehicle was being used at WORK

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy NO

Policy Number 5095127768-01

Cover Note Number

Driver

Name of Driver RAMESH S/O MUTHU KUMAR

NRIC No. S7625455I Date Of Birth 02/08/1976 Occupation OUTDOOR Date Of Driving Pass 09/04/2003

Driving Experience 15 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-88115028

Fax Number

Contact Number OTHERS-88115028

EMail Address NOEMAIL Address

BLK 432C YISHUN AVENUE 1

#05-545

Postcode

763432

Was driver an employee of the insured's Company NO

if No. Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

DRIZZLING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any Injured conveyed to hospital by

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

NO

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLS769Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

PUAR CHENG LOONG

NRIC/Passport Number

S7614891J

Contact Number

96611093 / 66036114

TRANS EUROKARS MAZDA

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (including Driver)

Page 2 of 30

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: NRIC/FIN No.:

SKETCH PLAN	Leng tre	A -SJT625' B-SLS 7692
Vechica A	total driving glow total durn infront ond hit my fortigh	q Leng kee Ld, suddonly into 1 side poistion.
DECLARATION I/We declare the foregoing part Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

WILLIAM LEE CAR AIRCON ENGINEERING

61 UBI AVENUE 2 #08-04B AUTOMOBILE MEGAMART SINGAPORE 408898 TEL: 6382 1006 FAX: 6383 4088

PHOTOCOPY

TO: IEXCEL MOTORING

AS PER REPORT SINGAPORE Our Reference:

AVANTE/SJT6259H

Date:

10-Jul-2018

Vehicle Num:

SJT 6259 H

Make/Model:

HYNDAI AVANTE 1.6 AT ABS

D/AB 2WD 4DR

Chassis No.:

KMHDU418MAU891755

Engine No.:

G4FC9U745122

Accident Date: 18-May-2018

		Amount
OTAL LUMP SUM REPAIR FOR	SJT 6259 H	\$5,000.00
	TOTAL:	\$ 5,000.00
	E. & O.E	

WILLIAM LEE CAR AIRCON ENGINEERING



PHOTOCOPY

INVOICE

TO: EXCEL MOTORING

Invoice No.:

518/WL665

C/O: WILLIAM LEE CAR AIRCON ENGINEERING

Date:

10-Jul-2018

61 UBI AVENUE 2 #08-04B AUTOMOBILE MEGAMART

SINGAPORE 408898

PARTICULARS

Vehicle Registration No.:

SJT 6259 H

Date of Loss:

18-May-2018

Date of Assessment:

22-May-2018

SERVICES

FEES

Assessment with report Photographs Including films, developing, storage and Transport.

\$400.00

TOTAL

\$400.00

SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to: "AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AUTOMOBILE ASSESSMENT REPORT

EXCEL MOTORING TO:

C/O: WILLIAM LEE CAR AIRCON ENGINEERING

61 UBI AVENUE 2 #08-04B **AUTOMOBILE MEGAMART** SINGAPORE 408898

Our Reference:

518/WL665

Date:

10-Jul-2018

ASSESSMENT OF VEHICLE NO. SJT 6259 H

DATE OF LOSS:

18-May-2018

We have carried out a physical assessment at WILLIAM LEE CAR AIRCON ENGINEERING, 61 Ubi Avenue 2 #08-04B Automobile Megamart Singapore 408898, according to your instruction

22-May-2018 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.:

SJT 6259 H

Make & Model:

HYNDAI AVANTE 1.6 AT ABS D/AB 2WD 4DR

Year of Registration:

2009 1591

Engine Capacity: Chassis No.:

KMHDU41BMAU891755

Engine No.:

G4FC9U745122

Colour:

MAROON

142868

Mileage (km):

2. VEHICLE CONDITION

Body Paint:

GOOD

Steering:

SERVICEABLE

Foot Brake:

SERVICEABLE

Parking Brake: Modification:

SERVICEABLE NIL

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size/Thread:

BRIDGESTONE 185/65 R15 - 70%

LH Make/Size/Thread:

BRIDGESTONE 185/65 R15-70%

Rear

RH Make/Size/Thread:

BRIDGESTONE 185/65 R15 - 70%

LH Make/Size/Thread:

BRIDGESTONE 185/65 R15 - 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

5. REMARKS

Market Value:

Na

Salvage Value:

Na

Repair Limit:

Na

Estimated Amount:

\$9,238.80

Adjusted Amount:


\$6,560.80

Lump Sum:

\$5,000.00

Estimated Repair Days:

8 days



Pursuant to your instruction, we have NOT AUTHORISED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SJT 6259 H

PARTS	(LIST	ITEMS)

		Condition	Workshop's Estimate	Our Assessment
Qty	Description	2-1-2-11-2		
1	FRONT GRILLE	Repair	366.00	65.00 NN X
1	FRONT GRILLE 'LOGO' EMBLEM	Reuse	65.00	39.00 N N X
6	FRONT GRILLE CLIPS	Necessary	39.00	480.00 / Cut
1	FRONT RH HEADLAMP	Cracked	480.00	480.00 × 5.00 1
2	FRONT RH HEADLAMP CLIPS	Necessary	13.00	35.00×///
1	FRONT RH HEADLAMP LOWER BRACKET	Faulty	35.00	435.00 Cut
1	FRONT BUMPER	Cracked	435.00	435.00 (1/4)
1	FRONT BUMPER INNER SPONGE	Cracked 16 Pro	113.00	113.00 NNX
1	FRONT BUMPER LOWER CENTER GRILLE	Cracked	48.00	48.00×///
1	FRONT BUMPER LOWER RUBBER MOULDING	Cracked	44.00	44.00×7V/V
1	FRONT BUMPER LOWER UNDER COVER	Cracked HO PIC	44.00	44:00×^\\\
1	FRONT BUMPER REINFORCEMENT	Repair	254.00	-XNN
1	FRONT BUMPER RH FOG LAMP COVER	Cracked No PC	26.00	26:00×1111×
2	FRONT BUMPER SIDE RETAINER L/R	Bent	50.00	/ 25 50.00
1	FRON SUPPORT PANEL	Repair	791.00	XNN
1	FRONT RH FENDER TOP GARNISH	Cracked	28.00	28/00 X 1/1/
3	FRONT RH FENDER TOP GARNISH CLIPS	Necessary	19.50	19/50 X
1	FRONT RH FENDER	Bent	402.00	/ 402.00 / Buc
1	FRONT RH FENDER 'VVT' EMBLEM	Necessary	22.00	/ 22.00 NEC.
- 1	FRONT RH FENDER BRACKET	Bent	15.00	15:00 X N/V
1	FRONT RH FENDER INNER PANEL	Repair	493.00	X-NW -
- 1	FRONT RH FENDER INNER SHIELD	Cracked	57.00	57,00 × NN
- 1	FRONT RH FENDER MUDFLAP	Repair	33.00	. NNX
- 1	FRONT SUSPENSION RH ABS SENSOR	Faulty	228.00	228.00 NNX
- 1	FRONT SUSPENSION RH DRIVE SHAFT ASSY	Repair	935.00	- MNX
- 1	FRONT SUSPENSION RH KNUCKLE ARM	Bent	363.00	363.00)
1	FRONT SUSPENSION RH KNUCKLE ARM BEARING	Jammed	114.00	114.00 WNX
i	FRONT SUSPENSION RH LOWER ARM	Bent	282.00	282.00
1	FRONT SUSPENSION RH LOWER BALL JOINT	Bent	77.00	77.00×711
- 1	FRONT SUSPENSION RH POWER STEERING RACK END	Repair	112.00	- ×.NN
- 1	FRONT SUSPENSION RH POWER STEERING TIE ROD	Bent	55.00	55.00 NM
- 1	FRONT SUSPENSION RH SHOCK ABSORBER	Bent	194.00	194.00× N.M
1	FRONT SUSPENSION RH SHOCK ABSORBER TOP MOUNTING	Bent	96.00	
1	FRONT SUSPENSION RH STABILIZER BAR LINK	Bent	69.00	69.00×N/N
			6,398.50	3,413.50
	17/11	Less 2007 discount	1 279 70	

1364 Less 20% discount Parts Total:

6,398.50 3,413.50 count 1,279.70 682.70 5,118.80 2,730.80

ASSESSMENT REPORT FOR VEHICLE NO. SJT 6259 H

SPECIAL NETT ITEMS

	FRONT BUMPER CLIPS - SET	Necessary	30.00	30.00
*	- 10 사이를 즐겁다 하시면 1차이를 하시면 10 HT		30.00	30.00 Nec
1	FRONT RH FENDER INNER SHIELD CLIPS - SET	Necessary		
		Bent	350.00	350.00× 1
1	FRONT RH 15" SPORT RIM		250.00	260.000
1	FRONT RH 185/65 R15 TYRE	Cut	260.00	260.00× N N
				The second second second

			7
Special Nett Total:	670.00	670.00	60
op weren to the second			

6,560.80

9,238.80

ABO			Workshop's	Our
5/N	Description		Estimate	Assessment
1	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing.		120.00	3 = 100:00
2	To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing drive shaft, anti-roll bar, top-arm and steering rack and pinion.	ig, bearing hub,	450.00	400.00-X M
3	To road test driving, check and resetting wheel alignments system.		160.00	160.00 X M
4	To re-spray painting on the front bonnet, front support panel, front fender and front bump	er.	1,200.00	1,100.00 400.0
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-const align body structure, body alignments and damaged consistent to the accident.	ruct and re-	1,400.00	1,300.00 400 0
6	To apply anti-rust chemical on repaired and replaced panel.	890	-120.00	100.00 60
		Labour Total :	3,450.00	3,160.00

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is (SINGAPORE DOLLARS FIVE THOUSAND ONLY) \$5,000.00

2041.2

TOTAL (PARTS & LABOUR) \$



Amas Ong Automobile Assessor

...CLAIM SUBFOLDER...(Pending for Survey Report) Paper Survey

LAIM SUB	OLDER TRA	CKING						
Case	Natified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status
Main	21 May 2018		06 Aug 2018 17:36 Edit Adj Rpt	5\$1,600.00 Edit Estimates	4	1,600.00 lew Rpt		Pending for Survey Report Cancel Case
	Main	∏ R	eference	Claim D	etails		Documents	Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by insurer]	
Insured:	TRANS EL	JROKARS PTE LT	D, Co. Reg. No.: 15	99103859N				
Main Claimant:	EXCEL MO	TORING, Co.	Reg. No.: 53180222A	ř				
Vehicle Reg No.:	SJT6259	9Н		Date	of Loss:		3 19:00 - :59 hs and 25 Days Fr	om LTA Reg Date (Man Yr)
Claim Type	TP / 559	0041		Policy Note	/Cover Va.:		TR (Comprehensi 01/01/2018 - 31/1	
Vehicle Reg No. (Insured):	SL5769Z			Policy (Clain	No. nant):			
				Exces	ST:	\$\$2,000.00)	
Repairer:	- Not App	ilicable - (-)						
Handling Insurer:			ore) Pte. Ltd. (HQ)					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 625	6-3561 [Hand	led by >	CING GUO Q	IANG) [Final	Rpt due 20/03/2019]
Driver/Cust dian (Insured):		NG LOONG () ,	NRIC: 57614891),	Tel: +659661109	3 Email	i		
ASSOCIAT	ED MAIL RE	CEIVED					View	w All Compose Case Ma
 M51G_5 	3 (18/03/2019): Report Send	Back Alerts - 5JT62	59H (TP)				
ALL ASSO	CIATED TAS	кѕ⊟				View All 5	Search Tasks C	reate New Task Complet
Due Dat	Priority	Type Task	Group Subject	Handler	Assign	ned By	Completed On	Created On Don

Claim Documents

*SJT6259H (559041)

[SLS769Z]

TP

EXCEL MOTORING

May 18 2018 7:00PM

[TRANS EUROKARS PTE LTD]

Vide	eo		1 per	page ~	4
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	18/02/19 19:18	Video from Premise From: OD - Reg. No: SLS769Z, Claiment: TRANS EUROKARS PTE LTD	0	Load MP4	
Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/08/18 17:31	Accident Statement From: OO - Reg. No: SLS7692, Claiment: TRANS EUROKARS PTE LTD	0	Load HTM	
Pho	tos/Images		3 per	page 🔻	₩
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/08/18 09:22	General View	0	Load JPG	V
2	07/08/18 09:22	General View	0	Load JPG	V
3	07/08/18 09:22	General View	0	Load JPG	V
4	07/08/18 09:22	General View	0	Load JPG	V
5	07/08/18 09:22	General View	0	Load JPG	M
6	07/08/18 09:22	General View	0	Load JPG	V
7	07/08/18 09:22	General View	0	Load JPG	S
8	07/08/18 09:22	General View	0	Load JPG	N
9	07/08/18 09:22	General View	0	Load JPG	V
10	07/08/18 09:22	General View	0	Load JPG	Z
11	07/08/18 09:22	General View	0	Load JPG	V
12	07/08/18 09:22	General View	0	Load JPG	V
13	07/08/18 09:22	General View	0	Load JPG	V
14	07/08/18 09:22	General View	0	Load JPG	V
15	07/08/18 09:22	General View	0	Load JPG	V
16	07/08/18 09:22	General View	0	Load JPG	V
17	07/08/18 09:22	General View	0	Load 3PG	V
18	07/08/18 09:22	General View	0	Load JPG	V
19	07/08/18 09:22	General View	0	Load JPG	120
20	07/08/18 09:22	General View	0	Load JPG	V
21	07/08/18 09:22	General View	0	Load JPG	V
22	07/08/18 09:22	General View	0	Load JPG	Ø
23	07/08/18 09:26	Photo After Spray	0	Load JPG	V
24	07/08/18 09:26	Photo After Spray	0	Load JPG	Ø
25	07/08/18 09:26	Photo After Spray	0	Load JPG	V
26	07/08/18 09:26	Photo After Spray	0	Load JPG	V
27	07/08/18 09:26	Photo After Spray	0	Load JPG	V
28	07/08/18 09:26	Photo After Spray	0	Load JPG	7
29	07/08/18 09:26	Photo After Spray	0	Load JPG	1
30	07/08/18 09:26	Photo After Spray	0	Load JPG	V

Vid	eo		1 per p	page V	N
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnall	Print
31	07/08/18 09:26	Photo After Spray	0	Load JPG	V
32	07/08/18 09:26	Photo After Spray	0	Load 3PG	\square
33	07/08/18 09:26	Photo After Spray	0	Load JPG	V
34	07/08/18 09:26	Photo After Spray	0	Load JPG	V
35	07/08/18 09:26	Photo After Spray	0	Load JPG	V
36	07/08/18 09:26	Photo After Spray	0	Load JPG	V
Doc	umentation		1 per ;	page V	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnall	Print
1	06/08/18 17:31	SJT6259H E- FILE REPORT From:DD - Reg. No: SLS766Z, Claiment: TRANS BURDKARS FTE LTD	0	Load PDF	
2	06/08/18 17:36	Direct Survey by LKK	0	Load PDF	
3	18/03/19 09:34	LOD, repair bill & survey report	0	Load PDF	
4	18/03/19 09:34	Survey photos	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/04/19 14:03	Colour Photo	0	Load PDF	
2	10/04/19 14:05	PRS Invoice	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18009296/GVD3E2-1

Date:

10/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

27636744MTR

Claimant Vehicle

SJT6259H

Insured Vehicle No:

SLS769Z

No: Date of Loss:

18/05/2018

Nature of Claim:

TP

Claim No: 559041

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJT6259H

Make & Model:

HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR

Engine No:

G4FC9U745122

Reg. Date:

23/10/2009 (Man. Year: 2009)

Chassis No:

KMHDU41BMAU891755

Colour:

Red

(A)

Odometer:

142868 km

Engine Capacity:

1591 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Ves

Handbrake (Serviceable):

CONDITION OF TYRES

185/65 R15

Rear Tyre Size:

185/65 R15

Front Tyre Size: Front Left Side:

Rear Left Side:

No:

Ecopia 5 mm

Front Right Side:

Ecopia 5 mm Ecopia 5 mm

Rear Right Side:

Ecopia 5 mm

The above values represent the remaining tyre freads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,788.80	1,151.20	4,637.60	80.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	890.00	2,560.00	74.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,238.80	2,041.20	7,197.60	77.91
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	9,238.80	1,600.00	7,638.80	82.68

INSPECTION

Date of Assignment:

06/08/2018

Date Inspected:

22/05/2018 Inspected At:

NO.2 KAKI BUKIT AVE 2 # 01-34

Repairer: WILLIAM LEE CAR AIR CON

ENGINEERING

Estimated Period of Repair:

4.0 days

Adjuster:

XING GUO QIANG

Manager:

VERON CHEN

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2019)
Parts:	143	HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	, no print-code for SJT6259H)
Validity:		ates are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Not Necessary	366.00 FL	*-FL
2	1		*FRONT GRILLE LOGO EMBLEM	Not Necessary	65.00 FL	*-FL
3	6		*FRONT GRILLE CLIPS	Not Necessary	39.00 FL	*-FL
4	1		*FRONT RH HEADLAMP	Cut	480.00 FL	*480.00 FL
5	2		*FRONT RH HEADLAMP CLIPS	Not Necessary	13.00 FL	*-FL
6	1		*FRONT RH HEADLAMP LOWER BRACKET	Not Necessary	35.00 FL	*-FL
7	1		*FRONT BUMPER	Cut	435.00 FL	*435.00 FL
8	1		*FRONT BUMPER INNER SPONGE	Not Necessary	113.00 FL	*-FL
9	1		*FRONT BUMPER LOWER CENTER GRILLE	Not Necessary	48.00 FL	*-FL
10	1		*FRONT BUMPER LOWER RUBBER MOULDING	Not Necessary	44.00 FL	*-FL
11	1		*FRONT BUMPER LOWER UNDER COVER	Not Necessary	44.00 FL	*-FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	254.00 FL	*-FL
13	1		*FRONT BUMPER RH FOG LAMP COVER	Not Necessary	26.00 FL	*-FL
14	1		*FRONT BUMPER SIDE RETAINER L/R (2PCS)	Bent-1pc only	50.00 FL	
15	1		*FRONT SUPPORT PANEL	Not Necessary	791.00 FL	*-FL
16	1		*FRONT RH FENDER TOP GARNISH	Not Necessary	28.00 FL	*-FL
17	3		*FRONT RH FENDER TOP GARNISH CLIPS	Not Necessary	19.50 FL	*-FL
18	1		*FRONT RH FENDER	Buckled	402.00 FL	*402.00 FL
19	1		*FRONT RH FENDER VVT EMBLEM	Necessary	22.00 FL	*22.00 FL
20	1		*FRONT RH FENDER BRACKET	Not Necessary	15.00 FL	*-FL
21	1		*FRONT RH FENDER INNER PANEL	Not Necessary	493.00 FL	*-FL
22	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	57.00 FL	*-FL
23	1		*FRONT RH FENDER MUDFLAP	Not Necessary	33.00 FL	*-FL
24	1		*FRONT SUSPENSION RH ABS SENSOR	Not Necessary	228.00 FL	*-FL
25	1		*FRONT SUSPENSION RH DRIVE SHAFT ASSY	Not Necessary	936.00 FL	*-FL
26	1		*FRONT SUSPENSION RH KNUCKLE ARM	Not Necessary	363.00 FL	*-FL
27	1		*FRONT SUSPENSION RH KNUCKLE ARM BEARING	Not Necessary	114.00 FL	*-FL
28	1		*FRONT SUSPENSION RH LOWER ARM	Not Necessary	282.00 FL	*-FL
29	1		*FRONT SUSPENSION RH LOWER BALL JOINT	Not Necessary	77.00 FL	*-FL
30	1		*FRONT SUSPENSION RH POWER STEERING RACK END	Not Necessary	112.00 FL	*-FL
31	1		*FRONT SUSPENSION RH POWER STEERING TIE ROD	Not Necessary	55.00 FL	*-FL
32	1		*FRONT SUSPENSION RH SHOCK ABSORBER	Not Necessary	194.00 FL	*-FL
33	1		*FRONT SUSPENSION RH SHOCK ABSORBER TOP MOUNTING	Not Necessary	96,00 FL	*-FL
34	1		*FRONT SUSPENSION RH STABILIZER BAR LINK	Not Necessary	69.00 FL	*-FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00FS
36	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
37	1		*FRONT RH 15 SPORT RIM (BENT)	Not Consistent With The 350.00 F Impact		*-FS
38	1		*FRONT RH 185/65 R15 TYRE	Not Necessary	260.00 FS	*-FS
F=Fn	anchise	part. S=	SpcNett. L=ListItemDisc			
				Sub Total (S\$)	7,068.50	1,424.00
	- List Item Discount on L Items 20.00/20.00% (S\$)				1,279.70	272.80
				Total Parts (S\$)	5,788.80	1,151.20
	_		Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSSING	New	120.00	30.00
TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	450.00	0.00
TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	160.00	0.00
TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER AND FRONT BUMPER	New	1,200.00	400.00
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New ND	1,400.00	400.00
TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labo	our Cost (S\$)	3,450.00	890.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSSING TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER AND FRONT BUMPER TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, New CHECK LIGHTING, RESETTING HEADLAMP FOCUSSING TO REMOVE, CHANGE FRONT SUSPENSION PARTS, New ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL New ALIGNMENTS SYSTEM TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT New SUPPORT PANEL, FRONT FENDER AND FRONT BUMPER TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND New	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, New 120.00 CHECK LIGHTING, RESETTING HEADLAMP FOCUSSING TO REMOVE, CHANGE FRONT SUSPENSION PARTS, New 450.00 ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL New 160.00 ALIGNMENTS SYSTEM TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER AND FRONT BUMPER TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND New 120.00

< END OF ESTIMATES >