

ASS. REC. BY:

REF:

CS/MSG19003706/KISD321

Special Instruction:

Survivor:

KALVIN

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time:

26/19 @ 4:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HC 6155L

Insured:

SGW 36422

at Workshop m/s

Premier Automotive

Tel:

6544 6689

of

23 Changi South Ave #01-02

Policy No:

28978758QMX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:41am @ 27/19

Person Contacted:

Vincent

Vehicle

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHC6155L-NAV/INC/6002489/63

DOA: 8/2/16

SGW 36422-CV+/VAL19003689/C9

DOA: 22/2/19

28/02/19

@ 15:58 p.m. revised IA to Irene Tan via memo.

Surveyor: Kalvin

REF: \_\_\_\_\_

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insured Vehicle No: \_\_\_\_\_

at Workshop no/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 6155 LYr Regn: 26 Sep, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / T.O. / Prime Mover /

Truck / Trailer or

Make: KIA Optimac.c. 1685Colour: Silver

AJC: Insured / Std / NI / NA

Sp. Reading: 553443

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAGM4KME5X68577

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Han Kook

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/2/19D.O.I. 27/2/19Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Kalvin, PLS write parts damaged. Y.</u>
<u>25/3/19</u>	<u>Chad c/p \$4450 / 10% deduction</u>
	<u>(\$ 6,375.07 Rd - 59%)</u>
	<u>26/3/2019</u>

RECEIVED 26 MAR 2019

Date/Time, File Pass to?

26/3/19☐ : Prel. Report☒ : Final Report1) Typist

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 10Resurvey No. of Trip: 1Survey Fee: 200

Transportation: \_\_\_\_\_

S + RS: SI

Photos

Others 10

TOTAL

210

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$) 4,450/- LLSAdd Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Feb 2019		26 Feb 2019 16:28 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HIANG BOON FONG, ID: S1411897G		
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	SHC6155L	Date of Loss:	22/02/2019 22:00 - :59 [52 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28978758QMX (Comprehensive) Coverage: 14/07/2018 - 13/07/2019
Vehicle Reg. No. (Insured):	SGW3642Z	Policy No. (Claimant):	5095103893
		Excess:	S\$500.00
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/02/2019]		
Driver/Custodian (Insured):	TOH TECK BEE (58 / Male) , NRIC: S1411878J Email:		
Adj Asg. Remarks:	Car in, on WP. Please contact us ASAP if you cannot attend this assignment. LIABILITY:UNCLEAR CONTACT:91550072/6544 6689 OUT SOURCE TO LKK IF IHS UNABLE TO SURVEY VEHICLE		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 28 Feb 2019

## Preliminary Advice

Insured Vehicle No	: SGW3642Z	Accident Date	: 22/02/2019
TP Vehicle No	: SHC6155L	Assignment Date	: 26/02/2019
Make	: KIA OPTIMA	Est. Duration of Repair	: 10 days
Date of Inspection	: 27/02/2019		
Inspection At	: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,825.07
Revised Amount	:S\$	4,488.67
Check Items (Estimated)	:S\$	1,478.10
Total	:S\$	5,966.77

Lump Sum Repair	:S\$
-----------------	------

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/02/2019 10:29
Date Of Accident	22/02/2019 22:00
Exact Location Of Accident	STADIUM WALK-NEXT TO KALLANG THEATRE/LEISURE MALL
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC6155L
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	
Driver	
Name of Driver	MASTAN BIN RADAN
NRIC No	S0650760C
Date Of Birth	13/07/1948
Occupation	OUTDOOR
Date Of Driving Pass	06/06/1979
Driving Experience	39 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98314330
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 220 #04-110 TAMPINES ST 24
Postcode	520220
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAX IN THE FRONT SEAT - MALAY GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

VEH. A - 1 PAX VEH. B - SOME PAX

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGW3642Z
Vehicle Make/Model/Colour	HONDA CIVIC
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	MALE CHINESE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE LEFT FRONT PORTION

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*X-50650760C*  
*X-SHC 6155 L*


25 FEB 2013

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHC6155L

B: JGW 36422

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*

25 FEB 2013

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Signature]*

Describe Circumstance of the Accident.

ON 22/02/2019 @ 2200HRS, I WAS DRIVING MY TAXI ( SHC 6155 L ), TRAVELLING ALONG STADIUM WALK WITH A PASSENGER ONBOARD, IN THE RIGHT LANE.

WHILE I WAS MOVING STRAIGHT AHEAD – WITHIN MY LANE, SUDDENLY VEHICLE B ( SGW 3642 Z – HONDA CIVIC/WHITE ) WHICH WAS EXITING FROM CARPARK @ SINGAPORE INDOOR STADIUM (ON MY RIGHT) – FAILED TO KEEP FOR PROPER LOOK OUT & FAILED TO STOP TO GIVE WAY TO ONCOMING VEHICLES APPROACHING FROM MY ROUTE, HAD ENCROACHED ONTO MY PATH ON MY FRONT ABRUPTLY.


AS SUCH, THE LEFT FRONT OF VEHICLE B COLLIDED ONTO THE FRONT PORTION OF MY TAXI – WHILE HE WAS MOVING OFF AHEAD INTO THE DRIVEWAY OF LEISURE MALL/KALLANG THEATRE.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE FRONT PORTION AND VEHICLE B HAD DAMAGES ON THE LEFT FRONT PORTION.

NO INJURY INVOLVED.

VEHICLE B HAD SOME PASSENGERS ONBOARD.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



*[Signature]* 30650760C

Driver's Signature & NRIC Number

@ 10:44:35 AM

(attended by

**CASH SALE/WORK ORDER** No:AL0577



**PEOPLE'S VEHICLE SERVICE PTE LTD**

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 ( 3 LINES ) FAX : 6743 0013

Reg No: 200415052W

Date, 22/2/2024

寶號

Messrs:

Premier Taxi

車號

Vehicle No: SBC ~~6155~~ 6155 L 車型 original

由

From: INFRONT OF INDOOR STADIUM

到

To: OWNER

其他

Remark: ① KEY

時間

Time : 

2	2	1	7	2	2	3	8	2	3	1	0
---	---	---	---	---	---	---	---	---	---	---	---

 AMOUNT: \$ 

--

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by: [Signature]

收貨人

Received by: [Signature]

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	26 Sep 2014 / 09:05:29	Receipt No.:	AACCK001-AX239-140926-000013
Asset Type:	Vehicle	Transaction Amount:	\$63,131.00
Asset ID:	SHC6155L	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140926090529346811		
Vehicle No.:	SHC6155L		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	26 Sep 2014		
Original Registration Date:	26 Sep 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5468577		
Engine No.:	D4FDDH308183		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,787.00		
Minimum PARF Benefit:	\$7,372.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	26 Sep 2014 09:05:29		
COE No.:	2014092601001566E		
COE Expiry Date:	25 Sep 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,704.00		
Lifespan Expiry Date:	25 Sep 2022		
Owner ID Type:	Company		

# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 02/27/2019 10:49 AM

Full Report

Registration: SHC6155L

Printed: 27/02/2019 10:49 AM

## Summary Information

### Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

## Vehicle Details

### Vehicle

Manufacturer:	KIA
Model:	OPTIMA (TF)
Sub Model:	BASE MODEL
Model Sheet Number:	28 36 01
Registration:	SHC6155L
VIN number:	
Odometer:	

### Model Specs

AIR CONDITIONING

# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 02/27/2019 10:49 AM

Full Report

Registration: SHC6155L

Printed: 27/02/2019 10:49 AM

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NN	FRONT NUMBER PLATE R&R / NEW PARTS		X 20.0*	100.00
NN	FRT NO PLATE REINF R&R / NEW PARTS		X 20.0*	100.00
NN	FRONT BUMPER R&R / NEW PARTS		X 20.0*	100.00
NN	FRT BUMPER TRIM CAP R&R / NEW PARTS		X 20.0*	100.00
NN	L/F BUMPER MOULDING R&R / NEW PARTS		X 20.0*	100.00
NN	R/F BUMPER MOULDING R&R / NEW PARTS		X 20.0*	100.00
NN	L/F BUMPER COVER R&R / NEW PARTS		X 20.0*	100.00
NN	R/F BUMPER COVER R&R / NEW PARTS		X 20.0*	100.00
NN	FRT BUMPER GRILLE R&R / NEW PARTS		X 20.0*	100.00
NN	UPP RAD AIR DEFLECT R&R / NEW PARTS		X 20.0*	100.00
NN	FRT LWR IMPACT DAMP R&R / NEW PARTS		X 20.0*	100.00
NN	L/F INN BUMPER BRKT R&R / NEW PARTS		X 20.0*	100.00
NN	R/F INN BUMPER BRKT R&R / NEW PARTS		X 20.0*	100.00
NN	L/F OUT BUMPER BRKT R&R / NEW PARTS		X 20.0*	100.00
NN	R/F OUT BUMPER BRKT R&R / NEW PARTS		X 20.0*	100.00
NN	FRT LWR BUMPER REINF R&R / NEW PARTS		X 20.0*	100.00

# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 02/27/2019 10:49 AM

Full Report

Registration: SHC6155L

Printed: 27/02/2019 10:49 AM

Code	Description		WU	Price SGD
NN	FRT BUMPER SUPPORT R&R / NEW PARTS	X	20.0*	100.00
NN	FRONT BUMPER SPOILER R&R / NEW PARTS	X	20.0*	100.00
NN	GRILLE R&R / NEW PARTS	X	20.0*	100.00
NN	BONNET R&R / NEW PARTS	X	20.0*	100.00
NN	L/BONNET HINGE R&R / NEW PARTS	X	20.0*	100.00
NN	R/BONNET HINGE R&R / NEW PARTS	X	20.0*	100.00
NN	BONNET LOCK R&R / NEW PARTS	X	20.0*	100.00
NN	FRONT BONNET SEAL R&R / NEW PARTS	X	20.0*	100.00
NN	LEFT HEADLAMP ASSY R&R / NEW PARTS	X	20.0*	100.00
NN	RIGHT HEADLAMP ASSY R&R / NEW PARTS	X	20.0*	100.00
NN	L/F WING R&R / NEW PARTS	X	20.0*	100.00
NN	R/F WING R&R / NEW PARTS	X	20.0*	100.00
NN	L/F WING MOULDING R&R / NEW PARTS	X	20.0*	100.00
NN	R/F WING MOULDING R&R / NEW PARTS	X	20.0*	100.00
NN	L/F WHEELHOUSE COVER R&R / NEW PARTS	X	20.0*	100.00
NN	R/F WHEELHOUSE COVER R&R / NEW PARTS	X	20.0*	100.00
NN	FRONT PANEL CPL R&R / NEW PARTS	X	20.0*	100.00
NN	Air-con condensor R&R / NEW PARTS	X	20.0*	100.00
NN	Intercooler R&R / NEW PARTS	X	20.0*	100.00
NN	Radiator R&R / NEW PARTS	X	20.0*	100.00
NN	Air Duct R&R / NEW PARTS	X	20.0*	100.00
1201	L/F SIDE MEMBER REPAIR	X	20.0*	100.00
1202	R/F SIDE MEMBER REPAIR	X	20.0*	100.00

## Labour Cost

Panel / Mechanical Labour

Hrs WU  
78.00 780.0

3,900.00

Total of Labour

3,900.00

## Paint

Paint Work

SYSTEM AZT

Time Basis 10WU/h

Code	Description	WU	Price SGD
	BONNET NEW PART PAINTING	24.0	
	L/F WING NEW PART PAINTING	X 9.0	
	R/F WING NEW PART PAINTING	9.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	
	FRONT BUMPER NEW PART PAINT K1R	11.0	
	FRT BUMPER TRIM CAP NEW PART PAINT K1R	3.0	
	L/F SIDE MEMBER SURFACE PAINT	4.0	
	R/F SIDE MEMBER SURFACE PAINT	4.0	

# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 02/27/2019 10:49 AM

Full Report

Registration: SHC6155L

Printed: 27/02/2019 10:49 AM

## Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	68.51
0741	L/F WING NEW PART PAINTING	X 12.90
0742	R/F WING NEW PART PAINTING	12.90
1009	FRONT PANEL CPL SURFACE PAINT	8.45
0283	FRONT BUMPER NEW PART PAINT K1R	47.12
0293	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.35
1201	L/F SIDE MEMBER SURFACE PAINT	3.17
1202	R/F SIDE MEMBER SURFACE PAINT	3.17

## Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint		61	70.0	
Preparation Main Work Metal		0.80	8.0	40.00
Preparation Comp. Work Plastic		0.30	3.0	15.00
<b>Total</b>	<b>10 WU/h</b>	<b>8.10</b>	<b>81.0</b>	<b>405.00</b>
		7.2	72	360

## Material Cost - Paint

	Price SGD
New Part Painting	81.41 94.31
New Part Painting - Plastic K1R	47.47
Surface-/Blend Paint	14.79
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>170.77 183.67</b>

## Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3	/		25.00
0258	FRT NO PLATE REINF	KNPL0	X		25.00
0283	FRONT BUMPER	865112T500	/		531.00
0293	FRT BUMPER TRIM CAP	865882T500	/		14.00
0295	L/F BUMPER MOULDING	865632T500	X		51.00
0296	R/F BUMPER MOULDING	865642T500	/		51.00
0297	L/F BUMPER COVER	865512T510	X		66.00
0298	R/F BUMPER COVER	865522T510	/		66.00
0303	FRT BUMPER GRILLE	865612T700	X		174.00
0309	UPP RAD AIR DEFLECT	865752T500	/		40.00
0315	FRT LWR IMPACT DAMP	865202T500	/		110.00



# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 02/27/2019 10:49 AM

Full Report

Registration: SHC6155L

Printed: 27/02/2019 10:49 AM

Code	Description	Part Number	Supplier	Price SGD
0317	L/F INN BUMPER BRKT	865832T500	X sm	16.00
0318	R/F INN BUMPER BRKT	865842T500	/ sm	16.00
0321	L/F OUT BUMPER BRKT	865812T500	X sm	16.00
0322	R/F OUT BUMPER BRKT	865822T500	/ sm	16.00
0335	FRT LWR BUMPER REINF	865712T000	/ Band	134.00
0340	FRT BUMPER SUPPORT	865302T500	/ Band	328.00
0391	FRONT BUMPER SPOILER	865912T500	/ sm	52.00
0410	GRILLE	863502T500	/ sm	385.00
0471	BONNET	664002T010	/ Band	979.00
0475	L/BONNET HINGE	791102T000	/ Band	23.00
0476	R/BONNET HINGE	791202T000	/ Band	23.00
0492	BONNET LOCK	811302T900	X sm	36.00
0527	FRONT BONNET SEAL	864352T000	X sm	58.00
0561	LEFT HEADLAMP ASSY	921012T573	/ sm	1,028.00
0562	RIGHT HEADLAMP ASSY	921022T573	/ sm	1,028.00
0741	L/F WING	663112T000	X repr	384.00
0742	R/F WING	663212T000	/ Buckle	384.00
0783	L/F WING MOULDING	877712T000	X sm	34.00
0784	R/F WING MOULDING	877722T000	X sm	34.00
0841	L/F WHEELHOUSE COVER	868112T500	X repr	120.00
0842	R/F WHEELHOUSE COVER	868122T500	/ Buckle	120.00
1009	FRONT PANEL CPL	641012T950	/ Band	645.00
1000	Air-con condensor	Air con	/ Band	805.00
1001	Intercooler	N.A	X sm	800.00
1002	Radiator	N.A	/ Band	669.00
1003	Air Duct	N.A	/ sm	210.00

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

<b>Savings</b>	0.00
<b>Subtotal</b>	9,496.00
<b>Subtotal Discount(+35.00%)</b>	-3,323.60
<b>Total</b>	6,172.40

## Extras

Code	Description	Price SGD
1004	Front bumper clips / n/a	48.00*
1005	LH fender sticker X n/a	30.00*
1006	RH fender sticker X n/a	30.00*
1007	LH Innershield clips X n/a	28.00*
1008	RH inner shield clip / n/a	28.00*

# Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2  
486443

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 02/27/2019 10:49 AM

Full Report

Registration: SHC6155L

Printed: 27/02/2019 10:49 AM

Code	Description	Price SGD
	<b>Total Extras</b>	<b>164.00</b>

## Final Calculation

	SGD	SGD
<b>Parts</b>	9,496.00	
Total Discount(+35.00%)	-3,323.60	
<b>Total Parts</b>		<b>6,172.40</b>
<b>Labour Time Base 10 WU/h</b>		
Total 780.0 WU X 50.00 SGD/h	3,900.00	
<b>Total of Labour</b>		<b>3,900.00</b>
<b>Total Of Extras</b>		<b>76 164.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 81.0 WU X 50.00 SGD/h	405.00	
Material Cost	183.67	
<b>Total Paint Including Material</b>		<b>588.67</b>
<b>Repair Cost Excludes GST</b>		<b>10,825.07</b>
GST (+7.0%)		<b>757.75</b>
<b>Repair Cost Included GST</b>		<b>11,582.82</b>

## Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants has hereby  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- All work must be resurveyed and approved from Insurance Company

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

**Claim Reference:**

**Assessment number: SHC6155L**

**Version: 1810**

**Date calculated: 03/26/2019 10:18 AM**

**Full Report**

**Registration: SHC6155L**

**Printed: 26/03/2019 10:18 AM**

---

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

**Vehicle**

Manufacturer:	KIA
Model:	OPTIMA (TF)
Sub Model:	BASE MODEL
Model Sheet Number:	28 36 01
Registration:	SHC6155L
VIN number:	
Odometer:	

**Model Specs**

AIR CONDITIONING

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
Assessment number: SHC6155L  
Version: 1810  
Date calculated: 03/26/2019 10:18 AM

Full Report  
Registration: SHC6155L  
Printed: 26/03/2019 10:18 AM


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Labour

		Time Base 10 WU/h		
Code	Description		WU	Price SGD
1201	L/F SIDE MEMBER REPAIR			
1202	R/F SIDE MEMBER REPAIR			
Labour Cost			Hrs	WU

## Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	BONNET NEW PART PAINTING		24.0	
	R/F WING NEW PART PAINTING		9.0	
	FRONT PANEL CPL SURFACE PAINT		6.0	
	FRONT BUMPER NEW PART PAINT K1R		11.0	
	FRT BUMPER TRIM CAP NEW PART PAINT K1R		3.0	

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 03/26/2019 10:18 AM

Full Report

Registration: SHC6155L

Printed: 26/03/2019 10:18 AM

Paint Work

SYSTEM AZT

Time Basis 10WU/h

Code	Description	WU	Price SGD
	L/F SIDE MEMBER SURFACE PAINT	4.0	
	R/F SIDE MEMBER SURFACE PAINT	4.0	

**Paint Material Per Part**

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	68.51
0742	R/F WING NEW PART PAINTING	12.90
1009	FRONT PANEL CPL SURFACE PAINT	8.45
0283	FRONT BUMPER NEW PART PAINT K1R	47.12
0293	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.35
1201	L/F SIDE MEMBER SURFACE PAINT	3.17
1202	R/F SIDE MEMBER SURFACE PAINT	3.17

**Labour Cost - Paint**

	Hrs	WU	Price SGD
Factor			50.00 SGD/h
Time Paint		61.0	
Preparation Main Work Metal	0.80	8.0	40.00
Preparation Comp. Work Plastic	0.30	3.0	15.00
<b>Total</b>	<b>7.20</b>	<b>72.0</b>	<b>360.00</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	81.41
New Part Painting - Plastic K1R	47.47
Surface-/Blend Paint	14.79
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>170.77</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3			25.00
0283	FRONT BUMPER	865112T500			531.00
0293	FRT BUMPER TRIM CAP	865882T500			14.00
0296	R/F BUMPER MOULDING	865642T500			51.00
0298	R/F BUMPER COVER	865522T510			66.00

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:

Assessment number: SHC6155L

Version: 1810

Date calculated: 03/26/2019 10:18 AM

Full Report

Registration: SHC6155L

Printed: 26/03/2019 10:18 AM

Code	Description	Part Number	Supplier	Price SGD
0309	UPP RAD AIR DEFLECT	865752T500		40.00
0315	FRT LWR IMPACT DAMP	865202T500		110.00
0318	R/F INN BUMPER BRKT	865842T500		16.00
0322	R/F OUT BUMPER BRKT	865822T500		16.00
0335	FRT LWR BUMPER REINF	865712T000		134.00
0340	FRT BUMPER SUPPORT	865302T500		328.00
0391	FRONT BUMPER SPOILER	865912T500		52.00
0410	GRILLE	863502T500		385.00
0471	BONNET	664002T010		979.00
0475	L/BONNET HINGE	791102T000		23.00
0476	R/BONNET HINGE	791202T000		23.00
0561	LEFT HEADLAMP ASSY	921012T573		1,028.00
0562	RIGHT HEADLAMP ASSY	921022T573		1,028.00
0742	R/F WING	663212T000		384.00
0842	R/F WHEELHOUSE COVER	868122T500		120.00
1009	FRONT PANEL CPL	641012T950		645.00
1000	Air-con condensor	Air con		805.00
1002	Radiator	N.A		669.00
1003	Air Duct	N.A		210.00
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			7,682.00
u: Used parts	<b>Subtotal Discount(+35.00%)</b>			-2,688.70
	<b>Total</b>			4,993.30

**Extras**

Code	Description	Price SGD
1004	Front bumper clips	48.00*
1008	RH inner shield clip	28.00*
	<b>Total Extras</b>	76.00

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
Assessment number: SHC6155L  
Version: 1810  
Date calculated: 03/26/2019 10:18 AM

Full Report  
Registration: SHC6155L  
Printed: 26/03/2019 10:18 AM

**Final Calculation**

	SGD	SGD
<b>Parts</b>	7,682.00	
Total Discount(+35.00%)	-2,688.70	
<b>Total Parts</b>		<b>4,993.30</b>
<b>Total Of Extras</b>		<b>76.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 72.0 WU X 50.00 SGD/h	360.00	
Material Cost	170.77	
<b>Total Paint Including Material</b>		<b>530.77</b>
<b>Repair Cost Excludes GST</b>		<b>5,600.07</b>
GST (+7.0%)		<b>392.00</b>
<b>Repair Cost Included GST</b>		<b>5,992.07</b>

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Feb 2019		26 Feb 2019 16:28 <a href="#">Edit Adj Rpt</a>	<b>S\$4,450.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,450.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>













































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>HIANG BOON FONG</b> , ID: S1411897G									
Main Claimant: <b>PREMIER TAXIS PTE LTD</b> , Co. Reg. No.: 200304975H									
Vehicle Reg. No.: <b>SHC6155L</b>		Date of Loss: 22/02/2019 21:00 - :59 [52 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 586405</b>		Policy/Cover Note No.: A28978758QMX (Comprehensive) Coverage: 14/07/2018 - 13/07/2019							
Vehicle Reg. No. (Insured): <b>SGW3642Z</b>		Policy No. (Claimant): 5095103893							
		Excess: S\$500.00							
Repairer: <b>Premier Automotive Services Pte Ltd (HQ)</b> 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 28/03/2019]									
Driver/Custodian (Insured): <b>TOH TECK BEE</b> (58 / Male) , NRIC: S1411878J Email:									
Adj Asg. Remarks: Car in, on WP. Please contact us ASAP if you cannot attend this assignment. LIABILITY:UNCLEAR CONTACT:91550072/6544 6689 OUT SOURCE TO LKK IF IHS UNABLE TO SURVEY VEHICLE									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SHC6155L (586405)**  
**[SGW3642Z]**  
**TP**  
**PREMIER TAXIS PTE LTD**  
**Feb 22 2019 9:00PM**  
**[HIANG BOON FONG]**  
**Premier Automotive Services Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Premier Automotive Services Pte Ltd (HQ)								Thumbnail	Print	
1	25/02/19 14:39	Accident Statement								Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	28/02/19 15:58	Adjuster Immediate Advice								Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Premier Automotive Services Pte Ltd (HQ)								Thumbnail	Print	
1	25/02/19 14:02	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
2	25/02/19 14:02	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
3	25/02/19 14:02	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
4	25/02/19 14:02	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
5	25/02/19 14:02	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
6	25/02/19 14:02	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
7	25/02/19 14:02	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
2	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
3	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
4	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
5	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
6	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
7	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
8	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
9	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
10	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
11	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
12	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
13	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
14	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
15	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
16	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
17	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
18	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
19	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
20	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
21	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	
22	27/02/19 16:54	General View								Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premier Automotive Services Pte Ltd (HQ)		
23	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
29	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
30	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
31	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
32	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
33	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
34	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
35	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
36	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
37	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
38	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/02/19 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	25/03/19 08:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		
1	26/02/19 11:27	SGW3642Z E-FILE REPORT	 Load PDF	
2	26/02/19 11:27	FAX FROM TP TO ARRANGE SURVEY	 Load PDF	
No	Finalized On	Premier Automotive Services Pte Ltd (HQ)		
1	25/02/19 14:39	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	26/03/19 14:38	SHC 6155L AUDATEX.pdf	 Load PDF	

## Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premier Automotive Services Pte Ltd (HQ)		Thumbnail	Print
1	25/02/19 14:39	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premier Automotive Services Pte Ltd (HQ)		Thumbnail	Print
1	25/02/19 14:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 14:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	25/02/19 14:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	25/02/19 14:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	25/02/19 14:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	25/02/19 14:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	25/02/19 14:02	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premier Automotive Services Pte Ltd (HQ)		Thumbnail	Print
1	25/02/19 14:39	Sketch Plan		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003700/K1SD3E2

Date: 02/04/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28978758QMX

Claimant Vehicle No: SHC6155L

Insured Vehicle No: SGW3642Z

Date of Loss: 22/02/2019

Nature of Claim: TP

Claim No: 586405

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6155L

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDDH308183

Reg. Date: 26/09/2014 (Man. Year: 2013)

Chassis No: KNAGM414ME5468577

Colour: Silver

Odometer: 553443 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,336.40	5,069.30	1,267.10	20.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,488.67	530.77	3,957.90	88.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,825.07</b>	<b>5,600.07</b>	<b>5,225.00</b>	<b>48.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,450.00</b>		
<b>(S\$)</b>	10,825.07	4,450.00	6,375.07	58.89
<b>+ GST 7.00/7.00% (S\$)</b>	757.75	311.50	446.25	58.89
<b>Nett Amount (S\$)</b>	<b>11,582.82</b>	<b>4,761.50</b>	<b>6,821.32</b>	<b>58.89</b>

### INSPECTION

Date of Assignment: 26/02/2019

Date Inspected: 27/02/2019 Inspected At:

Premier Automotive Services Pte Ltd (HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 10.0 days

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2019)
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6155L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	25.00 FL	*25.00 FL
2	1		*FRT NO PLATE REINF	Serviceable	25.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
4	1		*FRT BUMPER TRIM CAP	Missing	14.00 FL	*14.00 FL
5	1		*L/F BUMPER MOULDING	Repair	51.00 FL	*- FL
6	1		*R/F BUMPER MOULDING	Cracked	51.00 FL	*51.00 FL
7	1		*L/F BUMPER COVER	Serviceable	66.00 FL	*- FL
8	1		*R/F BUMPER COVER	Cracked	66.00 FL	*66.00 FL
9	1		*FRT BUMPER GRILLE	Serviceable	174.00 FL	*- FL
10	1		*UPP RAD AIR DEFLECT	Cracked	40.00 FL	*40.00 FL
11	1		*FRT LWR IMPACT DAMP	Bent	110.00 FL	*110.00 FL
12	1		*L/F INN BUMPER BRKT	Serviceable	16.00 FL	*- FL
13	1		*R/F INN BUMPER BRKT	Cracked	16.00 FL	*16.00 FL
14	1		*L/F OUT BUMPER BRKT	Serviceable	16.00 FL	*- FL
15	1		*R/F OUT BUMPER BRKT	Cracked	16.00 FL	*16.00 FL
16	1		*FRT LWR BUMPER REINF	Bent	134.00 FL	*134.00 FL
17	1		*FRT BUMPER SUPPORT	Deformed	328.00 FL	*328.00 FL
18	1		*FRONT BUMPER SPOILER	Cracked	52.00 FL	*52.00 FL
19	1		*GRILLE	Cracked	385.00 FL	*385.00 FL
20	1		*BONNET	Bent	979.00 FL	*979.00 FL
21	1		*L/BONNET HINGE	Bent	23.00 FL	*23.00 FL
22	1		*R/BONNET HINGE	Bent	23.00 FL	*23.00 FL
23	1		*BONNET LOCK	Serviceable	36.00 FL	*- FL
24	1		*FRONT BONNET SEAL	Serviceable	58.00 FL	*- FL
25	1		*LEFT HEADLAMP ASSY	Cracked	1,028.00 FL	*1,028.00 FL
26	1		*RIGHT HEADLAMP ASSY	Cracked	1,028.00 FL	*1,028.00 FL
27	1		*L/F WING	Repair	384.00 FL	*- FL
28	1		*R/F WING	Buckled	384.00 FL	*384.00 FL
29	1		*L/F WING MOULDING	Serviceable	34.00 FL	*- FL
30	1		*R/F WING MOULDING	Serviceable	34.00 FL	*- FL
31	1		*L/F WHEELHOUSE COVER	Repair	120.00 FL	*- FL
32	1		*R/F WHEELHOUSE COVER	Buckled	120.00 FL	*120.00 FL
33	1		*FRONT PANEL CPL	Bent	645.00 FL	*645.00 FL
34	1		*AIR-CON CONDENSOR	Bent	805.00 FL	*805.00 FL
35	1		*INTERCOOLER	Serviceable	800.00 FL	*- FL
36	1		*RADIATOR	Bent	669.00 FL	*669.00 FL
37	1		*AIR DUCT	Cracked	210.00 FL	*210.00 FL
38	1		*FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
39	1		*LH FENDER STICKER	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*RH FENDER STICKER	Not Necessary	30.00 FS	*- FS
41	1		*LH INNERSHIELD CLIPS	Not Necessary	28.00 FS	*- FS
42	1		*RH INNER SHIELD CLIP	Necessary	28.00 FS	*28.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,660.00	7,758.00
- List Item Discount on L Items 35.00/35.00% (S\$)	3,323.60	2,688.70

Total Parts (S\$)	6,336.40	5,069.30
-------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	780.0 WU X 50.00 SGD/H	New	3,900.00	0.00
2	LABOUR COST 81.0 WU X 50.00 SGD/H	New	405.00	360.00
3	MATERIAL COST	New	183.67	170.77
Gross Labour Cost (S\$)			<b>4,488.67</b>	<b>530.77</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >