

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19003705/KGA3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SHC5666K	Insured Vehicle No :	SGD6487K
Date of Loss:	20/02/2019	Nature of Claim:	TP
		Claim No:	5088417976SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5666K		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	HIDDEN
Reg. Date:	04/11/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC279757
Colour:	Metallic White/Red	Odometer:	460972 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,461.50	0.00	7,461.50	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,250.00	960.00	7,290.00	88.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,711.50	960.00	14,751.50	93.89
Approved Total (Overridden) (S\$)		750.00		
(S\$)	15,711.50	750.00	14,961.50	95.23
+ GST 7.00/7.00% (S\$)	1,099.81	52.50	1,047.31	95.23
Nett Amount (S\$)	16,811.31	802.50	16,008.81	95.23
+ Car Rental (3.0 x S\$96.99/day) (S\$)		290.97		
		(S\$) 1,093.47		
Liabe Amount (50.00%) (S\$)		546.74		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		554.23		
Global Sum Settlement (S\$)		550.00		

INSPECTION

Date of Assignment:	26/02/2019	Inspected At:	Trans-cab Auto Services Pte Ltd
Date Inspected:	26/02/2019		No 2 Ang Mo Kio Street 63
			Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
2	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
3	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
4	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*- FL
5	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
6	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
7	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
9	1		*REAR TAILLAMP RH	Serviceable	552.55 FL	*- FL
10	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
11	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
12	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
13	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
14	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
15	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
16	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
17	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
18	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,185.33	0.00
- List Item Discount on L Items 10.00/10.00% (S\$)	723.83	0.00
Total Parts (S\$)	7,461.50	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	300.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
3	TO RUST -PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
8	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
10	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (S\$)			8,250.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >