

2.03. REG. BY

REF

CS/FCT19003713/Dvd3n2

Special Instruction

Surveyor

Bryen

ASSIGNMENT (Office)

CWS

From Person

Karen Tan

of

FCT

Date/Time

12:04pm @ 27/2/19

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SHA1909Y

Insured

8HC3996X

at Workshop m/s

Chunni Motor

Tel

65425119

of

Blk 10, Amk Ind. park 2A # 03-19

Policy No.

Claim No

D19001395MPST

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

24/2/2019

CA / REV / REP. / REV 24 HRS

1ps

H.O.D. Endorsement

Date/Time

12:17pm @ 27/2/19

Person Contacted

Lynn

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHA1909Y - NS/INC 12006552/H/kn	DoA: 31/3/12
	8HC3996X - CS/FCT 17004238/T/lynn 2	DoA: 26/2/12
11/3/19	Email preli revised to FCT	

REF

ASSIGNMENT

COR June 2024

2016 June

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s:

at

Insured: _____

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair: 9 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 1909 Y in Rego

Type: M/Car / M/Cycle / Bus / Van / Lorry / Tractor / Prime Mover /

Truck / Trailer or

Make: Hyundai I40

CC 1685

Colour:

Blue

AC Insured / Std / NI / NA

Sp Reading:

4860250

T/Radio: Insured / Std / NI / NA

Eng No:

D4PDFU553310

Ch No:

KMHLB4IUMGU090138

Gen. Cond: Good / Fair / Poor / BurntSteering: Inter / Jammed / Leaked / Burnt orBrake: Inter / Jammed / Leaked / Burnt orMod: Nil / OS/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R14

R:

— " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Campeon

Front

Rear

R/Bal:

5 mm

R/Bal:

5 mm

L/Bal:

5 mm

L/Bal:

5 mm

D.O.A:

25/02/2019

D.O.I:

01/03/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/2 Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SHC 3996 X

11/04/19 Insured L/S 8950/- with 9 days & rev (Red 5555.12, 389)

RECEIVED 11 APR 2019

check with veon d.o.a 24/2/2019.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

11/4 - typist

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee:



Site Insp: \$



Interview: \$



Tech. Ins: \$



Workshop: \$

Report Format:

CWS

Lump Sum / L.B. \$:

8950/-

Survey Fee:

Transportation:

1) \$ + RS. 50

2) Photos 0.50

3) Other 11/4/19

4) 11/4/19

Total

4x15=60

170+60

50

50+50

110

490



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001395MFSH

Our ref: CS/FCI19003713/Dvd3

Date: 11/3/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SHA 1909Y


We thank you for your instruction on 27/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/3/2019 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$14,505.12
Revised Estimate Amount	: S\$6,049.28
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	26-02-2019	Our Ref No. D19001395MFSH
Accident Date	24-02-2019	Claim Type. Third Party
Insured Vehicle	SHC3996X	Third Party Vehicle. SHA1909Y
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 11 March 2019 5:33 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001395MFSH/1, SHA 1909Y
Attachments: SHA 1909Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHA 1909Y
Date of survey: 1/3/2019
Number of days : 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 27 February 2019 2:02 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001395MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 27 February 2019 12:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001395MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

REPAIR ESTIMATE*


DATE : 25.02.2019

TEL : 6542 5179

FAX : 6542 6039 FCI

MODEL	HYUNDAI i40	FAX	0342 6633	CT
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender With Housing (RH) <i>Deformed</i>			\$ 4,736.80 ✓
	Rear Fender Inner Lining (RH) <i>deformed</i>			\$ 169.30 ✓
	Rear Windscreen Moulding <i>h/c</i>			\$ 28.30 ✓
	Rear Door (RH) <i>Deformed</i>			\$ 2,201.10 ✓
	Rear Door Gear/Regulator (RH) <i>h/c</i>			\$ 242.80 X
	Rear Door Power Motor (RH) <i>h/c</i>			\$ 158.60 X
	Rocker Panel Outer Garnish (RH) <i>cut</i>			\$ 341.40 ✓
	Rear Tyre Rim (RH) <i>2 distorted</i>			\$ 325.30 2 ✓
	Rear Wheel Hub-Cap (RH) <i>h/c</i>			\$ 107.10 ✓
	Rear Wheelbearing ING & Hub <i>2 Distorted</i>			\$ 362.00 2 ✓
	Rear Trailing Arm (RH) <i>2 distorted</i>			\$ 192.00 2 ✓
	Rear Assist (RH) <i>2 distorted</i>			\$ 145.70 2 ✓
	Rear Shock Absorber (RH) <i>2 distorted</i>			\$ 276.30 2 ✓
	Rear Shock Absorber Mounting (RH) <i>h/c</i>			\$ 81.30 X
	Rear Crossmember <i>2 distorted</i>			\$ 1,021.50 2 ✓
	Stabilizer Bar <i>2 distorted</i>			\$ 199.60 2 ✓
	Stabilizer Link <i>2 distorted</i>			\$ 85.90 2 ✓
	Rear Upper Arm (RH) <i>2 distorted</i>			\$ 335.75 2 ✓
	Rear Lower Arm (RH) <i>2 distorted</i>			\$ 353.80 2 ✓
	Rear Knuckle Arm (RH) <i>2 distorted</i>			\$ 545.60 2 ✓
			11427.45	
			9141.96	
	SUB TOTAL			\$ 11,910.15
	LESS 20%			\$ 2,382.03
	DISCOUNTED TOTAL			\$ 9,528.12
	Rear Windscreen Sealant <i>h/c</i>			\$ 46.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>h/c</i>			\$ 80.00 Nett ✓
	Front Door Coloured Comfort Logo (RH) <i>h/c</i>			\$ 75.00 Nett ✓
	Rear Tyre (RH) <i>h/c</i>		201.00	\$ 216.00 Nett X
				\$ 417.00

SHA 1909Y

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,400.00 600/-
	Spray Painting Charge			\$ 1,250.00 600/-
	Wiring Charge			\$ 50.00 44
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 44
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 44
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Transfer of Door		1850.00	\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Re-set Rear Power Window System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 } 180/-
	TOTAL LABOUR			\$ 4,560.00
	ESTIMATE TOTAL			\$ 14,505.12
	01/03/2019 @ 1500m		11192.96	
	LIA Antenna		458950/-	
	2/5mm 9 9 days			
				
	LKK Auto			
				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 1909 Y

Technician:

Mileage: 460252

Time Printed 1.3.19 4:22 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°30'		-3°00' 3°00'
3°58'		-0°19' 5°41'
0°41'		-1°30' 1°30'
14°14'		
13°44'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°11'		-3°00' 3°00'
4°18'		-0°19' 5°41'
-1°18'		-1°30' 1°30'
19°01'		
18°50'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°19'		-3°00' 3°00'
-0°20'		-3°00' 3°00'
-4°48'		-3°00' 3°00'
-0°37'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°14'		-3°30' 2°30'
0°17'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°20'		-3°30' 2°30'
2°08'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°54'		-3°00' 3°00'
2°25'		-3°00' 3°00'
-0°55'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003713/Dvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3996X	Veh. Inspected	SHA 1909Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001395MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	27/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU090138	Colour	BLUE	
Odometer	460250	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CAMPEON	5 mm	
L/H Front Tyre	205/60 R16	CAMPEON	5 mm	
R/H Rear Tyre	205/60 R16	CAMPEON	5 mm	
L/H Rear Tyre	205/60 R16	CAMPEON	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/02/2019	Inspection Date	01/03/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1909Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER WITH HOUSING (RH)	DENTED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (RH)	DEFORMED	169.30	169.30
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (RH)	DENTED	2,201.10	2,201.10
1	REAR DOOR GEAR/REGULATOR (RH)	NOT NECESSARY	242.80	-
1	REAR DOOR POWER MOTOR (RH)	NOT NECESSARY	158.60	-
1	ROCKER PANEL OUTER GARNISH (RH)	CUT	341.40	341.40
1	REAR TYRE RIM (RH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	BENT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-2,382.03	-2,285.49
			9,528.12	9,141.96
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	REAR TYRE (RH)(SN)	NOT NECESSARY	216.00	-
			417.00	201.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		1,400.00	600.00
	SPRAY PAINTING CHARGE.		1,250.00	600.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	TRANSFER OF DOOR.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	180.00
	RE-SET REAR ABS SYSTEM. }		200.00	-
	RE-SET REAR POWER WINDOW SYSTEM. }		200.00	-
			4,560.00	1,850.00
	GRAND TOTAL		14,505.12	11,192.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,950.00

Report Ref No. CS/FCI19003713/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.