

ASS. REC. BY:

REF:

CS3/CTI19003714/Rld307 Special Instruction:

Surveyor:

Raisul

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

27/2/19 @ 11:01am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 4716 H

Insured:

at Workshop m/s

Hon Car Repairs

Tel:

62710275

of

Blk 1001 / Blk Merah Lane 3 #01-49

Policy No:

DMCENIS142518033

Claim No:

SNM19D200807002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:01pm @ 27/2/19

Person Contacted:

Susan

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(X) Estimate

GX 4716 H - ABA / INC19002797Y

DVA: 14/2/19

Expired: 30 Apr 2019

PRS

Date:

Expiry Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspected Vehicle No: GX 4716 H

at Workshop m/s: HAN CAR REPAIR

of: BUKIT MEKAR

Insured: CTI

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC/Accident Rpt. Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GX 4716 H

Reg: May 04

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA

CC: 2986

Colour: WHITE

AC: Insured / Std / NI / NA

Sp. Reading: 507957

T/Radio: Insured / Std / NI / NA

Eng/No:

LH 1726119891

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Rovero

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

D.O.I.

27/02/19 04:11pm

Survey held at

HAN CAR REPAIR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: Action / Instruction

Estimated repair range \$3,000 - \$4,000

7/5/2019

Date/Time: File Pass to?

☐ : Prel. Report

n

☐ : Final Report

Date/Time: File Return to?

s

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 \$ + R5. 24

2 Tickets

3 Office

4

TOTAL

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech Insp \$

☐ A/Round \$

Report Format:

Lump Sum / L.B. / L.C.

150
150

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Wednesday, 27 February 2019 11:01 AM
To: Hui Ting; 'assignments'
Cc: Corene
Subject: RE: PRS - YOUR REF: AJ.tk.HAN (GX4716H) / OUR REF: SNM19D200807C02/8

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Hui Ting,

We refer to your email of 27.02.19.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Hui Ting [mailto:huiting@crossbordersllc.com]
Sent: Wednesday, 27 February, 2019 9:29 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: Corene <corene@crossbordersllc.com>
Subject: RE: PRS - YOUR REF: AJ.tk.HAN (GX4716H) / OUR REF: SNM19D200807C02/8

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Elaine

1. We refer to your email dated 27 February 2019.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-
 - a) Dennis Yap PAL'S Appraiser Pte Ltd
 - b) Yap Teck Lee LCW Appraiser Pte Ltd
 - c) Yap Teck Chye MC-Coy Appraiser Pte Ltd
 - d) Dixon Yeo Treasure Appraiser Pte Ltd
 - e) Marc Ananda United Appraisal and Management Pte Ltd
 - f) Andrew How Prominent Appraiser Services
 - g) Alan Cheong K.H. C L Appraiser Pte Ltd
 - h) T.T. Rajan ST Appraisal Services
 - i) Sebastian Lim Constanct Appraiser Services
 - j) Aeon Auto Consultants LLP
4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Wednesday, 27 February 2019 9:25 AM
To: Hui Ting <huiting@crossbordersllc.com>
Subject: PRS - YOUR REF: AJ.tk.HAN (GX4716H) / OUR REF: SNM19D200807C02/8

WITHOUT PREJUDICE

Dear Huiting,

We refer to your fax of 22.02.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Nivitha (LKK Auto)

From: Hui Ting <huiting@crossbordersllc.com>
Sent: Wednesday, 27 February 2019 11:07 AM
To: Elaine Cheong; 'assignments'
Cc: Corene
Subject: RE: PRS - YOUR REF: AJ.tk.HAN (GX4716H) / OUR REF: SNM19D200807C02/8

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Elaine

1. We refer to your email dated 27 February 2019.
2. Please be informed that the said vehicle can be inspected at:

Venue:	Han Car Repairs
Address:	Blk 1001 Bukit Merah Lane 3 #01-49 Alexandra Village Ind'l Est Singapore 159718
Contact:	Susan Chin @ 6271 0275 / 6274 1311
3. Please liaise with the above workshop directly.

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Wednesday, 27 February 2019 11:01 AM
To: Hui Ting <huiting@crossbordersllc.com>; 'assignments' <assignments@lkkauto.com>
Cc: Corene <corene@crossbordersllc.com>
Subject: RE: PRS - YOUR REF: AJ.tk.HAN (GX4716H) / OUR REF: SNM19D200807C02/8

WITHOUT PREJUDICE
SAVE AS TO COSTS

> Back to OneMotoring

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GX4716H		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	HIACE DIESEL		
Chassis No. :	LH1726119891		
Propellant :	Diesel		
Engine No. :	5L5455315		
Engine Capacity :	2986 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3030 kg		
Unladen Weight :	1500 kg		
Year Of Manufacture :	2004		
Original Registration Date :	28 May 2004		
Lifespan Expiry Date :	27 May 2024		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$26,082.00		
COE Expiry Date :	30 Apr 2019		
Road Tax Expiry Date :	30 Apr 2019		
Inspection Due Date :	27 May 2019		
Intended Transfer Date :	22 Mar 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$46.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK Print

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9820R
Vehicle Details	
Vehicle No.:	GX4716H
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DIESEL
Primary Colour:	Green
Manufacturing Year:	2004
Engine No.:	5L5455315
Chassis No.:	LH1726119891
Maximum Power Output:	-
Open Market Value:	\$22,301.00
Original Registration Date:	28 May 2004
First Registration Date:	28 May 2004
Transfer Count:	2
Actual ARF Paid:	\$1,116.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$26,082.00
COE Rebate Amount:	\$550.00
Total Rebate Amount:	\$550.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 22 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/02/2019 15:44
Date Of Accident	14/02/2019 08:50 ✓
Exact Location Of Accident	UPP CHANGI RD NORTH TWRDS TANAH MERAH BESAR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX4716H ✓
Insured/Policyholder	
Name Of Registered Owner	MR PLUMBER SINGAPORE PTE. LTD.
Co Reg No	201719820R
Email Address	LEON@MRPLUMBER.SG
Mobile Phone No	(LOCAL) +65-92227888
Alternative Phone No	Office-92227888

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE DIESEL
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5096646271
Cover Note Number	

Driver

Name of Driver	AHMED MD MAHFUZ
Passport No/FIN	G6607323N
Date Of Birth	01/02/1983
Occupation	OUTDOOR
Date Of Driving Pass	17/06/2013
Driving Experience	5 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92227888

Fax Number

Contact Number

EMail Address

Address

Postcode

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

OTHERS-92227888

LEON@MRPLUMBER.SG

-

NO

PAID DRIVER

-

-

-

-

-

-

General Information of the Accident

Type Of Accident

Weather Conditions

Road Surface

COLLISION - HEAD TO REAR

CLEAR

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NO

2

NO

NO

YES

NO

2

Name: : COLLEAGUE

Gender: : Male

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

NO

NO

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

YES

NO

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

YN2108R ✓

COMMERCIAL VEHICLE

MANI SHANMUGAM

O 34167737

94480819

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

Vehicle No: _____
DOA: _____

IMPORTANT NOTICE

- 1) Please report correctly the details of the accident to speed up the claims process.
- 2) This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3) Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue & acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the Police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA):** I understand, acknowledge, agree and consent that:-
 - a) My insurer, my workshop & the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose & transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle (s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore & any relevant government agency/authority (such as the police), for the purpose(s) of:-
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims & any necessary investigations relating to the claims;
 - (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iii) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (iv) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
 - b) All insurer(s) involved in this accident and the Insurers' law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - c) My Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/ law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


PLEASE NOTE YOUR INSURER MAY HAVE A 14 DAY-TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY.

Long
Policyholder's Signature
Date & Time

[Signature]
Driver's Signature (Date & Time)
(If driver is not the policyholder)

[Signature]
Witnessed by Reporting Center
Personnel

Sketch Plan



Accident Sketch Plan

Describe Circumstances of the Accident

I was travelling along Upper Changi Road N. (towards Tanah Merah Besar Road) on 14/02/19 at about 8.5 am.


Traffic was slow and heavy. The vehicles in front stopped so I followed. Few seconds later, Vehicle B came from behind and hit onto me.


Declaration

I/We declare the foregoing particulars are true in every aspect.


Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not policyholder)
Date & Time


Witnessed by Reporting Centre
Personnel

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS3/CTI19003714/R1cd3e2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWER		Date: 08-05-2019		
SINGAPORE 079909		Code: CTI ✓		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YN 2108R ✓	Veh. Inspected	GX 4716H ✓	
Policy No.	DMCVSN15142518033 ✓	Coverage (\$)	0.00	
Claim No.	SNM19D200807C02 ✓	Excess (\$)	0.00	
Assign From	ELAINE CHEONG ✓	Assign Date	27/02/2019 ✓	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE ✓	c.c	2986 ✓	
Engine No.	HIDDEN	Year of Reg.	2004 ✓	
Chassis No.	LH1726119891 ✓	Colour	WHITE ✓	
Odometer	507957 KM ✓	Steering	IN ORDER ✓	
Brakes	IN ORDER ✓	Modification	NIL ✓	
General	FAIR ✓			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14C ✓	ROVELO ✓	6 mm ✓	
L/H Front Tyre	185 R14C ✓	ROVELO ✓	6 mm ✓	
R/H Rear Tyre	185 R14C ✓	ROVELO ✓	6 mm ✓	
L/H Rear Tyre	185 R14C ✓	ROVELO ✓	6 mm ✓	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	14/02/2019 ✓	Inspect Date / Time	27/02/2019 (04:41 PM) ✓	
Survey held at	RAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 ✓				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6-Working Days ✓		

Report Ref No. CS3/CTI19003714/R1cd3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2019		27 Feb 2019 10:54 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

- , Co. Reg. No.: -

Main Claimant:

MR PLUMBER SINGAPORE PTE. LTD., Co. Reg. No.: 201719820R

Vehicle Reg. No.:

GX4716H

Claim Type:

TP / SNM19D200807C02

Vehicle Reg. No. (Insured):

YN2108R

Repairer:

Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

Claimant's Insurer:

NTUC Income Insurance Co-operative Ltd (HQ) - Tel:

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/03/2019]

Date of Loss:

14/02/2019 08:00 - :59
[176 Months and 17 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

DMCVSN15142518033

Policy No. (Claimant):

5096646271

Excess:

S\$0.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.




































ALL ASSOCIATED TASKS














































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GX4716H (SNM19D200807C02)
 [YN2108R]
 TP
 MR PLUMBER SINGAPORE PTE. LTD.
 Feb 14 2019 8:00AM
 [-]
 Han Car Repairs

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
2	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
3	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
4	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
5	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
6	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
7	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
8	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
9	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
10	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
11	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
12	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
13	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
14	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
15	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
16	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
17	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
18	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
19	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
20	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
21	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
22	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
23	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
24	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
25	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
26	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
27	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
28	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
29	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
30	08/05/19 10:44	General View		Load JPG	<input checked="" type="checkbox"/>					
31	08/05/19 10:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
32	08/05/19 10:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
33	08/05/19 10:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
34	08/05/19 10:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
35	08/05/19 10:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
36	08/05/19 10:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
37	08/05/19 10:44	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/05/19 10:44	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	08/05/19 10:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	14/02/19 16:07	Accident Statement		Load HTM	
2	15/02/19 10:48	Addendum Sheet		Load JPG	<input checked="" type="checkbox"/>
3	15/02/19 10:48	Accident Statement Addm. #1		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	14/02/19 15:55	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	14/02/19 16:01	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	14/02/19 16:01	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119003714/R1CD3E2

Date: 31/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN15142518033

Claimant Vehicle
No : GX4716HInsured Vehicle
No : YN2108R

Date of Loss: 14/02/2019

Nature of Claim: TP

Claim
No: SNM19D200807C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GX4716H

Make & Model: TOYOTA HIACE, 2.0 (M)

Reg. Date: 28/05/2004 (Man. Year: 2004)

Colour: White

Engine Capacity: 2986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 5L5455315

Chassis No: LH1726119891

Odometer: 507957 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14C

Rear Tyre Size: 185 R14C

Front Left Side: Rovelo 6 mm

Rear Left Side: Rovelo 6 mm

Front Right Side: Rovelo 6 mm

Rear Right Side: Rovelo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/02/2019

Date Inspected: 27/02/2019 Inspected At:

Han Car Repairs (HQ)
BLK 1001 BUKIT MERAH LANE 3 #01-49
ALEXANDRA VILLAGE
Singapore 159718

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 May 2019)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX4716H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >