

ASSIGNMENT (Office)

REF: CS/FCI19003762/71sd3<sup>n2</sup>

From Person: **cus**

**Paulich**  
**Henry kao**

ASSIGNMENT (Office)

of **FCI**

Date/Time: **27/2/19 @ 3:11pm**

Estimated Cost

Bill to

OD (TP) WS/TP REST/OD REST/EVA/INV/MT/CS

To Inspect Vehicle No

**SIC 1905A**

Incarid

**SHA 8790A**

at Workshop no

**Hitachi Capital**

Tel

**68336282**

of

**& Fourth Lok Yong Rd**

Policy No

Claim No

**D1900171MFstH**

Sum Insured

Excess

Make of Veh  
(Client's Record)

D.O.A

**15/2/2019**

CA / REV / REP. / REV 24 HRS <sup>1up</sup>

H.O.B. Endorsement

Date/Time

**28/2/19 @ 9:16am**

Person Contacted

**Jiong How**

Vehicle

**IN/OUT**

Date/Time

Action/Instruction (✓) Estimate

**SIC 1905A-X**

**SHA 8790A-CS/FCI18006206/119bn2**

**DOA: 3/3/18**

Tajm

REF: FCI

Date: 28/02/2019

Sub No: SLC1905A at Post: 2016 May

Type: Motor / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Toyota Altis No: 1598

Colour: Grey A/C: Insured / Std / Nil / NA

Cap/Sealing: 19754. IE/Allo: Insured / Std / Nil / NA

Eng/No:

C/No: MROS3RE H104.548502

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modt: Nil / Std / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front: R/Bal: 6 mm

Rear: R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. D.O.I: 28/2/19 c320p

Survey held at: Hitachi Capital

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt w/s

The UIC / Chassis/frame / Body Structure affected due to collision.

(1) W/S / T / R / S / O / D / R / S / L / V / A / H / V / M / Y  
 To be used Vehicle No: SLC1905A  
 at Work: Hitachi Capital  
 at: 8 Fourth Lok Yang Road  
 In Use:   
 Excess:   
 (Client's Record)  
 Make of Veh:  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  

N/S	O/S

 Bal. or Market Value:  
 IDAC Accident Rpt. Consistent?: Yes or No  
 GLA / FR Seen. Consistent?: Yes or No  
 Est. Repair: days: Res: Yes or No  
 Turn Cost: %: 3 Val: Yes or No  
 GA / REV / REP. / 24 HRS <sup>lup</sup>  
 Date: Person Contacted: Vehicle: IN / OUT

Date/Time: 3/6/19 Action/Instruction: 94/77.30, 5 days email to You.  
 (\$ 3,988.20 Red - 49%)

RECEIVED 13 JUN 2019

  
 12/6/2019

Date/Time, File Path by: 13/06/19  
 Typist:  Final Report  
 Days Of Repair: 5  
 Resurvey No. of Trip: 1  
 Survey Fee: 160  
 Transportation: 50  
 Add Fee:  Site trip (\$)  
 Interview (\$)  
 Term fee (\$)  
 Weekend (\$)  
 Report Format: Lump Sum (L.R.) (\$ 4,177.30 e/r)  

160
50
50
56
316



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001171MFSH

Date: 04 March 2019

Our Ref: CS/FCI19003762/T1sd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 1905A**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/02/2019 at the premises of M/s Hitachi Capital Asia Pacific Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 8,165.50</u>
Revised Estimate Amount	: <u>S\$ 4,473.25</u>
"Check" Items Amount	: <u>S\$ 621.75</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

**Description of Damage:**

The vehicle sustained damages at the front n/s portion.



**Comments/ Present Status:**

Damages Consistent.  
Repair days: 4-5 Days

Yours faithfully,  
Mohamad Taufikh  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	18-02-2019	<b>Our Ref No.</b> D19001171MFSH
<b>Accident Date</b>	15-02-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA8790A	<b>Third Party Vehicle.</b> SLC1905A
<b>Survey Location</b>	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG ROAD	
<b>Contact Person.</b>	NG JIONG HOW	
<b>Contact No.</b>	68336282/ 0	<b>Fax No.</b> 68966591
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	HENRY KAO	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** JiongHow, Ng <jionghow.ng@hcspl.com.sg>  
**Sent:** Tuesday, 11 June 2019 3:58 PM  
**To:** Taufikh (LKKAuto); Vonn, LM Siow  
**Cc:** Jamilah, Binte MohdKassim; Shirley Hiew (LKK Auto)  
**Subject:** RE: SLC1905A DOA: 15/02/2019 FINALIZATION

Hi Taufikh,

P/P COR confirmed @ \$4177.30

5 days repair days

Regards

Ng Jiong How  
Motor Claims Advisor  
Auto Servicing  
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.  
**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**  
8 Fourth Lok Yang Road Singapore 629705  
t: 6833 6282  
e: [jionghow.ng@hcspl.com.sg](mailto:jionghow.ng@hcspl.com.sg)  
w: [www.hitachi-capital.com.sg](http://www.hitachi-capital.com.sg)

**HITACHI**  
Inspire the Next

---

**DISCLAIMER:**

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.  
This email is intended solely for the attention and use of the name addressee(s).  
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.  
If you have received this email in error, please notify the sender immediately by email and delete it from your system.

---

**From:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>  
**Sent:** Monday, June 3, 2019 12:11 PM  
**To:** Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>  
**Cc:** Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Subject:** RE: SLC1905A DOA: 15/02/2019 FINALIZATION

Hi Vonn,

Refer attached. Item 11 should be air cleaner resonator not air cleaner assy and the price I revised to \$280.40.

COR \$4177.30 , 5 days.

Regards  
Taufikh  
Lkk Auto

## Shirley Hiew (LKK Auto)

---

**From:** Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>  
**Sent:** Friday, 31 May 2019 11:21 AM  
**To:** taufikh@lkkauto.com; SUR; CS A Team  
**Cc:** Jamilah, Binte MohdKassim; JiongHow, Ng  
**Subject:** SLC1905A DOA: 15/02/2019 FINALIZATION  
**Attachments:** CALCULATION.pdf

Dear Taufikh,

Sending on behalf of Jiong How.

We refer to the subject above and the attachment is for your reference.

Kindly confirm the COR for us at PP, \$4,717.00 before GST, 5 days.

Thanks & Regards

Vonn Siow  
Motor Claims Advisor  
Auto Servicing  
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.  
**Jun Taiyo Service Centre (Automobile Leasing & Workshop)**  
8 Fourth Lok Yang Road Singapore 629705  
DID: 6833 6274 Mobile: 96435107  
e: [vonnlm.siow@hcspl.com.sg](mailto:vonnlm.siow@hcspl.com.sg)  
w: [www.hitachi-capital.com.sg](http://www.hitachi-capital.com.sg)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 4 March 2019 9:44 AM  
**To:** 'Henry Kao Cai Jie'; 'CWS Motor Claims'  
**Cc:** assignments; SUR; Admin-D (LKKAuto)  
**Subject:** RE: SURVEY ASSESSMENT - D19001171MFSH/1  
**Attachments:** SLC 1905A - Preli Advise.pdf

Dear Henry,

Enclosed preliminary revised of vehicle SLC 1905A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Thursday, 28 February 2019 9:24 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19001171MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Wednesday, 27 February 2019 3:11 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19001171MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**Hitachi Capital Asia Pacific Pte. Ltd.**  
**Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705  
 Tel : 64663022 Fax : 68966591  
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

**VEHICLE ESTIMATE**

FCIL

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :  
 ACCIDENT DATE : 15/02/2019@0845HRS  
 VRN : SLC1905A  
 MODEL : Toyota Altis  
 TP VRN : SHA8790A

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<b><u>PARTS REPLACEMENT</u></b>				
<b><u>1. Body Repair</u></b>				
1 Front Bumper	1	\$ 458.00	\$ 458.00	de
2 Front Bumper Clips	10	\$ 5.50	\$ 55.00	re
3 Front Bumper Re-inforcement	1	\$ 382.00	\$ 382.00	X ny
4 Front Bumper Re-inforcement Sponge	1	\$ 79.00	\$ 79.00	de
5 Fog Lamp LH	1	\$ 325.00	\$ 325.00	X un
6 Fog Lamp Cover LH	1	\$ 91.00	\$ 91.00	cut
7 Front Bumper Outer Bracket LH/RH	2	\$ 81.00	\$ 162.00	LH-de, RH-X un
8 Front Bumper Lower Grille	1	\$ 155.00	\$ 155.00	cut
9 Headlamp LH	1	\$ 850.00	\$ 850.00	are - too high
10 Headlamp Chrome Cover LH	1	\$ 181.00	\$ 181.00	cut - check
△ 11 Air Cleaner <i>resale photo</i>	1	\$ 1,000.00	\$ 1,000.00	de - 230.42 price
12 Air Cleaner Hose	1	\$ 160.00	\$ 160.00	de
13 Front Fender LH	1	\$ 781.00	\$ 781.00	bt
14 Front Fender Shield LH	1	\$ 200.00	\$ 200.00	de
15 Front Fender Shield Clips LH	10	\$ 5.50	\$ 55.00	re
16 VVT-I Logo LH	1	\$ 45.00	\$ 45.00	re
17 Bonnet	1	\$ 1,037.00	\$ 1,037.00	Rp
18 Bonnet Hinge LH/RH	2	\$ 75.00	\$ 150.00	X un
19 Bonnet Lock	1	\$ 130.00	\$ 130.00	X ny
20 Front Bumper Undertray	1	\$ 534.00	\$ 534.00	R ny
21 Front Bumper Undertray Clips	10	\$ 5.50	\$ 55.00	R ny
22 Front Support Panel	1	\$ 989.00	\$ 989.00	X un

Discount 25% \$ (1,968.50)

TOTAL \$ 5,905.50

**2. Labor Charges**

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	600	\$ 1,000.00
2 Spray painting on rear portion of affected area	700	\$ 1,000.00
3 Check Wiring, re-align headlamps and ensure proper function	30	\$ 80.00
4 Refill compressor oil, vacuum and refill aircond gas	un 100	\$ 180.00

Sub Total : \$ 2,260.00

Grand Total : \$ 8,165.50  
 Add 7% GST : \$ 571.59

No. of repair days: 7

CUSTOMER SIGNATURE

HITACHI CAPTIAL ASIA PACIFIC PTE LTD  
(MANAGER)

*[Handwritten Signature]*  
4/3/19

Taufik 97495749

-dup  
28/2/19 @ 3:20pm

4-5 days

Resurvey before paint  
sure@lkkauto.com

taufik@lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Hitachi Capital Asia Pacific Pte. Ltd.  
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705  
Tel : 64663022 Fax : 68966591  
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

**VEHICLE ESTIMATE**

FCIL	QUOTE NO	:	
	ACCIDENT DATE	:	15/02/2019@0845HRS
	VRN	:	SLC1905A
ATTN: MOTOR CLAIMS DEPT	MODEL	:	Toyota Altis
	TP VRN	:	SHA8790A

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$.Amt</u>	<u>S\$ Labor</u>
<b><u>PARTS REPLACEMENT</u></b>				
<b><u>1. Body Repair</u></b>				
1 Front Bumper	1	\$ 458.00	\$ 458.00 <i>de</i>	
2 Front Bumper Clips	10	\$ 5.50	\$ 55.00 <i>ne</i>	
3 Front Bumper Re-inforcement	1	\$ 382.00	\$ 382.00 <i>X nn</i>	
4 Front Bumper Re-inforcement Sponge	1	\$ 79.00	\$ 79.00 <i>de</i>	
5 Fog Lamp LH	1	\$ 325.00	\$ 325.00 <i>X one</i>	
6 Fog Lamp Cover LH	1	\$ 91.00	\$ 91.00 <i>cut</i>	
7 Front Bumper Outer Bracket LH/RH	2	\$ 81.00	\$ 162.00 <i>LH-dev, RH-AN</i>	
8 Front Bumper Lower Grille	1	\$ 155.00	\$ 155.00 <i>cut</i>	
9 Headlamp LH	1	\$ 850.00	\$ 850.00 <i>one</i>	
10 Headlamp Chrome Cover LH	1	\$ 181.00	\$ 181.00 <i>cut</i>	
11 Air Cleaner <i>Resonator</i>	1	\$ 1,000.00	\$ *1,000.00 <i>de - desk price</i>	280.40
12 Air Cleaner Hose	1	\$ 160.00	\$ 160.00 <i>de</i>	
13 Front Fender LH	1	\$ 781.00	\$ 781.00 <i>cut</i>	
14 Front Fender Shield LH	1	\$ 200.00	\$ 200.00 <i>de</i>	
15 Front Fender Shield Clips LH	10	\$ 5.50	\$ 55.00 <i>ne</i>	
16 VVT-I Logo LH	1	\$ 45.00	\$ 45.00 <i>ne</i>	
17 Bonnet	1	\$ 1,037.00	\$ 1,037.00 <i>Ry</i>	
18 Bonnet Hinge LH/RH	2	\$ 75.00	\$ 150.00 <i>X nn</i>	
19 Bonnet Lock	1	\$ 130.00	\$ 130.00 <i>X nn</i>	
20 Front Bumper Undertray	1	\$ 534.00	\$ 534.00 <i>X nn</i>	
21 Front Bumper Undertray Clips	10	\$ 5.50	\$ 55.00 <i>X nn</i>	
22 Front Support Panel	1	\$ 989.00	\$ 989.00 <i>X Rx</i>	
Discount 25%			\$ (1,968.50)	<i>3796.40</i> <i>25% = 2847.50</i>
			<b>TOTAL</b>	\$ 5,905.50

*Resonator  
5/3/19*

**2. Labor Charges**

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	600	\$ 1,000.00
2 Spray painting on rear portion of affected area	700	\$ 1,000.00
3 Check Wiring, re-align headlamps and ensure proper function	30	\$ 80.00
4 Refill compressor oil, vacuum and refill aircond gas	700	\$ 180.00
		<i>1530</i>
Sub Total		\$ 2,260.00
Grand Total		\$ 8,165.50
Add 7% GST		\$ 571.59

No. of repair days: 7

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
(MANAGER)

$$\begin{array}{r}
 P = 4,516 - W \\
 \underline{\quad 25\%} \\
 3,387 - W \\
 + L = 1,330 - W \\
 \hline
 T = 4,717 - W
 \end{array}$$

Taufik 97495749  
 - SUP  
 28/2/19 @ 320 pm  
 4-5 days  
 Resurvey before paint  
 sure @ Mhauto.com  
 taufik @ Mhauto.com

\* 3796.40  
 25% 2847.30  
 Labor - 1330  
\$4177.30 #  
 5 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003762/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-06-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8790A	Veh. Inspected	SLC 1905A
Policy No.		Coverage (\$)	0.00
Claim No.	D19001171MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	27/02/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104548502	Colour	GREY
Odometer	197594	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	HANKOOK	6 mm
L/H Front Tyre	205/55 R16	HANKOOK	6 mm
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/02/2019	Inspection Date	28/02/2019
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1905A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DEFORMED	458.00	458.00
10	FRONT BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	FRONT BUMPER RE-INFORCEMENT	NOT NECESSARY	382.00	-
1	FRONT BUMPER RE-INFORCEMENT SPONGE	DEFORMED	79.00	79.00
1	FOG LAMP LH	CRACKED	325.00	325.00
1	FOG LAMP COVER LH	CUT	91.00	91.00
2	FRONT BUMPER OUTER BRACKET LH/RH @\$81.00	N/S DEFORMED / O/S NOT NECESSARY	162.00	81.00
1	FRONT BUMPER LOWER GRILLE	CUT	155.00	155.00
1	HEADLAMP LH	CRACKED	850.00	850.00
1	HEADLAMP CHROME COVER LH	CUT	181.00	181.00
1	AIR CLEANER RESONATOR	DEFORMED	1,000.00	280.40
1	AIR CLEANER HOSE	DEFORMED	160.00	160.00
1	FRONT FENDER LH	BENT	781.00	781.00
1	FRONT FENDER SHIELD LH	DEFORMED	200.00	200.00
10	FRONT FENDER SHIELD CLIPS LH @\$5.50	NECESSARY	55.00	55.00
1	VVT-I LOGO LH	NECESSARY	45.00	45.00
1	BONNET	TO REPAIR SEE LABOUR	1,037.00	-
2	BONNET HINGE LH/RH @\$75.00	NOT NECESSARY	150.00	-
1	BONNET LOCK	NOT NECESSARY	130.00	-
1	FRONT BUMPER UNDERTRAY	NOT NECESSARY	534.00	-
10	FRONT BUMPER UNDERTRAY CLIPS @\$5.50	NOT NECESSARY	55.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	989.00	-
	LESS 25% DISCOUNT		-1,968.50	-949.10
			5,905.50	2,847.30
	<b>LABOUR</b>			
	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF AFFECTED AREA.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT SUPPORT PANEL		1,000.00	600.00

Report Ref No. CS/FCI19003762/T1sd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.		1,000.00	700.00
	CHECK WIRING,RE-ALIGN HEADLAMPS AND ENSURE PROPER FUNCTION.		80.00	30.00
	REFILL COMPRESSOR OIL,VACUUM AND REFILL AIRCOND GAS.	NOT NECESSARY	180.00	-
			2,260.00	1,330.00
	<b>GRAND TOTAL</b>		<b>8,165.50</b>	<b>4,177.30</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,177.30</b>

Report Ref No. CS/FCI19003762/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.