

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9440M**AAD1902-224***Not Authorized
Proposed 1/1 Samp @ 3800*

Vehicle No.:	SHD 9440M
Chassis No.:	KL1LA69RJB076775
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	25.2.2019
Third Party Insurer :	AIG
Date of Registration :	28/2/2012

	PART		LIST	
1	1	Rear Bumper	\$	<i>B₁</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$	<i>B₁</i> 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$	<i>CM</i> 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$	<i>SM</i> 68.76 X
6	1	Rear Bumper Reflectors RH	\$	<i>B₂</i> 119.74 ✓
7	1	Rear Bumper Reflectors LH	\$	<i>SM</i> 119.74 X
8	1	Rear Bumper Tow Hook Cover	\$	<i>SM</i> 93.00 ✓
9	1	Rear End Panel Outer	\$	<i>B₁</i> 623.76 ✓
10	1	Rear End Panel Inner Trim	\$	<i>D₁</i> 263.84 ✓
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 2,911.70 X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>SM</i> 1,991.70 X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>SM</i> 2,011.60 X
14	1	Bootlid	\$	<i>B₁</i> 973.00 ✓
15	1	Bootlid inner trim board	\$	<i>SM</i> 400.00 X
16	1	Bootlid Weatherstrip	\$	<i>SM</i> 344.28 <i>501SM</i>
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56 X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>SM</i> 120.62 ✓
19	1	Bootlid Logo	\$	<i>SM</i> 138.84 ✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>SM</i> 119.84 ✓
21	1	Bootlid Reflector Centre	\$	<i>SM</i> 217.97 X
22	1	Bootlid Reflector RH	\$	<i>SM</i> 128.40 X
23	1	Bootlid Reflector LH	\$	<i>SM</i> 128.40 X
24	1	Rear Tail Lamp RH	\$	<i>CM</i> 479.30 ✓
25	1	Rear Tail Lamp LH	\$	<i>SM</i> 479.30 X
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 X
27	1	Rear Fender LH	\$	<i>R</i> 1,145.00 X
28	1	Rear Fender Inner Trim LH	\$	<i>SM</i> 418.44 X
29	1	Rear Windscreen Inner Sponge Seal	\$	<i>SM</i> 80.00 X

Trans-cab Auto Services Pte Ltd

AAD1902-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9440M

TOTAL	\$	16,724.49
10%	\$	1,672.45
	\$	15,052.04

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i>	40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	<i>Radshan</i>	300.00	✓
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	44.00	✓
4	1Set	Rear Fender Inner Trim Clip <i>RH</i>	\$	<i>nn</i>	30.00	✓
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i>	30.00	X
6	1	Rear Exhaust Mounting	\$	<i>nn</i>	300.00	X
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	X

TOTAL	\$	924.00
--------------	-----------	---------------

TOTAL PARTS	\$	15,976.04
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>800</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>800</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>60</i>
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	<i>nn X</i>
To transfer of boot fittings and conduct water seepage test.	\$	170.00	<i>60</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>100</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>nn X</i>

Trans-cab Auto Services Pte Ltd

AAD1902-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9440M

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair. \$ *na* 170.00 X

To transfer of Rear Bumper fittings and conduct water seepage test. \$ *na* 170.00 X

\$ 10,450.00

TOTAL \$ 26,426.04

Repair Days (LUMP SUM)

15 **DAYS**

6 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: