



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2007683  
INV Date 16/11/2020  
Reference CC6/EQI19003769/Ega3q2  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. GW 611H  
Insured Veh. SJS 3558U  
Claim No. DM19HO00617  
Policy No. DMCPHQ18-000122  
Accident Date 25/02/2019  
Inspection Date 28/02/2019

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI19003769/Ega3q2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 16-11-2020



Code : EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJS 3558U	<b>Veh. Inspected</b>	GW 611H
<b>Policy No.</b>	DMCPHQ18-000122	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DM19HO00617	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	27/02/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN P/UP	<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2003
<b>Chassis No.</b>	JN1AHGD22Z0030808	<b>Colour</b>	BLUE
<b>Odometer</b>	509153	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	185 R14C	TRIANGLE	6 mm
<b>L/H Front Tyre</b>	185 R14C	TRIANGLE	6 mm
<b>R/H Rear Tyre</b>	185 R14C	TRIANGLE	6 mm
<b>L/H Rear Tyre</b>	185 R14C	TRIANGLE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	25/02/2019	<b>Inspection Date</b>	28/02/2019
<b>Survey held at</b>	14 DEFU LANE 10 #01-398		
<b>Repairer</b>	TRIPLE H AUTOMOTIVE SERVICE		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 611H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RIGHT HAND SIDE DOOR	DENTED	380.00	380.00
2	DOOR HINGES @\$56.00	NOT NECESSARY	112.00	-
1	FRONT BUMPER	DENTED	320.00	320.00
1	RIGHT HAND SIDE FRONT MUDGUARD	DENTED	280.00	280.00
1	MUDGUARD MUDFLAP	CUT	120.00	120.00
1	RIGHT FRONT LAMP (HEADLAMP)	BROKEN	320.00	320.00
1	FRONT LOWER ARM	NOT NECESSARY	160.00	-
1	FRONT UPPER ARM	NOT NECESSARY	160.00	-
1	FRONT RIGHT TYRE RIM	BENT	120.00	120.00
1	FRONT BUMPER BRACKET (RIGHT)	DENTED	150.00	150.00
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	280.00	-
	LESS 10% DISCOUNT		-	-169.00
			2,402.00	1,521.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	DOOR COMPANY STICKER (SN)	NECESSARY	60.00	60.00
1	WHEEL ALIGNMENT (SN)	NECESSARY	120.00	60.00
1	AIR-CON CONDENSER (SN) (ADDITIONAL)	DENTED	280.00	280.00
1	AIR-CON GAS (SN) (ADDITIONAL)	NECESSARY	50.00	50.00
			510.00	450.00
	<b><u>LABOUR</u></b>			
	LABOUR FOR ABOVE & PANEL RE-ALIGNMENT.INCLUSIVE OF THE REPAIR OF SUPPORT PANEL .		560.00	500.00
	SPRAY PAINTING FOR ACCIDENT AREA.		480.00	480.00
	CONDENSER LABOUR. (ADDITIONAL)		180.00	50.00
			1,220.00	1,030.00
	<b>GRAND TOTAL</b>		<b>4,132.00</b>	<b>3,001.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,400.00</b>

Report Ref No. CC6/EQ119003769/Ega3q2



Report Ref No. CC6/EQ119003769/Ega3q2

A black ink signature of Chen Tsue Yee, consisting of several fluid, overlapping strokes.

**CHEN TSUE YEE**

**Automotive Assessor**

A black ink signature of Ho Leong Chuan, featuring a stylized 'H' and 'L' with a small '2' below.

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GW 611H

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GW 611H

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GW 611H

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

