



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM19003774/Eps3q2 Date: 10/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4140Y	Veh. Inspected	YP 6263M	
Policy No.	GA422076	Coverage (\$)	0.00	
Claim No.	S9M01FFS	Excess (\$)	0.00	
Assign From		Assign Date	28/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HINO FD7JLMA	c.c	6403	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	FD7JLM11583	Colour	WHITE	
Odometer	56915 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	DUNLOP	6 mm	
L/H Front Tyre	295/80 R22.5	DUNLOP	6 mm	
R/H Rear Tyre	295/80 R22.5	DUNLOP	6 mm	
L/H Rear Tyre	295/80 R22.5	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/01/2019	Inspection Date	21/03/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	