...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	Submitted	Ins Auth'ed	Status		
Main	22 Feb 2019		28 Feb 2019 11:59 Edit Adj Rpt	S\$120,00 Edit Estim		120,000.00 Tiew Rpt		Pending for S Report Cancel Case		
	Main	R	eference	Cla	im Details		Document	s	Show All	
CLAIM SU	BFOLDER DI	TAILS				[Created I	by insurer]			
Insured:	FU CHEN	LOK, ID: S8708	241E, Tel: +6598	230937, Em	ail: NOEMAI	L				
Vehicle Re	SKE418	SKE418Y			ate of Loss		04:00 - :59 ns and 15 Days F	From LTA Reg Date (Man Yr)]		
Claim Type	OD / SN	M19D200887C	01		olicy/Cover lote No.:	DMPCSN18	17761800 (Comp	omprehensive)		
				E	xcess:	S\$6,000.00				
Repairer:	Ngee Sen	g Auto Works (H	IQ) Block 3022A, L	lbi Road 1, #0	1-50, 4087	16 Ubi - Tel: 6	841 2276			
Handling Insurer:	China Tai	ping Insurance	(Singapore) Pte.	Ltd. (HQ) - Te	el: 6389 61	11 [Handled	by Elaine Chec	ong]		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 6	256-3561 [Handled by	ADRIAN LIN	G] [Final R]	pt due 11/03	/2019]	
Driver/Cus dian:	FU CHEN I	OK (31 / Male) ,	NRIC: S8708241E	Tel: +659	8230937 En	nail: NOEMAIL				
ASSOCIA	TED MAIL RE	CEIVED					Vi	ew All Com	pose Case Mail	
CHINA_	TAIPING (20/0	3/2019): Alert -	Adj Mandate App	roved (S\$135	800.00) -	SKE418Y - C	laim Handler: E	laine Che		
ALL ASS	CIATED TAS	sks⊟				View All S	Search Tasks	Create New Task	Complete	
Due Dat	e Priority	Type Task	Group Subje	ct Handle	Assig	ned By	Completed On	Created	On Done	

Claim Documents

*SKE418Y (SNM19D200887C01) OD Feb 18 2019 4:00AM [FU CHEN LOK] Ngee Seng Auto Works

Ass	essment Reports		1 per page	$\overline{\mathbf{v}}$
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumb	nail Prin
1	04/03/19 15:23	Adjuster Immediate Advice	1 Load H	TM
Pho	otos/Images		3 per page	$\overline{\vee}$
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		nail Prin
1	19/06/19 09:21	General View	1 Load J	PG 🗹
2	19/06/19 09:21	General View	1 Load J	PG 🗸
3	19/06/19 09:21	General View	1 Load J	PG 🔽
4	19/06/19 09:21	General View	1 Load J	PG 🗸
5	19/06/19 09:21	General View	1 Load J	PG 🗸
6	19/06/19 09:21	General View	1 Load J	PG 🔽
7	19/06/19 09:21	General View	1 Load J	PG 🗸
8	19/06/19 09:21	General View	■ Load J	PG 🔽
9	19/06/19 09:21	General View	■ Load J	PG 🗸
10	19/06/19 09:21	General View	■ Load 3	PG 🔽
11	19/06/19 09:21	General View	■ Load J	PG 🗸
12	19/06/19 09:21	General View	■ Load 3	PG 🗸
13	19/06/19 09:21	General View	1 Load J	PG 🗹
14	19/06/19 09:21	General View	1 Load J	PG 🗸
15	19/06/19 09:21	General View	1 Load J	-
16	19/06/19 09:21	General View	■ Load 3	PG 🗸
17	19/06/19 09:21	General View	1 Load 3	PG 🗸
18	19/06/19 09:21	General View	1 Load 3	
19	19/06/19 09:21	General View	1 Load J	PG 🗸
20	19/06/19 09:21	General View	1 Load 3	PG 🔽
21	19/06/19 09:21	General View	1 Load J	PG 🗸
22	19/06/19 09:21	General View	⑥ Load J	PG 🛂
23	19/06/19 09:21	General View	■ Load J	PG 🗹
24	19/06/19 09:21	General View	■ Load 3	PG 🗸
25	19/06/19 09:21	General View	■ Load J	PG 🔽
26	19/06/19 09:21	General View	1 Load J	PG 🗸
27	19/06/19 09:21	General View	■ Load J	
28	19/06/19 09:21	General View	1 Load J	
29	19/06/19 09:21	General View	1 Load J	PG 🗸
30	19/06/19 09:21	General View	1 Load J	
31	19/06/19 09:21	General View	€ Load J	
32	19/06/19 09:21	General View	1 Load 3	
33	19/06/19 09:21	General View	1 Load J	PG 🗸
34	19/06/19 09:21	General View	1 Load 3	-
35	19/06/19 09:21	General View	■ Load J	

Ass	essment Reports		1 per page	-
No 36	Finalized On 19/06/19 09:21	LKK Auto Consultants Pte Ltd (HQ) General View	Thumbna Load JPC	_
37	19/06/19 09:21	General View	1 Load JPC	(<u>T</u>
38	19/06/19 09:21	General View	1 Load JPC	
39	19/06/19 09:21	General View	D Load JPC	-
40	19/06/19 09:21	General View	1 Load JPC	-
41	19/06/19 09:21	General View	① Load JPC	
42	19/06/19 09:21	General View	1 Load JPC	-
43	19/06/19 09:21	General View	D Load JPC	
44	19/06/19 09:21	General View	D Load JPC	-
45	19/06/19 09:21	General View	1 Load JPC	
46	19/06/19 09:21	General View	D Load JPC	
47	-	General View	1 Load JPC	
attas.	19/06/19 09:21	General View	1 Load JPC	
48	19/06/19 09:21	General View	1 Load JPC	
49	19/06/19 09:21			_
50	19/06/19 09:21	General View		-
51	19/06/19 09:21	General View	Load JPC	-
52	19/06/19 09:21	General View	1 Load JPC	1 1 1 1 1 1 1 1 1
53	19/06/19 09:21	General View	1 Load JPC	
54	19/06/19 09:21	General View	1 Load JPC	_
55	19/06/19 09:21	General View	1 Load JPC	
56	19/06/19 09:21	General View	1 Load JPC	
57	19/06/19 09:21	General View	1 Load JPC	-
58	19/06/19 09:21	General View	1 Load JPC	
59	19/06/19 09:21	General View	1 Load JPC	
60	19/06/19 09:21	General View	1 Load JPC	
61	19/06/19 09:21	General View	1 Load JPC	
62	19/06/19 09:21	General View	1 Load JPC	
63	19/06/19 09:21	General View	1 Load JPC	_
64	19/06/19 09:21	General View	1 Load JPC	
65	19/06/19 09:21	General View	1 Load JPC	_
66	19/06/19 09:21	General View	1 Load JPC	1,000
67	19/06/19 09:21	General View	1 Load JPC	-
68	19/06/19 09:21	General View	1 Load JPC	
69	19/06/19 09:21	General View	1 Load JPC	3 V
70	19/06/19 09:21	General View	1 Load JPC	_
71	19/06/19 09:21	General View	1 Load JPC	3 V
72	19/06/19 09:21	General View	1 Load JPC	
73	19/06/19 09:21	General View	1 Load JPC	-
74	19/06/19 09:21	General View	1 Load JPC	
75	19/06/19 09:21	General View	1 Load JPC	3 V
76	19/06/19 09:21	General View	1 Load JPC	3 4
77	19/06/19 09:21	General View	1 Load JPC	3 🗸
78	19/06/19 09:21	General View	1 Load JPC	3 4
79	19/06/19 09:21	General View	1 Load JPC	G 🗸
80	19/06/19 09:21	General View	Load JPC	3 4
81	19/06/19 09:21	General View	1 Load JPC	5 2
82	19/06/19 09:21	General View	1 Load JPC	G 🗸
83	19/06/19 09:21	General View	■ Load JPC	G 🔽
84	19/06/19 09:21	General View	1 Load 3PG	3 •
85	19/06/19 09:21	General View	■ Load JPC	G 🔽

Ass	essment Reports			
No 86	Finalized On 19/06/19 09:21	LKK Auto Consultants Pte Ltd (HQ) General View	Thumbna Load JPC	
		STATE OF THE STATE	1 Load JPC	
87	19/06/19 09:21	General View	Load JPC	
88	19/06/19 09:21	General View		
89	19/06/19 09:21	General View		
90	19/06/19 09:21	Reinspection Photo	Load JPC	
91	19/06/19 09:21	Reinspection Photo	1 Load JPC	-
92	19/06/19 09:21	Reinspection Photo	1 Load JPC	
93	19/06/19 09:21	Reinspection Photo	1 Load JPC	-
94	19/06/19 09:21	Reinspection Photo	6 Load JPC	
95	19/06/19 09:21	Reinspection Photo	1 Load JPC	-
96	19/06/19 09:21	Reinspection Photo	1 Load JPC	-
97	19/06/19 09:21	Reinspection Photo	1 Load JPC	
98	19/06/19 09:21	Reinspection Photo	1 Load JPG	
99	19/06/19 09:21	Reinspection Photo	1 Load JPG	0.10
100	19/06/19 09:21	Reinspection Photo	1 Load JPG	
101	19/06/19 09:21	Reinspection Photo	1 Load JPG	G ☑
102	19/06/19 09:21	Reinspection Photo	1 Load JPG	G ☑
103	19/06/19 09:21	Reinspection Photo	Load JPG	G ✓
104	19/06/19 09:21	Reinspection Photo	■ Load JPC	G ☑
105	19/06/19 09:21	Reinspection Photo	Load JP6	G ☑
106	19/06/19 09:21	Reinspection Photo	■ Load JPG	G 🔽
107	19/06/19 09:21	Reinspection Photo	1 Load JP	G ✓
108	19/06/19 09:21	Reinspection Photo	■ Load JP6	G ✓
109	19/06/19 09:21	Reinspection Photo	1 Load JPG	G ☑
110	19/06/19 09:21	Reinspection Photo	1 Load JPG	G 🗸
111	19/06/19 09:21	Reinspection Photo	■ Load JPC	G 🔽
112	19/06/19 09:21	Reinspection Photo	■ Load JPc	G ☑
113	19/06/19 09:21	Reinspection Photo	Load JP	G 🗸
114	19/06/19 09:21	Reinspection Photo	Load JP	
115		Reinspection Photo	Load JPs	-
116		Reinspection Photo	1 Load JP	
117		Reinspection Photo	■ Load JP	
118	100 St. W. 525 ST	Reinspection Photo	■ Load JPI	
119		Reinspection Photo	1 Load JP	
120		Reinspection Photo	1 Load JP	
			1 Load JP	-
121		Reinspection Photo	1 Load JP	
122		Reinspection Photo	1 Load JP	
123	Paramones article range and each	Reinspection Photo	1 Load JP	
124		Reinspection Photo	1 Load JP	
125		Reinspection Photo		
126		Reinspection Photo	1 Load JP	-
127		Reinspection Photo	1 Load JP	
128	V SOLVENSY PROTESTION AND STREET	Reinspection Photo	1 Load JPI	
129		Reinspection Photo	Load JP	
130	19/06/19 09:22	Reinspection Photo	1 Load JP	
131	19/06/19 09:22	Reinspection Photo	1 Load JP	
132	19/06/19 09:22	Reinspection Photo	1 Load JP	
133	19/06/19 09:22	Reinspection Photo	1 Load JP	
134	19/06/19 09:22	Reinspection Photo	1 Load JP	_
135	19/06/19 09:22	Reinspection Photo	1 Load JP	G ☑

9/06/19 09:22 9/06/19 09:22	LKK Auto Consultants Pte Ltd (HQ) Reinspection Photo	0 0 0 0 0	Load JPG	Print S
9/06/19 09:22 9/06/19 09:22	Reinspection Photo	0 0 0 0 0 0 0	Load JPG	
9/06/19 09:22 9/06/19 09:22	Reinspection Photo	6 6 6 6 6 6	Load JPG	
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo	0 0 0 0 0	Load JPG	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo	0 0 0 0	Load JPG Load JPG Load JPG Load JPG	N N
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo Reinspection Photo Reinspection Photo Reinspection Photo Reinspection Photo Reinspection Photo	0 0 0 0	Load JPG Load JPG Load JPG Load JPG	Z Z
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo Reinspection Photo Reinspection Photo Reinspection Photo Reinspection Photo	0 0 0	Load JPG Load JPG Load JPG	V
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo Reinspection Photo Reinspection Photo Reinspection Photo	0	Load JPG Load JPG	V
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo Reinspection Photo Reinspection Photo	0	Load JPG	///
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo Reinspection Photo	0		4
9/06/19 09:22 9/06/19 09:22 9/06/19 09:22	Reinspection Photo		Load JPG	
9/06/19 09:22 9/06/19 09:22		(3)		~
9/06/19 09:22	Reinspection Photo		Load JPG	~
		0	Load JPG	V
0/06/10 00:33	Reinspection Photo	0	Load JPG	~
9/06/19 09:22	Reinspection Photo	0	Load JPG	¥
9/06/19 09:22	Reinspection Photo	0	Load JPG	V
9/06/19 09:22	Reinspection Photo	0	Load JPG	-
9/06/19 09:22	Reinspection Photo	0	Load JPG	V
9/06/19 09:22	Reinspection Photo	0	Load JPG	V
9/06/19 09:22	Reinspection Photo	0	Load JPG	<u>-</u>
9/06/19 09:22	Reinspection Photo	0	Load JPG	5
9/06/19 09:22	Reinspection Photo	0	Load JPG	5
9/06/19 09:22	Reinspection Photo	0	Load JPG	5
9/06/19 09:22	Reinspection Photo	Ð	Load JPG	5
9/06/19 09:22	Reinspection Photo	0	Load JPG	5
9/06/19 09:22	Reinspection Photo	0	Load JPG	-
9/06/19 09:22	Reinspection Photo	0	Load JPG	5
9/06/19 09:22	Reinspection Photo	0	Load JPG	-
	And and the second of the seco	0	Load JPG	5
			Load JPG	6
	Studie App - Call Park Company for Execution		Load JPG	6
2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5			Load JPG	5
				-
	9400 00 E8 00		10	[V
				5
			THE STATE OF THE S	2
			25 SOSTANI	5
	I SQUIDORS CONTRACTOR CONTRACTOR			[v
CONTRACTOR OF THE PARTY OF THE				[]
				9
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			2
			1000000	-
	Handing the state of the state		011111111111111111111111111111111111111	5
9/06/19 09:22			VII UNRIDGE	-
9/06/19 09:22	Reinspection Photo			5
9/06/19 09:22	Reinspection Photo		Mark Control	5
9/06/19 09:22	Reinspection Photo		is itsuus	6
9/06/19 09:22	Reinspection Photo			6
9/06/19 09:22	Reinspection Photo		Load JPG	5
9/06/19 09:22	Reinspection Photo		Load JPG	5
9/06/19 09:22	Reinspection Photo		Load JPG	5
9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	9/06/19 09:22 9/06/19 09:22			

Asse	essment Reports		1 per p	age 🗸	4
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	The state of the s	Thumbnail	Print
186	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
187	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
188	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
189	19/06/19 09:22	Reinspection Photo	0	Load JPG	~
190	19/06/19 09:22	Reinspection Photo	0	Load JPG	▼
191	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
192	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
193	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
194	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
195	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
196	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
197	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
198	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
199	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
200	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
201	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
202	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
203	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
204	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
205	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
206	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
207	19/06/19 09:22	Reinspection Photo	0	Load JPG	✓
208	19/06/19 09:22	Reinspection Photo	0	Load JPG	~
209	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
210	19/06/19 09:22	Reinspection Photo	0	Load JPG	~
211	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
212	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
213	19/06/19 09:22	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per p	age V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	04/03/19 14:25	MARK ESTIMATE	0	Load PDF	

Linked Accident Report Documents

			View	View in Brows	ser v
Ass	essment Reports		1 per p	age 🔻	~
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	20/02/19 15:06	Accident Statement	0	Load HTM	
Pho	otos/Images		3 per p	age 🔽	V
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	20/02/19 15:02	Accident Photo	0	Load JPG	✓
2	20/02/19 15:02	Accident Photo	0	Load JPG	✓
3	20/02/19 15:02	Accident Photo	0	Load JPG	~
4	20/02/19 15:02	Accident Photo	0	Load JPG	V
5	20/02/19 15:02	Accident Photo	0	Load JPG	✓
6	20/02/19 15:02	Accident Photo	0	Load JPG	V
7	20/02/19 15:02	Accident Photo	0	Load JPG	V
8	20/02/19 15:02	Accident Photo	0	Load JPG	V
9	20/02/19 15:02	Accident Photo	0	Load JPG	V

Page 6 of 6

Ass	essment Reports		1 per s	page 🗸	~
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
10	20/02/19 15:02	Accident Photo	0	Load JPG	V
11	20/02/19 15:02	Accident Photo	0	Load JPG	V
12	20/02/19 15:02	Accident Photo	0	Load JPG	$\overline{\mathbf{v}}$
13	20/02/19 15:02	Accident Photo	0	Load JPG	~
14	20/02/19 15:02	Accident Photo	0	Load JPG	\checkmark
15	20/02/19 15:02	Accident Photo	0	Load JPG	✓
16	20/02/19 15:02	Accident Photo	0	Load JPG	V
17	20/02/19 15:02	Accident Photo	0	Load JPG	V
18	20/02/19 15:02	Accident Photo	0	Load JPG	V
19	20/02/19 15:02	Accident Photo	0	Load JPG	V
20	20/02/19 15:02	Accident Photo	0	Load JPG	~
21	20/02/19 15:02	Accident Photo	0	Load JPG	✓
22	20/02/19 15:02	Accident Photo	0	Load JPG	V
Do	cumentation		1 per	page 🔻	V
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	20/02/19 15:01	Accident Sketch Plan	0	Load JPG	V
2	20/02/19 15:01	Accident Sketch Plan	0	Load JPG	~
3	20/02/19 15:01	Accident Sketch Plan	0	Load JPG	V
4	20/02/19 15:01	POLICE REPORT	0	Load JPG	~
5	20/02/19 15:02	DRIVING DOC	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909

Our File No:

CS/CTI19003790/AVD3E2

Date:

26/06/2019

REFERENCE

Insured/Claimant:

FU CHEN LOK

Policy No:

DMPCSN1817761800

Date of Loss:

18/02/2019

Nature of Claim:

OD

Claim No: SNM19D200887C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKE418Y

Make & Model:

NISSAN GTR, 3.8 (A) 03/10/2008 (Man. Year: 2008) Engine No: Chassis No: VR38006991A

Reg. Date: Colour:

Odometer:

R35004855 251728 km

Engine Capacity:

3799 cc

Market Value/New Car Price: S\$175,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size:

285/35 R20

Rear Tyre Size: Rear Left Side:

285/35 R20

Front Left Side: Front Right Side: Dunlop 6 mm Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	196,177.72	150,126.24	46,051.48	23.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,350.00	8,350.00	14,000.00	62.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	218,527.72	158,476.24	60,051.48	27.48
Approved Total (Overridden) (S\$)		120,000.00		
- Excess (S\$)	6,000.00	6,000.00	0.00	0.00
Nett Amount (S\$)	212,527.72	114,000.00	98,527.72	46.36

INSPECTION

Date of Assignment:

28/02/2019

Date Inspected:

01/03/2019

Inspected At:

Ngee Seng Auto Works (HQ)

Block 3022A, Ubi Road 1, #01-50

Singapore 408716

Estimated Period of Repair:

28.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2019)
Parts:	192	NISSAN GTR 3.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for SKE418Y)
Validity:		es are valid only if they contain the print code (above) on all estimate pages, running page he END OF ESTIMATES marker on the last estimate page
Further Info	Items/values n	ot in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Missing	6,990.30 FL	*6,990.30 FL
2	1		*FRONT BUMPER SPONGE	Missing	580.20 FL	*580.20 FL
3	1		*FRONT BUMPER SPOILER	Missing	4,500.00 FL	*4,500.00 FL
4	2		*FRONT BUMPER SIDE LAMP RH / LH	Missing	550.00 FL	*550.00 FL
5	2		*FRONT BUMPER SIDE RETAINER RH / LH	Missing	390.00 FL	*390.00 FL
6	2		*FRONT BUMPER SIDE BRACKET RH / LH	Missing	370.00 FL	*370.00 FL
7	1		*FRONT BUMPER BEAM	Missing	360.50 FL	*360.50 FL
8	1		*FRONT BUMPER REINFORCEMENT	Missing	2,650.50 FL	*2,650.50 FL
9	2		*FRONT BUMPER REINFORCEMENT BRACKET	Missing	424.00 FL	*424.00 FL
10	2		*FRONT FENDER RH / LH	Distorted	5,971.00 FL	*5,971.00 FL
11	2		*FRONT FENDER INNER SHIELD (FRONT)	Torn	662.60 FL	*662.60 FL
12	2		*FRONT FENDER INNER SHIELD (REAR)	Torn	709.00 FL	*709.00 FL
13	1		*FRONT SUPPORT PANEL	Distorted	5,980.80 FL	*5,980.80 FL
14	1		*FRONT SUPPORT PANEL GARNISH	Distorted	1,680.00 FL	*1,680.00 FL
15	2		*FRONT HEADLAMP RH / LH	Smashed	7,901.00 FL	*7,901.00 FL
16	2		*FRONT HEADLAMP BRACKET	Bent	330.00 FL	*330.00 FL
17	1		*ROCKER PANEL GARNISH RH / LH	N/S Distorted	3,964.00 FL	*1,982.00 FL
18	1		*FRONT LOWER ARM	N/S Distorted /O/SNotNecessary	5,720.00 FL	*2,860.00 FL
19	1		*FRONT KNUCKLE ARM	N/S Distorted /O/SNotNecessary	6,320.40 FL	*3,160.20 FL
20	1		*FRONT KNUCKLE ARM BEARING	N/S Distorted /O/SNotNecessary	1,901.00 FL	*950.50 FL
21	1		*FRONT UPPER ARM	N/S Distorted /O/SNotNecessary	2,100.00 FL	*1,050.00 FL
22	1		*FRONT CROSS MEMBER	Bent	6,120.00 FL	*6,120.00 FL
23	1		*FRONT STEERING RACK & PINION	Distorted	9,211.00 FL	*9,211.00 FL
24	1		*FRONT DRIVSHAFT RH / LH	N/S Distorted	9,183.00 FL	*4,591.00 FL
25	1		*FRONT STABILISER BAR LH	Distorted	2,510.50 FL	*2,510.50 FL
26	2		*FRONT STABILISER BAR LINK	Bent	1,361.00 FL	*680.50 FL
27	2		*FRONT SHOCK ABSORBER	Bent	7,600.00 FL	*3,800.00 FL
28	1		*FRONT OIL COOLEN	Distorted	8,200.00 FL	*8,200.00 FL
29	1		*RADIATOR	Distorted	3,480.00 FL	*3,480.00 FL
30	1		*RADIATOR FAN	Distorted	1,160.00 FL	*1,160.00 FL
31	1		*AIR CON FAN	Distorted	1,238.00 FL	*1,238.00 FL
0.1			*AIR CON CONDENSER	Bent	3,346.00 FL	*3,346.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*FRONT CALIPER	Cut	4,120.00 FL	*4,120.00 FL
34	1		*FRONT OIL COOLEN BRACKET	Bent	678.00 FL	*678.00 FL
35	1		*FRONT OIL COOLEN HOSE IN	Bent	1,950.00 FL	*1,950.00 FL
36	1		*FRONT OIL COOLEN HOSE OUT	Bent	1,850.00 FL	*1,850.00 FL
37	1		*FRONT ENGINE LOWER COVER REAR	Torn	1,750.00 FL	*1,750.00 FL
38	1		*FRONT ENGINE LOWER COVER FRONT	Torn	1,320.00 FL	*1,320.00 FL
39	1		*FRONT DOOR	Dented	6,990.30 FL	*6,990.30 FL
40	1		*FRONT DOOR MOULDING	Not Necessary	760.00 FL	*-FL
41	1		*FRONT GRILLE	Smashed	882.00 FL	*882.00 FL
42	1		*FRONT GRILLE CHROME	Smashed	1,678.00 FL	
43	1		*FRONT GRILLE HOUSEING	Smashed	932.00 FL	*932.00 FL
44	1		*FRONT GRILLE LOGO	Necessary	180.00 FL	*180.00 FL
45	1		*FRONT BUMPER LOWER GRILLE	Distorted	970.00 FL	*970.00 FL
46	1		*SET FRONT BUMPER CLIPS	Necessary	150.00 FL	*150.00 FL
47	1		*SET FRONT FENDER INNER SHIELD	Necessary	110.00 FL	*110.00 FL
48	1		*FRONT BUMPER RUBBER	Missing	260.50 FL	*260.50 FL
49	2		*FRONT FENDER LOGO (GTR) RH / LH	Necessary	560.00 FL	*560.00 FL
50	1		*FRONT BUMPER LOWER LIP	Missing	6,231.00 FL	*6,231.00 FL
51	1		*FRONT BONNET	Dented	5,600.00 FL	
52	2		*FRONT BONNET HINGE RH / LH	Bent	1,310.00 FL	and the control of th
53	2		*FRONT BONNET HINGE COVER RH / LH	200	520.60 FL	*520.60 FL
54	2		*FRONT BONNET LOCK RH / LH	Damaged	560.00 FL	*560.00 FL
55	1		*FRONT BONNET INSULATION RH / LH	Not Necessary	878.00 FL	*-FL
56	1		*FRONT DOOR LOCK	Not Necessary	760.60 FL	*-FL
57	1		*ROCKER PANEL	Repair	1,950.40 FL	*-FL
58	3		*TOP UP BONNET SENSOR	Missing	1,758.00 FL	*1,758.00 FL
59	2		*FRONT FENDER AIR DUCT	Distorted	797.60 FL	*797.60 FL
60	2		*TURBO COOLER	Missing	1,301.00 FL	*1,301.00 FL
61	1		*FRONT WINDSCREEN	Cracked	4,500.00 FL	
62	2		*FRONT CHASSIS	Repair	11,970.00 FL	*-FL
63	1		*FRONT AIR CON PIPE (IN)	Bent	975.00 FL	
64	1		*FRONT AIR CON PIPE (OUT)	Bent	860.00 FL	*860.00 FL
65	1		*REAR BUMPER	Torn	6,990.00 FL	*6,990.00 FL
66	1		*REAR BUMPER LOWER LIP	Repair	3,282.50 FL	*-FL
67	1		*SPORT RIM (4PCS)	Cut-3pcs only		*12,000.00 FL
68	1		*SET FRONT BUMPER LED LAMP	Missing	3,600.00 FL	*3,600.00 FL
69	1		*REAR TAILLAMP	Not Necessary	2,480.50 FL	*- FL
70	1		*FRONT / REAR NUMBER PLATE	Front Missing	100.00 FS	
71	1		*TYRE (4PCS)	Punctured-1pc only	6,000.00 FS	*800.00 FS
72	2		*FRONT / REAR WINDSCREEN SEALANT / SEAL	Necessary	240.00 FS	*80.00 FS

- List Item Discount on L Items 10.00/10.00% (S\$) 21,093.08 16,577.36

> 150,126.24 Total Parts (S\$) 196,177.72

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TOWING	New	200.00	150.00
2	TO REMOVE & REFIX FRONT WINDSCREEN	New	400.00	120.00
3	TO REMOVE & REFIX FRONT DOOR COMPONENT	New	300.00	80.00
4	TO REMOVE & REFIX RIM, TYRE & BALANCING	New	350.00	150.00
5	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	400.00	80.00
6	TO CHECK & RECTIFY WIRING SYSTEM, RESET COMPUTER	New	800.00	300.00
7	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	3,800.00	1,200.00
8	TO CARRY OUT CHASSIS ALIGN RH / LH	New	600.00	350.00
9	TO RUST PROOF AFFECTED AREAS	New	300.00	120.00
10	TO SETING AIR BAG SYSTEM	New	1,200.00	0.00
11	TO REMOVE DASHBOARD / AIR BAG	New	1,500.00	0.00
12	TO REMOVE & REFIX ENGINE	New	2,500.00	1,000.00
13	TO PANEL BEATING	New	6,000.00	3,000.00
14	TO SPRAY PAINTING	New	4,000.00	1,800.00
	Gross Labou	ır Cost (S\$)	22,350.00	8,350.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >