

SA/VA/PA

ASSIGNMENT (Office)

From/Person: chong Buonsen

CTI

Date/Time: 27/2/19 @ 3:25pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

GBB 5812 G

Insured

GBD 409SE

at Workshop no/

Ah dim motor

Tel:

64831244

of

No. 10 Amk Ind. Park 2A # 01-09

Policy No:

GA230773/1

MCN SN 30779618000

Claim No

SNM197200888002

Sum Insured

Excess:

Make of Veh

(Client's Record)

D.O.A

17/2/2019

11/3/19 @ 1pm (onw)

H.O.D. Endorsement:

CA / REV / REP / REV 24 HRS

Date/Time: 28/2/19 @ 10:09am

Person Contacted:

zila

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBB 5812 G - NA / CTI19003213 / K1 DOA: 17/2/19
	GBD 409SE - NA / CTI19003213 / K1 DOA: 17/2/19
	Kenacyle confirmed us \$4250 (Red \$5297.84, 55%)

REF: CTI

ASSIGNMENT

From

Date: 1/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBB 5812 G

at Workshop n/s Ah Lim Motor

of No. 10 Amk Ind. Park 2A #01-09

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

1pm (waiting)

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAG Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBB 5812G

Yt Regn:

06 C 9

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dyna

C.O.

2982

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading:

262198

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT 53Y00K00710

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

N/A

1P5R15R12

R: B.S

155R12x8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

Rear

R/Bal.

mm

R/Bal.

22

mm

L/Bal.

mm

L/Bal.

22

mm

D.O.A.

17/2/19

D.O.I.

1/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 AUG 2019

Date/Time, File Pass to?



Preli. Report

13/8/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Weekend (\$)

Survey Fee:

Transportation

) S + P = \$

) Photos

) Other:

Report Format:

MER-PP

Lump Sum / I.B.L. (\$)

4250

220

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 27 February 2019 3:25 PM
To: assignments
Subject: FW: TP / OUR CLIENT GBB5812G DOA: 17/02/2019 POLICY NO. GA230773/1 YOUR INSURED GBD4095E

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 27 February 2019 3:25 PM
To: zila <zila@ahlimmotor.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: TP / OUR CLIENT GBB5812G DOA: 17/02/2019 POLICY NO. GA230773/1 YOUR INSURED GBD4095E

Without prejudice

Dear Zila,

We pri.

Dear LKK,

Pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore)

Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: zila [mailto:zila@ahlimmotor.com.sg]

Sent: Wednesday, 27 February, 2019 2:25 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: TP / OUR CLIENT GBB5812G DOA: 17/02/2019 POLICY NO. GA230773/1 YOUR INSURED GBD4095E

Hi Boon Sen,

We choose Kenneth Kong to be the surveyor.

Thanks.

Best Regards,

Zila

Ah Lim Motor

Tel: 64831244 Fax: 64836170

On 27/02/2019 2:18 PM, Chong Boon Sen wrote:

> Dear Sirs

> We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

>

>

>

>

> Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

> You may select one of the listed motor surveyors and we will bear the

> cost of the pre-repair survey carried out by the sin

>

>

> Regards,

> Chong Boon Sen

> Claims Executive

> Claims

>

> China Taiping Insurance (Singapore) Pte. Ltd.

> 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No.

> 200208384E

> DID: 63896171

> Fax: 62247175

> Email: boonsen.chong@sg.cntaiping.com

> Website: www.sg.cntaiping.com

>

>

> Disclaimer :

> This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore)

Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

>

>

> -----Original Message-----

> From: zila [mailto:zila@ahlimmotor.com.sg]

> Sent: Tuesday, 26 February, 2019 3:30 PM

> To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Irene Tay

> <irene.tay@sg.cntaiping.com>; Elaine Cheong

> <elaine.cheong@sg.cntaiping.com>

> Subject: Fwd: TP / OUR CLIENT GBB5812G DOA: 17/02/2019 POLICY NO.

> GA230773/1 YOUR INSURED GBD4095E

> Importance: High

>

> Hi Claims Dept,

>

> Please kindly arrange survey.

> Note: Vehicle is not in. – To be arrange

>

> Thanks.

>

>

>

> Best Regards,

>

>

> Zila

> Ah Lim Motor

> Tel: 64831244 Fax: 64836170

>

>

> ----- Forwarded Message -----

> Subject: TP / OUR CLIENT GBB5812G DOA: 17/02/2019 POLICY NO.

> GA230773/1 YOUR INSURED GBD4095E

> Date: Fri, 22 Feb 2019 10:05:16 +0800

> From: zila <zila@ahlimmotor.com.sg>

> To: CLAIMSDEPT@SG.CNTAIPING.COM, Chong Boon Sen CHINA TAIPING

> <BOONSEN.CHONG@SG.CNTAIPING.COM>, IRENE TAY CHINA

> <IRENE.TAY@SG.CNTAIPING.COM>

>

> Hi Claims Dept,

>

> Please kindly arrange survey.

> Note: Vehicle is not in. – To be arrange

>

> Thanks.

>

>

> --

> Best Regards,

>

>

> Zila

> Ah Lim Motor

> Tel: 64831244 Fax: 64836170

>

> This email has been scanned by the Symantec Email Security.cloud service.
> For more information please visit <http://www.symanteccloud.com>

For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

3691K

Vehicle Details

Vehicle No.:

GBB5812G

Vehicle to be Exported:

No

Intended Deregistration Date:

19 Feb 2019

Vehicle Make:

TOYOTA

Vehicle Model:

DYNA 150 MANUAL 3SEATER

Primary Colour:

Blue

Manufacturing Year:

2009

Engine No.:

1KD1932542

Chassis No.:

JTFAT35Y00K200710

Maximum Power Output:

-

Open Market Value:

\$24,970.00

Original Registration Date:

29 Jun 2009

First Registration Date:

29 Jun 2009

Transfer Count:

0

Actual ARF Paid:

\$1,249.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

28 Jun 2019

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$12,615.00

COE Rebate Amount:

\$452.00

Total Rebate Amount:

\$452.00

The information contained herein is correct as at 19 Feb 2019

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: PRELIM CONSTRUCTION PTE LTD
 81 TAGORE LANE #01-21 TAG A

SINGAPORE 787502

TEL: 64816615

ATTN:

Estimate No: MC1900153

Date: 21 Feb 2019

Policy No: GA230773/1

Veh Reg No: GBB5812G

Make/Model: TOYOTA DYNA 150 M
 3SEATER

Your Ref No: GBB5812G

Claim Type: Third Party — China

Accident Date: 17/02/2019

TP Veh Reg No: GBD4095E

LKK
 1pm
 01/03

Not Authorised
 11/02/19
 Recovery After Paint 6 days

Estimate Repair Cost to Vehicle No :GBB5812G

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT WINDSCREEN RUBBER	1 PC	284.22	X
2 FRONT PANEL	1 PC	1,219.30	X
3 FRONT PANEL DYNA LOGO	1 PC	69.40	✓
4 FRONT GRILLE	1 PC	490.50	✓
5 FRONT GRILLE EMBLEM	1 PC	74.60	✓
6 FRONT GRILLE CLIPS	6 PC	19.26	✓
7 HEADLAMP LH & RH	2 PC	1,187.00	✓
8 FRONT BUMPER	1 PC	401.20	✓
9 TAILGATE	1 PC	1,267.30	✓
10 TAILGATE TOYOTA STICKER	1 PC	204.70	✓
11 TAILAMP LH & RH	2 PC	485.40	✓
12 TAILAMP PANEL LH & RH	2 PC	157.60	X
13 NO PLATE PANEL	1 PC	201.60	X
14 END PANEL DYNA LOGO	1 PC	41.70	✓
		6,103.78	
	Less 25%	1,525.95	4,577.84
Special Nett			
15 NUMBER PLATE	2 PC	70.00	40.00
16 REVERSE SENSOR	1 SET	200.00	X
17 TAILGATE ALUMINIUM PLATE	1 PC	350.00	✓
18 TAILGATE ALUMINIUM PLATE RIVET	30 PC	90.00	✓
19 REAR REINFORCEMENT	1 PC	450.00	X
20 70 KM/H STICKER	1 PC	15.00	✓
21 13 PAX STICKER	1 PC	15.00	✓
		1,190.00	1,190.00
LABOUR			
22 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
23 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	X
24 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	280.00	240.00
25 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	30.00
26 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD FRONT PANEL TO KNOCK & REPAIR INNER PANELS & AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	500.00
27 TO SPRAY FRONT PANEL, FRONT GRILLE, FRT BUMPER.	1 PC	900.00	500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before the spray painting
- To display damaged parts during survey
- To parts painter to rectify the damage
- To the repairer to rectify the damage
- To the repairer to rectify the damage
- To the repairer to rectify the damage

Authorised by Repairer
 Signature:
 Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PRELIM CONSTRUCTION PTE LTD
81 TAGORE LANE #01-21 TAG A

SINGAPORE 787502

TEL: 64816615

ATTN:

Estimate No: MC1900153
Date: 21 Feb 2019
Policy No: GA230773/1
Veh Reg No: GBB5812G
Make/Model: TOYOTA DYNA 150 M
3SEATER

Your Ref No: GBB5812G
Claim Type: Third Party
Accident Date: 17/02/2019
TP Veh Reg No: GBD4095E

Estimate Repair Cost to Vehicle No :GBB5812G

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
28 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
29 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
30 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	301
31 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD NO PLATE PANEL,REAR REINFORCEMENT.TO KNOCK & REPAIR FLOOR PANEL INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	5001
32 TO SPRAY TAILGATE,FLOOR PANEL.	1 PC	500.00	8001
		3,780.00	3,780.00
		Total	S\$ 9,547.84
		Add GST @ 7%	668.35
		Total Amount Payable	S\$ 10,216.19

TOTAL: SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED SIXTEEN AND CENTS NINETEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALIZATION

M/S : PRELIM CONSTRUCTION PTE LTD
81 TAGORE LANE #01-21 TAG A

SINGAPORE 787502

TEL: 64816615

ATTN:

Claim No: MC1900153

No: MF1900312

Date: 28 May 2019

Policy No: GA230773/1

Veh Reg No: GBB5812G

Make/Model: TOYOTA DYNA 150 M
3SEATER

Your Ref No: GBB5812G

Claim Type: Third Party

Accident Date: 17/02/2019

TP Veh Reg No: GBD4095E

Repair Cost to Vehicle No (For Finalization):GBB5812G

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT PANEL DYNA LOGO	1 PC	69.40	
2 FRONT GRILLE	1 PC	490.50	
3 FRONT GRILLE EMBLEM	1 PC	74.60	
4 FRONT GRILLE CLIPS	6 PC	19.26	
5 HEADLAMP RH	1 PC	593.50	
6 FRONT BUMPER	1 PC	401.20	
7 TAILGATE	1 PC	1,267.30	
8 TAILGATE TOYOTA STICKER	1 PC	204.70	
9 TAILAMP LH	1 PC	242.70	
10 END PANEL DYNA LOGO	1 PC	41.70	
		3,404.86	
	Less 25%	851.22	2,553.65
Special Nett			
11 NUMBER PLATE	2 PC	40.00	
12 TAILGATE ALUMINIUM PLATE	1 PC	350.00	
13 TAILGATE ALUMINIUM PLATE RIVET	30 PC	90.00	
14 70 KM/H STICKER	1 PC	15.00	
15 13 PAX STICKER	1 PC	15.00	
		510.00	510.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
17 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	240.00	
18 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
19 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT PANEL.TO KNOCK & REPAIR INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
20 TO SPRAY FRONT PANEL,FRONT GRILLE,FRT BUMPER.	1 PC	500.00	
21 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : PRELIM CONSTRUCTION PTE LTD
81 TAGORE LANE #01-21 TAG A

SINGAPORE 787502
TEL: 64816615
ATTN:

Your Ref No: GBB5812G
Claim Type: Third Party
Accident Date: 17/02/2019
TP Veh Reg No: GBD4095E

Claim No: MC1900153
No: MF1900312
Date: 28 May 2019
Policy No: GA230773/1
Veh Reg No: GBB5812G
Make/Model: TOYOTA DYNA 150 M
3SEATER

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):GBB5812G

Description	Quantity	List Price S\$	Amount S\$
24 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD NO PLATE PANEL,REAR REINFORCEMENT.TO KNOCK & REPAIR FLOOR PANEL INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
25 TO SPRAY TAILGATE,FLOOR PANEL.	1 PC	400.00	
		2,290.00	2,290.00
	Total		S\$ 5,353.65
	Lump Sum Less 20%		-1,070.73
	Sub Total		S\$ 4,282.92
	Less Rounding		-32.92
	Lum Sum Repair		S\$ 4,250.00
	Less Excess		S\$ 0.00
	Amount Before GST		S\$ 4,250.00
	Add GST @ 7%		297.50
	Total Amount Payable		S\$ 4,547.50

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FIVE HUNDRED FORTY SEVEN AND CENTS FIFTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 01/03/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PRELIM CONSTRUCTION PTE LTD
81 TAGORE LANE #01-21 TAG A

SINGAPORE 787502

TEL: 64816615

ATTN:

Estimate No: MC1900153
Date: 21 Feb 2019
Policy No: GA230773/1
Veh Reg No: GBB5812G
Make/Model: TOYOTA DYNA 150 M
3SEATER

Your Ref No: GBB5812G

Claim Type: Third Party - China

Accident Date: 17/02/2019

TP Veh Reg No: GBD4095E

Estimate Repair Cost to Vehicle No : GBB5812G

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT WINDSCREEN RUBBER	1 PC	284.22	X
2 FRONT PANEL	1 PC	1,219.30	X
3 FRONT PANEL DYNA LOGO	1 PC	69.40	
4 FRONT GRILLE	1 PC	490.50	
5 FRONT GRILLE EMBLEM	1 PC	74.60	
6 FRONT GRILLE CLIPS	6 PC	19.26	
7 HEADLAMP LH & RH	2 PC	1,187.00	
8 FRONT BUMPER	1 PC	401.20	
9 TAILGATE	1 PC	1,267.30	
10 TAILGATE TOYOTA STICKER	1 PC	204.70	
11 TAILAMP LH & RH	2 PC	485.40	
12 TAILAMP PANEL LH & RH	2 PC	157.60	X
13 NO. PLATE PANEL	1 PC	201.60	X
14 END PANEL DYNA LOGO	1 PC	41.70	
		6,103.78	
	Less 25%	1,525.95	4,577.84
Special Nett			
15 NUMBER PLATE	2 PC	70.00	405.00
16 REVERSE SENSOR	1 SET	200.00	X
17 TAILGATE ALUMINIUM PLATE	1 PC	350.00	
18 TAILGATE ALUMINIUM PLATE RIVET	30 PC	90.00	
19 REAR REINFORCEMENT	1 PC	450.00	X
20 70 KM/H STICKER	1 PC	15.00	
21 13 PAX STICKER	1 PC	15.00	
		1,190.00	1,190.00
LABOUR			
22 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
23 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	X
24 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	280.00	2401
25 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	301
26 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD FRONT PANEL TO KNOCK & REPAIR INNER PANELS & AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	5001
27 TO SPRAY FRONT PANEL, FRONT GRILLE, FRONT BUMPER.	1 PC	900.00	5001



PHOTO TAKEN BY SIMON 13/3/19
Email photo back

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PRELIM CONSTRUCTION PTE LTD
81 TAGORE LANE #01-21 TAG A

SINGAPORE 787502
TEL: 64816615
ATTN:

Estimate No: MC1900153
Date: 21 Feb 2019
Policy No: GA230773/1
Veh Reg No: GBB5812G
Make/Model: TOYOTA DYNA 150 M
3SEATER

Your Ref No: GBB5812G
Claim Type: Third Party
Accident Date: 17/02/2019
TP Veh Reg No: GBD4095E

Estimate Repair Cost to Vehicle No :GBB5812G

Description	Quantity	List Price	Amount
		SS	SS
28 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
29 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
30 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	301
31 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD NO PLATE PANEL,REAR REINFORCEMENT.TO KNOCK & REPAIR FLOOR PANEL INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	5001
32 TO SPRAY TAILGATE,FLOOR PANEL.	1 PC	500.00	8001
		3,780.00	3,780.00
Total			SS 9,547.84
Add GST @ 7%			668.35
Total Amount Payable			SS 10,216.19

TOTAL: SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED SIXTEEN AND CENTS NINETEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19003799/KQD3N2

Date: 27/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30279618000
Claimant Vehicle No :	GBB5812G	Insured Vehicle No :	GBD4095E
Date of Loss:	17/02/2019	Nature of Claim:	TP
		Claim No:	SNM19D200888C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB5812G	Engine No:	1KD1932542
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Chassis No:	JTFAT35Y00K200710
Reg. Date:	29/06/2009 (Man. Year: 2009)	Odometer:	262196 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15 R12	Rear Tyre Size:	155R12X8 (D)
Front Left Side:	West Lake 7 mm	Rear Left Side:	Bridgestone 2/2 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	Bridgestone 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,767.83	3,063.64	2,704.19	46.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,290.00	1,490.00	39.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,547.83	5,353.64	4,194.19	43.93
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	9,547.83	4,250.00	5,297.83	55.49
+ GST 7.00/7.00% (S\$)	668.35	297.50	370.85	55.49
Nett Amount (S\$)	10,216.18	4,547.50	5,668.68	55.49

INSPECTION

Date of Assignment:	23/08/2019	
Date Inspected:	01/03/2019 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Aug 2019)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB5812G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN RUBBER	Serviceable	284.22 FL	*- FL
2	1		*FRONT PANEL	Repair	1,219.30 FL	*- FL
3	1		*FRONT PANEL DYNA LOGO	Necessary	69.40 FL	*69.40 FL
4	1		*FRONT GRILLE	Cracked	490.50 FL	*490.50 FL
5	1		*FRONT GRILLE EMBLEM	Necessary	74.60 FL	*74.60 FL
6	6		*FRONT GRILLE CLIPS	Necessary	19.26 FL	*19.26 FL
7	1		*HEADLAMP LH & RH	O/s Cracked	1,187.00 FL	*593.50 FL
8	1		*FRONT BUMPER	Bent	401.20 FL	*401.20 FL
9	1		*TAILGATE	Bent	1,267.30 FL	*1,267.30 FL
10	1		*TAILGATE TOYOTA STICKER	Necessary	204.70 FL	*204.70 FL
11	1		*TAILAMP LH & RH	N/s Cracked	485.40 FL	*242.70 FL
12	2		*TAILAMP PANEL LH & RH	Repair	157.60 FL	*- FL
13	1		*NO PLATE PANEL	Repair	201.60 FL	*- FL
14	1		*END PANEL DYNA LOGO	Necessary	41.70 FL	*41.70 FL
15	2		*NUMBER PLATE	Dented	70.00 FS	*40.00 FS
16	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
17	1		*TAILGATE ALUMINIUM PLATE	Buckled	350.00 FS	*350.00 FS
18	1		*TAILGATE ALUMINIUM PLATE RIVET (30 Pcs)	Necessary	90.00 FS	*90.00 FS
19	1		*REAR REINFORCEMENT	Repair	450.00 FS	*- FS
20	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
21	1		*13 PAX STICKER	Necessary	15.00 FS	*15.00 FS
					Sub Total (\$\$)	7,293.78 3,914.86
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,525.95 851.22
					Total Parts (\$\$)	5,767.83 3,063.64

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN	New	120.00	0.00
3	TO REMOVE AND REINSTALL/REPLACE DASHBOARD	New	280.00	240.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	80.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT PANEL TO KNOCK & REPAIR INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	900.00	500.00
6	TO SPRAY FRONT PANEL,FRONT GRILLE,FRT BUMPER	New	900.00	500.00
7	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
8	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	60.00	50.00
9	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
10	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD NO PLATE PANEL,REAR REINFORCEMENT.TO KNOCK & REPAIR FLOOR PANEL INNER PANELS & AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
11	TO SPRAY TAILGATE,FLOOR PANEL	New	500.00	400.00
Gross Labour Cost (\$\$)			3,780.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >