



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving 1 2016 SUBARU FORESTER 2.0 (SLL2603S)

Date of Loss 1 March 2019

Time of Loss 0.00

Loss Description SLL2603S (INSD) C/W SLS7052L (TP)

Comment 

### Workshop Details

Total Rebate Amount 50071

Nett Loss Amount \$32,929.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion \* 47



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

SLL2603S

Purchase Date

dd/mm/yyyy 

Registration State

SINGAPORE

Registration Date \*

20/02/2017 

Mileage

45994

Age of Vehicle

2

CATEGORY

POLICY INFORMATION

ASSESSMENT  
INFORMATIONManufacturing  
Year

2016

2016

Make

SUBARU

SUBARU

Model

FORESTER 2.0

FORESTER 2.0I-L C'

### Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY  
INFORMATION

Driver Name

KERK HONG CHEONG

Date of Birth

4 August 1971

dd/mm/yyyy 

Age

47

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	JF1SJ5KC5GG082791	<input type="text" value="JF1SJ5KC5GG0827"/>
Engine No	FB20Y525246	<input type="text" value="FB20Y525246"/>
Engine Capacity		<input type="text" value="1995"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="83000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	13	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yy"/>
License Expiration Date		<input type="text" value="dd/mm/yy"/>
Address	BLK 435C FERVALE ROAD, #20-224, 793435, Singapore	<input type="text" value=""/>
Address type	Residential	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text"/>
Marital status	Married	<input type="text"/>
Identification #	S7127660J	<input type="text"/>



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

01/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

Other Excess

### Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

### Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/55R16

Rear Tyre Size

225/55R16

Front left side

YOKOHAMA8mm

Rear left side

YOKOHAMA8mm

Front right side

YOKOHAMA8mm

Rear right side

YOKOHAMA8mm



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No



SERVICE REQUESTS

MESSAGES

CLAIMS

## << Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary

### Parts

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		1	1			FRONT BUMPER			Bent	694.3		20		555.44	Reviewing	
<input type="checkbox"/>		2	1			FRONT BUMPER REINFORCEMENT			Bent	288.2		20		230.56	Reviewing	
<input type="checkbox"/>		3	1			FRONT BUMPER SPONGE			Bent	140.3		20		112.24	Reviewing	
<input type="checkbox"/>		4	2			FRONT BUMPER RETAINER			Damaged	18.7		20		29.92	Reviewing	
<input type="checkbox"/>		5	1			FRONT BUMPER RIGHT FOG LAMP TOP CHROME			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		6	2			HEADLAMP			Cracked	2400.3		20		3840.48	Reviewing	
<input type="checkbox"/>		7	2			HEADLAMP LOWER BRACKET			Cracked	40.3		20		64.48	Reviewing	
<input type="checkbox"/>		8	1			FRONT GRILLE			Cracked	316.8		20		253.44	Reviewing	
<input type="checkbox"/>		9	1			FRONT GRILLE TOP CHROME			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		10	1			FRONT CENTRE CHROME			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		11	1			FRONT GRILLE EMBLEM			Necessary	78.1		20		62.48	Reviewing	
<input type="checkbox"/>		12	1			TOP GARNISH			Cracked	38.2		20		30.56	Reviewing	
<input type="checkbox"/>		13	1			N/S/F FENDER			Buckled	300.8		20		240.64	Reviewing	
<input type="checkbox"/>		14	1			N/S/F FENDER SHIELD			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		15	1			BONNET			Buckled	882		20		705.6	Reviewing	
<input type="checkbox"/>		16	1			BONNET LOCK			Damaged	65.2		20		52.16	Reviewing	
<input type="checkbox"/>		17	2			BONNET HINGES			Repair	0	0	0	0	0	Deny	
<input type="checkbox"/>		18	1			SUPPORT PANEL			Buckled	400.8		20		320.64	Reviewing	
<input type="checkbox"/>		19	1			BONNET ABSORBER			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		20	1			AIR CONDENSER			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		21	1			RADIATOR ASSY			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		22	1			N/S FRONT BUMPER NOZZLE			Cracked	98.2		20		78.56	Reviewing	
<input type="checkbox"/>		23	1			O/S FRONT BUMPER NOZZLE			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		24	1			N/S FRONT BUMPER NOZZLE COVER			Missing	89.5		20		71.6	Reviewing	
<input type="checkbox"/>		25	1			O/S FRONT BUMPER NOZZLE COVER			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		26	1			AIR INTAKE DUCT			Serviceable	0	0	0	0	0	Deny	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	27	1			AIR BAG SENSOR			Dented	300.5		20		240.4	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		PANEL KNOCKING	700	0	0	Reviewing		
	2		SPRAY PAINTING	800	0	0	Reviewing		
	3		WIRE CHECKING	20	0	0	Reviewing		
	4		RESET AIR BAG SYSTEM	150	0	0	Reviewing		
	5		VACCUME AND TOP UP AIR CON GAS	100	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
		2	SET NUMBER PLATE	Reviewing	45	BENT	

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount  
\$8,704.20

Claim Amount  
\$8,704.20

## Spare Parts

\$6,889.20

\$6,889.20

## Labour

\$1,770.00

\$1,770.00

## Miscellaneous

\$45.00

\$45.00

Submit for Review