Claim Reference: SDK1818X Assessment number: SHAH0021

Version: 1810

Date calculated: 02/28/2019 03:04 PM

Full Report Registration: SLJ6337U Printed: 28/02/2019 3:05 PM

Summary Information

Claim

Location: Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days: Singapore (SG) Ethoz Bukit Batok 01

SDK1818X

5

Work Provider: Currency: Date of Incident:

Hire Car Start: Hire Car End: AXA Insurance Pte Ltd

SGD

2019-02-18

Vehicle Details

Vehicle

Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration: VIN number:

Odometer: Model Specs

REAR PARKING SYSTEM

NISSAN NOTE (E12E)

BASE MODEL 71 6N 01 SLJ6337U

JN1TBAE12Z0982730

Claim Reference: SDK1818X Assessment number: SHAH0021

Version: 1810

Date calculated: 02/28/2019 03:04 PM

Full Report Registration: SLJ6337U Printed: 28/02/2019 3:05 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Labour	Time Base 10 WU/h	Price = 45.00 SGD/h		
Code	Description Time Base 10 Woy.	wu	Price SGD	
NO NUMBER	JOB ALLOWANCE	5.0	22.50	
NO NUMBER	R + R LEFT REAR SILL PANEL	1.0	4.50	
VB10A1)	R + R RIGHT REAR SILL PANEL	1.0	4.50	
VB10A1) 5540A1	RENEW REAR END PANEL INCLUDES: REAR BUMPER, ABSORBER/BRACKET AND REAR BUMPER SUPPORT, CARPET BOOT COMPART, BOTH TAILLAMPS AND ALL TAILGATE TRIMS AND SEALS	35.0	157.50	
=01011	REMOVE AND REFIT RENEW REAR BUMPER (REMOVED)	1.0	4.50	
5010A1	R + R REAR PARKING AID SENSOR/S	2.0	9.00	
NO NUMBER	ADD/WORK FOR PARKING AID SENSOR DRILLING	2.0	9.00	
NO NUMBER		1.0	4.50	
6898A1	R + R L/BOOT COVER	1.0	4.50	
6899A1	R + R R/BOOT COVER	2.0	9.00	
UT28A1 4430A1)	R + R NISSAN EMBLEM R + R LEFT REAR SEAT REST	1.0	4.50	

Claim Reference: SDK1818X Assessment number: SHAH0021

Version: 1810

Date calculated: 02/28/2019 03:04 PM

Full Report Registration: SLJ6337U Printed: 28/02/2019 3:05 PM

Code	Description			WU	Price SGD
442044)	R + R RIGHT REAR SEAT REST			1.0	4.50
4430A1) 2931	BOOTLID/TAILGATE REPAIR		X	10.0*	45.00
	Labarra Cook		Hrs	wu	
	Labour Cost Panel / Mechanical Labour		6.30	63.0	283.50
	Total of Labour				283.50
Paint	SYSTEM AZT		Tir	me Basi	s 10WU/h
Paint Work					Price SGD
Code	Description				
	REAR PANEL NEW PART PAINTING			20.0	
	REAR BUMPER COVER NEW PART PAINT K1R			10.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%			15.0	
Paint Mater	ial Per Part				
Code	Description				Price SGD 21.41
2711	REAR PANEL NEW PART PAINTING				39.44
2581	REAR BUMPER COVER NEW PART PAINT KIR				21.25
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%				
			Hrs	wu	Price SGD
	Labour Cost - Paint Factor	45.00 SGD/h			
	Time Paint			45.0	
	Preparation Main Work Metal		1.70	17.0	76.50
	Preparation Comp. Work Plastic		0.30	3.0	13.50 292.50
	Total	10 WU/h	6.50	65.0	292.50
	and the second				Price SGD
	Material Cost - Paint				21.41
	New Part Painting New Part Painting - Plastic K1R				39.44
	Repair Painting				21.25
	Material-constant Metal				18.10
	Material-constant Plastic				9.00 109.20
	Total				109.20

Spare Parts

Claim Reference: SDK1818X Assessment number: SHAH0021

Version: 1810

Date calculated: 02/28/2019 03:04 PM

Full Report Registration: SLJ6337U Printed: 28/02/2019 3:05 PM

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
	DEAD DUMBED COVED	85022 3VU0H	00	210.00
2581	REAR BUMPER COVER	85090 3VU0A	7	90.00
2625	REAR BUMPER DAMPER	85210 3VV0A ×		40.00
2627	L/R INN BUMPER BRKT			40.00
2628	R/R INN BUMPER BRKT	85210 3VV0A 7		26.00
2629	L/R OUT BUMPER BRKT	85221 3VU0A ×	00	26.00
2630	R/R OUT BUMPER BRKT	85220 3VU0A	RR	15.00
2650	RR BUMPER CLAMP KIT	KE980 3V600 /	0 00 10/11	280.00
2711	REAR PANEL	G9100 3VVMA >	K 20	36.00
3015	REAR MANUFACT BADGE	E 90890 3VA0A 🗵		57.00
3016	VERSION BADGE	90892 BH00A K		
3017	BADGE MODEL	90892 3VA0A		48.00
	Continue			0.00
f: OEM Parts	Savings			868.00
n: Non-OEM Parts u: Used parts	Subtotal Addition(+15.00%))		130.20
	Total			998.20

Ex	tr	a	S
----	----	---	---

EXTras		Price SGD	
Code	Description	File 3db	
1000	REVERSE SENSOR 01 / # AR	200.00*	
	Total Extras	220.00	

Steve (LKK) W/L pr/LL 4/3/19 3.20pm 8392 8813 3 days P/P Rey bot & At spry

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company PRINT DATE 28/02/2019

Acknowledged by Repairer

Signature:

Date:

Audatex System Using Manufacturer Times

Page 4 of 5

Claim Reference: SDK1818X Assessment number: SHAH0021

Version: 1810

Date calculated: 02/28/2019 03:04 PM

Full Report Registration: SLJ6337U Printed: 28/02/2019 3:05 PM

Final Calculation		CCD
	SGD	SGD
	868.00	
Parts	130.20	
Addition(+15.00%)		998.20
Total Parts		
Labour Time Base 10 WU/h	283.50	
Total 63.0 WU X 45.00 SGD/h	283.30	283.50
Total of Labour		200.00
		220.00
Total Of Extras		
Paint Work Time Base 10 WU/h	292.50	
Labour Cost 65.0 WU X 45.00 SGD/h	109.20	
Material Cost	109.20	401.70
Total Paint Including Material		402.70
		1,903.40
Repair Cost Excludes GST		133.24
GST (+7.00%)		2,036.64
Repair Cost Included GST		

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS