



簡 福 星 摩 哆 工 廠
KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147
Tel: (65) 6747 9560, 6743 5344, 6858 4361 • Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net / patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883
Tel: (65) 6481 5150 • Fax: (65) 6481 8683

TAX INVOICE

No. 46581

Business Reg. No. 221468-00E
GST Reg. No. M9-0005333-E

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2
SINGAPORE 068807


INVOICE NO : 46581
DATE : 25-04-2019

VEHICLE NO. : SDV700A
ACCIDENT DATE : 18-02-2019 16:50
THIRD PARTY REF. : SLF7658H

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SDV700A BMW 523I XL

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
	LABOUR CHARGES	
1	LUMP SUM REPAIRS	11400.00



TOTAL (D)	11,400.00
TOTAL REPAIR COST :	11,400.00
G S T % :	745.50
EXCESS AMOUNT :	750.00
INVOICE AMOUNT :	11,395.50

IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在鈹金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。