

ASS. REC. BY:

REF:

CS/MSA1903934/913

Special Instruction:

SUPERVISOR:

ASSIGNMENT (Office)From (Person): Nor Azfan of MSG Date/Time: 04/3/19Estimated Cost: 18'030.49 Bill to: \_\_\_\_\_**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**To Inspect Vehicle No: SDV 700A Insured: \_\_\_\_\_at Workshop m/s Kan Fook Sing Tel: 6747-9560of Defa LanePolicy No: 800754835mp Claim No: 585575Sum Insured: \_\_\_\_\_ Excess: 750Make of Veh: \_\_\_\_\_ D.O.A. 18/02/19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN/OUT

Date/Time Action/Instruction ( ) Estimate

SDV 700A NP/MSA1903123/34 008-18/2/195/3/2019 @ 15:00 - Revert via merimen, repairer ask lump sum.5/3/2019 @ 4:01 - 2nd revert via merimen proposed on us 13k.5/3/2019 @ 5:50pm - authorize repair by Azfan. not exceeding 11,400/-included checked item. excess 7505/3 @ 5:50pm Inform Kan Fook Sing Patricia authorize repairnot exceeding 11,400/-



## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	28 Feb 2019 14:08 <a href="#">Sendback Est</a>	01 Mar 2019 10:34 <b>S\$18,030.49</b>	04 Mar 2019 08:32 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured: **CHOO BOON PENG**, ID: S1380884H, Tel: +6596336363, Email: NOEMAIL

Vehicle Reg. No.: <b>SDV700A</b>	Date of Loss: 18/02/2019 16:00 - :59 [133 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type: <b>OD / 585575</b>	Policy/Cover Note No.: 80075483SMP (Comprehensive) Coverage: 29/12/2018 - 28/12/2019
	Excess: S\$750.00

Repairer: **Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560**

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Nor Azian Binte Noordin - 6594 2558]**

Adjuster: **LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/03/2019]**

Driver/Custodian: **CHOO BOON PENG (59 / Male) , NRIC: S1380884H, Tel: +6596336363 Email: NOEMAIL**

Adj Asg. Remarks: **Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Pls revert**

---

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

In

Auo Qiang

## Denise Tay (LKKAuto)

---

**From:** Nor Azian Binte Noordin <NorAzian\_Noordin@sg.msig-asia.com>  
**Sent:** Tuesday, 5 March 2019 5:50 PM  
**To:** Denise Tay (LKKAuto); SUR; assignments  
**Cc:** Keny Ong  
**Subject:** RE: SDV700A on 18/02/2019 (M585575)

Dear Denise,

Please proceed to authorise Kan Fook Sing to repair at lumpsum of not more than \$11,400.00 (including checked items). Excess of \$750.00 is applicable.

Meantime, please confirm on the number of repair days and get Kan Fook Sing to update OI about this as he wants to know the repair downtime.

Thanks.

Best Regards

**Nor Azian Binte Noordin**  
Executive, Claims Services (Motor)  
Direct line +65 6594 2558 | Direct fax +65 6225 7402 | [NorAzian\\_Noordin@sg.msig-asia.com](mailto:NorAzian_Noordin@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)    

A Member of **MS&AD** INSURANCE GROUP

---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Tuesday, March 05, 2019 5:38 PM  
**To:** Nor Azian Binte Noordin <NorAzian\_Noordin@sg.msig-asia.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Cc:** Keny Ong <Keny\_Ong@sg.msig-asia.com>  
**Subject:** RE: SDV700A on 18/02/2019 (M585575)

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Dear Azian,

We have check with Kan Fook Sing, they accept on not exceeding \$11,400(lump sum).

Kindly let us have your approval.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0884H
Vehicle Details	
Vehicle No.:	SDV700A
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	523I XL
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	71314155N52B25AE
Chassis No.:	WBANU12010CW24897
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$53,948.00
Original Registration Date:	29 Dec 2007
First Registration Date:	29 Dec 2007
Transfer Count:	0
Actual ARF Paid:	\$59,343.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,168.00
COE Rebate Amount:	\$43,841.00
<b>Total Rebate Amount:</b>	<b>\$43,841.00</b>

The information contained herein is correct as at 04 Mar 2019

OK

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

**Claim Reference:**  
**Assessment number: KFSA10030**  
**Version: 1810**  
**Date calculated: 03/01/2019 10:30 AM**

**Full Report**  
**Registration: SDV700A**  
**Printed: 01/03/2019 10:30 AM**

---

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Ryan Kan	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-18
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

**Vehicle**

Manufacturer:	BMW
Model:	5-SERIES E60/61
Sub Model:	523 I
Model Sheet Number:	01 45 04
Registration:	SDV700A
VIN number:	WBANU12010CW24897
Odometer:	

**Model Specs**

FROM 09/2007	AIR CON AUTOMATIC	DIP/FOLD MIRROR	RADIO BUSINESS CD
XENON HEADLAMPS	HEADLAMP WASHERS	DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
FRT/RR DRINK HOLDER	RR SCREEN SUN BLIND	TRIM POPLAR WOOD	DIP REAR VIEW MIRROR
SOFT CLOSE AUTOMATIC	2.5 LTR 140 KW	6-SPEED AUTOMATIC	TYRES 225/55 WR 16
WHEELS 7J X 16 ALLOY	4-DOOR	PARK DISTANCE CONT	CHROME LINE
SPEED CRUISE ONTROL	TWO COAT METALLIC		

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All   
 Underbody



**Labour**

Code	Description	Time Base 12 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
32 00 590	ELECTRONIC TRACK AND WHEEL ALIGNMENT CHECK (NOT INCLUDED: ADJUSTMENT AFTER REPAIR)		17.0	70.83
32 00 620	ADJUST REAR AXLE (TOE AND CAMBER) (TO WORK NO 32 00 590)		6.0	25.00
NO NUMBER	CONVERT CHASSIS JIG		14.0	58.33
NO NUMBER	CHASSIS JIG		18.0	75.00
41 35 000)	R + R R/F WING INCLUDES: R + R BUMPER, INDICATOR AND WHEELHOUSE COVER DOES NOT INCLUDE: R + R SILL MOULDING		17.0	70.83
51 13 501)	R + R L/FRONT GRILLE		1.0	4.17
51 13 501)	R + R R/FRONT GRILLE		1.0	4.17
41 11 925)	ADD/WORK: RENEW R/SILL PANEL AND CENTRE DOOR PILLAR		195.0	812.50
41 51 501	RENEW R/F DOOR (REMOVED)		38.0	158.33

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

Code	Description	WU	Price SGD
NO NUMBER	RENEW R/F LOWER DOOR HINGE	1.0	4.17
NO NUMBER	RENEW R/F UPPER DOOR HINGE	1.0	4.17
51 33 503)	RENEW WINDOW LIFT (ASS-WORK)	1.0	4.17
41 52 501	RENEW R/R DOOR (REMOVED)	42.0	175.00
NO NUMBER	RENEW R/R LOWER DOOR HINGE	1.0	4.17
41 35 111	RENEW R/R SIDE PANEL (PARTIAL REPAIR OF THE C-PILLAR) INCLUDES: R + R REAR SEAT, SEAT BACKREST, TAILGATE, REAR WINDOW, TAIL LAMP, BUMPER, BUMPER CARRIER, SILL MOULDING, LUGGAGE COMPARTMENT TRIM AND REAR DOOR	204.0	850.00
31 12 571	REPLACE LH FRONT SUSPENSION ARM (WITH SUSPENSION STRUT REMOVED)	2.0	8.33
36 11 505	R + R L/F WHEEL/TYRE	5.0	20.83
31 21 579	REMOVE/REFIT LH FRT WHEEL HUB (BEARING) (WITH BRAKE CALIPER AND BRAKE DISC REMOVED)	11.0	45.83
31 31 502	R + R LEFT FRONT SUSPENSION STRUT INCLUDES: R + R WHEEL AND PRESSURE ROD	13.0	54.17
31 31 501	REPLACE LH FRONT SUSPENSION STRUT (WITH SUSPENSION STRUT ASSEMBLY REMOVED)	4.0	16.67
31 35 501)	R + R L/FRT PRESSURE ROD	2.0	8.33
31 35 501)	R + R FRONT PRESSURE ROD	1.0	4.17
36 11 505	R + R R/R WHEEL/TYRE	5.0	20.83
1478	PULLING R/SIDE ADDITIONAL WORK	10.0*	41.67
0283	FRONT BUMPER COVER REPAIR	20.0*	83.33
2583	REAR BUMPER COVER REPAIR	20.0*	83.33
	<b>Labour Cost</b>	<b>Hrs</b>	<b>WU</b>
	<b>Panel / Mechanical Labour</b>	<b>52.30</b>	<b>627.0</b>
	<b>Alignment</b>		
	<b>Measuring Work</b>	<b>1.90</b>	<b>23.0</b>
	<b>Total of Labour</b>		<b>2,708.33</b>

**Paint**

Code	Description - TWO COAT METALLIC	WU	Price SGD
99 35 519	R/F WING PAINTING STAGE 2	10.0	41.67
99 51 548	RIGHT FRONT DOOR PAINTING STAGE 2	15.0	62.50

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

Paint Work

Code	Description - TWO COAT METALLIC	WU	Price SGD
99 52 548	R/R DOOR PAINTING STAGE 2	13.0	54.17
99 21 519	RIGHT B-PILLAR PAINTING STAGE 3	13.0	54.17
99 37 529	RIGHT SILL PAINTING STAGE 3	16.0	66.67
99 64 519	RIGHT SILL MOULDING PAINTING STAGE 2	13.0	54.17
99 36 529	R/R SIDE PANEL PAINTING STAGE 3	14.0	58.33
99 68 539	FRONT BUMPER PAINTING STAGE 3	36.0	150.00
99 69 539	REAR BUMPER PAINTING STAGE 3	37.0	154.17
KN	L/WASHER NOZZLE TRIM PAINTING STAGE 1	1.0	4.17
KN	R/WASHER NOZZLE TRIM PAINTING STAGE 1	1.0	4.17
99 35 520	L/F WING PAINTING STAGE 1	6.0	25.00
99 16 609	R/DOOR MIRROR PAINTING STAGE 1	1.0	4.17
99 21 609	R/R OUTER HANDLE PAINTING STAGE 1	1.0	4.17
L 2228	RIGHT A-PILLAR PAINTING STAGE 1	3.0	12.50
99 99 000	ADD/TIME FOR MAIN WORK	26.0	108.33

Time Basis 12WU/h

**Total Paint**

Hrs 17.20 WU 206.0 Price SGD 858.33

**Material Cost - Paint**

	Price SGD
New Part Painting	124.50
Repair Painting	148.83
Surface-/Blend Paint	18.63
Material-constant Metal	13.47
<b>Total</b>	<b>305.43</b>

**Spare Parts**

Code	Description	Part Number	Supplier	Price SGD
0742	R/F WING / <i>hmc</i>	41 35 7 111 430		500.00
1482	RIGHT FRONT DOOR / <i>M</i>	41 51 7 202 340		1,000.00
1488	R/F UPPER DOOR HINGE / <i>GT</i>	41 51 7 176 848		58.00
1496	R/F LOWER DOOR HINGE / <i>M</i>	41 51 7 176 850		58.00
1510	R/F DOOR SEAL / <i>MLC</i>	51 21 7 033 787		125.00
1548	R/F WINDOW REGULATOR / <i>NN</i>	51 33 7 184 384		370.00
1552	R/F WINDOW MOTOR / <i>NN</i>	67 62 6 981 142		330.00

prices as at 2018-09-10/02

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

Code	Description	Part Number	Supplier	Price SGD
1644	R/F DOOR TRIM FRAME	51 33 7 072 886	- MCC	210.00
1782	R/R DOOR / BT	41 52 7 202 342		1,000.00
1796	R/R LOWER DOOR HINGE / BT	41 52 7 200 246		58.00
1810	R/R DOOR SEAL / MCC	51 22 7 033 795		125.00
1836	R/QTR WINDOW FRAME	51 35 7 033 646	- MCC } NN	0.00
1837	QTR WINDOW SEAL KIT	83 19 2 289 285		0.00
1839	CLEANER R1 / MCC	83 19 2 211 217		0.00
1944	R/R DOOR TRIM FRAME	51 35 7 072 890	- MCC	210.00
2102	R/B-PILLAR SILL / BT	41 21 7 111 326		3,000.00
2172	RIGHT SILL MOULDING	51 77 7 178 126	- TV	400.00
2192	R/F SILL COVER - BT	51 47 7 034 304		95.00
2198	R/R SILL COVER X NN	51 47 7 034 306		95.00
3160	REAR SCREEN BOND KIT	83 19 2 289 285	<del>X MCC</del> } X NN	0.00
3162	CLEANER R1 RR SCREEN	83 19 2 211 217		0.00
3171	UP/COVER REAR SCREEN / MCC	51 31 7 027 916		95.00
3172	LOWER R/SCREEN TRIM	51 31 7 115 412	-	0.00
3482	R/R SIDE PANEL / TV	41 21 7 111 320		1,050.00
3508	R/SIDE PANEL REP KIT	USE SINGLE PARTS		
3512	R/S/PNL ADHESIVE K5A	83 19 2 158 654	} Repair.	0.00
3514	R/S/PNL ADHESIVE K5B	83 19 2 157 298		0.00
3516	R/S/PANEL CLEANER R1	83 19 2 211 217		0.00
3518	S/PNL STAMP RIVET N4	83 19 2 457 307		0.00
3520	S/PANEL B/RIVET N3	83 19 0 301 421		0.00
3521	SIDE PANEL GLUE SET	83 19 0 413 015		0.00
3524	R/SILL REINFORCEMENT	41 21 7 275 567		0.00
3526	R/C-PILLAR REINF	41 21 7 275 596	0.00	
3536	SIDE PANEL EMC SCREW	83 19 0 301 639	0.00	
7053	L/F TRACK CONT ARM	31 12 2 347 963	} BT	380.00
7071	L/F TENSION ROD	31 10 2 348 047		380.00
7077	L/F CPL SPRING STRUT	31 30 6 775 055		605.00
7081	L/F STEERING KNUCKLE	31 21 6 760 953	} Repair	610.00
7131	L/F WHEEL HUB	31 22 6 765 601		480.00
7201	L/F WHEEL	36 11 6 777 345	} Repair	0.00
7277	L/SWING SUPPORT	31 30 6 781 547		110.00
9552	R/R WHEEL	36 11 6 777 345	X repair	0.00
	<b>Savings</b>			0.00
	<b>Subtotal</b>			11,344.00
	<b>Addition (+10.00%)</b>			1,134.40
	+15%			

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts



**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFS10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM


Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

**Final Calculation**

	SGD	SGD
<b>Parts</b>		
Addition(+10.00%)	11,344.00	
<b>Total Parts</b>	1,134.40	<b>12,478.40</b>
<b>Labour Time Base 12 WU/h</b>		
Total 627.0 WU X 50.00 SGD/h	2,612.50	
Alignment		
Measuring Work	95.83	
<b>Total of Labour</b>		<b>2,708.33</b>
<b>Total Of Extras</b>		<b>1,680.00</b>
<b>Paint Work Time Base 12 WU/h</b>		
Labour Cost 206.0 WU X 50.00 SGD/h	858.33	
Material Cost	305.43	
<b>Total Paint Including Material</b>		<b>1,163.76</b>
<b>Repair Cost Excludes GST</b>		<b>18,030.49</b>
GST (+7.0%)		1,262.13
<b>Repair Cost Included GST</b>		<b>19,292.62</b>
<b>Deductions (Excludes GST)</b>		
<b>Total Of Deductions (Excludes GST)</b>		<b>-750.00</b>
<b>Grand Total Excludes GST</b>		<b>17,280.49</b>
GST (+7.0%)		1,209.63
<b>Grand Total Included GST</b>		<b>18,490.12</b>

**Comments**

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS



**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
Assessment number: KFS10030  
Version: 1810  
Date calculated: 03/01/2019 10:30 AM

Full Report  
Registration: SDV700A  
Printed: 01/03/2019 10:30 AM

---

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Ryan Kan	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-18
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

<b>Vehicle</b>			
Manufacturer:	BMW		
Model:	5-SERIES E60/61		
Sub Model:	523 I		
Model Sheet Number:	01 45 04		
Registration:	SDV700A		
VIN number:	WBANU12010CW24897		
Odometer:			
<b>Model Specs</b>			
FROM 09/2007	AIR CON AUTOMATIC	DIP/FOLD MIRROR	RADIO BUSINESS CD
XENON HEADLAMPS	HEADLAMP WASHERS	DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
FRT/RR DRINK HOLDER	RR SCREEN SUN BLIND	TRIM POPLAR WOOD	DIP REAR VIEW MIRROR
SOFT CLOSE AUTOMATIC	2.5 LTR 140 KW	6-SPEED AUTOMATIC	TYRES 225/55 WR 16
WHEELS 7J X 16 ALLOY	4-DOOR	PARK DISTANCE CONT	CHROME LINE
PEED CRUISE ONTROL	TWO COAT METALLIC		

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM


Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

**Vehicle Condition**

**Vehicle Status**  
 Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All   
 Underbody



**Labour**

Code	Description	Time Base 12 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
32 00 590	ELECTRONIC TRACK AND WHEEL ALIGNMENT CHECK (NOT INCLUDED: ADJUSTMENT AFTER REPAIR)		17.0	70.83
32 00 620	ADJUST REAR AXLE (TOE AND CAMBER) (TO WORK NO 32 00 590)		6.0	25.00
NO NUMBER	CONVERT CHASSIS JIG		14.0	58.33
NO NUMBER	CHASSIS JIG		18.0	75.00
41 35 000)	R + R R/F WING INCLUDES: R + R BUMPER, INDICATOR AND WHEELHOUSE COVER DOES NOT INCLUDE: R + R SILL MOULDING		17.0	70.83
51 13 501)	R + R L/FRONT GRILLE		1.0	4.17
51 13 501)	R + R R/FRONT GRILLE		1.0	4.17
41 11 925)	ADD/WORK: RENEW R/SILL PANEL AND CENTRE DOOR PILLAR		195.0	812.50
41 51 501	RENEW R/F DOOR (REMOVED)		38.0	158.33

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFS10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

Code	Description	WU	Price SGD
NO NUMBER	RENEW R/F LOWER DOOR HINGE	1.0	4.17
NO NUMBER	RENEW R/F UPPER DOOR HINGE	1.0	4.17
51 33 503)	RENEW WINDOW LIFT (ASS-WORK)	1.0	4.17
41 52 501	RENEW R/R DOOR (REMOVED)	42.0	175.00
NO NUMBER	RENEW R/R LOWER DOOR HINGE	1.0	4.17
1 35 111	RENEW R/R SIDE PANEL (PARTIAL REPAIR OF THE C-PILLAR) INCLUDES: R + R REAR SEAT, SEAT BACKREST, TAILGATE, REAR WINDOW, TAIL LAMP, BUMPER, BUMPER CARRIER, SILL MOULDING, LUGGAGE COMPARTMENT TRIM AND REAR DOOR	204.0	850.00
31 12 571	REPLACE LH FRONT SUSPENSION ARM (WITH SUSPENSION STRUT REMOVED)	2.0	8.33
36 11 505	R + R L/F WHEEL/TYRE	5.0	20.83
31 21 579	REMOVE/REFIT LH FRT WHEEL HUB (BEARING) (WITH BRAKE CALIPER AND BRAKE DISC REMOVED)	11.0	45.83
31 31 502	R + R LEFT FRONT SUSPENSION STRUT INCLUDES: R + R WHEEL AND PRESSURE ROD	13.0	54.17
31 31 501	REPLACE LH FRONT SUSPENSION STRUT (WITH SUSPENSION STRUT ASSEMBLY REMOVED)	4.0	16.67
31 35 501)	R + R L/FRT PRESSURE ROD	2.0	8.33
31 35 501)	R + R FRONT PRESSURE ROD	1.0	4.17
36 11 505	R + R R/R WHEEL/TYRE	5.0	20.83
478	PULLING R/SIDE ADDITIONAL WORK	10.0*	41.67
0283	FRONT BUMPER COVER REPAIR	20.0*	83.33
2583	REAR BUMPER COVER REPAIR	20.0*	83.33
	<b>Labour Cost</b>	<b>Hrs</b>	<b>WU</b>
	<b>Panel / Mechanical Labour</b>	52.30	627.0
	<b>Alignment</b>		
	<b>Measuring Work</b>	1.90	23.0
	<b>Total of Labour</b>		<b>2,708.33</b>

**Paint**

Code	Description - TWO COAT METALLIC	WU	Price SGD
99 35 519	R/F WING PAINTING STAGE 2	10.0	41.67
99 51 548	RIGHT FRONT DOOR PAINTING STAGE 2	15.0	62.50

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

Paint Work Code	Description - TWO COAT METALLIC	Time Basis 12WU/h	
		WU	Price SGD
99 52 548	R/R DOOR PAINTING STAGE 2	13.0	54.17
99 21 519	RIGHT B-PILLAR PAINTING STAGE 3	13.0	54.17
99 37 529	RIGHT SILL PAINTING STAGE 3	16.0	66.67
99 64 519	RIGHT SILL MOULDING PAINTING STAGE 2	13.0	54.17
99 36 529	R/R SIDE PANEL PAINTING STAGE 3	14.0	58.33
99 68 539	FRONT BUMPER PAINTING STAGE 3	36.0	150.00
99 69 539	REAR BUMPER PAINTING STAGE 3	37.0	154.17
KN	L/WASHER NOZZLE TRIM PAINTING STAGE 1	1.0	4.17
KN	R/WASHER NOZZLE TRIM PAINTING STAGE 1	1.0	4.17
99 35 520	L/F WING PAINTING STAGE 1	6.0	25.00
99 16 609	R/DOOR MIRROR PAINTING STAGE 1	1.0	4.17
99 21 609	R/R OUTER HANDLE PAINTING STAGE 1	1.0	4.17
L 2228	RIGHT A-PILLAR PAINTING STAGE 1	3.0	12.50
99 99 000	ADD/TIME FOR MAIN WORK	26.0	108.33

	Hrs	WU	Price SGD
<b>Total Paint</b>	<b>17.20</b>	<b>206.0</b>	<b>858.33</b>

	Price SGD
<b>Material Cost - Paint</b>	
New Part Painting	124.50
Repair Painting	148.83
Surface-/Blend Paint	18.63
Material-constant Metal	13.47
<b>Total</b>	<b>305.43</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2018-09-10/02	Price SGD
0742	R/F WING <i>hmc</i>	41 35 7 111 430			500.00
1482	RIGHT FRONT DOOR <i>M</i>	41 51 7 202 340			1,000.00
1488	R/F UPPER DOOR HINGE	41 51 7 176 848	<i>GT</i>		58.00
1496	R/F LOWER DOOR HINGE <i>M</i>	41 51 7 176 850			58.00
1510	R/F DOOR SEAL <i>MCC</i>	51 21 7 033 787			125.00
1548	R/F WINDOW REGULATOR <i>?</i>	51 33 7 184 384			370.00
1552	R/F WINDOW MOTOR <i>?</i>	67 62 6 981 142			330.00

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

Code	Description	Part Number	Supplier	Price SGD
1644	R/F DOOR TRIM FRAME	51 33 7 072 886	MCC	210.00
1782	R/R DOOR / BT	41 52 7 202 342		1,000.00
1796	R/R LOWER DOOR HINGE / BT	41 52 7 200 246		58.00
1810	R/R DOOR SEAL / MCC	51 22 7 033 795		125.00
836	R/QTR-WINDOW-FRAME	51-35-7-033 646	MCC	0.00
1837	QTR-WINDOW SEAL-KIT	83-19-2-289-285		0.00
1839	CLEANER-R1 / MCC	83-19-2-211-217		0.00
1944	R/R DOOR TRIM FRAME	51 35 7 072 890	MCC	210.00
2102	R/B-PILLAR SILL / BT	41 21 7 111 326		3,000.00
2172	RIGHT SILL MOULDING	51 77 7 178 126	TN	400.00
2192	R/F SILL COVER / BT	51 47 7 034 304		95.00
2198	R/R SILL COVER / X-M	51-47-7-034-306		95.00
3160	REAR-SCREEN-BOND-KIT	83-19-2-289-285	X-S	0.00
3162	CLEANER-R1-RR SCREEN	83-19-2-211-217	X-S	0.00
3171	UP/COVER REAR SCREEN / MCC	51 31 7 027 916		95.00
3172	LOWER-R/SCREEN-TRIM	51-31-7-115-412	R	0.00
3482	R/R SIDE PANEL / TN	41 21 7 111 320		1,050.00
3508	R/SIDE PANEL REP KIT	USE SINGLE PARTS		
3512	R/S/PNL-ADHESIVE-K5A	83-19-2-158-654		0.00
3514	R/S/PNL-ADHESIVE-K5B	83-19-2-157-298		0.00
3516	R/S/PANEL-CLEANER-R1	83-19-2-211-217		0.00
3518	S/PNL-STAMP-RIVET-N4	83-19-2-457-307		0.00
3520	S/PANEL-B/RIVET-N3	83-19-0-301-421		0.00
3521	SIDE-PANEL-GLUE-SET	83 19 0 413 015		0.00
3524	R/SILL-REINFORCEMENT	41-21-7-275-567		0.00
3526	R/C-PILLAR-REINF	41 21 7 275 596		0.00
3536	SIDE-PANEL-EMC SCREW	83-19-0-301-639		0.00
7053	L/F TRACK CONT ARM ?	31 12 2 347 963		380.00
7071	L/F TENSION ROD ?	31 10 2 348 047		380.00
7077	L/F CPL SPRING STRUT ?	31 30 6 775 055		605.00
7081	L/F STEERING KNUCKLE ?	31 21 6 760 953		610.00
7131	L/F WHEEL HUB ?	31 22 6 765 601		480.00
7201	L/F WHEEL / X-S	36-11-6-777-345		0.00
7277	L/SWING SUPPORT ?	31 30 6 781 547		110.00
9552	R/R-WHEEL / X-S	36 11 6 777 345		0.00

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

Savings  
 Subtotal  
 Addition (+10.00%)

0.00  
 11,344.00  
 1,134.40

7.15%

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

**Total** **12,478.40**

**Extras**

Code	Description	Price SGD
1000	RR WINDSCREEN GUM RWG / MEC.	40.00*
1001	R/F TYRE RFT X <sup>2/W</sup>	300.00*
1002	L/F WHEEL FLR / Cut	500.00*
1003	R/R WHEEL RRR / Cut	500.00*
1004	RR WINDSCREEN GUM RWG / MEC.	40.00*
1006	R/R TYRE RRT / Cut	210. 300.00*
<b>Total Extras</b>		<b>1,680.00</b>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To inspect damaged part(s) during resurvey
- To provide message to confirmation
- To be on a "Without Prejudice" basis
- To be notified during allowed
- To be notified when to be resurveyed and
- To be notified approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Not Authorized  
 Excess \$750  
~~before paint~~  
 lump sum repair.  
 After repair photos.

10 Days.  
 Eric Qian  
 82880282  
 06/3/19.

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 03/01/2019 10:30 AM

Full Report  
 Registration: SDV700A  
 Printed: 01/03/2019 10:30 AM

**Final Calculation**

	SGD	SGD
<b>Parts</b>	11,344.00	
Addition(+10.00%)	1,134.40	
<b>Total Parts</b>		<b>12,478.40</b>
<b>Labour Time Base 12 WU/h</b>		
Total 627.0 WU X 50.00 SGD/h	2,612.50	
Alignment		
Measuring Work	95.83	
<b>Total of Labour</b>		<b>2,708.33</b>
<b>Total Of Extras</b>		<b>1,680.00</b>
<b>Paint Work Time Base 12 WU/h</b>		
Labour Cost 206.0 WU X 50.00 SGD/h	858.33	
Material Cost	305.43	
<b>Total Paint Including Material</b>		<b>1,163.76</b>
<b>Repair Cost Excludes GST</b>		<b>18,030.49</b>
GST (+7.0%)		1,262.13
<b>Repair Cost Included GST</b>		<b>19,292.62</b>
<b>Deductions (Excludes GST)</b>		
<b>Total Of Deductions (Excludes GST)</b>		<b>-750.00</b>
<b>Grand Total Excludes GST</b>		<b>17,280.49</b>
GST (+7.0%)		1,209.63
<b>Grand Total Included GST</b>		<b>18,490.12</b>

**Comments**

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

**LIK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

*Revised*

**Claim Reference:**  
**Assessment number: KFSA10030**  
**Version: 1810**  
**Date calculated: 04/11/2019 01:16 PM**

**Full Report**  
**Registration: SDV700A**  
**Printed: 11/04/2019 1:16 PM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Ryan Kan	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-18
Estimated Repair Time:	10	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	BMW
Model:	5-SERIES E60/61
Sub Model:	523 I
Model Sheet Number:	01 45 04
Registration:	SDV700A
VIN number:	WBANU12010CW24897
Odometer:	

**Model Specs**

FROM 09/2007	AIR CON AUTOMATIC	DIP/FOLD MIRROR	RADIO BUSINESS CD
XENON HEADLAMPS	HEADLAMP WASHERS	DAKOTA LEATHER TRIM	ELEC/SEAT ADJ MEMORY
FRT/RR DRINK HOLDER	RR SCREEN SUN BLIND	TRIM POPLAR WOOD	DIP REAR VIEW MIRROR
SOFT CLOSE AUTOMATIC	2.5 LTR 140 KW	6-SPEED AUTOMATIC	TYRES 225/55 WR 16
WHEELS 7J X 16 ALLOY	4-DOOR	PARK DISTANCE CONT	CHROME LINE
SPEED CRUISE ONTROL	TWO COAT METALLIC		

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFS10030  
 Version: 1810  
 Date calculated: 04/11/2019 01:16 PM


Full Report  
 Registration: SDV700A  
 Printed: 11/04/2019 1:16 PM

**Vehicle Condition**

**Vehicle Status**  
 Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All   
 Underbody



**Labour**

Code	Description	Time Base 12 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
32 00 590	ELECTRONIC TRACK AND WHEEL ALIGNMENT CHECK (NOT INCLUDED: ADJUSTMENT AFTER REPAIR)		17.0	70.83
32 00 620	ADJUST REAR AXLE (TOE AND CAMBER) (TO WORK NO 32 00 590)		6.0	25.00
NO NUMBER	CONVERT CHASSIS JIG		14.0	58.33
NO NUMBER	CHASSIS JIG		18.0	75.00
41 35 000)	R + R R/F WING INCLUDES: R + R BUMPER, INDICATOR AND WHEELHOUSE COVER DOES NOT INCLUDE: R + R SILL MOULDING		17.0	70.83
51 13 501)	R + R L/FRONT GRILLE		1.0	4.17
51 13 501)	R + R R/FRONT GRILLE		1.0	4.17
41 11 925)	ADD/WORK: RENEW R/SILL PANEL AND CENTRE DOOR PILLAR		195.0	812.50
41 51 501	RENEW R/F DOOR (REMOVED)		38.0	158.33

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFS10030  
 Version: 1810  
 Date calculated: 04/11/2019 01:16 PM

Full Report  
 Registration: SDV700A  
 Printed: 11/04/2019 1:16 PM

Code	Description	WU	Price SGD
NO NUMBER	RENEW R/F LOWER DOOR HINGE	1.0	4.17
NO NUMBER	RENEW R/F UPPER DOOR HINGE	1.0	4.17
41 52 501	RENEW R/R DOOR (REMOVED)	42.0	175.00
NO NUMBER	RENEW R/R LOWER DOOR HINGE	1.0	4.17
41 35 111	RENEW R/R SIDE PANEL (PARTIAL REPAIR OF THE C-PILLAR) INCLUDES: R + R REAR SEAT, SEAT BACKREST, TAILGATE, REAR WINDOW, TAIL LAMP, BUMPER, BUMPER CARRIER, SILL MOULDING, LUGGAGE COMPARTMENT TRIM AND REAR DOOR	204.0	850.00
31 12 571	REPLACE LH FRONT SUSPENSION ARM (WITH SUSPENSION STRUT REMOVED)	2.0	8.33
36 11 505	R + R L/F WHEEL/TYRE	5.0	20.83
31 21 579	REMOVE/REFIT LH FRT WHEEL HUB (BEARING) (WITH BRAKE CALIPER AND BRAKE DISC REMOVED)	11.0	45.83
31 31 502	R + R LEFT FRONT SUSPENSION STRUT INCLUDES: R + R WHEEL AND PRESSURE ROD	13.0	54.17
31 31 501	REPLACE LH FRONT SUSPENSION STRUT (WITH SUSPENSION STRUT ASSEMBLY REMOVED)	4.0	16.67
31 35 501)	R + R L/FRT PRESSURE ROD	2.0	8.33
31 35 501)	R + R FRONT PRESSURE ROD	1.0	4.17
36 11 505	R + R R/R WHEEL/TYRE	5.0	20.83
1478	PULLING R/SIDE ADDITIONAL WORK	10.0*	41.67
0283	FRONT BUMPER COVER REPAIR	20.0*	83.33
2583	REAR BUMPER COVER REPAIR	20.0*	83.33
	<b>Labour Cost</b>	<b>Hrs</b>	<b>WU</b>
	<b>Panel / Mechanical Labour</b>	<b>52.20</b>	<b>626.0</b>
	<b>Alignment</b>		
	<b>Measuring Work</b>	<b>1.90</b>	<b>23.0</b>
	<b>Total of Labour</b>		<b>2,704.16</b>

**Paint**

Code	Description - TWO COAT METALLIC	WU	Price SGD
99 35 519	R/F WING PAINTING STAGE 2	10.0	41.67
99 51 548	RIGHT FRONT DOOR PAINTING STAGE 2	15.0	62.50
99 52 548	R/R DOOR PAINTING STAGE 2	13.0	54.17

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFSA10030  
 Version: 1810  
 Date calculated: 04/11/2019 01:16 PM

Full Report  
 Registration: SDV700A  
 Printed: 11/04/2019 1:16 PM

Paint Work		Time Basis 12WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
99 21 519	RIGHT B-PILLAR PAINTING STAGE 3	13.0	54.17
99 37 529	RIGHT SILL PAINTING STAGE 3	16.0	66.67
99 64 519	RIGHT SILL MOULDING PAINTING STAGE 2	13.0	54.17
99 36 529	R/R SIDE PANEL PAINTING STAGE 3	14.0	58.33
99 68 539	FRONT BUMPER PAINTING STAGE 3	36.0	150.00
99 69 539	REAR BUMPER PAINTING STAGE 3	37.0	154.17
KN	L/WASHER NOZZLE TRIM PAINTING STAGE 1	1.0	4.17
KN	R/WASHER NOZZLE TRIM PAINTING STAGE 1	1.0	4.17
99 35 520	L/F WING PAINTING STAGE 1	6.0	25.00
99 16 609	R/DOOR MIRROR PAINTING STAGE 1	1.0	4.17
99 21 609	R/R OUTER HANDLE PAINTING STAGE 1	1.0	4.17
L 2228	RIGHT A-PILLAR PAINTING STAGE 1	3.0	12.50
99 99 000	ADD/TIME FOR MAIN WORK	26.0	108.33

	Hrs	WU	Price SGD
<b>Total Paint</b>	<b>17.20</b>	<b>206.0</b>	<b>858.33</b>

	Price SGD
<b>Material Cost - Paint</b>	
New Part Painting	124.50
Repair Painting	148.83
Surface-/Blend Paint	18.63
Material-constant Metal	13.47
<b>Total</b>	<b>305.43</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2018-09-10/02	Price SGD
0742	R/F WING	41 35 7 111 430			500.00
1482	RIGHT FRONT DOOR	41 51 7 202 340			1,000.00
1488	R/F UPPER DOOR HINGE	41 51 7 176 848			58.00
1496	R/F LOWER DOOR HINGE	41 51 7 176 850			58.00
1510	R/F DOOR SEAL	51 21 7 033 787			125.00
1644	R/F DOOR TRIM FRAME	51 33 7 072 886			210.00
1782	R/R DOOR	41 52 7 202 342			1,000.00
1796	R/R LOWER DOOR HINGE	41 52 7 200 246			58.00

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFS10030  
 Version: 1810  
 Date calculated: 04/11/2019 01:16 PM

Full Report  
 Registration: SDV700A  
 Printed: 11/04/2019 1:16 PM

Code	Description	Part Number	Supplier	Price SGD
1810	R/R DOOR SEAL	51 22 7 033 795		125.00
1836	R/QTR WINDOW FRAME	51 35 7 033 646		0.00
1837	QTR WINDOW SEAL KIT	83 19 2 289 285		0.00
1839	CLEANER R1	83 19 2 211 217		0.00
1944	R/R DOOR TRIM FRAME	51 35 7 072 890		210.00
2102	R/B-PILLAR SILL	41 21 7 111 326		3,000.00
2172	RIGHT SILL MOULDING	51 77 7 178 126		400.00
2192	R/F SILL COVER	51 47 7 034 304		95.00
3160	REAR SCREEN BOND KIT	83 19 2 289 285		0.00
3162	CLEANER R1 RR SCREEN	83 19 2 211 217		0.00
3171	UP/COVER REAR SCREEN	51 31 7 027 916		95.00
3172	LOWER R/SCREEN TRIM	51 31 7 115 412		0.00
3482	R/R SIDE PANEL	41 21 7 111 320		1,050.00
3508	R/SIDE PANEL REP KIT	USE SINGLE PARTS		
3512	R/S/PNL ADHESIVE K5A	83 19 2 158 654		0.00
3514	R/S/PNL ADHESIVE K5B	83 19 2 157 298		0.00
3516	R/S/PANEL CLEANER R1	83 19 2 211 217		0.00
3518	S/PNL STAMP RIVET N4	83 19 2 457 307		0.00
3520	S/PANEL B/RIVET N3	83 19 0 301 421		0.00
3521	SIDE PANEL GLUE SET	83 19 0 413 015		0.00
3524	R/SILL REINFORCEMENT	41 21 7 275 567		0.00
3526	R/C-PILLAR REINF	41 21 7 275 596		0.00
3536	SIDE PANEL EMC SCREW	83 19 0 301 639		0.00
7053	L/F TRACK CONT ARM	31 12 2 347 963		380.00
7071	L/F TENSION ROD	31 10 2 348 047		380.00
7077	L/F CPL SPRING STRUT	31 30 6 775 055		605.00
7081	L/F STEERING KNUCKLE	31 21 6 760 953		610.00
7131	L/F WHEEL HUB	31 22 6 765 601		480.00
7201	L/F WHEEL	36 11 6 777 345		0.00
7277	L/SWING SUPPORT	31 30 6 781 547		110.00
9552	R/R WHEEL	36 11 6 777 345		0.00
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			10,549.00
u: Used parts	<b>Addition(+15.00%)</b>			1,582.35
	<b>Total</b>			<b>12,131.35</b>

**Extras**

Code	Description	Price SGD
1000	RR WINDSCREEN GUM RWG	40.00*

**Kan Fook Sing Motor Workshop**  
**61 Defu Lane 12**  
**539147**

Claim Reference:  
 Assessment number: KFS10030  
 Version: 1810  
 Date calculated: 04/11/2019 01:16 PM

Full Report  
 Registration: SDV700A  
 Printed: 11/04/2019 1:16 PM

Code	Description	Price SGD
1001	R/F TYRE RFT	210.00*
1002	L/F WHEEL FLR	500.00*
1003	R/R WHEEL RRR	500.00*
1004	RR WINDSCREEN GUM RWG	40.00*
1006	R/R TYRE RRT	210.00*
	<b>Total Extras</b>	<b>1,500.00</b>

**Final Calculation**

	SGD	SGD
<b>Parts</b>	10,549.00	
Addition(+15.00%)	1,582.35	
<b>Total Parts</b>		<b>12,131.35</b>
<b>Labour Time Base 12 WU/h</b>		
Total 626.0 WU X 50.00 SGD/h	2,608.33	
Alignment		
Measuring Work	95.83	
<b>Total of Labour</b>		<b>2,704.16</b>
<b>Total Of Extras</b>		<b>1,500.00</b>
<b>Paint Work Time Base 12 WU/h</b>		
Labour Cost 206.0 WU X 50.00 SGD/h	858.33	
Material Cost	305.43	
<b>Total Paint Including Material</b>		<b>1,163.76</b>
<b>Repair Cost Excludes GST</b>		<b>17,499.27</b>
GST (+7.0%)		1,224.95
<b>Repair Cost Included GST</b>		<b>18,724.22</b>
<b>Deductions (Excludes GST)</b>		
<b>Total Of Deductions (Excludes GST)</b>		<b>-750.00</b>
<b>Grand Total Excludes GST</b>		<b>16,749.27</b>
GST (+7.0%)		1,172.45
<b>Grand Total Included GST</b>		<b>17,921.72</b>

**Kan Fook Sing Motor Workshop  
61 Defu Lane 12  
539147**

**Claim Reference:**

**Assessment number: KFSA10030**

**Version: 1810**

**Date calculated: 04/11/2019 01:16 PM**

**Full Report**

**Registration: SDV700A**

**Printed: 11/04/2019 1:16 PM**

---

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Feb 2019 14:08 <a href="#">Sendback Est</a>	01 Mar 2019 10:34 <b>S\$18,030.49</b>	04 Mar 2019 08:32 <a href="#">Edit Adj Rpt</a>	<b>S\$11,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$11,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	CHOO BOON PENG, ID: S1380884H, Tel: +6596336363, Email: NOEMAIL								
Vehicle Reg. No.:	SDV700A	Date of Loss:	18/02/2019 16:00 - :59 [133 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 585575	Policy/Cover Note No.:	80075483SMP (Comprehensive) Coverage: 29/12/2018 - 28/12/2019						
		Excess:	S\$750.00						
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Nor Azian Binte Noordin - 6594 2558]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/04/2019]								
Driver/Custodian:	CHOO BOON PENG (59 / Male), NRIC: S1380884H, Tel: +6596336363 Email: NOEMAIL								
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Pls revert								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>MSIG_SG (05/03/2019): Alert - Adj Mandate Approved (S\$11400.00) - SDV700A - Claim Handler: Nor Azian B...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SDV700A (585575)  
OD  
Feb 18 2019 4:00PM  
[CHOO BOON PENG]  
Kan Fook Sing Motor Workshop

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View	View in Browser
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	19/02/19 18:38	<b>National Assessment Centre Services (Ubi)</b> <b>Accident Statement</b>	 Load HTM	<input type="checkbox"/>
No	Finalized On	<b>Kan Fook Sing Motor Workshop (Defu)</b>	Thumbnail	Print
1	01/03/19 10:34	<b>Repairer Estimates</b>	 Load HTM	<input type="checkbox"/>
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	05/03/19 14:59	<b>Adjuster Immediate Advice</b>	 Load HTM	<input type="checkbox"/>
2	05/03/19 15:52	<b>Adjuster Immediate Advice</b>	 Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	19/02/19 18:36	<b>National Assessment Centre Services (Ubi)</b> <b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
2	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
3	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
4	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
5	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
6	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
7	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
8	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
9	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
10	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
11	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
12	19/02/19 18:36	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	05/03/19 09:25	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
15	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
52	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
53	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
54	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
55	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
56	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
57	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
58	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
59	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
60	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
61	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
62	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
63	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>
64	05/03/19 09:25	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
65	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
66	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
67	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
68	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
69	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
70	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
71	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
72	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
73	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
74	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
75	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
76	05/03/19 09:25	General View		<input checked="" type="checkbox"/>
77	05/03/19 09:25	Chassis Number		<input checked="" type="checkbox"/>
78	05/03/19 09:25	Odometer Reading		<input checked="" type="checkbox"/>
79	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
80	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
81	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
82	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
83	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
84	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
85	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
86	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
87	12/04/19 09:33	Dismantled Parts		<input checked="" type="checkbox"/>
88	15/04/19 13:20	Photo After Spray		<input checked="" type="checkbox"/>
89	15/04/19 13:20	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/02/19 14:54	COE / PARF Value		<input type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	28/02/19 14:09	E-filed GIA report		<input type="checkbox"/>
2	01/03/19 10:35	Audatex report		<input type="checkbox"/>
3	25/04/19 17:47	Repairer's Bill		<input type="checkbox"/>
4	25/04/19 17:47	Signed DV		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/19 15:01	Estimate		<input type="checkbox"/>

### Linked Accident Report Documents

View 

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	19/02/19 18:38	Accident Statement		<input type="checkbox"/>
2	27/02/19 10:34	Addendum Sheet		<input checked="" type="checkbox"/>
3	27/02/19 10:34	Accident Statement Addm. #1		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	19/02/19 18:36	Accident Photo		<input checked="" type="checkbox"/>
2	19/02/19 18:36	Accident Photo		<input checked="" type="checkbox"/>
3	19/02/19 18:36	Accident Photo		<input checked="" type="checkbox"/>
4	19/02/19 18:36	Accident Photo		<input checked="" type="checkbox"/>
5	19/02/19 18:36	Accident Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
6	19/02/19 18:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	19/02/19 18:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	19/02/19 18:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	19/02/19 18:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	19/02/19 18:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	19/02/19 18:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	19/02/19 18:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	19/02/19 18:36	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	19/02/19 18:36	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	19/02/19 18:36	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	19/02/19 18:36	Police Report	 Load JPG	<input checked="" type="checkbox"/>
5	19/02/19 18:36	Police Report	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p><b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG19003934/GTD3E2

**Date:** 07/05/2019

#### REFERENCE

Insured/Claimant:	CHOO BOON PENG	Policy No:	80075483SMP	
Date of Loss:	18/02/2019	Nature of Claim:	OD	Claim No: 585575

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDV700A			
Make & Model:	BMW 523i, 2.5 XL (A)	Engine No:	71314155N52B25AE	
Reg. Date:	29/12/2007 (Man. Year: 2007)	Chassis No:	WBANU12010CW24897	
Colour:	Grey	Odometer:	134719 km	
Engine Capacity:	2497 cc			
Market Value/New Car Price:	S\$58,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,478.40	12,131.35	347.05	2.78
Miscellaneous Items	1,680.00	1,500.00	180.00	10.71
Paintwork Materials	305.43	305.43	0.00	0.00
Labour	2,708.33	2,704.16	4.17	0.15
Paintwork Labour	858.33	858.33	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,030.49</b>	<b>17,499.27</b>	<b>531.22</b>	<b>2.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,400.00</b>		
<b>- Excess (S\$)</b>	750.00	750.00	0.00	0.00
<b>(S\$)</b>	17,280.49	10,650.00	6,630.49	38.37
<b>+ GST 7.00/7.00% (S\$)</b>	1,209.63	745.50	464.13	38.37
<b>Nett Amount (S\$)</b>	<b>18,490.12</b>	<b>11,395.50</b>	<b>7,094.62</b>	<b>38.37</b>

#### INSPECTION

Date of Assignment:	04/03/2019 Present Location:	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	04/03/2019 Inspected At:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12 Singapore 539147
Estimated Period of Repair:	10.0 days	

---

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
<b>Parts:</b> 143	BMW 523I 2.5 XL (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SDV700A)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts (WCP)		12,478.40 F	*10,549.00 F
					<b>Sub Total (S\$)</b>	<b>12,478.40</b>
					<b>+ Margin on L,N Items 0.00/15.00% (S\$)</b>	<b>1,582.35</b>
					<b>Total Parts (S\$)</b>	<b>12,131.35</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork Materials	305.43	305.43
<u>Miscellaneous Items</u>				
2	1	Miscellaneous	1,680.00	1,500.00
<b>Sub Total (S\$)</b>			<b>1,985.43</b>	<b>1,805.43</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Spraypainting charges	New	858.33	858.33
<u>Labour Items</u>				
2	Labour charges	New	2,708.33	2,704.16
<b>Gross Labour Cost (S\$)</b>			<b>3,566.66</b>	<b>3,562.49</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;