

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19003950/KGA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHB9831D	Insured Vehicle No :	SHA1241P
Date of Loss: 25/02/2019	Nature of Claim: TP	Claim No: MCT19020748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9831D		
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Engine No:	M9R8839C000323
Reg. Date:	20/08/2013 (Man. Year: 2013)	Chassis No:	VF1ABL15AUC273328
Colour:	Metallic White/Red	Odometer:	0 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 4 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	92,068.15	41,407.99	50,660.16	55.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,130.00	3,650.00	15,480.00	80.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	111,198.15	45,057.99	66,140.16	59.48
Approved Total (Overridden) (\$\$)		10,000.00		
(\$\$)	111,198.15	10,000.00	101,198.15	91.01
+ GST 7.00/7.00% (\$\$)	7,783.87	700.00	7,083.87	91.01
Nett Amount (\$\$)	118,982.02	10,700.00	108,282.02	91.01
+ Loss of Use (6.0 x S\$40.00/day) (\$\$)		240.00		
+ Car Rental (16.0 x S\$95.04/day) (\$\$)		1,520.64		
Nett Liability (\$\$)		12,460.64		
Global Sum Settlement (\$\$)		12,400.00		

INSPECTION

Date of Assignment:	01/03/2019	
Date Inspected:	01/03/2019 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2020)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB9831D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER FRT	Bent / Cracked	1,259.42 FL	*1,259.42 FL
2	1	*BUMPER SPOILER FRT	Distorted	181.75 FL	*181.75 FL
3	1	*BUMPER ABSORBER FRT	Cracked	394.68 FL	*394.68 FL
4	1	*BUMPER RETAINER FRT LH	Cracked	151.41 FL	*151.41 FL
5	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1	*BUMPER RETAINER FRT RH	Cracked	150.77 FL	*150.77 FL
7	1	*BUMPER SUPPORT FRT	Distorted	123.88 FL	*123.88 FL
8	1	*BUMPER UNDERTRAY FRT	Cracked	472.83 FL	*472.83 FL
9	1	*BUMPER GRILLE LOWER FRT	Distorted	266.80 FL	*266.80 FL
10	1	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
11	1	*BUMPER FOG LAMP GRILLE RH	Cracked	207.21 FL	*207.21 FL
12	1	*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
13	1	*TOW COVER FRT	Dented	28.61 FL	*28.61 FL
14	1	*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
15	1	*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
16	1	*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
17	1	*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
18	1	*FRAME FULL SUPPORT BRACKET	Distorted	89.79 FL	*89.79 FL
19	1	*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
20	1	*HORN	Serviceable	314.17 FL	*- FL
21	1	*HORN BRACKET	Repair	40.45 FL	*- FL
22	1	*HEADLAMP LH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
23	1	*HEADLAMP HARNESS	Serviceable	928.29 FL	*- FL
24	1	*HEADLAMP RH	Broken	1,184.43 FL	*1,184.43 FL
25	1	*HEADLAMP HARNESS	Serviceable	928.29 FL	*- FL
26	1	*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
27	1	*HEADLAMP PANEL FRT RH	Bent	152.15 FL	*152.15 FL
28	1	*BONNET	Bent	1,941.63 FL	*1,941.63 FL
29	1	*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
30	1	*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
31	1	*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
32	1	*BONNET HINGE LH	Distorted	348.31 FL	*348.31 FL
33	1	*BONNET HINGE RH	Distorted	348.31 FL	*348.31 FL
34	1	*BONNET LOCK	Repair	305.48 FL	*- FL
35	1	*BONNET CABLE	Serviceable	119.19 FL	*- FL
36	1	*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
37	1	*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
38	1	*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
39	1	*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
40	1	*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
41	1	*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
42	1	*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
43	1	*FENDER PANEL INNER FRT RH L70Y	Repair	1,654.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FENDER PANEL SUPPORT FRT RH L70Y	Repair	1,095.24 FL	*- FL
45	1		*FENDER PANEL BRACKET FRT RH L70Y	Repair	209.97 FL	*- FL
46	1		*FENDER PANEL BRACKET FRT RH L70Y	Repair	143.27 FL	*- FL
47	1		*WHEEL HOUSING PANEL FRT RH L70Y	Repair	4,682.09 FL	*- FL
48	1		*WIPER RESERVOIR	Dented	348.25 FL	*348.25 FL
49	1		*WIPER RESERVOIR NECK	Dented	136.11 FL	*136.11 FL
50	1		*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
51	1		*AIR CLEANER BOX	Serviceable	271.26 FL	*- FL
52	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*- FL
53	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
54	1		*TURBO DUCT	Serviceable	1,027.80 FL	*- FL
55	1		*A/C HEATER VALVE	Serviceable	484.50 FL	*- FL
56	1		*SUBFRAME OUTER FRT	Bent	2,652.45 FL	*2,652.45 FL
57	1		*SUBFRAME BRACKET OUTER LH	Repair	92.36 FL	*- FL
58	1		*SUBFRAME BRACKET OUTER RH	Distorted	92.36 FL	*92.36 FL
59	1		*ENGINE UNDERTRAY	Serviceable	564.98 FL	*- FL
60	1		*A/C CONDENSER	Punctured	2,020.37 FL	*2,020.37 FL
61	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*- FL
62	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*- FL
63	1		*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*- FL
64	1		*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*- FL
65	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
66	1		*A/C PIPE CONDENSER TO EXPENSION VALVE	Serviceable	658.72 FL	*- FL
67	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
68	1		*A/C PIPE	Serviceable	658.72 FL	*- FL
69	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
70	1		*AIR COOLER	Serviceable	792.60 FL	*- FL
71	1		*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
72	1		*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
73	1		*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
74	1		*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*- FL
75	1		*RADIATOR	Not Necessary	1,202.20 FL	*- FL
76	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
77	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
78	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
79	1		*RADIATOR FAN COWLING	Not Necessary	820.54 FL	*- FL
80	1		*RADIATOR FAN MOTOR LH	Not Necessary	967.36 FL	*- FL
81	1		*RADIATOR FAN MOTOR RH	Not Necessary	1,479.46 FL	*- FL
82	1		*RADIATOR TANK	Dented	324.62 FL	*324.62 FL
83	1		*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*- FL
84	1		*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*- FL
85	1		*RADIATOR TANK HOSE	Serviceable	61.18 FL	*- FL
86	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
87	1		*INJECTION COMPUTER	Serviceable	4,706.30 FL	*- FL
88	1		*RHD HYDRAULIC POWER (ROCK & PINION)	Not Necessary	5,154.52 FL	*- FL
89	1		*STEERING PUMP ELECTRIC	Serviceable	2,306.90 FL	*- FL
90	1		*STEERING PINION RACK	Serviceable	4,413.11 FL	*- FL
91	1		*SEATBELT LH L70Y	Jammed	2,937.80 FL	*2,937.80 FL
92	1		*SEATBELT RH L70Y	Jammed	2,925.37 FL	*2,925.37 FL
93	1		*SEATBELT BUCKLE LH L70Y	Serviceable	984.13 FL	*- FL
94	1		*SEATBELT BUCKLE RH L70Y	Serviceable	949.80 FL	*- FL
95	1		*PASSENGER AIRBAG L70Y	Burnt	3,412.40 FL	*3,412.40 FL
96	1		*STEERING AIRBAG L70Y	Burnt	2,525.75 FL	*2,525.75 FL
97	1		*AIRBAG COMPUTER L70Y	Necessary	1,259.82 FL	*1,259.82 FL
98	1		*AIRBAG SENSOR L70Y	Necessary	724.63 FL	*724.63 FL
99	1		*AIRBAG SENSOR L70Y	Necessary	289.30 FL	*289.30 FL
100	1		*DASHBOARD L70Y	Torn	4,900.54 FL	*4,900.54 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
101	1		*WINDSCREEN FRT L70Y	Cracked	1,364.06 FL	*1,364.06 FL
102	1		*AIRBAG COMPUTER L70Y	Serviceable	1,259.82 FL	*- FL
103	1		*AIRBAG SENSOR L70Y	Serviceable	724.63 FL	*- FL
104	1		*AIRBAG SENSOR L70Y	Serviceable	289.30 FL	*- FL
105	1		*LOWER ARM RH L70Y	Bent	685.76 FL	*685.76 FL
106	1		*KNUCKLE ARM RH L70Y	Bent	846.98 FL	*846.98 FL
107	1		*ABSORBER FRT RH L70Y	Bent	360.54 FL	*360.54 FL
108	1		*FRONT RIGHT DOOR PANEL	Bent	2,844.66 FL	*2,844.66 FL
109	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
110	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
111	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
112	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
113	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
114	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
115	1		*TOW COVER FRT	Not Necessary	14.50 FS	*- FS
116	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
117	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
118	1		*SET FRAME CLIP SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
119	2		*FRAME CLIP SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
120	2		*FRAME CLIP SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
121	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
122	1		*SET FRONT LICENCE PLATE WITH HOLDER	Dented	80.00 FS	*25.00 FS
123	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
124	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
125	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
126	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
127	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
128	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
129	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
130	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS
131	1		*WINDSCREEN SEALANT	Necessary	253.80 FS	*40.00 FS
132	1		*FRONT RIGHT TYRE (60%)	Punctured	300.00 FS	*180.00 FS
133	1		*FRONT RIGHT TYRE RIM	Bent	380.00 FS	*380.00 FS
134	1		*FRONT RIGHT FENDER ADVERTISEMENT STICKER	Necessary	300.00 FS	*150.00 FS
135	1		*FRONT RIGHT DOOR ADVERTISEMENT STICKER	Necessary	300.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 102,053.73 45,881.88
- List Item Discount on L Items 10.00/10.00% (\$\$) 9,985.58 4,473.89

Total Parts (\$\$) 92,068.15 41,407.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	1,000.00
2	TOWING FEES	New	120.00	50.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	1,320.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	120.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
8	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK }	New	380.00	250.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR }	New	380.00	0.00
10	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT	New	440.00	250.00
11	TO REMOVE AND RENEW POWER STEERING PUMP ,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
12	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET	New	480.00	200.00
13	TO DROP DIESEL TANK ,PIPES ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING	New	380.00	0.00
14	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR CONDENSER	New	380.00	100.00
15	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	50.00
16	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	50.00
17	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
18	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
19	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
20	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING	New	380.00	0.00
21	TO DISMANTLE AND REFIT ENGINE CROSS -MEMBER AND ENGINE MOUNTING	New	380.00	0.00
22	TO REMOVE AND RENEW POWER STEERING PUMP OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
23	TO CHECK ABS BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
24	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR	New	380.00	0.00
25	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	20.00
Gross Labour Cost (\$\$)			19,130.00	3,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >