



TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

Not Authorised
24th Nov 2018
Shingheo Be for party
EUROKARS GROUP
3rdy
7/3/18

LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER SINGAPORE 189702 ATTN. : MOTOR CLAIMS FAX :		NAME : Ms Tan Chen Hoon ADDRESS : 816 Jellicoe Road #15-06 Singapore 200816 TEL : 90478290		WIP : 44869 EXCESS : DATE : 1-Mar-19	
VEH NO :	SMH2767L	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BN24A8K0251716	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3	DATE REG.:	17-Jan-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES	
1	1	REAR BUMPER MB63B-50-221ABB	DS	\$ 949.20	✓
2	1	RETAINER LHS MBHN9-50-2J1C	SM	\$ 35.60	✓
3	1	BRACKET LHS MBHN9-51-077B		\$ 45.60	?
4	1	BRACKET CENTER MKD53-50-251		\$ 5.10	?
5	1	PROTECTOR CENTER, REAR BUMPER MBHN9-50-369		\$ 56.00	?
6	1	COVER LOWER LHS, REAR BUMPER MB63D-50-371	M.S	\$ 29.10	✓
7	1	REAR REINFORCEMENT MB45C-50-260	R	\$ 537.30	X
8	1	SHIELD SPLASH LHS MBHN9-50-350C	11	\$ 77.60	X
9	1	REFLECTOR LHS MD350-51-5L0E	520	\$ 50.40	✓
10	4	GROMMET, REAR BUMPER MBHN1-50-0Z1A	24	\$ 10.00	✓
11	10	RIVET, REAR BUMPER MBBM4-50-355	24	\$ 42.00	✓
12	2	RIVET, REAR BUMPER MEA01-50-037	24	\$ 15.20	✓
13	2	CLIP, REAR BUMPER MBGV4-56-145	24	\$ 5.40	✓
14	2	GROMMET, REAR BUMPER M9991-00-501	24	\$ 5.60	✓
15	1	REAR END PANEL MB4YC-70-75ZA	R	\$ 624.70	X
16	1	PANEL LOWER LHS, REAR FENDER MB4YC-71-40X	11	\$ 354.40	X
17	1	EXTRACTOR VENT LHS MD350-51-920A	11	\$ 71.30	X
18	1	TRIM, END PANEL MBHN9-68-89X	11	\$ 95.90	X
19	5	FASTENER, TRIM MGJ21-68-885B02	11	\$ 14.00	X
20	1	TAILGATE MBHY3-62-02XA	11	\$ 1,268.70	X
21	1	GROMMET, FINISHER TAILGATE MBHN9-50-ES1	11	\$ 2.70	X
22	4	CLIP, FINISHER TAILGATE MBHY1-51-0A6A	11	\$ 38.40	X
23	1	CLIP, FINISHER TAILGATE MKD53-51-0B6B	11	\$ 2.50	X
24	3	CLIP, FINISHER TAILGATE MKD53-51-0B6B	11	\$ 7.50	X
25	2	FASTENER, FINISHER TAILGATE MBHN9-50-EA1	11	\$ 5.40	X
26	1	GASKET LHS, TAILGATE LAMP MB45C-51-3J8	11	\$ 20.90	X
27	1	GASKET RHS, TAILGATE LAMP MB45C-51-3H8	11	\$ 20.90	X
28	1	GASKET LHS, TAILLAMP MBHP1-51-163	24	\$ 20.90	✓
29	1	GASKET RHS, TAILLAMP MBHP1-51-153	12C	\$ 20.90	✓
30	1	MASCOT, REAR MBHN9-51-730	11	\$ 74.40	X

31	REAR WINDSCREEN MOULDING	1	MBHN9-50-614F	17	\$	47.50	X
32	SPACER, REAR WINDSCREEN	1	MGJ6A-50-897	17	\$	12.10	X
33	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	17	\$	5.20	X
34	FASTENER, REAR WINDSCREEN	2	MBHS2-50-896	17	\$	17.40	X
35	GUARD STONE LHS	1	MBHS2-50-4R2	17	\$	16.50	X
TOTAL PARTS						\$	4,606.30
LESS 10%						\$	460.63
TOTAL PARTS COST						\$	4,145.67
Labour Description							
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL LOWER LH AND TAILGATE. TO REPAIR REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.			660	\$	4,290.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL LOWER LH, REAR FENDER LH AND TAILGATE.			1260	\$	3,150.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			17 X	NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			17 X	NETT	\$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.			17 X		\$ 330.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)			200	NETT	\$ 330.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.			17 X		\$ 330.00
8	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.			17 X		\$ 990.00
9	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING			17 X		\$ 350.00
10	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			17 X		\$ 250.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120		\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			150		\$ 350.00
13	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.			17 X	NETT	\$ 120.00
14	MZ-BR-SUNDRI	SUNDRIES.			17 X	NETT	\$ 100.00
					TOTAL LABOUR	\$ -	\$ 11,520.00
					TOTAL PARTS	\$ -	\$ 4,145.67
					TOTAL	\$ -	\$ 15,665.67
					LESS EXCESS	\$ -	\$ -

TOTAL AFTER EXCESS	\$	-	
GST 7%	\$	-	\$ -
GRAND TOTAL	\$	-	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: