

ASS. REC. BY:

REF:

CS/MSG1 9004011/U943/12 Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time:

05/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 606C

Insured:

GBD7998E

at Workshop m/s

FOCUS AUTO

Tel:

68869097

of

CARI BUILT

Policy No:

29080980MCC

Claim No:

586723

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp1

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

() Estimate

GBE 606C x

GBD7998E x

06/3/19 @ 12.20pm informed Monica Chung, we are pending estimate from repairs.

18/3/19 @ 1.38pm revised to Monica Chung via Memo.

108/11/13) wef

ASS. REC. BY: Marcus

REF:

MSIAW ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 27310

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/3/19 L/S 7200 confirmed with driver way. (Red 69422.18, 57%)

RECEIVED 18 MAR 2019

[Signature]

15/3/2019

Date/Time, File Pass to?

☐

: Preli. Report

15/3/19

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

200
10

210

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 18 Mar 2019

Preliminary Advice

Insured Vehicle No	: GBD7998E	Accident Date	: 01/03/2019
TP Vehicle No	: GBE606C	Assignment Date	: 05/03/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 8.00
Date of Inspection	: 05/03/2019		
Inspection At	: FOCUS AUTO PTE LTD (KAKI BUKIT) NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-50 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,622.28
Revised Amount	:S\$	9,005.63
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,005.63
Lump Sum Repair	:S\$	7,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2019		05 Mar 2019 10:13 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SME PRINTING & OFFICE SUPPLIES PTE LTD , Co. Reg. No.: 201205412E		[Created by insurer]
Main Claimant:	SPECIALIST STATIONERY PTE LTD , Co. Reg. No.: 200207995Z		
Vehicle Reg. No.:	GBE606C	Date of Loss:	01/03/2019 15:00 - :59 [42 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29080980MKC (Comprehensive) Coverage: 09/05/2018 - 08/05/2019
Vehicle Reg. No. (Insured):	GBD7998E	Policy No. (Claimant):	
		Excess:	
Repairer:	Focus Auto Pte Ltd (Kaki Bukit) NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-50, 417883 Kaki Bukit - Tel: 68869097		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/03/2019]		
Driver/Custodian (Insured):	QU ZHIFENG (28 / Male) , NRIC: G8645518N Email:		
Adj Asg. Remarks:	ON WP, car in. Please contact us ASAP if you cannot attend this assignment. LIAB 100%. PLS CONTACT LAU LC @ 6886 9097		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(1)

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 6 March 2019 12:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE GBE 606C (YOUR REF: 586723)

This mail is associated with :
***GBE606C (586723)**
[GBD7998E]
TP
SPECIALIST STATIONERY PTE LTD
Mar 1 2019 3:00PM
[SME PRINTING & OFFICE SUPPLIES PTE LTD]
Focus Auto Pte Ltd

Dear Monica,

Please be informed that we have inspected the vehicle GBE 606C on 05/03/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

dealers
competed to
buy my car!



Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR



Toyota Price Range Depreciation 2015 Van

Home » Used Cars » Breaking Point » Toyota Hiace

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Hiace

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Issue

More Account

Share

Price \$49,800

Depreciation \$7,690 /yr
View models with similar depreciation

Reg Date 21-Aug-2015
(6yrs 5mths 18days COE left)

Manufactured 2014

Mileage -

Transmission Manual

Engine Cap 2,982 cc

Curb Weight 1,740 kg

Fuel type Diesel

Features -

Accessories -

Description Superb Condition! Well Maintained By One Owner Only!
Power And Comfort All In One! Beauty! Very Rare In
The Market! Well Maintained By Previous Owner!

COE \$50,001

OMV \$27,502

ARF \$1,376

Dereg Value \$32,371 as of today (change)

No. of Owners 1

Type of Veh Van

Category Premium Ad Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 07-Feb-2019 | Last Updated on: 12-Feb-2019

Tags: Toyota Hiace, toyota hiace, 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, hiace, Used Toyota

Estimated Payments

Transfer Fee \$25

Down Payment \$4,980 (change) (Maximum 30% Loan)

1st Instalment \$709

Total Upfront Payment \$5,714 (excluding insurance)

Estimates based on 99% loan at 3.4% interest rate. Check with seller for exact figure.

Items for Toyota Hiace

View All

Rear Book Mirror
From \$95



Rear Compact Aircon
Fan Blower
\$200



Price Analysis

Company

Breaking Point

= dealer's pricelist

= 6 vehs sold | 11 vehs available

Address

252 Jurong East Street 24 #03-127

Search cars nearby this location

Office No

65614858

Contact Person(s)

Alex Gan

87972000

Useful Services



Afraid of lemons? Request to have
this car evaluated professionally.



Find out the market value for your car.
Get a free Car Valuation.

Free Valuation



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Reg Dec 2013:



Mazda CX-5.
Direct Owner StarAd

Browse by Category Sort by Date Posted 20 results/page

13 vehicles

TOYOTA HIACE

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	TOYOTA HIACE		Any	Any	2015	Any	Any	Any	Available
	Toyota Hiace		\$56,800	\$8,460 /yr	19-Nov-2015	2,982 cc	-	Van	Available
	Fuel Type: Diesel Good Condition, Well Maintained, Low Mileage, Smooth Engine.								
	Posted: 05-Mar-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace		\$50,800	\$7,620 /yr	02-Nov-2015	2,982 cc	-	Van	Available
	Fuel Type: Diesel PRICE REVISED. 1 Owner! Rear Aircon Unit! More Than 100 Units Of Brand New & Preowned Available! Guaranteed One Of The Cheapest! Agent Unit! Servicing Done Regularly! Wear & Tears Replaced Regularly! ...								
	Car (S) Pte Ltd Posted: 05-Mar-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace		\$44,800	\$7,490 /yr	24-Feb-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Lowest Depreciation In Town. Super Good Condition. Regular Servicing Done With Service Record Proven. New Paintwork And Well Kept. Call And View Now Before You Miss It.								
	ABWIN Bus Pte Ltd Posted: 02-Mar-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace Commuter		\$59,800	\$9,650 /yr	15-May-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Please Call To Arrange For Viewing, Thanks								
	Posted: 01-Mar-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Otocar Jet Auto Service Pte Ltd - Repair & Servicing At Otocar Jet Auto, they are committed to care for your cars and service, customers satisfaction is our top priority. More info about this shop								
	Toyota Hiace Commuter		\$58,800	\$8,670 /yr	14-Dec-2015	2,982 cc	17,300 km	Bus	Available
	Fuel Type: Diesel Think One Automobile & Trading Posted: 28-Feb-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace Commuter		\$65,000	\$9,850 /yr	08-Oct-2015	2,982 cc	180,000 km	Bus	Available
	Fuel Type: Diesel Car Register On Oct 2015, Accident Free.								
	Posted: 25-Feb-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								

[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	7995Z

Vehicle Details

Vehicle No.:	GBE606C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2545737
Chassis No.:	JTFHT02P100174445
Maximum Power Output:	-
Open Market Value:	\$27,741.00
Original Registration Date:	26 Aug 2015
First Registration Date:	26 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$1,388.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	25 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,156.00
COE Rebate Amount:	\$27,310.00
Total Rebate Amount:	\$27,310.00

The information contained herein is correct as at 02 Mar 2019

OK

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focusautoptehd@yahoo.com.sg

GST: 201004495R RCB NO: 201004495R

Not Authorised
Helen
5/3/19
6/3/19
2/5/19 7200/
Theodore Atkinson
8 dy.

M/S: MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay,
#24-01 Hong Leong Building,
Singapore 048581

TEL: 6220 9644 FAX: 6225 6371

ATTN: Motor Claim Department

Your Ref No: GBE606C

Claim Type: Third Party

Accident Date: 01-03-2019

TP Veh Reg No: GBD7998E

Estimate No: EST0000849

Date: 02 Mar 2019

Policy No: A28794271MKC

Veh Reg No: **GBE606C**

Make/Model: TOYOTA HIANCE VAN

Chassis No: JTFHT02P100174445

Engine No: 1KD2545737

Reg. Date: 26-08-2015

Estimate Repair Cost for Vehicle No : GBE606C

PAGE: 1/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Rear Boot <i>Body D 1957.30</i>	2,250.0000	1 PC	2,250.00	✓
2 Rear Boot Top Hinge <i>11</i>	112.2000	2 PC	224.40	X
3 Rear Boot Shock Absorber <i>11</i>	195.0000	2 PC	390.00	X
4 Rear Boot 'toyota hiance sticker' <i>neu</i>	65.0000	1 PC	65.00	✓
5 Rear Boot Centre Logo <i>neu 68.10</i>	75.0000	1 PC	75.00	✓
6 Rear Boot Centre Garnish <i>scr</i>	165.0000	1 PC	165.00	✓
7 Rear Boot Inner Cover Board <i>T.O.A 248.10</i>	368.0000	1 PC	368.00	✓
8 Rear Boot Inner Cover Board Clipse <i>neu 50</i>	5.5000	14 PC	77.00	✓
9 Rear Boot Lock <i>DD/3M</i>	275.0000	1 PC	275.00	✓
10 Rear Boot Inner Lock Actuator <i>11</i>	450.0000	1 PC	450.00	X
11 Rear Boot Rubber <i>Tw1 248.10</i>	395.0000	1 PC	395.00	✓
12 Rear Windscreen <i>shoffland 1015.30</i>	1,250.0000	1 PC	1,250.00	✓
13 Rear Floor Panel <i>R</i>	1,650.0000	1 PC	1,650.00	X
14 Rear Floor Panel Top Beam <i>MS</i>	185.2000	1 PC	185.20	X
15 Rear Fender <i>R</i>	1,400.0000	1 PC	1,400.00	X
16 Rear Tail Lamp <i>ols cre 365.10</i>	398.0000	2 PC	796.00	1 pc
17 Rear Tail Lamp Panel <i>o/s D</i>	545.0000	1 PC	545.00	✓
18 Rear Tail Lamp Panel Garnish Bracket <i>cre</i>	56.0000	1 PCS	56.00	✓
19 Rear End Panel Inner <i>Body D</i>	890.0000	1 PC	890.00	✓
20 Rear End Panel Outer <i>Body D</i>	544.5000	1 PC	544.50	✓
21 Rear Bumper <i>D.S</i>	415.0000	1 PC	415.00	✓
22 Rear Bumper Side Retainer <i>o/s cre</i>	55.0000	2 PC	110.00	1 pc
23 Rear Bumper Lower Bracket <i>o/s cre</i>	46.0000	4 PC	184.00	2 pcs.
24 Rear Bumper Lower Clipse <i>neu</i>	5.5000	6 PC	33.00	✓
25 Rear Fender Air duct <i>D.S</i>	75.0000	1 PC	75.00	✓
26 Rear Exhaust Pipe <i>R</i>	586.2000	1 PC	586.20	X
27 Rear Exhaust Pipe Rubber <i>11</i>	45.2000	2 PC	90.40	X
28 Rear Tail Lamp Panel Garnish <i>cre</i>	145.0000	1 PCS	145.00	✓
			13,689.70	
Less 25%			3,422.43	10,267.28

FOCUS AUTO PTE LTD

NO 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST 201004495R RCB NO.201004495R

M/S : MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay,

#24-01 Hong Leong Building,

Singapore 048581

TEL: 6220 9644

FAX: 6225 6371

ATTN: Motor Claim Department

Your Ref No: GBE606C

Claim Type: Third Party

Accident Date: 01-03-2019

TP Veh Reg No: GBD7998E

Estimate No: EST0000849

Date: 02 Mar 2019

Policy No: A28794271MKC

Veh Reg No: GBE606C

Make/Model: TOYOTA HIANCE VAN

Chassis No: JTFHT02P100174445

Engine No: 1KD2545737

Reg. Date: 26-08-2015

Estimate Repair Cost for Vehicle No :GBE606C

PAGE:2/2

Description	U/Price	Quantity	List Price SS	Amount SS
Special Net				
29 Rear Boot Sticker 70km/h	15.0000	1 PC	15.00	10
30 Rear Boot Inner Aluminium Plate	450.0000	1 PCS	450.00	400
31 Rear Windscreen Gump sealant	80.0000	1 PC	80.00	40
32 Rear Floor Panel Top Aluminium Plate	1,200.0000	1 PC	1,200.00	LR 180
33 Rear Bumper Sensor	300.0000	1 SET	300.00	200
34 Rear Number Plate	40.0000	1 PC	40.00	15
			2,085.00	2,085.00
Labour				
35 Panel Beating	2,200.0000	1	2,200.00	1400
36 Check Wiring	60.0000	1	60.00	30
37 To Remove & Refit Rear Windscreen	100.0000	1	100.00	✓
38 To Remove & Replace Rear Aluminium Plate	450.0000	1	450.00	100
39 To Remove & Refit Exhaust Pipe	80.0000	1	80.00	X
40 To Remove & Replace Bumper Sensor	80.0000	1	80.00	50
41 To Spray Rust Proofing	100.0000	1	100.00	✓
42 Spray Painting	1,200.0000	1	1,200.00	900
			4,270.00	4,270.00
Total			SS 16,622.28	

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND SIX HUNDRED TWENTY TWO AND CENTS TWENTY EIGHT ONLY

LKK Auto Consultants hence certify and repair on the following:

- To rectify damage after spray painting
- To replace damaged parts during holiday
- Parts prices will be subject to change
- Third party claims will be on a "pro-rata" basis
- No time requirement for repair
- Disputes may be referred to the nearest court and arbitration for resolution

For FOCUS AUTO PTE LTD
No 1 Kaki Bukit Avenue 6 Auto Bay
#02-50 Singapore 417883
Tel: 66349695

AUTHORISED SIGNATURE

P-7307.50
252
P-5480.62
S-A-845
1680-2680
9005-62

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19004011/UQD3N2

Date: 19/03/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29080980MKC (COMP)	
Claimant Vehicle No :	GBE606C	Insured Vehicle No :	GBD7998E	
Date of Loss:	01/03/2019	Nature of Claim:	TP	Claim No: 586723

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE606C	Engine No:	1KD2545737
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Chassis No:	JTFHT02P100174445
Reg. Date:	26/08/2015 (Man. Year: 2015)	Odometer:	80109 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,352.27	6,325.62	6,026.65	48.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	2,680.00	1,590.00	37.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,622.27	9,005.62	7,616.65	45.82
Approved Total (Overridden) (\$\$)		7,200.00		
(\$\$)	16,622.27	7,200.00	9,422.27	56.68
+ GST 7.00/7.00% (\$\$)	1,163.56	504.00	659.56	56.68
Nett Amount (\$\$)	17,785.83	7,704.00	10,081.83	56.68

INSPECTION

Date of Assignment:	05/03/2019	
Date Inspected:	05/03/2019 Inspected At:	Focus Auto Pte Ltd (Kaki Bukit) NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-50 Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2019)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE606C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	2,250.00 FL	*1,957.30 FL
2	2		*REAR BOOT TOP HINGE	Not Necessary	224.40 FL	*- FL
3	2		*REAR BOOT SHOCK ABSORBER	Not Necessary	390.00 FL	*- FL
4	1		*REAR BOOT TOYOTA HIACE STICKER	Necessary	65.00 FL	*65.00 FL
5	1		*REAR BOOT CENTRE LOGO	Necessary	75.00 FL	*68.10 FL
6	1		*REAR BOOT CENTRE GARNISH	Scratched	165.00 FL	*165.00 FL
7	1		*REAR BOOT INNER COVER BOARD	Torn	368.00 FL	*248.10 FL
8	1		*REAR BOOT INNER COVER BOARD CLIPSE	Necessary	77.00 FL	*50.00 FL
			(14 Pcs)			
9	1		*REAR BOOT LOCK	Dented/Jammed	275.00 FL	*275.00 FL
10	1		*REAR BOOT INNER LOCK ACTUATOR	Not Necessary	450.00 FL	*- FL
11	1		*REAR BOOT RUBBER	Twisted	395.00 FL	*248.10 FL
12	1		*REAR WINDSCREEN	Shattered	1,250.00 FL	*1,015.30 FL
13	1		*REAR FLOOR PANEL	Repair	1,650.00 FL	*- FL
14	1		*REAR FLOOR PANEL TOP BEAM	No such part	185.20 FL	*- FL
15	1		*REAR FENDER	Repair	1,400.00 FL	*- FL
16	1		*REAR TAIL LAMP	O/s Cracked	796.00 FL	*365.10 FL
17	1		*REAR TAIL LAMP PANEL O/S	Dented	545.00 FL	*545.00 FL
18	1		*REAR TAIL LAMP PANEL GARNISH BRACKET	Cracked	56.00 FL	*56.00 FL
19	1		*REAR END PANEL INNER	Badly Dented	890.00 FL	*890.00 FL
20	1		*REAR END PANEL OUTER	Badly Dented	544.50 FL	*544.50 FL
21	1		*REAR BUMPER	Distorted	415.00 FL	*415.00 FL
22	1		*REAR BUMPER SIDE RETAINER	O/s Cracked	110.00 FL	*55.00 FL
23	1		*REAR BUMPER LOWER BRACKET	O/s Bent (2 Pcs only)	184.00 FL	*92.00 FL
			(4 Pcs)			
24	6		*REAR BUMPER LOWER CLIPSE	Necessary	33.00 FL	*33.00 FL
25	1		*REAR FENDER AIR DUCT	Distorted	75.00 FL	*75.00 FL
26	1		*REAR EXHAUST PIPE	Repair	586.20 FL	*- FL
27	2		*REAR EXHAUST PIPE RUBBER	Not Necessary	90.40 FL	*- FL
28	1		*REAR TAIL LAMP PANEL GARNISH	Cracked	145.00 FL	*145.00 FL
29	1		*REAR BOOT STICKER 70KM/H	Necessary	15.00 FS	*10.00 FS
30	1		*REAR BOOT INNER ALUMINIUM PLATE	Bent/Twisted	450.00 FS	*400.00 FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*REAR FLOOR PANEL TOP ALUMINIUM PLATE (LOCAL REPAIR)	Bent	1,200.00 FS	*180.00 FS
33	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS
34	1		*REAR NUMBER PLATE	Bent	40.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,774.70	8,152.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,422.43	1,826.88
Total Parts (\$\$)	12,352.27	6,325.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	1,400.00
2	CHECK WIRING	New	60.00	30.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	100.00	100.00
4	TO REMOVE & REPLACE REAR ALUMINIUM PLATE	New	450.00	100.00
5	TO REMOVE & REFIT EXHAUST PIPE	New	80.00	0.00
6	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
7	TO SPRAY RUST PROOFING	New	100.00	100.00
8	SPRAY PAINTING	New	1,200.00	900.00
Gross Labour Cost (\$\$)			4,270.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >