

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19004023/KBA3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700034285
Claimant
Vehicle No : SJF7621L **Insured Vehicle No :** SLR931B
Date of Loss: 01/03/2019 **Nature of Claim:** TP **Claim No:** 4700951842SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF7621L**
 Make & Model: DAIHATSU COPEN, 660cc (A) Engine No: JB0371139
 Reg. Date: 10/06/2008 (Man. Year: 2007) Chassis No: L880K0040640
 Colour: Metallic Silver Odometer: 76933 km
 Engine Capacity: 659 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/50 R15 Rear Tyre Size: 165/50 R15
 Front Left Side: Conomist 8 mm Rear Left Side: Falken 6 mm
 Front Right Side: Conomist 8 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,341.75	2,094.25	1,247.50	37.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	485.00	825.00	62.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,651.75	2,579.25	2,072.50	44.55
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	4,651.75	2,050.00	2,601.75	55.93
+ GST 7.00/7.00% (S\$)	325.62	143.50	182.12	55.93
Nett Amount (S\$)	4,977.37	2,193.50	2,783.87	55.93
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,730.50		

INSPECTION

Date of Assignment: 05/03/2019
 Date Inspected: 05/03/2019 Inspected At: Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A,
 #01-15/16 & 17, AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	790.00 FL	*790.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
3	1		*REAR BUMPER LAMP LH	Scratched	470.00 FL	*470.00 FL
4	1		*BOOT	Repair	1,050.00 FL	*- FL
5	1		*REAR BUMPER STICKER	Necessary	50.00 FS	*30.00 FS
6	1		*REAR NUMBER PLATE (3D)	Cracked	145.00 FS	*45.00 FS
7	1		*REAR BOOT CARBON SPOILER	Dented	480.00 FS	*480.00 FS
8	1		*REAR BOOT LOGO AUDI	Not Necessary	105.00 FS	*- FS
9	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
10	1		*REAR BUMPER REVERSE CAMERA	Damaged	380.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,695.00	2,290.00
- List Item Discount on L Items 15.00/15.00% (\$)	353.25	195.75
Total Parts (\$)	3,341.75	2,094.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT REAR ELECTRICAL CHECK ,LOCKING SYSTEM ,ADJUST ,TAIL LAMP ETC	New	30.00	15.00
2	TO REPAIR /REPLACE & ALIGN MUFFLER /EXHAUST SYSTEM AND CONDUCT CARBON MONOXIDE LEAKAGE TEST	New	80.00	0.00
3	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF END PANEL AND PARTS REPLACEMENT	New	450.00	250.00
4	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS	New	150.00	0.00
5	TO RESPRAY AFFECTED AREAS	New	600.00	220.00
Gross Labour Cost (\$\$)			1,310.00	485.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >