

ASS. REC. BY:

REF:

CS/FCI 9004031/Nqd3n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

05/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6227M

Insured:

SHB 4346X

at Workshop m/s

Premier Automotive

Tel:

of

73 Changi South Ave 2 #03-02

Policy No:

Claim No:

Q19001507NFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/3/19

(Client's Record)

WPI

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SHC 6227M X

SHB 4346X

CC01E 19003944/Dha3 DOA: 01/3/19

11/3/19 09pm NOTED to Karen Tan by email.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001507MFSH

Date: 11 March 2019

Our Ref: CS/FCI19004031/Nqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6227M

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/03/2019 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,412.90 .
Revised Estimate Amount	: S\$ 1,281.80 .
"Check" Items Amount	: S\$ 1,223.10 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Naz
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	01-03-2019	Our Ref No. D19001507MFSH
Accident Date	01-03-2019	Claim Type. Third Party
Insured Vehicle	SHB4346X	Third Party Vehicle. SHC6227M
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	65446676/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 11 March 2019 1:09 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001507MFSH/1
Attachments: CSFCI19004031Nqd3.pdf

Dear Karen,

Enclosed herewith preliminary advise of SHC 6227M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Monday, 4 March 2019 3:38 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19001507MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	23 Oct 2014 / 08:57:26	Receipt No.:	AACCK001-AX239-141023-000004
Asset Type:	Vehicle	Transaction Amount:	\$63,308.00
Asset ID:	SHC6227M	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141023085726613667		
Vehicle No.:	SHC6227M		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	23 Oct 2014		
Original Registration Date:	23 Oct 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5542430		
Engine No.:	D4FDEH311476		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$19,730.00		
Minimum PARF Benefit:	\$7,338.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	23 Oct 2014 08:57:26		
COE No.:	2014102301001304E		
COE Expiry Date:	22 Oct 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,938.00		
Lifespan Expiry Date:	22 Oct 2022		
Owner ID Type:	Company		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

1-Mar-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6227 M

1 pc	Rear bumper	\$ 696.00	CRK
1 pc	Rear bumper lower cover	\$ 206.00	DEF
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$ 58.00	XJUL
1 pc	Rear bumper inner sponge	\$ 114.00	CRK
1 pc	Rear bumper reinforcement	\$ 607.00	DEF
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$ 108.00	XJUL
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$ 36.00	XJUL
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$ 36.00	XJUL
		\$ 1,861.00	1,623
		\$ 186.10	
		\$ 1,674.90	1460.70

S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor
1 pc	Rear bumper top protector

Sundry

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same

To putty and spray painting on rear bumper, end panel

To apply rustproofing on the repaired and replaced panels.

\$ 48.00	XNN
\$ 280.00	XJUL
\$ 80.00	NEC
\$ 50.00	XNN

\$ 120.00 30

\$ 180.00 XNN

\$ 500.00 180

\$ 400.00 180

\$ 80.00
\$ 3,412.90 470

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Signature
11/3/19

NA2 LKK 2,010.70
5/3/19 1,608.56
1700

LIS

2 DAYS

CHECK ITEMS PHOTOS
AFTER REPAIR PHOTOS

PARTS \$1,623
LESS 10% \$1,460.70
S/NETT \$ 80
LABOUR \$ 470
\$2,010.70
LESS 10% \$1,608.56
TOTAL \$1,600.00 / 2 REPAIR DAYS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19004031/Nqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4346X	Veh. Inspected	SHC 6227M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001507MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	05/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414MF5542430	Colour	SILVER	
Odometer	411825	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	6 mm	
L/H Front Tyre	205/65 R16	MAXXIS	6 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	6 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2019	Inspection Date	05/03/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6227M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	696.00	696.00
1	REAR BUMPER LOWER COVER	DEFORMED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	CRACKED	114.00	114.00
1	REAR BUMPER REINFORCEMENT	DEFORMED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-186.10	-162.30
			1,674.90	1,460.70
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	80.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			458.00	80.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME.		500.00	180.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, END PANEL.		400.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	80.00
			1,280.00	470.00

Report Ref No. CS/FCI19004031/Nqd3n2



GRAND TOTAL		3,412.90	2,010.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/FCI19004031/Nqd3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.