## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO: SHA 8850K

MAKE

DATE 4/3/2019 10:26

CHINA - JU

: HYUNDAI i40 MODEL Amount Unit Price Type Parts Description/ Labour Qty 553.00 Rear Bumper \$ 22.00 Rear Bumper Clip 10 pcs X 17 71.20 Rear Bumper Bracket X500 35.60 \$ \$ Rear Bumper Sponge 103.50 Rear Bumper Under Cover \$ 228.00 \$ 977.70 SUB TOTAL 195.54 **LESS 20%** 782.16 DISCOUNTED TOTAL 50.00 Nett Rear Bumper Rubber Mat Rear Bumper Advertisement Logo - No 50.00 Nett Rear Fender Advertisement Logo (LH/RH) \$ . 100.00 \$ 200.00 Nett 135.70 Nett Rear Bumper Reverse Sensor 435.70 Labour Charge Panel Beating \$ Spray Painting Charge \$ Wiring Charge \$ Remove/Refix Reverse Sensor TOTAL LABOUR KK Auto Consultants hence notify 810.00 \$ ne Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey 2,027.86 \$ ESTIMATE TOTAL Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" Kahir 100kg

M 4/3/19 1115h.

2 hrs

PIP

Alle Rever plh No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

> This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.