

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19004067/APA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJQ3044X	Insured Vehicle No :	SHD3145E
Date of Loss: 03/03/2019	Nature of Claim: TP	Claim No: MCT19030057

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ3044X		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4188365
Reg. Date:	30/04/2009 (Man. Year: 2009)	Chassis No:	GE61172157
Colour:	White	Odometer:	223922 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,076.00	11,245.20	11,830.80	51.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,620.00	5,870.00	3,750.00	38.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,696.00	17,115.20	15,580.80	47.65
Approved Total (Overridden) (\$\$)		13,700.00		
(\$\$)	32,696.00	13,700.00	18,996.00	58.10
+ GST 7.00/7.00% (\$\$)	2,288.72	959.00	1,329.72	58.10
Nett Amount (\$\$)	34,984.72	14,659.00	20,325.72	58.10
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	04/03/2019	
Date Inspected:	04/03/2019 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	14.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ3044X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	820.30 F	*820.30 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	97.80 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Bent	369.80 F	*369.80 FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	38.10 F	*38.10 FL
5	1		*REAR BOOT LID FIT LOGO	Necessary	38.00 F	*38.00 FL
6	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 F	*50.00 FL
7	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	96.40 F	*- FL
8	1		*REAR BOOT LID CENTRE MOULDING	Cracked	120.60 F	*120.60 FL
9	1		*REAR BOOT LID CENTRE MOULDING CLIP (6PCS)	Necessary	39.00 F	*20.00 FL
10	1		*REAR BOOT LID INNER LOCK	Jammed	232.10 F	*232.10 FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	128.10 F	*128.10 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	296.70 F	*296.70 FL
13	1		*REAR BOOT LID WIPER LINK	Not Necessary	175.90 F	*- FL
14	1		*REAR BOOT LID WIPER COVER	Not Necessary	45.00 F	*- FL
15	1		*REAR BOOT LID WIPER ARM	Not Necessary	86.00 F	*- FL
16	1		*REAR BOOT LID WIPER MOTOR	Not Necessary	328.50 F	*- FL
17	1		*REAR BOOT LID WINDSCREEN	Not Necessary	1,256.20 F	*- FL
18	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	136.20 F	*136.20 FL
19	2		*REAR TAIL LAMP	Cracked	593.00 F	*593.00 FL
20	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
21	2		*REAR TAIL LAMP PANEL	Dented	383.40 F	*383.40 FL
22	2		*REAR TAIL LAMP INNER PANEL	Repair	964.60 F	*- FL
23	1		*REAR BUMPER	Distorted	494.60 F	*494.60 FL
24	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
25	2		*REAR BUMPER SIDE RETAINER	Necessary	57.40 F	*57.40 FL
26	1		*REAR BUMPER TOWING COVER	Distorted	28.00 F	*28.00 FL
27	1		*REAR BUMPER MUD SHIELD	O/S Torn	189.60 F	*94.80 FL
28	8		*REAR BUMPER MUD SHIELD CLIP	Necessary	52.00 F	*10.00 FL
29	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
30	1		*REAR END PANEL	Distorted	365.30 F	*365.30 FL
31	1		*REAR END PANEL TOP GARNISH	Deformed	140.20 F	*140.20 FL
32	2		*REAR FENDER	Buckled	1,364.40 F	*1,364.40 FL
33	2		*REAR FENDER GLASS	Not Necessary	576.00 F	*- FL
34	2		*REAR FENDER AIR DUCT	Not Necessary	76.00 F	*- FL
35	2		*REAR FENDER INNER PANEL	Repair	1,266.00 F	*- FL
36	1		*REAR FENDER INNER HOUSING	O/S Buckled	1,192.80 F	*596.40 FL
37	2		*REAR FENDER TOP TRIM BOARD	Deformed	587.20 F	*587.20 FL
38	2		*REAR FENDER INNER TRIM BOARD	Distorted	679.60 F	*679.60 FL
39	16		*REAR FENDER INNER TRIM BOARD CLIP	Necessary	104.00 F	*60.00 FL
40	1		*REAR SPARE TYRE PANEL	Distorted	737.40 F	*737.40 FL
41	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	260.40 F	*260.40 FL
42	1		*REAR SPARE TYRE PANEL TOP SPONGE	Torn	206.00 F	*206.00 FL
43	1		*REAR SPARE TYRE PANEL SEALANT	Necessary	450.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR SPARE TYRE SIDE PANEL	O/S Distorted	302.40 F	*151.20 FL
45	1		*REAR R/H CHASSIS	Repeated	560.30 F	*- FL
46	1		*REAR EXHAUST	Bent	586.50 F	*586.50 FL
47	1		*REAR CENTRE EXHAUST	Not Necessary	562.40 F	*- FL
48	1		*REAR EXHAUST ALUMINIUM COVER	Torn	95.00 F	*95.00 FL
49	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 F	*- FL
50	1		*REAR AXLE	Bent	1,206.60 F	*1,206.60 FL
51	2		*REAR AXLE BEARING	Damaged	544.60 F	*544.60 FL
52	2		*REAR SHOCK ABSORBER	Bent	588.40 F	*588.40 FL
53	1		*REAR R/H DOOR	Buckled	765.00 F	*765.00 FL
54	2		*REAR R/H DOOR HINGE	Not Necessary	80.20 F	*- FL
55	2		*REAR R/H DOOR FRAME STICKER	Necessary	64.80 F	*64.80 FL
56	1		*REAR R/H DOOR LOCK	Damaged	231.40 F	*231.40 FL
57	1		*REAR R/H DOOR INNER RUBBER	Not Necessary	120.20 F	*- FL
58	1		*REAR R/H DOOR INNER TRIM BOARD	Not Necessary	401.20 F	*- FL
59	1		*REAR R/H DOOR PILLAR ASSY	Repair	806.40 F	*- FL
60	1		*REAR RH CHASSIS SUB MEMBER	Distorted	528.00 F	*528.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	23,076.00	13,991.50
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,746.30
Total Parts (S\$)	23,076.00	11,245.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	250.00
2	TO REMOVE & REFIT ROOF LINING	New	380.00	0.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
4	GUM	New	50.00	50.00
5	TO REMOVE & REFIT REAR LH & RH FENDER GLASS	New	200.00	120.00
6	GUM	New	100.00	60.00
7	TO REMOVE & REFIT REAR R/H DOOR, GLASS, LOCK, RUBBER, TRIM BOARD & FRAME STICKER	New	280.00	80.00
8	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	160.00
10	TO REMOVE & REFIT REAR AXLE	New	380.00	350.00
11	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
12	TO PERFORM CHASSIS ALIGNMENT	New	480.00	320.00
13	TO CHECK WIRING	New	120.00	30.00
14	TOWING FEE	New	150.00	120.00
15	TUFF KOTE	New	150.00	80.00
16	PANEL BEATING	New	3,500.00	2,200.00
17	SPRAY PAINTING	New	2,800.00	1,800.00
Gross Labour Cost (\$\$)			9,620.00	5,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >