



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

06/03/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111

Xiao Tong.

mv: 27K
rv: 12.8K
nett: 14K

Accident date: 03/03/2019

Estimated repair cost for vehicle no: SJQ3044X HONDA FIT 1.3G A '09

CHASSIS: GE61172157

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid Distorted		\$820.30	✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$48.90	\$97.80	✓
3	2	Rear Boot Lid Shock Absorber <i>Dist.</i>	\$184.90	\$369.80	✓
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$38.10	✓
5	1	Rear Boot Lid Fit Logo <i>new</i>		\$38.00	✓
6	1	Rear Boot Lid Number Plate <i>Dist</i>		\$50.00	✓
7	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$48.20	\$96.40	✓
8	1	Rear Boot Lid Centre Moulding <i>cracked</i>		\$120.60	✓
9	6	Rear Boot Lid Centre Moulding Clip <i>new</i>	\$6.50	\$39.00	20 ✓
10	1	Rear Boot Lid Inner Lock <i>Jammed</i>		\$232.10	✓
11	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$128.10	✓
12	1	Rear Boot Lid Inner Trim Board <i>cracked</i>		\$296.70	✓
13	1	Rear Boot Lid Wiper Link		\$175.90	✓
14	1	Rear Boot Lid Wiper Cover <i>new</i>		\$45.00	✓
15	1	Rear Boot Lid Wiper Arm <i>new</i>		\$86.00	✓
16	1	Rear Boot Lid Wiper Motor		\$328.50	✓
17	1	Rear Boot Lid Windscreen <i>new</i>		\$1,256.20	✓
18	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$136.20	✓
19	2	Rear Tail Lamp <i>cracked</i>	\$296.50	\$593.00	✓
20	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	✓
21	2	Rear Tail Lamp Panel <i>Dented</i>	\$191.70	\$383.40	✓
22	2	Rear Tail Lamp Inner Panel <i>Repair</i>	\$482.30	\$964.60	✓
23	1	Rear Bumper <i>Distorted</i>		\$494.60	✓
24	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00	30 ✓
25	2	Rear Bumper Side Retainer <i>new</i>	\$28.70	\$57.40	✓
26	1	Rear Bumper Towing Cover <i>Distorted</i>		\$28.00	✓
27	2	Rear Bumper Mud Shield <i>RH torn</i>	\$94.80	\$189.60	94.8 ✓
28	8	Rear Bumper Mud Shield Clip <i>new</i>	\$6.50	\$52.00	10 ✓
29	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00	200/50 ✓

30	1	Rear End Panel	Distorted		\$365.30	✓
31	1	Rear End Panel Top Garnish	Defound		\$140.20	✓
32	2	Rear Fender	Buckled	\$682.20	\$1,364.40	✓
33	2	Rear Fender Glass	NE NE	\$288.00	\$576.00	X
34	2	Rear Fender Air Duct	NE NE	\$38.00	\$76.00	X
35	2	Rear Fender Inner Panel	R/R	\$633.00	\$1,266.00	X
36	2	Rear Fender Inner Housing	RH Buckled	\$596.40	\$1,192.80	586
37	2	Rear Fender Top Trim Board	Defound	\$293.60	\$587.20	✓
38	2	Rear Fender Inner Trim Board	Distorted	\$339.80	\$679.60	✓
39	16	Rear Fender Inner Trim Board Clip	NE	\$6.50	\$104.00	60
40	1	Rear Spare Tyre Panel	Distorted		\$737.40	✓
41	1	Rear Spare Tyre Panel Top Cover	Defound		\$260.40	✓
42	1	Rear Spare Tyre Panel Top Sponge	torn		\$206.00	✓
43	1	Rear Spare Tyre Panel Sealant	NE		\$450.00	60(SN)
44	2	Rear Spare Tyre Side Panel	RH Distorted	\$151.20	\$302.40	151.20
45	1	Rear R/H Chassis	Distorted X Repeated		× \$560.30	×
46	1	Rear Exhaust	Bent		\$586.50	✓
47	1	Rear Centre Exhaust	NE NE		\$562.40	X
48	1	Rear Exhaust Aluminium Cover	torn		\$95.00	✓
49	2	Rear Exhaust Mounting	NE NE	\$38.20	\$76.00	X
50	1	Rear Axle	Bent		\$1,206.60	✓
51	2	Rear Axle Bearing	Damaged	\$272.30	\$544.60	✓
52	2	Rear Shock Absorber	Bent	\$294.20	\$588.40	✓
53	1	Rear R/H Door	Buckled		\$765.00	✓
54	2	Rear R/H Door Hinge	NE NE	\$40.10	\$80.20	+
55	2	Rear R/H Door Frame Sticker	NE	\$32.40	\$64.80	✓
56	1	Rear R/H Door Lock	Damaged		\$231.40	✓
57	1	Rear R/H Door Inner Rubber	Open		\$120.20	X
58	1	Rear R/H Door Inner Trim Board			\$401.20	X
59	1	Rear R/H Door Pillar Assy	R/R		\$806.40	X

60 1 Rear RH Chassis Sub Member Distorted.

528

Subtotal :- \$22,548.00

14291.80

S.N : 200

1173344

Labour charges

To remove & refit cushion & trim board	\$280.00 250
To remove & refit roof lining	\$380.00 X.
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit rear LH & RH fender glass	\$200.00 120
Gum	\$100.00 60
To remove & refit rear R/H door, glass, lock, rubber, trim board & frame sticker	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 160
To remove & refit rear axle	\$380.00 350
To check wheel alignment	\$150.00 80
To <i>perform chassis alignment</i>	\$480.00 320
To check wiring	\$120.00 30
Towing fee	\$150.00 120
Tuff kote	\$150.00 80
Panel beating	\$3,500.00 2200
Spray painting	\$2,800.00 1800

5870

total 17503.44

n/s 14K

14 Days.

14 Days
14K

Subtotal :- \$9,620.00

Total:- \$32,168.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0779F
Vehicle Particulars	
Vehicle No.:	SJQ3044X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	L13A4188365
Chassis No.:	GE61172157
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,071.00
Original Registration Date:	30 Apr 2009
First Registration Date:	30 Apr 2009
Transfer Count:	1
Actual ARF Paid:	\$14,071.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2019
PARF Rebate Amount:	\$7,035.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2024
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$88.00
Total Rebate Amount:	\$7,123.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Mar 2019

OK

MV: 27K

PV: 128K

14.2K