



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9887S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FACE,FR.BUMPER (SN)	DENTED	378.45	378.45
1	LOWER GRILLEFR.BUMPER (SN)	NOT NECESSARY	21.22	-
1	GARNISHR.FR.BUMPER (SN)	CUT	17.77	17.77
1	SPOILERFR.BUMPER LIP (SN)	NOT NECESSARY	43.50	-
1	BEAM COMPFR.BUMPER (SN)	NOT NECESSARY	167.85	-
1	BRACKETR.HEADLIGHT (SN)	NECESSARY	18.07	18.07
1	BRACKETL.HEADLIGHT (SN)	NOT NECESSARY	16.42	-
1	SPACERR.FR.BUMPER (SN)	BROKEN	7.80	7.80
1	SPACERL.FR.BUMPER (SN)	BROKEN	7.80	7.80
17	CLIP,BUMPER (SN)	NECESSARY	29.32	29.32
1	GRILLE ASSYFR. (SN)	NOT NECESSARY	221.02	-
1	HEADLIGHT ASSY, R (SN)	BROKEN	855.67	855.67
1	PANELR.FR.FENDER (SN)	DENTED	311.02	298.95
1	FENDER ASSYR.FR.INNER (SN)	TORN	54.97	54.97
1	BRACKET, COMP R.FR.FENDER (SN)	BENT	32.92	32.92
1	ENCLOSURE,R.FR (SN)	NOT NECESSARY	13.20	-
1	HOOD COMP (SN)	TO REPAIR SEE LABOUR	403.12	-
1	PANEL COMP,R.FR.DOOR (SN)	TO REPAIR SEE LABOUR	579.22	-
1	TAPE SETR.FR.DOOR (SN)	NOT NECESSARY	25.20	-
1	DISKALUMINIUM WHEEL 16X6J (SN)	CUT	627.00	627.00
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
2	CLIP ABUMPER (SN) (ADDITIONAL)	NECESSARY	3.90	3.90
11	CLIP, INNER FENDER (SN) (ADDITIONAL)	NECESSARY	23.10	23.10
1	EXTENSION SETR.FR (SN) (ADDITIONAL)	DENTED	70.80	70.80
1	MEMBER COMPR. FR.WHEELHOUSE (SN) (ADDITIONAL)	DENTED	71.17	71.17
1	TANKWASHER (SN) (ADDITIONAL)	CRACKED	42.90	42.90
			4,143.41	2,590.59
<u>LABOUR</u>				
	BODY JOINT SEALANT FRO FRONT RHS FENDER.		150.00	120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		380.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW RR L DR.		450.00	450.00
	RESET & CALIBRATE SMART ENTRY SYSTEM.		450.00	450.00
	REMOVE & RENEW FR BUMPER. RENEW ALL DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF HOOD COMP AND PANEL COMP,R.FR.DOOR.		3,500.00	2,800.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)		2,500.00	2,025.00
	TOWING SERVICE.	NOT NECESSARY	180.00	-
	WHEEL ALIGNMENT X4.		180.00	180.00
			7,790.00	6,305.00
GRAND TOTAL			11,933.41	8,895.59

RECOMMENDED COST OF REPAIRS				8,895.59
------------------------------------	--	--	--	-----------------

Report Ref No. CS/FCI19004074/Evd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.