

Your Ref : S9M01EBD

Date: 15th March 2019

Our Ref : CS/ASM19004100/Kqd3s2

M/s AXA Insurance Pte Ltd
8 SHENTON WAY #24-01
AXA TOWER
Singapore 068811
(The Motor Claims Department)

Attn: Yvonne Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJJ 5522G
ACCIDENT ON 17/02/2019**

Instruction was received to inspect the vehicle Reg. No. SJJ 5522G. The inspection was conducted on 06/03/2019 at the premises of M/s Ah Lim Motor Company, No 10 Ang Mo Kio Industrial Park 2A #01-09 AMK Autopoint Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SJJ 5522G
Make/Model	: Volvo V40 D2 (A)
Year of Registration	: 2014
Body Colour	: Metallic Light Brown
Chassis Number	: YV1MV845BF2175885
Engine Capacity	: 1560 cc
Speedometer Reading	: 92079 km

The vehicle sustained damages at the front o/s portion. The undercarriage and body structure affected due to collision. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as “**uneconomical Total Loss**”.

Market Value	S\$ 55,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 43,741.00)
Nett Liability	<u>S\$ 11,259.00</u>

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.