




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19004106/Aga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:TAN JUN HONG			Date : 25-09-2020	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	GBC 1181P	<b>Veh. Inspected</b>	GBD 8890A	
<b>Policy No.</b>	VCA/P1912360	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	S9M01FP2	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>		<b>Assign Date</b>	05/03/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	TOYOTA DYNA	<b>c.c</b>	2982	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015	
<b>Chassis No.</b>	KDY2318018020	<b>Colour</b>	SILVER	
<b>Odometer</b>	160725	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	175/75 R15	BRIDGESTONE	6 mm	
<b>L/H Front Tyre</b>	175/75 R15	BRIDGESTONE	6 mm	
<b>R/H Rear Tyre</b>	165 R13	FALKEN	6 mm	
<b>L/H Rear Tyre</b>	165 R13	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	02/03/2019	<b>Inspection Date</b>	06/03/2019	
<b>Survey held at</b>	LIANG HEE MOTOR WORKSHOP 1 KAKI BUKIT AVE 6 #01-62 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		