

ASS. REC. BY:

REF:CS/CT/19004109/ASJ3

Special instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CAI

Date/Time: 5/3/2019 5:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 2285L

Insured: GX 8A83B

at Workshop m/s 1000 Kang Car

Tel:

of 1 Kaki Bukit Ave 6

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01/3/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS (WP)

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Sharon

Vehicle-IN/OUT

Date/Time

Action/Instruction	(✓) Estimate
--------------------	--------------

[illegible]

ASS. REC. BY:

REF:


Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMC285L Yr Regn: 2018 / June
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienna Hybrid c.c. 1496
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 8224 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NH P1707119124Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15

BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 06/03/19Sunray held at KangyDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFront o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/04/19 TP Chian
Confirmed r/p \$3,034.97 @ 4 days with Adrian
(\$1,237.71 Reb - 29%)

MV:

PV:

Nett:

RECEIVED 15 APR 2019

Resurvey No. of Trip - 1

Date/Time, File Pass to?

Date/Time, File Return to?

1) 15/04/19

2)

3) Typ 34

4)

5)

6)

Prel. Report:

Final Report: \$3,034.97 r/p

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 5 March 2019 5:26 PM
To: assignments
Subject: FW: NOTICE TO INSPECT OUR CLIENT'S VEHICLE : SMC2285L; ACCDT INVLG SMC2285L & GX8983B ON 01.03.19

(IN) Adrian
6/3 @ 10:37am
Sharon

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 5 March 2019 5:22 PM
To: kangcar@singnet.com.sg
Cc: kangcar176@yahoo.com.sg; Admin A <admin-a@lkkauto.com>
Subject: RE: NOTICE TO INSPECT OUR CLIENT'S VEHICLE : SMC2285L; ACCDT INVLG SMC2285L & GX8983B ON 01.03.19

Without Prejudice

Save as to costs

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

Estimate No: EST1900064

Date: 04 Mar 2019

Veh Reg No: SMC2285L

Make/Model: TOYOTA SIENTA
HYBRID 1.5G CVT

Chasis No: NHP1707119124

Reg. Date: 27/06/2018

Your Ref No: GX8983B

Claim Type: Third Party

Accident Date: 01/03/2019

TP Veh Reg No: GX8983B

Estimate Repair Cost to Vehicle No :SMC2285L

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC HEADLAMP RH <i>cut</i>	1,050.10	✓
2	1 PC FRT BUMPER <i>Del d</i>	594.70	✓
3	1 PC FRT BUMPER RH SIDE PROTECTOR <i>at</i>	186.90	✓
4	1 PC FRT BUMPER SIDE RETAINER RH <i>m</i>	73.90	✓
5	1 PC FRT GRILLE <i>2mb</i>	747.60	✓
6	1 PC FRT FENDER RH <i>2mb</i>	708.90	+
7	1 PC FRT FENDER COWLING RH <i>Del d</i>	180.10	✓
		3,542.20	65
	Less 25%	885.55	2,656.68
	Special Net		
8	1 SET FRT GRILLE CLIPS <i>Ne</i>	48.00	20
9	1 SET FRT BUMPER CLIPS <i>ne</i>	48.00	30
10	1 SET FRT FENDER COWLING CLIPS RH <i>ne</i>	40.00	30
		136.00	136.00
	Labour		
11	1 TO CHECK WIRING	50.00	30
12	1 TO SPRAY UNDERSEAL	80.00	X
13	1 (FRONT) TO SPRAY PAINTING	650.00	400
14	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00	400
		1,480.00	1,480.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 01/03/2019
TP Veh Reg No: GX8983B

Estimate No: EST1900064
Date: 04 Mar 2019

Veh Reg No: SMC2285L
Make/Model: TOYOTA SIENTA
HYBRID 1.5G CVT
Chasis No: NHP1707119124
Reg. Date: 27/06/2018
Your Ref No: GX8983B


Estimate Repair Cost to Vehicle No :SMC2285L

Quantity	Description	List Price	Amount
		SS	SS
	Total		SS 4,272.68 65
	Add GST @ 7%		299.09
	Total Amount Payable		SS 4,571.77

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FIVE HUNDRED SEVENTY ONE AND CENTS SEVENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Adrian Lj
P/P 06/03/19.
04 days

total: 3034.97
(P/P)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004109/ASD3N2

Date: 16/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30645318000	
Claimant Vehicle No :	SMC2285L	Insured Vehicle No :	GX8983B	
Date of Loss:	01/03/2019	Nature of Claim:	TP	Claim No: SNM19D201058C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC2285L	Engine No:	1NZ8487139
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Chassis No:	NHP1707119124
Reg. Date:	27/06/2018 (Man. Year: 2018)	Odometer:	8224 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,792.65	2,204.97	587.68	21.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	830.00	650.00	43.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,272.65	3,034.97	1,237.68	28.97
+ GST 7.00/7.00% (\$\$)	299.09	212.45	86.64	28.97
Nett Amount (\$\$)	4,571.74	3,247.42	1,324.32	28.97

INSPECTION

Date of Assignment:	12/04/2019	
Date Inspected:	06/03/2019	Inspected At:
		Kang Car Repairers Pte Ltd (HQ)
		NO.1 KAKI BUKIT AVE 6 #02-06
		AUTOBAY @ KAKI BUKIT
		Singapore 17883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2019)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC2285L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cut	1,050.10 FL	*1,050.10 FL
2	1		*FRT BUMPER	Deformed	594.70 FL	*594.70 FL
3	1		*FRT BUMPER RH SIDE PROTECTOR	Cut	186.90 FL	*186.90 FL
4	1		*FRT BUMPER SIDE RETAINER RH	Necessary	73.90 FL	*73.90 FL
5	1		*FRT GRILLE	Cracked	747.60 FL	*747.60 FL
6	1		*FRT FENDER RH	Repair	708.90 FL	*- FL
7	1		*FRT FENDER COWLING RH	Deformed	180.10 FL	*180.10 FL
8	1		*SET FRT GRILLE CLIPS	Necessary	48.00 FS	*20.00 FS
9	1		*SET FRT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
10	1		*SET FRT FENDER COWLING CLIPS RH	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,678.20	2,913.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	885.55	708.33
Total Parts (\$\$)	2,792.65	2,204.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY UNDERSEAL	New	80.00	0.00
3	(FRONT) TO SPRAY PAINTING	New	650.00	400.00
4	TO REMOVE AND REPLACE THE DAMAGED PARTS.KNOCK OUT ACCIDENT DENTED PORTIONS.AND FOR CUTTING/WELDING WORKS	New	700.00	400.00
Gross Labour Cost (\$\$)			1,480.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >