

AIG



ESTEE PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.eesteperf.com.sg

Repair Estimates

SLT 2619 E

Parts	(a) Cost / List Price Items	\$	4,337.00
	Plus/Less 25%	\$	1,084.25
	Total of Cost / List	\$	3,252.75
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	245.00
Total Parts Cost		\$	3,497.75
Labour		\$	2,630.00
Total		\$	6,127.75

Not Authorized
Resurvey B4 painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 6/3/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Se Date: 6/3/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com

Spare Parts

Vehicle No. : SLT 2619 E
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU103562552

Submit By : _____
Year Manufacture : _____
Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price
1	Front number plate <i>By</i>	1	\$45.00	S.N ✓
2	Front number plate garnish <i>CMA</i>	1	\$129.00	✓
3	Front bumper	1	\$450.80	?
4	Front bumper clip	10	\$40.00	?
5	Front bumper reinforcement - upper	1	\$711.50	?
6	Front bumper reinforcement - lower	1	\$245.30	?
7	Front bumper side retainer RH <i>Sn</i>	1	\$107.20	X
8	Front bumper side retainer LH <i>Sn</i>	1	\$107.20	X
9	Front bumper upper grille	1	\$321.90	?
10	Front bumper lower grille <i>Sn</i>	1	\$148.60	X
11	Reverse sensor	1	\$200.00	S.N ?
12	Rear bumper <i>Ru/CMA</i>		\$497.50	✓
13	Rear bumper clip <i>Sn</i>	10	\$40.00	✓
14	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70	X
15	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70	X
16	Rear bumper reinforcement	1	\$398.90	?
17	Rear bumper lower garnish centre <i>Sn</i>	1	\$582.60	✓
18	Rear bumper lower garnish LH <i>Sn</i>	1	\$149.70	X
19	Rear bumper lower garnish RH <i>Sn</i>	1	\$149.70	X
20	Rear bumper tow cover <i>Sn</i>	1	\$31.70	X
21				
22				
23				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLT 2619 E** Submit By : **Carmen Lim**
Make & Model : **0** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$1,000.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$1,000.00	4401
3	TO Check wiring	\$50.00	301
4	To tuff coat. <i>nn</i>	\$100.00	X
5	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit reverse sensor	\$120.00	501
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.