

22/03/2002

ASS. REC. BY:

REF

C33/CT/1900453/Gcd302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Boon Sen

of

CAJ

Date/Time:

6/3 @ 3:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 8217H

Insured:

GBH 5858T

at Workshop m/s

Team Auto pro

Tel:

of

Faki Bukit Ave 4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/2/19

CA / REV / REP. / REV 24 HRS

(WP)

8/3/2019

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

| Date/Time | Action/Instruction () Estimate |
|-----------|---------------------------------|
| | SJL 8217H - X |
| | GBH 5858T - X |
| | Dismantle: 11/3/2019 |
| | After repair: 13/3/2019 |

PRS
GR

REF:

CT

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: CSL 8217H
 at Workshop m/s Bam Auto pro
 of 8 Kaki Bukit Ave 4
 Insured: 06-21
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

| | |
|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| N/S | O/S |
| <input type="checkbox"/> | <input type="checkbox"/> |

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL847H Yr Regn: Dec / 08
 Type: ☒ M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Stream 1.8 RSZ
 Colour: silver A/C Insured / Std / NI / NA
 Sp. Reading: 259571 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RN6 1069393
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modl: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245 / 50 8R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. 08-03-19
 Survey held at w/s 3:50pm
 Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
\$2000 - \$3000

RECEIVED 21 MAR 2019

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____

Days Of Repair: 3
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp. (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: 150
 Transportation
) \$ + RS. SI
) Photos
) Others
)
 TOTAL

Report Format: PRE
 Lump Sum / I.B.I: (\$)

| |
|-----|
| 150 |
| 150 |

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 6 March 2019 3:57 PM
To: assignments
Subject: FW: Our Ref: SJL 8217H (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJL 8217H & GBH 5858T ALONG YISHUN RING ROAD ON 3 FEBRUARY 2019
Attachments: 20190306152711885.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 6 March 2019 3:56 PM
To: Weng Kit <wengkit@chiaarul.com>
Cc: 'Jerone' <jerone@chiaarul.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our Ref: SJL 8217H (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SJL 8217H & GBH 5858T ALONG YISHUN RING ROAD ON 3 FEBRUARY 2019

Without Prejudice
Save as to costs

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJL 8217H (wk)

Your Ref : To be advised

6 March 2019

China Taiping Insurance (S) Pte. Ltd.

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : 5M PARTNERS PTE LTD
ACCIDENT INVOLVING SJL 8217H & GBH 5858T ALONG YISHUN RING
ROAD ON 3 FEBRUARY 2019
PRE-REPAIR SURVEY NOTICE

1. We act for 5M Partners Pte Ltd, the owner of motor vehicle no. SJL 8217H which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. GBH 5858T for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

| | |
|----------------|--|
| Workshop | Team AutoPro Pte Ltd |
| Address | 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875 |
| Contact Person | Mr. Alan Koh (9092 7279) Mr. Frederick Lim (9674 6635) |

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 1126M |
| Vehicle Details | |
| Vehicle No.: | SJL8217H |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 21 Mar 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | STREAM 1.8 RSZ A |
| Primary Colour: | Silver |
| Manufacturing Year: | 2008 |
| Engine No.: | R18A1776807 |
| Chassis No.: | RN61069393 |
| Maximum Power Output: | 103.0 kW (138 bhp) |
| Open Market Value: | \$22,880.00 |
| Original Registration Date: | 12 Dec 2008 |
| First Registration Date: | 12 Dec 2008 |
| Transfer Count: | 3 |
| Actual ARF Paid: | \$22,880.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 11 Dec 2023 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 5 |
| PQP Paid: | \$15,777.00 |
| COE Rebate Amount: | \$14,897.00 |
| Total Rebate Amount: | \$14,897.00 |
| Message | |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 21 Mar 2019

OK

MVA219016383 / VAC - Sin Ming
 ENTRY DATE & TIME: 04/02/2019 14:29
 SUBMITTED BY: James Ng Wing Kin

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 04/02/2019 14:29 |
| Date Of Accident | 03/02/2019 18:15 |
| Exact Location Of Accident | YISHUN RING RD OPEN SPACE CAR PARK OF BLK 115 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJL8217H |
| Insured/Policyholder | |
| Name Of Registered Owner | 5M PARTNERS PTE LTD |
| Co Reg No | 201811126M |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-86546975 |
| Alternative Phone No | Office-86546975 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | HONDA |
| Model | STREAM |
| Exact Purpose for which vehicle was being used at time of accident | WORK PURPOSE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | YES |
| Policy Number | 5104270765 |
| Cover Note Number | |

Driver

| | |
|----------------------|---------------------------------|
| Name of Driver | MOHAMAD SAZALI BIN MOHAMAD SANI |
| NRIC No | S1511708G |
| Date Of Birth | 24/06/1961 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 06/03/1982 |
| Driving Experience | 36 YEARS AND 10 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-86546975 |

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 1147 YISHUN RING ROAD #06-581

Postcode

760114

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBH5858T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

3/21/2019

E-FILE

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)






































...CLAIM SUBFOLDER...(Pending for Survey Report)












| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 06 Mar 2019 | | 07 Mar 2019 17:29 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | -, Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | 5M PARTNERS PTE LTD , Co. Reg. No.: 201811126M | | | | | | | | |
| Vehicle Reg. No.: | SJL8217H | Date of Loss: | 03/02/2019 18:00 - :59 [121 Months and 22 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / SNM19D200746C02 | Policy/Cover Note No.: | DMCVSN1812861800 | | | | | | |
| Vehicle Reg. No. (Insured): | GBH5858T | Policy No. (Claimant): | 5104270765 | | | | | | |
| | | Excess: | S\$500.00 | | | | | | |
| Repairer: | Team Auto Pro Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #06-21 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong] | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/03/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |


Claim Documents










*SJL8217H (SNM19D200746C02)
[GBH5858T]
TP
5M PARTNERS PTE LTD
Feb 3 2019 6:00PM
[-]
Team Auto Pro Pte Ltd




| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 12/03/19 08:56 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 12/03/19 08:57 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 12/03/19 08:57 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 12/03/19 10:27 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 14/03/19 09:41 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--------------------|---|-------------------------------------|
| No | Finalized On | VAC (Sin Ming) | Thumbnail | Print |
| 1 | 04/02/19 14:37 | Accident Statement |  Load HTM | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|-----------------|--|-------------------------------------|
| No | Finalized On | VAC (Sin Ming) | Thumbnail | Print |
| 1 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 04/02/19 14:35 | Driving License |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 04/02/19 14:35 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|----------------|--|-------------------------------------|
| No | Finalized On | VAC (Sin Ming) | Thumbnail | Print |
| 1 | 04/02/19 14:37 | Sketch Plan |  Load TIF | |
| 2 | 04/02/19 14:37 | Sketch Plan #2 |  Load TIF | |
| 3 | 04/02/19 14:37 | Sketch Plan #3 |  Load TIF | |

Documents Checklist

| |
|--|
| DOCUMENTS CHECKLIST Reset Save Print |
| There are no document checklists configured. |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> |

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI19004153/GCD3E2**Date:** 22/03/2019REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1812861800

**Claimant Vehicle
No :** SJL8217H**Insured Vehicle
No :** GBH5858T

Date of Loss: 03/02/2019

Nature of Claim: TP

**Claim
No:** SNM19D200746C02DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJL8217H**

Make & Model: HONDA STREAM, 1.7 (A)

Reg. Date: 12/12/2008 (Man. Year: 2008)

Colour: Silver

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: R18A1776807

Chassis No: RN61069393

Odometer: 259571 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17

Front Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Tyre Size: 215/50Z R17

Rear Left Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (\$\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 07/03/2019

Date Inspected: 08/03/2019 Inspected At:

Team Auto Pro Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #06-21 Premier @ Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 22 Mar 2019) |
| Parts: | M1-MPV | HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJL8217H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >