

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9597U**AAD1903-015***Not Authorised**Resuming Bk repair**82077.28*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9597U

JTDKB3FU503077301

RENAULT

LATITUDE

3.3.2019

EQ

12/12/2018

PART**LIST**

1	1 FRONT BUMPER	\$	<i>As</i>	499.90	✓
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>SL</i>	101.20	X
3	1 REINFORCEMENT, FRONT BUMPER	\$	<i>N</i>	696.40	X
4	1 ABSORBER, FRONT BUMPER, LOWER	\$	<i>SL</i>	130.20	X
5	1 ABSORBER, FRONT BUMPER ENERGY	\$	<i>SL</i>	78.10	X
6	1 FRONT BUMPER SIDE RETAINER RH	\$	<i>Dir</i>	78.00	✓
7	1 FRONT BUMPER SIDE RETAINER LH	\$	<i>SL</i>	78.00	} X
8	1 FRONT BUMPER SUPPORT	\$	<i>SL</i>	81.70	
9	1 EXTENSION, FRONT BUMPER, RH	\$	<i>SL</i>	117.80	
10	1 EXTENSION, FRONT BUMPER, LH	\$	<i>SL</i>	117.80	
11	1 FRONT LED LAMP (LOWER) RH	\$	<i>SL</i>	907.75	
12	1 FRONT LED LAMP (LOWER) LH	\$	<i>SL</i>	907.75	
13	1 FRONT HEADLAMP RH	\$	<i>SL</i>	2,909.04	
14	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>SL</i>	492.30	
15	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>SL</i>	413.10	
16	1 FRONT HEADLAMP LH	\$	<i>SL</i>	2,909.04	
17	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>SL</i>	492.30	} X
18	1 MOTOR, HEADLAMP LEVELING, RH	\$	<i>SL</i>	413.10	
19	1 FRONT FENDER RH	\$	<i>As</i>	945.30	✓
20	1 EXTENSION, FRONT FENDER, RH	\$	<i>SL</i>	48.80	X
21	1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>SL</i>	98.30	X
22	1 LINER, FRONT FENDER, RH	\$	<i>SL</i>	200.70	X
23	1 FRONT FENDER EMBLEM RH	\$	<i>SL</i>	86.50	✓
24	1 SEAL, FENDER APRON MUDGUARD, RH	\$	<i>SL</i>	50.90	} X
25	1 FRONT BONNET	\$	<i>N</i>	950.50	
26	1 FRONT LOWER ARM	\$	<i>SL</i>	631.90	
27	1 FRONT SHOCK ABSORBER	\$	<i>SL</i>	398.20	
28	1 SHAFT ASSY, FRONT DRIVE, RH	\$	<i>N</i>	1,186.20	
29	1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	<i>SL</i>	637.50	

Trans-cab Auto Services Pte Ltd

AAD1903-015

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9597U

30	1 KNUCKLE, STEERING, RH	\$	562.30	}	X
31	1 LINK ASSY, FRONT STABILIZER, RH	\$	199.00		
32	1 BAR, STABILIZER, FRONT	\$	360.30		
33	1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	200.60		
34	1 ABSORBER ASSY, SHOCK, FRONT RH	\$	401.80		
35	1 COCK ASSY, RESERVE TANK	\$	117.80		
		\$	18,500.08		
		25% \$	4,625.02		
		\$	13,875.06		

Specical Nett

1	1 FRONT WHEEL RIM	\$	1,570.55	X
2	1 FRONT WHEEL RIM COVER	\$	175.80	X
3	1 CLIP, FRONT FENDER LINER	\$	22.00	X
		TOTAL \$	1,768.35	
		TOTAL PARTS \$	15,643.41	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	440/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	400/
To Rust-Proofing Of The Affected Areas.	\$	170.00	3d
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9597U**AAD1903-015**

To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00 X
To replace, refix and top up coolant for radiator	\$	nn 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn 380.00 X

TOTAL \$ 10,400.00**Over All Total \$ 39,918.47****(PART-BY-PART) Repair Days**~~14~~ days

2 days

LKK Auto Company will ensure notify the Repairer of the following:

- To resurvey before resurvey, painting
- To display damage to the car during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplemental work must be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: