



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2082Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	830.00	830.00
1	FRONT BUMPER SIDE RETAINER (RHS) (CONSISTENT)	NECESSARY	70.00	70.00
2	FRONT BUMPER RIVET @\$5.00 (CONSISTENT)	NECESSARY	10.00	10.00
10	FRONT BUMPER CLIPS @\$4.00 (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT FENDER (RHS) (CONSISTENT)	BENT	395.00	395.00
1	FRONT HEADLAMP (RHS) (CONSISTENT)	NOT NECESSARY	1,020.00	-
1	WASHER TANK (CONSISTENT)	DEFORMED	125.00	125.00
1	FENDER BRACKET (CONSISTENT)	BENT	45.00	45.00
	LESS 20% DISCOUNT		-507.00	-303.00
			2,028.00	1,212.00
	<u>LABOUR</u>			
	TO REMOVE & REFOCUS FRONT HEADLAMP.		120.00	30.00
	TO PANEL BEAT & KNOCKING.		800.00	500.00
	TO PUTTY & SPRAY PAINT ON THE FRONT BUMPER & RHS FRONT FENDER.		600.00	500.00
	TO APPLY RUST PROOFING & TUFFCOATING TREATMENT.		100.00	30.00
			1,620.00	1,060.00
	GRAND TOTAL		3,648.00	2,272.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00

Report Ref No. CC4/ASM19004198/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.