

Accident Photo



YANG RU JIA TRANSPORT PTE LTD
c/o Connect3
566 Woodlands Road
Singapore 728697

VEHICLE DAMAGE INSPECTION REPORT

CLAIM REFERENCE

| | | | |
|---------------|--------------|---------------|---------------|
| Our Ref. No. | : 22903 | Policy Number | : 5106637311 |
| Accident Date | : 04-03-2019 | Claim Type | : Third Party |
| Survey Date | : 08-03-2019 | | |
| Report Date | : 04-04-2019 | | |

DESCRIPTION AND IDENTIFICATION OF VEHICLE

| | | | |
|-------------------|-----------------------|--------------|-----------------|
| Vehicle No. | : PC5632M | Chassis No. | : KDH2010198076 |
| Registration Date | : 18-01-2017 | Engine No. | : 1KD2620563 |
| Make | : TOYOTA | Engine Cap. | : 2982 |
| Model | : REGIUS ACE DX 3.0 A | Transmission | : Automatic |
| | | Colour | : Silver |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | |
|------------|---------------|--------------|---------------|
| Foot Brake | : Serviceable | Steering | : Serviceable |
| Hand Brake | : Serviceable | Modification | : None |
| Odometer | : 143426 | | |

| <u>TYRES</u> | <u>SIZE</u> | <u>MAKE</u> | <u>BALANCE</u> |
|--------------|-------------|-------------|----------------|
| FRONT RH | 195R15 | BRIDGESTONE | 5 mm |
| FRONT LH | 195R15 | BRIDGESTONE | 5 mm |
| REAR RH | 195R15 | BRIDGESTONE | 5 mm |
| REAR LH | 195R15 | BRIDGESTONE | 5 mm |

SURVEY CONDUCTED PLACE

CONNECT3
566 WOODLANDS ROAD
SINGAPORE 728697

INSPECTION SUMMARY

| | |
|-------------------------|------------------|
| Workshop Estimate | : S\$ 8497.77 |
| Our Recommendation | : S\$ 5713.63 |
| Estimated Repair Period | : 5 working days |

We have not authorised repairs. This survey was carried out on without prejudice basis.

INFINITI APPRAISAL SERVICE

RECOMMENDED SPARE PARTS

PC5632M-04032019

| # | Qty | Parts Description | Condition | Repairer's Estimate (\$) | Our Adjustment (\$) |
|------------------|-----|----------------------------|-------------|--------------------------|---------------------|
| LIST ITEM | | | | | |
| 1 | 1 | Rear Tailgate | Bent | 1775.30 2459.13 | 2459.13 |
| 2 | 1 | Rear Bumper | Bent | 491.11 | 491.11 |
| 3 | 1 | Rear Bumper Clips | Necessary | 25.00 | 25.00 |
| 4 | 1 | Rear Lh Taillamp | Crack | 354.80 449.20 | 449.20 |
| 5 | 1 | Rear Lh Corner Panel | Dent | 230.52 | 230.52 |
| 6 | 1 | Rear Tailgate Lock | Dent | 332.21 | 332.21 |
| 7 | 1 | Rear Tailgate Inner Trim | Serviceable | 324.60 | 0.00 |
| 8 | 1 | Supplementary | | 0.00 | 0.00 |
| 9 | 1 | Rear End Panel Outer | Dent | 289.70 429.80 | 429.80 |
| 10 | 1 | Rear End Panel Top Garnish | Dent | 154.41 | 154.41 |
| 11 | 1 | Rear Tailgate Outer Handle | Dent | 140.01 | 140.01 |
| 12 | 1 | Rear Tailgate Logo | Necessary | 86.78 | 86.78 |
| Less 25 % | | | | 3913.63 : | 4798.17 |
| | | | | | 0.00 |
| | | | | TOTAL 2925.22 : | 3598.63 |

| | | | | | |
|--------------------------|---|------------------------|-----------|----------------|---------------|
| SPECIAL NETT ITEM | | | | | |
| 1 | 1 | Reverse Sensor | Cut | 250.00 | 250.00 200 |
| 2 | 1 | Sealant | Necessary | 80.00 | 60.00 |
| 3 | 1 | Rear No Plate W/holder | Dent | 50.00 | 50.00 45 |
| 4 | 1 | 70km/h Sticker | Necessary | 15.00 | 15.00 |
| | | | | TOTAL : | 395.00 |
| | | | | | 375.00 |

320

INFINITI APPRAISAL SERVICE RECOMMENDED LABOUR

PC5632M-04032019

| # | Job Description | Repairer's Estimate (S\$) | Our Adjustment (S\$) |
|-------------------|----------------------------|---------------------------|----------------------|
| 1 | Transfer tailgate fitting. | 200.00 | 120.00 60. |
| 2 | Check wiring. | 80.00 | 20.00 |
| 3 | Spray painting. | 1200.00 | 800.00 500 |
| 4 | Panel beating. | 1500.00 | 800.00 600 |
| TOTAL LABOUR COST | | : 2980.00 | 1740.00 |

COST OF CLAIM

| Description | Repairer's Estimate (S\$) | Our Adjustment (S\$) |
|--------------------------|---------------------------|----------------------|
| Total Recommended Parts | : 5517.77 | 3973.63 |
| Total Recommended Labour | : 2980.00 | 1740.00 |
| Total Cost of Claim | : 8497.77 | 5713.63 |

\$4435.22
5day.

OUR FINDINGS AND RECOMMENDATION

OUR FINDINGS

At the place of survey, we saw this vehicle sustained rear damage.

The damages seen during our survey were rear tailgate, rear taillamp, rear bumper and etc being damaged. The detailed description of the damages is listed as 'RECOMMENDED SPARE PARTS'.

OUR RECOMMENDATION

CONNECT3 estimated a repair cost of S\$8497.77. We adjusted it to S\$5713.63 on a part-by-part basis.

We recommend repairs to this vehicle be carried out on a part-by-part basis S\$5713.63 .

The repairs would require a period of 5 working days.

We submit our inspection report for your kind attention and would add the inspection was carried out to the best of our ability, knowledge and experience.



Edward Cho
INFINITI APPRAISAL SERVICE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|--|--|------------|---|
| Main | 05 Mar 2019 | | 07 Mar 2019 15:19 Edit Adj Rpt | S\$4,435.22 Edit Estimates | S\$4,435.22 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

| | | | | |
|-----------------------------|---|------------------------|--|--|
| Insured: | -, Co. Reg. No.: - | | [Created by insurer] | |
| Main Claimant: | YANG RU JIA TRANSPORT PTE LTD, Co. Reg. No.: 201506952R | | | |
| Vehicle Reg. No.: | PC5632M | Date of Loss: | 04/03/2019 15:00 - :59 [25 Months and 14 Days From LTA Reg Date (Man Yr)] | |
| Claim Type: | TP / SNM19D201075C02 | Policy/Cover Note No.: | DMCVSN17257718011 | |
| Vehicle Reg. No. (Insured): | GBE8568B | Policy No. (Claimant): | 5106637311 | |
| | | Excess: | S\$500.00 | |
| Repairer: | Connect 3 (HQ) 7 OLD TOH TUCK ROAD, 597648 Bukit Batok - Tel: | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong] | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 18/03/2019] | | | |

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*PC5632M (SNM19D201075C02)
[GBE8568B]
TP
YANG RU JIA TRANSPORT PTE LTD
Mar 4 2019 3:00PM
[-]
Connect 3

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Documentation

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | 1 per page ▼ | ✓ |
|----|-----------------|-----------------------------------|--------------|-------|
| 1 | 09/09/19 09:11 | LETTER | Thumbnail | Print |
| | | | Load PDF | |

Linked Accident Report Documents

Assessment Reports

View [View in Browser](#) ▼

| No | Finalized On | Hua Hong Pte Ltd (Sungei Kadut) | 1 per page ▼ | ✓ |
|----|----------------|---------------------------------|--------------|-------|
| 1 | 05/03/19 13:37 | Accident Statement | Thumbnail | Print |
| | | | Load HTM | |

Photos/Images

| No | Finalized On | Hua Hong Pte Ltd (Sungei Kadut) | 3 per page ▼ | ✓ |
|----|----------------|---------------------------------|--------------|-------|
| 1 | 05/03/19 13:35 | Accident Photo | Thumbnail | Print |
| | | | Load JPG | ✓ |
| 2 | 05/03/19 13:35 | Accident Photo | Thumbnail | Print |
| | | | Load JPG | ✓ |
| 3 | 05/03/19 13:35 | Accident Photo | Thumbnail | Print |
| | | | Load JPG | ✓ |
| 4 | 05/03/19 13:35 | Accident Photo | Thumbnail | Print |
| | | | Load JPG | ✓ |

Documentation

| No | Finalized On | Hua Hong Pte Ltd (Sungei Kadut) | 1 per page ▼ | ✓ |
|----|----------------|---------------------------------|--------------|-------|
| 1 | 05/03/19 13:34 | Accident Sketch Plan | Thumbnail | Print |
| | | | Load TIF | |
| 2 | 05/03/19 13:34 | Accident Sketch Plan | Thumbnail | Print |
| | | | Load TIF | |
| 3 | 05/03/19 13:34 | POLICE REPORT | Thumbnail | Print |
| | | | Load TIF | |
| 4 | 05/03/19 13:34 | POLICE REPORT | Thumbnail | Print |
| | | | Load TIF | |
| 5 | 05/03/19 13:34 | POLICE REPORT | Thumbnail | Print |
| | | | Load TIF | |

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#)
[Save](#)
[Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

 (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

 Our File No: CS1/CTI19004210/T1QD3S2
 Date: 09/09/2019

REFERENCE

| | | | |
|-----------------------|---|----------------------|-------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSN17257718011 |
| Claimant Vehicle No : | PC5632M | Insured Vehicle No : | GBE8568B |
| Date of Loss: | 04/03/2019 | Nature of Claim: | TP |
| | | Claim No: | SNM19D201075C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---------------------------------|-------------|---------------|
| Reg No: | PC5632M | Engine No: | 1KD2620563 |
| Make & Model: | TOYOTA REGIUS ACE, 3.0 D DX (A) | Chassis No: | KDH2010198076 |
| Reg. Date: | 18/01/2017 (Man. Year: 2016) | Odometer: | 143426 km |
| Colour: | Silver | | |
| Engine Capacity: | 2982 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 195 R15 | Rear Tyre Size: | 195 R15 |
| Front Left Side: | Bridgestone 5 mm | Rear Left Side: | Bridgestone 5 mm |
| Front Right Side: | Bridgestone 5 mm | Rear Right Side: | Bridgestone 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 5,517.77 | 3,255.22 | 2,262.55 | 41.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,980.00 | 1,180.00 | 1,800.00 | 60.40 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 8,497.77 | 4,435.22 | 4,062.55 | 47.81 |
| + GST 7.00/7.00% (S\$) | 594.84 | 310.47 | 284.37 | 47.81 |
| Nett Amount (S\$) | 9,092.61 | 4,745.69 | 4,346.92 | 47.81 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--------------------|
| Date of Assignment: | 07/03/2019 | Inspected At: | 566 WOODLANDS ROAD |
| Date Inspected: | 22/08/2019 | Repairer: | Connect 3 |
| Estimated Period of Repair: | 5.0 days | | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|----------------------|--|
| Part Source: | (Last Synchronised: 09 Sep 2019) |
| Parts: | N/A TOYOTA REGIUS ACE 3.0 D DX (A) (Model not available in database) |
| Labour: | Repairer's (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for PC5632M) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|-------------|--|-----------------|
| 1 | 1 | | *REAR TAILGATE | Bent | 2,459.13 F | *1,775.30 FL |
| 2 | 1 | | *REAR BUMPER | Bent | 491.11 F | *491.11 FL |
| 3 | 1 | | *REAR BUMPER CLIPS | Necessary | 25.00 F | *25.00 FL |
| 4 | 1 | | *REAR LH TAILLAMP | Cracked | 449.20 F | *354.80 FL |
| 5 | 1 | | *REAR LH CORNER PANEL | Dented | 230.52 F | *230.52 FL |
| 6 | 1 | | *REAR TAILGATE LOCK | Dented | 332.21 F | *266.00 FL |
| 7 | 1 | | *REAR TAILGATE INNER TRIM | Serviceable | 324.60 F | *- FL |
| 8 | 1 | | *REAR END PANEL OUTER | Dented | 429.80 F | *389.70 FL |
| 9 | 1 | | *REAR END PANEL TOP GARNISH | Dented | 154.41 F | *154.41 FL |
| 10 | 1 | | *REAR TAILGATE OUTER HANDLE | Dented | 140.01 F | *140.01 FL |
| 11 | 1 | | *REAR TAILGATE LOGO | Necessary | 86.78 F | *86.78 FL |
| 12 | 1 | | *REVERSE SENSOR | Cut | 250.00 FS | *200.00 FS |
| 13 | 1 | | *SEALANT | Necessary | 80.00 FS | *60.00 FS |
| 14 | 1 | | *REAR NO PLATE W/HOLDER | Dented | 50.00 FS | *45.00 FS |
| 15 | 1 | | *70KM/H STICKER | Necessary | 15.00 FS | *15.00 FS |
| | | | | | Sub Total (S\$) | 5,517.77 |
| | | | | | - List Item Discount on L Items 0.00/25.00% (S\$) | 0.00 |
| | | | | | Total Parts (S\$) | 5,517.77 |
| | | | | | | 4,233.63 |
| | | | | | | 978.41 |
| | | | | | | 3,255.22 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|----------------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TRANSFER TAILGATE FITTING. | New | 200.00 | 60.00 |
| 2 | CHECK WIRING. | New | 80.00 | 20.00 |
| 3 | SPRAY PANTING. | New | 1,200.00 | 500.00 |
| 4 | PANEL BEATING. | New | 1,500.00 | 600.00 |
| Gross Labour Cost (\$\$) | | | 2,980.00 | 1,180.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >