

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Mar 2019 Edit Reg		07 Mar 2019 00:00 Edit Adj Rpt	S\$733.60 Edit Estimates	S\$733.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Alsecure International Pte Ltd , Co. Reg. No.: -									
Main Claimant: BAN HOCK HIN COMPANY PRIVATE LIMITED , Co. Reg. No.: 197000288K									
Vehicle Reg. No.:	FBN1513H	Date of Loss:	03/03/2019 12:00 - :59 [7 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0511407137SG	Policy/Cover Note No.:	2100359501 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKL7647U	Policy No. (Claimant):	AVFMSB0000651800						
		Excess:							
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (08/03/2019): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBN1513H (0511407137SG)**
[SKL7647U]

TP

BAN HOCK HIN COMPANY PRIVATE LIMITED

Mar 3 2019 12:00PM

[Alsecure International Pte Ltd]

Ban Hock Hin Co. Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/03/19 17:38	Odometer Reading	 Load JPG	☒
2	07/03/19 17:39	General View	 Load JPG	☒
3	07/03/19 17:39	General View	 Load JPG	☒
4	07/03/19 17:39	General View	 Load JPG	☒
5	07/03/19 17:39	General View	 Load JPG	☒
6	07/03/19 17:39	General View	 Load JPG	☒
7	07/03/19 17:39	General View	 Load JPG	☒
8	07/03/19 17:39	General View	 Load JPG	☒
9	07/03/19 17:39	General View	 Load JPG	☒
10	07/03/19 17:39	General View	 Load JPG	☒
11	07/03/19 17:39	General View	 Load JPG	☒
12	07/03/19 17:39	General View	 Load JPG	☒
13	07/03/19 17:39	General View	 Load JPG	☒
14	07/03/19 17:39	General View	 Load JPG	☒
15	07/03/19 17:39	General View	 Load JPG	☒
16	07/03/19 17:39	General View	 Load JPG	☒
17	07/03/19 17:39	General View	 Load JPG	☒
18	07/03/19 17:39	General View	 Load JPG	☒
19	07/03/19 17:39	General View	 Load JPG	☒
20	07/03/19 17:39	General View	 Load JPG	☒
21	07/03/19 17:39	General View	 Load JPG	☒
22	07/03/19 17:39	General View	 Load JPG	☒
23	07/03/19 17:39	General View	 Load JPG	☒
24	07/03/19 17:39	General View	 Load JPG	☒
25	07/03/19 17:39	General View	 Load JPG	☒
26	07/03/19 17:39	General View	 Load JPG	☒
27	07/03/19 17:39	General View	 Load JPG	☒
28	07/03/19 17:39	General View	 Load JPG	☒
29	07/03/19 17:39	General View	 Load JPG	☒
30	07/03/19 17:39	General View	 Load JPG	☒
31	07/03/19 17:39	General View	 Load JPG	☒
32	07/03/19 17:39	General View	 Load JPG	☒
33	07/03/19 17:39	General View	 Load JPG	☒
34	07/03/19 17:39	General View	 Load JPG	☒
35	07/03/19 17:39	General View	 Load JPG	☒
36	07/03/19 17:39	General View	 Load JPG	☒
37	07/03/19 17:39	General View	 Load JPG	☒
38	07/03/19 17:39	General View	 Load JPG	☒
39	07/03/19 17:39	General View	 Load JPG	☒
40	07/03/19 17:39	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
41	07/03/19 17:39	General View		Load JPG ☒
42	07/03/19 17:39	General View		Load JPG ☒
43	07/03/19 17:39	General View		Load JPG ☒
44	07/03/19 17:39	General View		Load JPG ☒
45	07/03/19 17:39	General View		Load JPG ☒
46	07/03/19 17:39	General View		Load JPG ☒
47	07/03/19 17:39	General View		Load JPG ☒
48	07/03/19 17:39	General View		Load JPG ☒
49	07/03/19 17:39	General View		Load JPG ☒
50	07/03/19 17:39	General View		Load JPG ☒
51	07/03/19 17:39	General View		Load JPG ☒
52	07/03/19 17:39	General View		Load JPG ☒
53	07/03/19 17:39	General View		Load JPG ☒
54	07/03/19 17:39	General View		Load JPG ☒
55	07/03/19 17:39	General View		Load JPG ☒
56	07/03/19 17:39	General View		Load JPG ☒
57	07/03/19 17:39	General View		Load JPG ☒
58	07/03/19 17:39	General View		Load JPG ☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/03/19 15:26	TP ESTIMATE- MARKED		Load PDF
2	08/03/19 15:26	TP GIA REPORT		Load PDF
3	14/03/19 10:27	Non reporting letter		Load PDF
4	31/03/19 14:16	Email from OI dd 210319		Load PDF
5	27/04/20 22:28	EMAIL TO WSP DD 160120		Load PDF
6	11/05/20 11:05	EMAIL TO AIG DD 110520		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	24/04/20 23:07	OI GIA report		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19004218/UEA3S2**Date:** 15/05/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100359501
Claimant Vehicle No :	FBN1513H	Insured Vehicle No :	SKL7647U
Date of Loss:	03/03/2019	Nature of Claim:	TP
		Claim No:	0511407137SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1513H	Engine No:	G3H6E0009677
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG431000007473
Reg. Date:	26/07/2018 (Man. Year: 2018)	Odometer:	13374 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	130-70-13	Rear Tyre Size:	130-70-13
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	809.00	498.60	310.40	38.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	240.00	235.00	5.00	2.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,049.00	733.60	315.40	30.07
+ GST 7.00/7.00% (S\$)	73.43	51.35	22.08	30.07
Nett Amount (S\$)	1,122.43	784.95	337.48	30.07

INSPECTION

Date of Assignment:	07/03/2019		
Date Inspected:	07/03/2019	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Cut	35.00 F	*35.00 FL
2	1		*BOARD FOOTREST LH	Cut	52.00 F	*52.00 FL
3	1		*BOARD FOOTREST RH	Cut	52.00 F	*52.00 FL
4	1		*COVER CLUTCH OUTER	Cut	28.00 F	*28.00 FL
5	2		*COVER CLUTCH OUTER DAMPER 1	Necessary	24.00 F	*24.00 FL
6	1		*COVER CLUTCH OUTER DAMPER 2	Necessary	7.00 F	*7.00 FL
7	1		*COVER CLUTCH OUTER DAMPER 3	Necessary	7.00 F	*7.00 FL
8	1		*COVER CLUTCH OUTER DAMPER 4	Necessary	12.00 F	*12.00 FL
9	1		*COVER SIDE CENTRE LH (WHITE)	Necessary	30.00 F	*30.00 FL
10	1		*COVER SIDE CENTRE RH (WHITE)	Cut	30.00 F	*30.00 FL
11	1		*COVER SIDE REAR LH (WHITE)	Cut	38.00 F	*38.00 FL
12	1		*COWLING FRONT LH (WHITE)	Cut	34.00 F	*34.00 FL
13	1		*EMBLEM (YAMAHA) LOGO	Necessary	12.00 F	*12.00 FL
14	1		*LAMP SIGNAL FRONT LH	Scratched	35.00 F	*35.00 FL
15	1		*MUDGUARD FRONT (WHITE)	Not Necessary	52.00 F	*- FL
16	1		*PROTECTOR EXHAUST	Serviceable	38.00 F	*- FL
17	1		*SIDE STAND	Repair	25.00 F	*- FL
18	1		*STAND MAIN	Repair	68.00 F	*- FL
19	1		*STICKER (CERTIS CISCO) SIDE REAR NEW MODEL	Necessary	45.00 F	*45.00 FL
20	1		*STICKER (CERTIS CISCO) WINDSHIELD NEW MODEL	Necessary	60.00 F	*60.00 FL
21	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	38.00 F	*38.00 FL
22	1		*STICKER (CISCO) SIDE REAR LH NEW MODEL	Necessary	15.00 F	*15.00 FL
23	1		*STICKER NUMBER PLATE FRONT (BLACK)	Not Necessary	12.00 F	*- FL
24	1		*WINDSHIELD	Not Necessary	60.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	809.00	554.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	55.40
Total Parts (\$\$)	809.00	498.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR - FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED.	New	105.00	100.00
2	SPRAY PAINT FRONT MUDGUARD (LAQUER).	New	40.00	40.00
3	SPRAY PAINT TAIL COWLING LH (LACQUER).	New	60.00	60.00
4	TRANSPORT CHARGES - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BACK ONCE REPAIR DONE.	New	35.00	35.00
Gross Labour Cost (\$\$)			240.00	235.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >