

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMG6313S

Chassis No : JHMRC1890KC200480

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : HO CHIN NING

Ins Policy No. :

Date of Accident : 5/3/2019

Document No. : SQT19001062

Date : 6. Mar 2019

Customer No. : WZA006

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : K24W72460389

Date | Time : 6. Mar 2019 7:48:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: HO CHIN NING						
	OWNER INSURER: AVIVA						
	ACC DATE: 05/03/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA						
	TP VEH: SLQ7060Z						
68100-T6A-Q10ZZ	TAILGATE COMP	1 <i>ht</i>	1070.80	25	803.10	56.22	859.32
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1 <i>?</i>	206.30	25	154.72	10.83	165.55
84433-T6A-J01ZA	GARNISH ASSYTAILGATE UPPER	1 <i>?</i>	42.60	25	31.95	2.24	34.19
68210-T6A-003ZZ	HINGE COMPTAILGATE	2 <i>Ry</i>	35.80	25	53.70	3.76	57.46
74440-T6A-003	WEATHERSTRIPTAILGATE	1 <i>?</i>	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE	1 <i>?</i>	185.40	25	139.05	9.73	148.78
74820-T6A-013	STAY ASSYR.TAILGATE OPEN	1 <i>?</i>	164.50	25	123.37	8.64	132.01
74870-T6A-013	STAY ASSYL.TAILGATE OPEN	1 <i>?</i>	164.50	25	123.37	8.64	132.01
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1 <i>?</i>	10.70	25	8.02	0.56	8.58
74890-T6A-N11ZE	GARNISH ASSY,RR.LICEION LID	1 <i>?</i>	164.20	25	123.15	8.62	131.77
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1 <i>?</i>	175.50	25	131.62	9.21	140.83
75701-T6A-000	EMBLEMH	1 <i>nei</i>	26.30	25	19.72	1.38	21.10
91512-SR3-004	CLIP TUBULAR	2 <i>nei</i>	2.30	25	3.45	0.24	3.69
75722-T6A-901	EMBLEM,RR.	1 <i>nei</i>	31.00	25	23.25	1.63	24.88
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2 <i>nei</i>	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1 <i>nei</i>	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1 <i>nei</i>	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4 <i>nei</i>	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	1 <i>nei</i>	3.70	25	2.77	0.19	2.96

Printed on 7/3/2019 1:33:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMG6313S

Chassis No : JHMRC1890KC200480

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : HO CHIN NING

Ins Policy No. :

Date of Accident : 5/3/2019

Document No. : SQT19001062

Date : 6. Mar 2019

Customer No. : WZA006

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : K24W72460389

Date | Time : 6. Mar 2019 7:48:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5	2 <i>na</i>	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT	1 <i>na</i>	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2 <i>na</i>	60.00		120.00	8.40	128.40
33500-T6A-J51	LIGHT ASSY,R.TAIL	1 ?	838.10	25	628.57	44.00	672.57
33550-T6A-J51	LIGHT ASSY,L.TAIL	1 ?	838.10	25	628.57	44.00	672.57
34150-T6A-J51	LIGHT ASSY,R.LID	1 <i>cur</i>	386.20	25	289.65	20.28	309.93
34155-T6A-J51	LIGHT ASSY,L.LID	1 <i>cur</i>	378.60	25	283.95	19.88	303.83
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER	1 <i>de</i>	557.20	25	417.90	29.25	447.15
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1 <i>na</i>	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1 <i>na</i>	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	8 <i>na</i>	2.30	25	13.80	0.97	14.77
84640-T6A-003ZA	LINING ASSYRR.PANEL	1 ?	103.60	25	77.70	5.44	83.14
33505-SLJ-013	REFLECTOR ASSYR.RR.	1 ?	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR.	1 ?	45.40	25	34.05	2.38	36.43
66100-T6A-Q00ZZ	PANEL COMP,REAR	1 ?	460.80	25	345.60	24.19	369.79
04656-T6A-310ZZ	PAN SET,3RD SEAT	1 ?	337.90	25	253.42	17.74	271.16
74940-TR0-003	BUZZER ASSYSMART	1 ?	60.10	25	45.07	3.15	48.22
72841-SH3-315	OILSHEET	3 ?	40.70	25	91.57	6.41	97.98
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1 <i>na</i>	320.00		320.00	22.40	342.40
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1 ?	45.00		45.00	3.15	48.15
Sum Item					5567.22	389.70	5,956.92
BOSUN	SUNDRIES	1 <i>50</i>	100.00		100.00	7.00	107.00
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1 ✓	200.00		200.00	14.00	214.00
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1 ✓	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 ✓	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1 <i>80</i>	100.00		80	100.00	7.00
BOJSE	BODY JOINT SEALANT END PANEL	1 <i>80</i>	100.00		80	100.00	7.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1 <i>80</i>	100.00		80	100.00	7.00

Printed on 7/3/2019 1:33:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMG6313S

Chassis No : JHMRC1890KC200480

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : HO CHIN NING

Ins Policy No. :

Date of Accident : 5/3/2019

Document No. : SQT19001062

Date : 6. Mar 2019

Customer No. : WZA006

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : K24W72460389

Date | Time : 6. Mar 2019 7:48:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Date of Accident : 5/3/2019						0% GST Amount	Amount incld GST
Item	Description	Qty	Unit Price	Disc %	Amount		
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00		800.00	56.00	856.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00		800.00	56.00	856.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	120.00		120.00	8.40	128.40
BKRP22B	CUT OFF & RENEW RR FLOOR PANEL & DAMAGE PARTS.	1	4000.00		4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00		3000.00	210.00	3210.00
Repair - 1350					Sum Labor	10260.00	718.20
							10,978.20

Survey By

Date & Time

Excess

Status

Signature

Total Amount 15,827.22 1,107.90 16,935.12

Total (Inclusive of GST) 16,935.12

Tanfile 17495749
12/3/19 1730
WP
Repair before paint.
sure lkhauto.com
tanfile & lkhauto.com
7-8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during repair
- Parts prices are subject to change without notice
- Third party survey is on "Without Prejudice"
- No illegal modifications allowed
- Supplementary items are subject to final approval from

Acknowledged by Repairer

Signature:

Date:

Printed on 7/3/2019 1:33:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****4345G / HO CHIN NING
Chassis No: JHMRC1890KC200480
License No: SMG6313S
Mileage: 4159
Engine No: K24W72460389

Document No: SVO19016013
Printed By: ANIKKALAI
Order Date: 12. March 2019
Order Time: 6:11:17 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
39683-T6A-N11ZC	RETAINER,PARKING	1	41.80	25	31.35	2.19	33.54
39683-T6A-N11ZB	RETAINER,PARKING	1	41.80	25	31.35	2.19	33.54
SUM PARTS:					62.70	4.38	67.08
TOTAL SGD					62.70	4.38	67.08

Total Payable (SGD)

67.08

GST Amount is calculated from individual line(s)