# Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North. #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER:

China Taiping Insurance (Singapore) Pte, Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

Ref. No: Date of Loss:

02/03/2019

Policy No:

DMCVSN3079271803 GBE3828J

Driveable?

Vehicle Reg. No.:

UNKNOWN

Driver Age/Info:

56 / MALE

Party At Fault:

TP Injury Involved?

YES

Third Party Involved?

YES

MEYER HOUSEWARE (SINGAPORE)

Insured/Claimant:

PTE LTD

Driver:

CHAN GEEN WAI

Make/Model:

TOYOTA DYNA, 3.0 D (M)

Vehicle Reg. Date:

11/11/2015

Vehicle Colour:

WHITE

1KD2549523

Chassis No:

KDY2318021241

Engine No: Odometer:

5 KM

Paint Type:

Total Loss?

NO

Est. Duration of Repair (day)

Description of Accident/Loss

AS PER POLICE REPORT NO: T/20190302/2137

**Present Location:** 

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS		Amount
Parts		2,090.00
Miscellaneous Items		0.00
Labour		1,550.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	3,640.00
	+ GST 7.00% (S\$)	254.80
	Nett Amount (S\$)	3,894.80

This claim is handled by: SAMANTHA TAN YONG SING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# REPAIR DETAILS

### Reference

Part Source:

(Last Synchronised: 06 Mar 2019)

Parts:

TOYOTA DYNA 3.0 D (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE3828J)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF

ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Estimates on Parts

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*FRT TYRE MUDGUARD RH	0.00	0.00	*170.00 F
2	1	*FRT TYRE MUDFLAP RH	0.00	0.00	*120.00 F
3	1	*FRT TYRE MUDGUARD BRACKET RH # 155	0.00	0.00	*55.00 F
4	1	*FRT AIR INTAKE DUCT "DE 🗸	0.00	0.00	*75.00 F
5	1	*FRT AIR INTAKE JOINT	0.00	0.00	*75.00 F
6	1	*FRT AIR INTAKE CLEANER BOX ***********************************	0.00	0.00	*340.00 F
7	1	*FRT AIR INTAKE FILTER "# /	0.00	0.00	*35.00 F
8	1	*DIESEL TANK B1 7 4 7 / 0 4 - 84/	0.00	0.00	*450.00 F
9	2,	*DIESEL TANK BRACKET	0.00	0.00	*110.00 F
10 /	RILL	*DIESEL TANK HOLDER "# / '	0.00	0.00	*110.00 F
11	£100	*DIESEL TANK RUBBER AUC	0.00	0.00	*100.00 F
12 1	1 1	*REAR BOX SLIDING DOOR LOWER PANEL PA	0	0.00	*450.00 FS

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

Total Parts (S\$)

2,090.00

#### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

#### Estimates on Labour

No Particulars Lab.Type **Amount Labour Items** TO KNOCK, WELD FRT DOOR PILLAR RH, RR BOX STEP (SIDE) RH, REMOVE & FIX ON ABOVE PARTS New TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS 2 New TO REMOVE & FIX DIESEL TANK New **Gross Labour Cost (S\$)** 1,550.00

> Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

> > < END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Cumpany

Acknowledged by Repairer

Signature:

Date:

EXCER: SOU

RELET

OB/03/19 P1650

Resurry before paint