

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 11 Mar 2019

Preliminary Advice

Vehicle No	: GBE3828J	Accident Date	: 02/03/2019
Make	: TOYOTA DYNA	Policy No.	: DMCVSN3079271803
Assignment Date	: 07/03/2019	Excess	: S\$500.00
Date of Inspection	: 08/03/2019	Est. Duration of Repair	: 6.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,640.00
Revised Amount	:S\$	3,000.00
Check Items (Estimated)	:S\$	55.00
Total	:S\$	3,055.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	14,948.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,052.00

Brake System : In Order
Steering System : In Order
Tyre Condition (Front) : 7/7 mm
Tyre Condition (Rear) : 6/6 (D)

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part.