



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLP 8700 J

*Not Authorized
Resurvey Repaint*

Parts	(a) Cost / List Price Items	\$	8,560.35
	Plus/Less 25%	\$	2,140.09
	Total of Cost / List	\$	6,420.26
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	300.00
Total Parts Cost		\$	6,720.26
Labour		\$	3,350.00
Total		\$	10,070.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 8/3/11 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 8/3/11



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLP 8700 J**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU803560359**

Submit By : **SERENCE**
Year Manufacture : **2017**
Engine No. : **2ZRS053253**

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	2	\$200.00	S.N	✓
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		?
7	Rear bumper lower garnish centre	1	\$582.60		✓
8	Rear bumper lower garnish LH	1	\$149.70		X
9	Rear bumper lower garnish RH	1	\$149.70		X
10	Rear bumper tow cover	1	\$31.70		X
11	Tail door	1	\$1,122.50		X
12	Tail door lock	1	\$487.70		X
13	Tail door emblem	1	\$61.70		✓
14	Wording "PRIUS"	1	\$51.90		✓
15	Wording "HYBRID"	1	\$55.47		✓
16	Tail door hinge LH	1	\$87.60		X
17	Tail door hinge RH	1	\$87.60		X
18	Tail door plate garnish	1	\$782.50		?
19	Tail door inner trim	1	\$278.90		X
20	Tail door inner trim clip	10	\$28.00		X
21	Tail end panel	1	\$596.60		X
22	Tail end panel garnish	1	\$151.60		X
23	Tail end panel garnish clip	10	\$35.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Vehicle No. :	SLP 8700 J
Make & Model :	TOYOTA PRIUS
Chassis No :	JTDKB3FU803560359

Submit By	:	
Year Manufacture	:	2017
Engine No.	:	2ZRS053253

Cost / List

[illegible]

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLP 8700 J Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, TAIL DOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, TAIL DOOR PLATE GARNISH, SPARE TYRE COMPARTMENT)	\$1,200.00	6001
3	To Check wiring	\$50.00	151
4	To remove & refit rear windscreen. <i>nn</i>	\$120.00	X
5	To remove & refit Taildoor glass to assit work load <i>h</i>	\$120.00	X
6	To transfer boot mechanism to new boot <i>h</i>	\$120.00	X
7	To conduct water leakage tests to ensure proper air and sealing <i>h</i>	\$120.00	X
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>h</i>	\$150.00	X
9	To tuff coat <i>h</i>	\$150.00	X
10	To remove & refit reverse sensor	\$120.00	501

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.