

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | |
|--|---|---------------------------------|---------------|------------------|-------------------------|
| ALLIE | LLIED WORLD ASSURANCE COMPANY LTD | | | CS3/AWA19004313/ | /R1cd3e2 |
| (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR)MAPLETREE ANSON S 079914 | | | Date: | 24-05-2019 | |
| | | | Code: | AWA | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SJR 4618D | Veh. Ir | nspected | FBN 1918Z |
| | Policy No. | AVPPSB0522481803 | Coverage (\$) | | 0.00 |
| | Claim No. | NSV1900079/BT | Excess (\$) | | 0.00 |
| | Assign From | STELLA GOH | Assign Date | | 08/03/2019 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA CB190R MANUAL | c.c | | 184 |
| | Engine No. | HIDDEN | Year of Reg. | | 2018 |
| | Chassis No. | LWBPCL10XH1005398 | Colour | | MULTI COLOUR |
| | Odometer | 10135 KM | Steering | | IN ORDER |
| | Brakes | IN ORDER | Modification | | SPORTS RIM |
| | General | FAIR | | | |
| 3. Conditions of Tyres | | | | | |
| | Size Make | | | Balance | |
| | R/H Front Tyre | 110/70 R17 | RADIAL | - | 3 mm |
| | L/H Front Tyre | | | | mm |
| | R/H Rear Tyre | 110/70 R17 | RADIAL | - | 3 mm |
| | L/H Rear Tyre | | | | mm |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. | | | | |
| 5. General Information | | | | | |
| | Accident Date | 13/02/2019 | Inspec | t Date / Time | 12/03/2019 (02:36 PM) |
| | Survey held at | eld at UNIVERSAL MOTORS PTE LTD | | | |
| | BLK 1006 BUKIT MERAH LANE 2 #01-04 SINGAPORE 159762 | | | | |
| 5a. | Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000 | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |

Report Ref No. CS3/AWA19004313/R1cd3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons), B. Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.