

72000000

ASS. REC. BY

SMV/vjv

REF

CA/TM119004325/Asd3n2

Special Instruction

ASSIGNMENT (Office)

From (Person)

Telma Gomez

of

TM

Date/Time

8/3/2019

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLE3493Y

Insured

SLD3063S

at Workshop m/c

96 Motorsports

Tel:

670-6996

of

62/64 Kaki Bukit Ave 6

Policy No.

MK000196

Claim No.

M1901458

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

8/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

Person Contacted

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLE3493Y - NA/AIG Model 57/h4 DOA: 8/3/2019

SLD3063S - X

As check workshop spare parts price - High side.

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SLE3493XYr Regn: 2016 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqaic.c. 1197Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 57547

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SJNFAAJ11U1706930Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rip / STD A/Rim orTyre Size: F: 215/60R17R: 215/60R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

P/Bal. 06

mm

R/Bal. 06

mm

L/Bal. 06

mm

L/Bal. 06

mm

D.O.A. _____

D.O.I. 11/03/19Survey held at 96 MotorsportsDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Tokio Marine22/03/19Confirmed HS \$ 3,500/- @ 4 days with Adrian
(\$10,648.59 Red - 75%)

MV: _____

PV: _____

Nett: _____

RECEIVED 25 MAR 2019

Resurvey no. of Trip: 1

Date/Time, File Pays to?

Date/Time, File Return to?

1) 35/03/19

2) _____

3) Typist

4) _____

5) _____

6) _____

Prel. Report: _____

Final Report: HS \$ 3,500/-

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

___ S + RS, ___ SI

Photos

Others

TOTAL

45010460

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2019		08 Mar 2019 14:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K			
Main Claimant:	KOH KIM CHOON, ID: S1830645Z			
Vehicle Reg. No.:	SLE3493Y	Date of Loss:	07/03/2019 14:00 - :59	
Claim Type:	TP / M1901458	Policy/Cover Note No.:	MK000196 (Third Party Only) Coverage: 25/02/2019 - 24/02/2020	
Vehicle Reg. No. (Insured):	SLQ3063S	Policy No. (Claimant):		
		Excess:	\$1,600.00	
Repairer:	96 Motorsports Pte Ltd (HQ) 62/64 Kaki Bukit Avenue 6, 417893 Kaki Bukit - Tel: 6702 6996			
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/03/2019]			
Driver/Custodian (Insured):	JASON NICODEMUS ANG HO KIAT (), NRIC: S7907088B, Tel: +6590106639 Email: -			
Adj Asg. Remarks:	PLS. CHECK WSHOP SPARE PARTS PRIVE-HIGH SIDE			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(1n)

WKSAP will contact Adrian

S JNFEA J1141706930

TP Tokio Marine.

Shirley.

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	TAIL GATE <i>Repair</i>	1	\$ 2,936.00	+
2	TAIL GATE BADGE <i>3 per</i>	1	\$ 69.70	✓
3	TAIL GATE EMBLEM (QASHQAI)	1	\$ 97.00	✓
4	TAIL GATE INNER LOCK <i>new</i>	1	\$ 167.80	+
5	TAIL GATE LOCK CATCH <i>2</i>	1	\$ 46.00	+
6	TAIL GATE WEATHERSTRIP <i>1</i>	1	\$ 198.50	+
7	TAIL GATE WINDSCREEN MOULDING <i>1</i>	1	\$ 98.40	+
8	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 50.00	x.
9	REAR BUMPER <i>Rehnd</i>	1	\$ 747.80	✓
10	REAR BUMPER SIDE RETAINER L+R <i>new</i>	2	\$ 80.00	80
11	REAR BUMPER CLIP <i>new</i>	10	\$ 50.00	30
12	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 649.00	✓
13	REAR BUMPER REINFORCEMENT BRACKET L+R <i>Rehnd</i>	2	\$ 360.00	+
14	REAR BUMPER SPONGE <i>Rehnd</i>	1	\$ 164.70	✓
15	REAR BUMPER TOWING COVER <i>Rehnd</i>	1	\$ 32.00	✓
16	REAR BUMPER REFLECTOR L+R <i>Rehnd</i>	2	\$ 140.00	70
17	TAIL LAMP L+R <i>new</i>	2	\$ 744.00	+
18	TAIL LAMP INNER SEALANT L+R <i>new</i>	2	\$ 80.00	+
19	TAIL LAMP CLIP <i>new</i>	10	\$ 20.00	+
20	END PANEL <i>Rehnd</i>	1	\$ 537.80	✓
21	END PANEL TOP TRIM <i>Rehnd</i>	1	\$ 123.00	✓
22	END PANEL TOP TRIM CLIP <i>new</i>	10	\$ 30.00	30
23	REAR KEY ANTERNE SENSOR <i>Rehnd</i>	1	\$ 84.80	+
24	SPARE TYRE PANEL TOP BOARD (OUTER)	1	\$ 398.00	+
25	SPARE TYRE PANEL TOP BOARD (INNER)	1	\$ 382.00	+
26	SPARE TYRE PANEL TOP TOOL SPONGE <i>new</i>	1	\$ 240.00	+
27	REAR FENDER ARCH PROTECTOR L+R <i>Rehnd</i>	2	\$ 986.00	493
28	REAR FENDER ARCH PROTECTOR CLIP <i>new</i>	10	\$ 30.00	15
29	REAR EXHAUST SILENSER <i>3119</i>	1	\$ 475.80	+
30	REAR EXHAUST MOUNTING <i>new</i>	2	\$ 60.00	+
31	REAR EXHAUST GASKET <i>2807.10</i>	1	\$ 40.00	+
32	REAR EXHAUST HEAT PLATE	1	\$ 146.80	+

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19004325/ASD3N2

Date: 02/04/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000196
Claimant Vehicle No :	SLE3493Y	Insured Vehicle No :	SLQ3063S
Date of Loss:	07/03/2019	Nature of Claim:	TP
		Claim No:	M1901458

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE3493Y		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2300674A
Reg. Date:	19/07/2016 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1706930
Colour:	Red	Odometer:	57547 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,078.59	3,067.10	7,011.49	69.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	1,370.00	2,700.00	66.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,148.59	4,437.10	9,711.49	68.64
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	14,148.59	3,500.00	10,648.59	75.26
+ GST 7.00/7.00% (S\$)	990.40	245.00	745.40	75.26
Nett Amount (S\$)	15,138.99	3,745.00	11,393.99	75.26

INSPECTION

Date of Assignment:	08/03/2019		
Date Inspected:	11/03/2019	Inspected At:	96 Motorsports Pte Ltd (HQ) 62/64 Kaki Bukit Avenue 6 Singapore 417893
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2019)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE3493Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE	Repair	2,936.00 FL	*- FL
2	1	*TAIL GATE BADGE	Necessary	69.70 FL	*69.70 FL
3	1	*TAIL GATE EMBLEM (QASHQAI)	Necessary	97.00 FL	*97.00 FL
4	1	*TAIL GATE INNER LOCK	Not Necessary	167.80 FL	*- FL
5	1	*TAIL GATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
6	1	*TAIL GATE WEATHERSTRIP	Not Necessary	198.50 FL	*- FL
7	1	*TAIL GATE WINDSCREEN MOULDING	Not Necessary	98.40 FL	*- FL
8	1	*TAIL GATE WINDSCREEN INNER SEAL	Not Necessary	50.00 FL	*- FL
9	1	*REAR BUMPER	Deformed	747.80 FL	*747.80 FL
10	2	*REAR BUMPER SIDE RETAINER L+R	Necessary	80.00 FL	*80.00 FL
11	10	*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
12	1	*REAR BUMPER REINFORCEMENT	Bent	649.00 FL	*649.00 FL
13	2	*REAR BUMPER REINFORCEMENT BRACKET L+R	Not Necessary	360.00 FL	*- FL
14	1	*REAR BUMPER SPONGE	Cracked	164.70 FL	*164.70 FL
15	1	*REAR BUMPER TOWING COVER	Deformed	32.00 FL	*32.00 FL
16	1	*REAR BUMPER REFLECTOR L+R	O/s Cracked	140.00 FL	*70.00 FL
17	2	*TAIL LAMP L+R	Not Necessary	744.00 FL	*- FL
18	2	*TAIL LAMP INNER SEALANT L+R	Not Necessary	80.00 FL	*- FL
19	10	*TAIL LAMP CLIP	Not Necessary	20.00 FL	*- FL
20	1	*END PANEL	Dented	537.80 FL	*537.80 FL
21	1	*END PANEL TOP TRIM	Deformed	123.00 FL	*123.00 FL
22	10	*END PANEL TOP TRIM CLIP	Necessary	30.00 FL	*10.00 FL
23	1	*REAR KEY ANTERNE SENSOR	Not Necessary	84.80 FL	*- FL
24	1	*SPARE TYRE PANEL TOP BOARD (OUTER)	Not Necessary	398.00 FL	*- FL
25	1	*SPARE TYRE PANEL TOP BOARD (INNER)	Not Necessary	382.00 FL	*- FL
26	1	*SPARE TYRE PANEL TOP TOOL SPONGE	Not Necessary	240.00 FL	*- FL
27	1	*REAR FENDER ARCH PROTECTOR L+R	O/s Deformed	986.00 FL	*493.00 FL
28	10	*REAR FENDER ARCH PROTECTOR CLIP	Necessary	30.00 FL	*15.00 FL
29	1	*REAR EXHAUST SILENSER	Not Necessary	475.80 FL	*- FL
30	2	*REAR EXHAUST MOUNTING	Not Necessary	60.00 FL	*- FL
31	1	*REAR EXHAUST GASKET	Not Necessary	40.00 FL	*- FL
32	1	*REAR EXHAUST HEAT PLATE	Not Necessary	146.80 FL	*- FL
33	1	*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
34	1	*REVERSE SENSOR	Damaged	450.00 FS	*200.00 FS
35	1	*BODY PANEL JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
36	1	*REAR NUMBER PLATE WITH COVER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,105.10 3,379.00
 - List Item Discount on L Items 10.00/10.00% (\$\$) 1,026.51 311.90

Total Parts (\$\$) 10,078.59 3,067.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	1,600.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,500.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	60.00
4	TO R&R REAR WINDSCREEN	New	150.00	0.00
5	TO R&R TAIL GATE PARTS	New	150.00	0.00
6	TO R&R REVERSE SENSOR	New	150.00	50.00
7	TO R&R CARPET AND SEAT	New	250.00	60.00
8	TO R&R REAR EXHAUST	New	150.00	0.00
Gross Labour Cost (\$\$)			4,070.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >